




TOYOKAWA 0307+444 2023/08/14(226)05:32:49-05:36:15JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0311+363 2023/08/14(226)05:36:51-05:40:17JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C84


2023/08/14(226)05:42:04-05:45:30JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0323+416 2023/08/14(226)05:48:55-05:52:21JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0326+455 2023/08/14(226)05:52:39-05:56:05JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0333+32 2023/08/14(226)05:58:37-06:02:03JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 0347+05 2023/08/14(226)06:11:39-06:15:05JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0349+382 2023/08/14(226)06:15:20-06:18:46JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0355+50 2023/08/14(226)06:21:51-06:25:17JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0400+128 2023/08/14(226)06:25:33-06:28:59JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0404+035 2023/08/14(226)06:29:13-06:32:39JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0411+05 2023/08/14(226)06:36:24-06:39:50JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0418+236 2023/08/14(226)06:43:18-06:46:44JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0422+178 2023/08/14(226)06:47:17-06:50:43JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C119

2023/08/14(226)06:54:45-06:58:11JST 203Rs

7972+/- 668




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C138 2023/08/14(226)07:42:53-07:46:19JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0531+194 2023/08/14(226)07:56:26-07:59:52JST 181Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C147 2023/08/14(226)08:04:44-08:08:10JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0548+16 2023/08/14(226)08:12:57-08:16:23JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0552+12 2023/08/14(226)08:17:08-08:20:34JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0556+191 2023/08/14(226)08:21:34-08:25:00JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C152 2023/08/14(226)08:26:07-08:29:33JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C158 2023/08/14(226)08:43:13-08:46:39JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C161 2023/08/14(226)08:48:29-08:51:55JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0629+160 2023/08/14(226)08:54:14-08:57:40JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0652-130 2023/08/14(226)09:16:02-09:19:28JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0703+138 2023/08/14(226)09:27:38-09:31:04JST 126Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0713-024 2023/08/14(226)09:37:01-09:40:27JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2023/08/14(226)09:40:41-09:44:07JST 125Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0723+10 2023/08/14(226)09:47:12-09:50:38JST 112Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0732+33 2023/08/14(226)09:57:26-10:00:52JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0741-06 2023/08/14(226)10:05:29-10:08:55JST 122Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0752-200 2023/08/14(226)10:15:14-10:18:40JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190 2023/08/14(226)10:22:48-10:26:14JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0806-103 2023/08/14(226)10:29:54-10:33:20JST 117Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C196 2023/08/14(226)10:35:12-10:38:38JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2023/08/14(226)10:41:57-10:45:23JST 65Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0821+394 2023/08/14(226)10:46:22-10:49:48JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0834-19 2023/08/14(226)10:58:03-11:01:29JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0839-071 2023/08/14(226)11:03:08-11:06:34JST 92Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208 2023/08/14(226)11:14:09-11:17:35JST 36Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0857-191 2023/08/14(226)11:20:29-11:23:55JST 124Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C216 2023/08/14(226)11:30:49-11:34:15JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2023/08/14(226)11:35:35-11:39:01JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0919-142 2023/08/14(226)11:43:02-11:46:28JST 106Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0926+117 2023/08/14(226)11:49:41-11:53:07JST 11Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C222 2023/08/14(226)11:57:25-12:00:51JST 38Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0941-08 2023/08/14(226)12:04:26-12:07:52JST 85Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230 2023/08/14(226)12:12:47-12:16:13JST 57Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C236 2023/08/14(226)12:26:54-12:30:20JST 80Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1011+110 2023/08/14(226)12:35:04-12:38:30JST 40Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241 2023/08/14(226)12:42:45-12:46:11JST 51Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1031-11 2023/08/14(226)12:54:15-12:57:41JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1035-058 2023/08/14(226)12:58:48-13:02:14JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1044-008 2023/08/14(226)13:08:01-13:11:27JST 89Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1055+20 2023/08/14(226)13:18:59-13:22:25JST 78Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1059-010 2023/08/14(226)13:22:41-13:26:07JST 99Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2023/08/14(226)13:30:23-13:33:49JST 88Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C255 2023/08/14(226)13:40:00-13:43:26JST 114Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2023/08/14(226)13:50:38-13:54:04JST 143Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1136-13 2023/08/14(226)13:59:42-14:03:08JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2023/08/14(226)14:03:58-14:07:24JST 114Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C267 2023/08/14(226)14:10:25-14:13:51JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1154+552 2023/08/14(226)14:17:50-14:21:16JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2023/08/14(226)14:29:39-14:33:05JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1213-17 2023/08/14(226)14:36:13-14:39:39JST 170Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2023/08/14(226)14:49:30-14:52:56JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C275 2023/08/14(226)15:02:41-15:06:07JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1245-19 2023/08/14(226)15:08:46-15:12:12JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C279 2023/08/14(226)15:16:30-15:19:56JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C283 2023/08/14(226)15:31:59-15:35:25JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1313+453 2023/08/14(226)15:36:18-15:39:44JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1323+32 2023/08/14(226)15:46:24-15:49:50JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C286 2023/08/14(226)15:51:14-15:54:40JST 181Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2023/08/14(226)15:57:51-16:01:17JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1345+12 2023/08/14(226)16:07:41-16:11:07JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1355+01 2023/08/14(226)16:18:01-16:21:27JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C298 2023/08/14(226)16:39:12-16:42:38JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1428-03 2023/08/14(226)16:50:55-16:54:21JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1436-16 2023/08/14(226)16:59:36-17:03:02JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1453-10 2023/08/14(226)17:16:00-17:19:26JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318 2023/08/14(226)17:39:53-17:43:19JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1536+574 2023/08/14(226)17:56:39-18:00:05JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545+497 2023/08/14(226)18:06:41-18:10:07JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1556+419 2023/08/14(226)18:17:51-18:21:17JST 216Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

