




TOYOKAWA 0345+337 2023/08/21(233)05:43:23-05:46:49JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0349+382 2023/08/21(233)05:47:49-05:51:15JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2023/08/21(233)05:54:19-05:57:45JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0402+160 2023/08/21(233)05:59:25-06:02:51JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0406+386 2023/08/21(233)06:03:59-06:07:25JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2023/08/21(233)06:08:53-06:12:19JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2023/08/21(233)06:15:47-06:19:13JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0422+178 2023/08/21(233)06:19:46-06:23:12JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C119 2023/08/21(233)06:27:13-06:30:39JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138 2023/08/21(233)07:15:21-07:18:47JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0531+194 2023/08/21(233)07:28:55-07:32:21JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147 2023/08/21(233)07:37:13-07:40:39JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2023/08/21(233)07:45:26-07:48:52JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2023/08/21(233)07:49:37-07:53:03JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2023/08/21(233)07:54:03-07:57:29JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C152 2023/08/21(233)07:58:36-08:02:02JST 181Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C158 2023/08/21(233)08:15:42-08:19:08JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161


2023/08/21(233)08:20:58-08:24:24JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2023/08/21(233)08:48:31-08:51:57JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0656+213 2023/08/21(233)08:53:36-08:57:02JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2023/08/21(233)09:00:06-09:03:32JST 145Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2023/08/21(233)09:13:10-09:16:36JST 141Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2023/08/21(233)09:19:41-09:23:07JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2023/08/21(233)09:29:55-09:33:21JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2023/08/21(233)09:37:58-09:41:24JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2023/08/21(233)09:47:43-09:51:09JST 152Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2023/08/21(233)09:55:17-09:58:43JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2023/08/21(233)10:02:23-10:05:49JST 126Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196 2023/08/21(233)10:07:40-10:11:06JST 145Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2023/08/21(233)10:14:26-10:17:52JST 89Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2023/08/21(233)10:18:50-10:22:16JST 121Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2023/08/21(233)10:30:32-10:33:58JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2023/08/21(233)10:35:37-10:39:03JST 99Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208 2023/08/21(233)10:46:38-10:50:04JST 60Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2023/08/21(233)10:52:58-10:56:24JST 124Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2023/08/21(233)11:03:18-11:06:44JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2023/08/21(233)11:08:04-11:11:30JST 102Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2023/08/21(233)11:15:31-11:18:57JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2023/08/21(233)11:22:09-11:25:35JST 27Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2023/08/21(233)11:29:54-11:33:20JST 36Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2023/08/21(233)11:36:54-11:40:20JST 77Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230 2023/08/21(233)11:45:16-11:48:42JST 46Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C237 2023/08/21(233)12:01:17-12:04:43JST 20Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2023/08/21(233)12:07:33-12:10:59JST 15Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241 2023/08/21(233)12:15:14-12:18:40JST 41Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2023/08/21(233)12:26:43-12:30:09JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2023/08/21(233)12:31:17-12:34:43JST 77Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2023/08/21(233)12:40:29-12:43:55JST 67Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+20 2023/08/21(233)12:51:28-12:54:54JST 60Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1059-010 2023/08/21(233)12:55:10-12:58:36JST 77Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2023/08/21(233)13:02:51-13:06:17JST 65Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2023/08/21(233)13:12:29-13:15:55JST 92Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2023/08/21(233)13:23:07-13:26:33JST 125Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2023/08/21(233)13:32:10-13:35:36JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2023/08/21(233)13:36:27-13:39:53JST 97Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2023/08/21(233)13:42:54-13:46:20JST 98Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2023/08/21(233)13:50:19-13:53:45JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2023/08/21(233)14:02:08-14:05:34JST 145Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2023/08/21(233)14:08:42-14:12:08JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2023/08/21(233)14:21:59-14:25:25JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2023/08/21(233)14:35:10-14:38:36JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1245-19 2023/08/21(233)14:41:15-14:44:41JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C279 2023/08/21(233)14:48:58-14:52:24JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283 2023/08/21(233)15:04:28-15:07:54JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2023/08/21(233)15:08:47-15:12:13JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2023/08/21(233)15:18:53-15:22:19JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2023/08/21(233)15:23:43-15:27:09JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2023/08/21(233)15:30:19-15:33:45JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2023/08/21(233)15:40:10-15:43:36JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2023/08/21(233)15:50:30-15:53:56JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2023/08/21(233)16:11:41-16:15:07JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2023/08/21(233)16:23:24-16:26:50JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1436-16 2023/08/21(233)16:32:05-16:35:31JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2023/08/21(233)16:48:29-16:51:55JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1508-05 2023/08/21(233)17:03:21-17:06:47JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318 2023/08/21(233)17:12:21-17:15:47JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2023/08/21(233)17:18:08-17:21:34JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2023/08/21(233)17:29:48-17:33:14JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1548+334 2023/08/21(233)17:42:52-17:46:18JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1556+419 2023/08/21(233)17:50:19-17:53:45JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1600+335 2023/08/21(233)17:54:07-17:57:33JST 216Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1610+408 2023/08/21(233)18:03:41-18:07:07JST 216Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

