




TOYOKAWA 0548+16 2023/09/16(259)06:03:12-06:06:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0552+12 2023/09/16(259)06:07:23-06:10:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0556+191 2023/09/16(259)06:11:50-06:15:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C152

2023/09/16(259)06:16:22-06:19:48JST

10848+/- 29




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C158

2023/09/16(259)06:33:28-06:36:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C161

2023/09/16(259)06:38:44-06:42:10JST


10431+/- 56




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2023/09/16(259)07:06:17-07:09:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0703+138 2023/09/16(259)07:17:53-07:21:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0713-024 2023/09/16(259)07:27:16-07:30:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0716+022 2023/09/16(259)07:30:56-07:34:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0723+10 2023/09/16(259)07:37:28-07:40:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0732+33 2023/09/16(259)07:47:42-07:51:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2023/09/16(259)07:55:45-07:59:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0752-200 2023/09/16(259)08:05:29-08:08:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190


2023/09/16(259)08:13:03-08:16:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0806-103 2023/09/16(259)08:20:09-08:23:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C196


2023/09/16(259)08:25:27-08:28:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2023/09/16(259)08:32:12-08:35:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0821+394 2023/09/16(259)08:36:37-08:40:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0834-19 2023/09/16(259)08:48:18-08:51:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0839-071 2023/09/16(259)08:53:23-08:56:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208


2023/09/16(259)09:04:24-09:07:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0857-191 2023/09/16(259)09:10:45-09:14:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C216

2023/09/16(259)09:21:05-09:24:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0912-132 2023/09/16(259)09:25:50-09:29:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2023/09/16(259)09:33:17-09:36:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0926+117 2023/09/16(259)09:39:56-09:43:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C222


2023/09/16(259)09:47:41-09:51:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0941-08 2023/09/16(259)09:54:41-09:58:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230

2023/09/16(259)10:03:03-10:06:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C236


2023/09/16(259)10:17:09-10:20:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1011+110 2023/09/16(259)10:25:19-10:28:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C241


2023/09/16(259)10:33:00-10:36:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1031-11 2023/09/16(259)10:44:30-10:47:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1035-058 2023/09/16(259)10:49:03-10:52:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1044-008 2023/09/16(259)10:58:16-11:01:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2023/09/16(259)11:09:20-11:12:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1059-010 2023/09/16(259)11:12:57-11:16:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1107+109 2023/09/16(259)11:20:38-11:24:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C255 2023/09/16(259)11:30:15-11:33:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1127-14 2023/09/16(259)11:40:53-11:44:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1136-13 2023/09/16(259)11:49:57-11:53:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2023/09/16(259)11:54:13-11:57:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2023/09/16(259)12:00:40-12:04:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1154+552 2023/09/16(259)12:08:05-12:11:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2023/09/16(259)12:19:55-12:23:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2023/09/16(259)12:26:28-12:29:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C273 2023/09/16(259)12:39:45-12:43:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C275 2023/09/16(259)12:52:56-12:56:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1245-19 2023/09/16(259)12:59:01-13:02:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C279


2023/09/16(259)13:06:45-13:10:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C283 2023/09/16(259)13:22:14-13:25:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1313+453 2023/09/16(259)13:26:33-13:29:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2023/09/16(259)13:36:39-13:40:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C286 2023/09/16(259)13:41:29-13:44:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1334-17 2023/09/16(259)13:48:06-13:51:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1345+12 2023/09/16(259)13:57:56-14:01:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1355+01 2023/09/16(259)14:08:17-14:11:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C298


2023/09/16(259)14:29:27-14:32:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2023/09/16(259)14:41:11-14:44:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1436-16 2023/09/16(259)14:49:52-14:53:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1453-10 2023/09/16(259)15:06:15-15:09:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1508-05 2023/09/16(259)15:21:08-15:24:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C318 2023/09/16(259)15:30:08-15:33:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1523+03 2023/09/16(259)15:35:55-15:39:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2023/09/16(259)15:47:34-15:51:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545-12 2023/09/16(259)15:57:58-16:01:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1607+26 2023/09/16(259)16:19:02-16:22:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1623-228 2023/09/16(259)16:36:31-16:39:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1631-222 2023/09/16(259)16:45:01-16:48:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1638-025 2023/09/16(259)16:50:39-16:54:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1644-106 2023/09/16(259)16:57:33-17:00:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1650+004 2023/09/16(259)17:02:54-17:06:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1656+053 2023/09/16(259)17:08:26-17:11:52JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1714+437 2023/09/16(259)17:25:19-17:28:45JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )

