




TOYOKAWA 0636-167 2023/09/29(272)05:58:58-06:02:24JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)










DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)










DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)









DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
JPS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
JPS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)









DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
PS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
PS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)









DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C267 2023/09/29(272)11:09:34-11:13:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
IPS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




Tot.P: 0.0000  
NosLv: 0.51848E-43  
StDev: 0.0000  
NosPo: 0.10300E-41  
IPS-P: -0.10300E-41  
S/N R: -1.0000  
Sci.P: 0.0000  
N.ScP: 0.0000  
MaxLv: 0.0000





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)










DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1355+01 2023/09/29(272)13:17:10-13:20:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2023/09/29(272)13:38:21-13:41:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2023/09/29(272)13:50:04-13:53:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1434+03 2023/09/29(272)13:56:06-13:59:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2023/09/29(272)14:15:08-14:18:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1508-05 2023/09/29(272)14:30:01-14:33:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318


2023/09/29(272)14:39:01-14:42:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1523+03 2023/09/29(272)14:44:48-14:48:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1535+139 2023/09/29(272)14:56:28-14:59:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1545-12 2023/09/29(272)15:06:51-15:10:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1607+26 2023/09/29(272)15:27:55-15:31:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1623-228 2023/09/29(272)15:45:24-15:48:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1631-222 2023/09/29(272)15:53:55-15:57:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1638-025 2023/09/29(272)15:59:32-16:02:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2023/09/29(272)16:06:27-16:09:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1650+004 2023/09/29(272)16:11:47-16:15:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1656+053 2023/09/29(272)16:17:19-16:20:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1712-033 2023/09/29(272)16:33:49-16:37:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1730-13 2023/09/29(272)16:51:51-16:55:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1748+031 2023/09/29(272)17:09:16-17:12:42JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1757-150 2023/09/29(272)17:18:45-17:22:11JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

