




TOYOKAWA 0656-242 2023/10/05(278)05:55:35-05:59:01JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2023/10/05(278)06:03:11-06:06:37JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0707+063 2023/10/05(278)06:06:57-06:10:23JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2023/10/05(278)06:12:34-06:16:00JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2023/10/05(278)06:16:14-06:19:40JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2023/10/05(278)06:22:46-06:26:12JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2023/10/05(278)06:33:00-06:36:26JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2023/10/05(278)06:41:02-06:44:28JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0752-200 2023/10/05(278)06:50:47-06:54:13JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190

2023/10/05(278)06:58:21-07:01:47JST 204Rs


9888+/- 39




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0806-103 2023/10/05(278)07:05:27-07:08:53JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196

2023/10/05(278)07:10:45-07:14:11JST 210Rs


10995+/- 57




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2023/10/05(278)07:17:30-07:20:56JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2023/10/05(278)07:21:55-07:25:21JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2023/10/05(278)07:33:36-07:37:02JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2023/10/05(278)07:38:41-07:42:07JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208 2023/10/05(278)07:49:42-07:53:08JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2023/10/05(278)07:56:03-07:59:29JST 178Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2023/10/05(278)08:06:23-08:09:49JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2023/10/05(278)08:11:08-08:14:34JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2023/10/05(278)08:25:14-08:28:40JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2023/10/05(278)08:32:59-08:36:25JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2023/10/05(278)08:39:59-08:43:25JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230 2023/10/05(278)08:48:21-08:51:47JST 145Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C237 2023/10/05(278)09:04:21-09:07:47JST 138Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2023/10/05(278)09:10:37-09:14:03JST 137Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241 2023/10/05(278)09:18:18-09:21:44JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2023/10/05(278)09:29:48-09:33:14JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2023/10/05(278)09:34:21-09:37:47JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2023/10/05(278)09:43:34-09:47:00JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2023/10/05(278)09:54:38-09:58:04JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1059-010 2023/10/05(278)09:58:15-10:01:41JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2023/10/05(278)10:05:56-10:09:22JST 98Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2023/10/05(278)10:15:33-10:18:59JST 75Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1127-14 2023/10/05(278)10:26:11-10:29:37JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2023/10/05(278)10:35:15-10:38:41JST 66Rs


10791+/- 207




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2023/10/05(278)10:39:31-10:42:57JST 107Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2023/10/05(278)10:45:58-10:49:24JST 78Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2023/10/05(278)10:53:23-10:56:49JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2023/10/05(278)11:05:13-11:08:39JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2023/10/05(278)11:11:46-11:15:12JST 53Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C273 2023/10/05(278)11:25:03-11:28:29JST 26Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1245-19 2023/10/05(278)11:44:19-11:47:45JST 57Rs


11479+/- 447




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C279 2023/10/05(278)11:52:03-11:55:29JST 14Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283 2023/10/05(278)12:07:32-12:10:58JST 70Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2023/10/05(278)12:11:51-12:15:17JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2023/10/05(278)12:21:57-12:25:23JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2023/10/05(278)12:26:47-12:30:13JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2023/10/05(278)12:33:24-12:36:50JST 71Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2023/10/05(278)12:43:14-12:46:40JST 85Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2023/10/05(278)12:53:35-12:57:01JST 72Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2023/10/05(278)13:14:45-13:18:11JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2023/10/05(278)13:26:29-13:29:55JST 98Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1434+03 2023/10/05(278)13:32:31-13:35:57JST 106Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2023/10/05(278)13:51:33-13:54:59JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1508-05 2023/10/05(278)14:06:25-14:09:51JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318 2023/10/05(278)14:15:26-14:18:52JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2023/10/05(278)14:21:13-14:24:39JST 142Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2023/10/05(278)14:32:52-14:36:18JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1545-12 2023/10/05(278)14:43:16-14:46:42JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1607+26 2023/10/05(278)15:04:20-15:07:46JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1623-228 2023/10/05(278)15:21:49-15:25:15JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1631-222 2023/10/05(278)15:30:19-15:33:45JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2023/10/05(278)15:35:57-15:39:23JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2023/10/05(278)15:42:51-15:46:17JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1650+004 2023/10/05(278)15:48:12-15:51:38JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1656+053 2023/10/05(278)15:53:44-15:57:10JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2023/10/05(278)16:10:14-16:13:40JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2023/10/05(278)16:28:16-16:31:42JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1748+031 2023/10/05(278)16:45:41-16:49:07JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2023/10/05(278)16:56:34-17:00:00JST 212Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1819-096 2023/10/05(278)17:17:34-17:21:00JST 213Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

