




TOYOKAWA 0705-235 2023/10/09(282)05:48:02-05:51:28JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0709-206 2023/10/09(282)05:52:42-05:56:08JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0713-024 2023/10/09(282)05:56:50-06:00:16JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2023/10/09(282)06:00:30-06:03:56JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0723+10 2023/10/09(282)06:07:02-06:10:28JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0732+33 2023/10/09(282)06:17:16-06:20:42JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2023/10/09(282)06:25:19-06:28:45JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0752-200 2023/10/09(282)06:35:03-06:38:29JST 206Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C190

2023/10/09(282)06:42:38-06:46:04JST 207Rs


10708+/- 123




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0806-103 2023/10/09(282)06:49:43-06:53:09JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196 2023/10/09(282)06:55:01-06:58:27JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2023/10/09(282)07:01:46-07:05:12JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0821+394 2023/10/09(282)07:06:11-07:09:37JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0834-19 2023/10/09(282)07:17:53-07:21:19JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0839-071 2023/10/09(282)07:22:58-07:26:24JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C208

2023/10/09(282)07:33:58-07:37:24JST 191Rs

24340+/- 5084




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0857-191 2023/10/09(282)07:40:19-07:43:45JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C216 2023/10/09(282)07:50:39-07:54:05JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0912-132 2023/10/09(282)07:55:24-07:58:50JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2023/10/09(282)08:02:52-08:06:18JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0926+117 2023/10/09(282)08:09:30-08:12:56JST 174Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C222 2023/10/09(282)08:17:15-08:20:41JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0941-08 2023/10/09(282)08:24:15-08:27:41JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230

2023/10/09(282)08:32:37-08:36:03JST 155Rs

11916+/- 53




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C237 2023/10/09(282)08:48:37-08:52:03JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1010+250 2023/10/09(282)08:53:44-08:57:10JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241

2023/10/09(282)09:02:35-09:06:01JST 156Rs


11820+/- 42




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1031-11 2023/10/09(282)09:14:04-09:17:30JST 125Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1035-058 2023/10/09(282)09:18:38-09:22:04JST 120Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1044-008 2023/10/09(282)09:27:50-09:31:16JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2023/10/09(282)09:38:55-09:42:21JST 108Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1107+109 2023/10/09(282)09:50:12-09:53:38JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C255 2023/10/09(282)09:59:50-10:03:16JST 88Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1127-14 2023/10/09(282)10:10:27-10:13:53JST 83Rs


12093+/- 58




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2023/10/09(282)10:19:31-10:22:57JST 75Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C263.1 2023/10/09(282)10:23:48-10:27:14JST 117Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2023/10/09(282)10:30:15-10:33:41JST 90Rs


10734+/- 450




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1154+552 2023/10/09(282)10:37:39-10:41:05JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1206+439 2023/10/09(282)10:49:29-10:52:55JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1213-17 2023/10/09(282)10:56:02-10:59:28JST 56Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C273 2023/10/09(282)11:09:20-11:12:46JST 39Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C275 2023/10/09(282)11:22:30-11:25:56JST 13Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2023/10/09(282)11:28:35-11:32:01JST 52Rs

14328+/- 605




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C283 2023/10/09(282)11:51:48-11:55:14JST 61Rs


12079+/- 203




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1313+453 2023/10/09(282)11:56:07-11:59:33JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1323+32 2023/10/09(282)12:06:13-12:09:39JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286 2023/10/09(282)12:11:04-12:14:30JST 130Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1334-17 2023/10/09(282)12:17:40-12:21:06JST 58Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1345+12 2023/10/09(282)12:27:31-12:30:57JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1355+01 2023/10/09(282)12:37:51-12:41:17JST 62Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2023/10/09(282)12:59:02-13:02:28JST 87Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1428-03 2023/10/09(282)13:10:45-13:14:11JST 86Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1434+03 2023/10/09(282)13:16:47-13:20:13JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2023/10/09(282)13:35:49-13:39:15JST 107Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1508-05 2023/10/09(282)13:50:42-13:54:08JST 118Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C318 2023/10/09(282)13:59:42-14:03:08JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1523+03 2023/10/09(282)14:05:29-14:08:55JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2023/10/09(282)14:17:09-14:20:35JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1548+05 2023/10/09(282)14:30:14-14:33:40JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2023/10/09(282)14:48:36-14:52:02JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1623-228 2023/10/09(282)15:06:05-15:09:31JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2023/10/09(282)15:14:36-15:18:02JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2023/10/09(282)15:20:13-15:23:39JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1644-106 2023/10/09(282)15:27:08-15:30:34JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1650+004 2023/10/09(282)15:32:28-15:35:54JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1656+053 2023/10/09(282)15:38:00-15:41:26JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2023/10/09(282)15:54:30-15:57:56JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1730-13 2023/10/09(282)16:12:32-16:15:58JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2023/10/09(282)16:29:57-16:33:23JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2023/10/09(282)16:40:50-16:44:16JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2023/10/09(282)17:01:50-17:05:16JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1830-210 2023/10/09(282)17:13:05-17:16:31JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )





TOYOKAWA 1836-206 2023/10/09(282)17:19:04-17:22:30JST 213Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

