




TOYOKAWA 0719-187 2023/10/13(286)05:47:19-05:50:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0727-115 2023/10/13(286)05:55:32-05:58:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0731+021 2023/10/13(286)05:59:14-06:02:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0735+076 2023/10/13(286)06:03:04-06:06:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0741-06 2023/10/13(286)06:09:35-06:13:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0746+162 2023/10/13(286)06:14:22-06:17:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0752-200 2023/10/13(286)06:19:20-06:22:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0755+029 2023/10/13(286)06:22:57-06:26:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C190 2023/10/13(286)06:26:54-06:30:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0806-103 2023/10/13(286)06:34:00-06:37:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0817+183 2023/10/13(286)06:46:03-06:49:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0821+394 2023/10/13(286)06:50:28-06:53:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0826+095 2023/10/13(286)06:54:48-06:58:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0834-19 2023/10/13(286)07:02:09-07:05:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0839-071 2023/10/13(286)07:07:14-07:10:40JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C208

2023/10/13(286)07:18:15-07:21:41JST


14967+/- 2066




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0857-191 2023/10/13(286)07:24:35-07:28:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C216


2023/10/13(286)07:34:56-07:38:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2023/10/13(286)07:39:41-07:43:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2023/10/13(286)07:47:08-07:50:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0923+392 2023/10/13(286)07:52:18-07:55:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C222 2023/10/13(286)08:01:31-08:04:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0941-08 2023/10/13(286)08:08:32-08:11:58JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )









TOYOKAWA 3C237 2023/10/13(286)08:32:54-08:36:20JST

9345+/- 391




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1011+110 2023/10/13(286)08:39:10-08:42:36JST

9975+/- 591




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241

2023/10/13(286)08:46:51-08:50:17JST


10304+/- 48




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1026-056 2023/10/13(286)08:54:15-08:57:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1035-058 2023/10/13(286)09:02:54-09:06:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1044-008 2023/10/13(286)09:12:07-09:15:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1055+01 2023/10/13(286)09:23:11-09:26:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1107+109 2023/10/13(286)09:34:29-09:37:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C255 2023/10/13(286)09:44:06-09:47:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2023/10/13(286)09:54:44-09:58:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1136-13 2023/10/13(286)10:03:47-10:07:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2023/10/13(286)10:08:04-10:11:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C267 2023/10/13(286)10:14:31-10:17:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 1206+439 2023/10/13(286)10:33:45-10:37:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1213-17 2023/10/13(286)10:40:19-10:43:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2023/10/13(286)10:53:36-10:57:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275 2023/10/13(286)11:06:47-11:10:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2023/10/13(286)11:12:52-11:16:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C279 2023/10/13(286)11:20:35-11:24:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C283 2023/10/13(286)11:36:05-11:39:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2023/10/13(286)11:40:24-11:43:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1323+32 2023/10/13(286)11:50:30-11:53:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C286 2023/10/13(286)11:55:20-11:58:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2023/10/13(286)12:01:57-12:05:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1345+12 2023/10/13(286)12:11:47-12:15:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1355+01 2023/10/13(286)12:22:07-12:25:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2023/10/13(286)12:43:18-12:46:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2023/10/13(286)12:55:01-12:58:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1434+03 2023/10/13(286)13:01:04-13:04:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1453-10 2023/10/13(286)13:20:06-13:23:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1508-05 2023/10/13(286)13:34:58-13:38:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C318 2023/10/13(286)13:43:59-13:47:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2023/10/13(286)13:49:45-13:53:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2023/10/13(286)14:01:25-14:04:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1548+05 2023/10/13(286)14:14:31-14:17:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2023/10/13(286)14:32:53-14:36:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1623-228 2023/10/13(286)14:50:22-14:53:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1631-222 2023/10/13(286)14:58:52-15:02:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1638-025 2023/10/13(286)15:04:30-15:07:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1644-106 2023/10/13(286)15:11:24-15:14:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1656+053 2023/10/13(286)15:22:17-15:25:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2023/10/13(286)15:38:46-15:42:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1730-13 2023/10/13(286)15:56:48-16:00:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2023/10/13(286)16:14:13-16:17:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1759+13 2023/10/13(286)16:25:07-16:28:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1819-096 2023/10/13(286)16:46:06-16:49:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1830-210 2023/10/13(286)16:57:21-17:00:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1850-147 2023/10/13(286)17:16:39-17:20:05JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1859-235 2023/10/13(286)17:26:27-17:29:53JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )

