




TOYOKAWA 0928-179 2023/11/19(323)05:30:13-05:33:39JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0942-196 2023/11/19(323)05:44:39-05:48:05JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0948-080 2023/11/19(323)05:50:09-05:53:35JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0952-224 2023/11/19(323)05:53:59-05:57:25JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0955-014 2023/11/19(323)05:57:54-06:01:20JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C237 2023/11/19(323)06:07:26-06:10:52JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1011+110 2023/11/19(323)06:13:42-06:17:08JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1017+040 2023/11/19(323)06:19:57-06:23:23JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1022+066 2023/11/19(323)06:24:23-06:27:49JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1026-056 2023/11/19(323)06:28:47-06:32:13JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1031-11 2023/11/19(323)06:32:52-06:36:18JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1035-058 2023/11/19(323)06:37:26-06:40:52JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1043+158 2023/11/19(323)06:45:28-06:48:54JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2023/11/19(323)06:57:43-07:01:09JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2023/11/19(323)07:09:00-07:12:26JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C255 2023/11/19(323)07:18:38-07:22:04JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1127-14 2023/11/19(323)07:29:15-07:32:41JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2023/11/19(323)07:38:19-07:41:45JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2023/11/19(323)07:42:36-07:46:02JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2023/11/19(323)07:49:03-07:52:29JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1206+439 2023/11/19(323)08:08:17-08:11:43JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2023/11/19(323)08:14:50-08:18:16JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C273 2023/11/19(323)08:28:08-08:31:34JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275 2023/11/19(323)08:41:19-08:44:45JST 148Rs

15715+/- 335




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1245-19 2023/11/19(323)08:47:23-08:50:49JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1252-106 2023/11/19(323)08:53:46-08:57:12JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C283 2023/11/19(323)09:10:37-09:14:03JST 117Rs


19808+/- 229




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2023/11/19(323)09:14:55-09:18:21JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2023/11/19(323)09:25:01-09:28:27JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286 2023/11/19(323)09:29:52-09:33:18JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2023/11/19(323)09:36:28-09:39:54JST 99Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1345+12 2023/11/19(323)09:46:19-09:49:45JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1355+01 2023/11/19(323)09:56:39-10:00:05JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2023/11/19(323)10:17:50-10:21:16JST 112Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1428-03 2023/11/19(323)10:29:33-10:32:59JST 80Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1434+03 2023/11/19(323)10:35:36-10:39:02JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2023/11/19(323)10:54:38-10:58:04JST 45Rs

18681+/- 77




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1508-05 2023/11/19(323)11:09:30-11:12:56JST 54Rs

15792+/- 78




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C318 2023/11/19(323)11:18:30-11:21:56JST 135Rs

14187+/- 77




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2023/11/19(323)11:24:17-11:27:43JST 81Rs

14609+/- 257




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 1535+139 2023/11/19(323)11:35:57-11:39:23JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545-12 2023/11/19(323)11:46:20-11:49:46JST 28Rs


19314+/- 199




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2023/11/19(323)12:07:24-12:10:50JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1621-11 2023/11/19(323)12:22:27-12:25:53JST 51Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2023/11/19(323)12:33:24-12:36:50JST 52Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2023/11/19(323)12:39:01-12:42:27JST 83Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1644-106 2023/11/19(323)12:45:56-12:49:22JST 70Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1650+004 2023/11/19(323)12:51:16-12:54:42JST 97Rs

16841+/- 485




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1656+053 2023/11/19(323)12:56:48-13:00:14JST 112Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2023/11/19(323)13:13:18-13:16:44JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1732-092 2023/11/19(323)13:33:25-13:36:51JST 108Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2023/11/19(323)13:48:45-13:52:11JST 136Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2023/11/19(323)13:59:38-14:03:04JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2023/11/19(323)14:20:38-14:24:04JST 140Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1830-210 2023/11/19(323)14:31:53-14:35:19JST 141Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1858+171 2023/11/19(323)14:58:19-15:01:45JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1908-20 2023/11/19(323)15:09:02-15:12:28JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1915-121 2023/11/19(323)15:15:53-15:19:19JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1928-142 2023/11/19(323)15:29:35-15:33:01JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1938-15 2023/11/19(323)15:39:14-15:42:40JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C422 2023/11/19(323)16:44:47-16:48:13JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2059-127 2023/11/19(323)16:59:56-17:03:22JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2023/11/19(323)17:05:25-17:08:51JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2120-166 2023/11/19(323)17:20:41-17:24:07JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2128-123 2023/11/19(323)17:29:12-17:32:38JST 211Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2135-209 2023/11/19(323)17:35:28-17:38:54JST 211Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

