




TOYOKAWA 0845-177 2023/11/07(311)05:34:25-05:37:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0850-206 2023/11/07(311)05:39:39-05:43:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0857-191 2023/11/07(311)05:46:18-05:49:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0903-041 2023/11/07(311)05:52:22-05:55:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2023/11/07(311)06:01:23-06:04:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2023/11/07(311)06:08:50-06:12:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0926+117 2023/11/07(311)06:15:29-06:18:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0930-200 2023/11/07(311)06:19:20-06:22:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C222 2023/11/07(311)06:23:14-06:26:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0941-08 2023/11/07(311)06:30:14-06:33:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230

2023/11/07(311)06:38:36-06:42:02JST

11172+/- 59




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C237

2023/11/07(311)06:54:36-06:58:02JST


9620+/- 77




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1011+110 2023/11/07(311)07:00:53-07:04:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241

2023/11/07(311)07:08:34-07:12:00JST


10462+/- 45




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1031-11 2023/11/07(311)07:20:03-07:23:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1035-058 2023/11/07(311)07:24:37-07:28:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1044-008 2023/11/07(311)07:33:49-07:37:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2023/11/07(311)07:44:54-07:48:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2023/11/07(311)07:56:11-07:59:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C255 2023/11/07(311)08:05:49-08:09:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2023/11/07(311)08:16:26-08:19:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2023/11/07(311)08:25:30-08:28:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2023/11/07(311)08:29:47-08:33:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C267 2023/11/07(311)08:36:13-08:39:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1154+552 2023/11/07(311)08:43:38-08:47:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1205-167 2023/11/07(311)08:53:57-08:57:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2023/11/07(311)09:02:01-09:05:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C273 2023/11/07(311)09:15:19-09:18:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275 2023/11/07(311)09:28:29-09:31:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1245-19 2023/11/07(311)09:34:34-09:38:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C279

2023/11/07(311)09:42:18-09:45:44JST


10323+/- 423




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C283 2023/11/07(311)09:57:47-10:01:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1313+453 2023/11/07(311)10:02:06-10:05:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1323+32 2023/11/07(311)10:12:12-10:15:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286

2023/11/07(311)10:17:02-10:20:28JST


10506+/- 57




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2023/11/07(311)10:23:39-10:27:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1345+12 2023/11/07(311)10:33:29-10:36:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1355+01 2023/11/07(311)10:43:50-10:47:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2023/11/07(311)11:05:01-11:08:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1428-03 2023/11/07(311)11:16:44-11:20:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1434+03 2023/11/07(311)11:22:46-11:26:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1453-10 2023/11/07(311)11:41:48-11:45:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1508-05 2023/11/07(311)11:56:41-12:00:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318

2023/11/07(311)12:05:41-12:09:07JST


11414+/- 43




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2023/11/07(311)12:11:28-12:14:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2023/11/07(311)12:23:08-12:26:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545-12 2023/11/07(311)12:33:31-12:36:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1607+26 2023/11/07(311)12:54:35-12:58:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1623-228 2023/11/07(311)13:12:04-13:15:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2023/11/07(311)13:20:34-13:24:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2023/11/07(311)13:26:12-13:29:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2023/11/07(311)13:33:06-13:36:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1650+004 2023/11/07(311)13:38:27-13:41:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1656+053 2023/11/07(311)13:43:59-13:47:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2023/11/07(311)14:00:29-14:03:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1730-13 2023/11/07(311)14:18:31-14:21:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1748+031 2023/11/07(311)14:35:56-14:39:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1759+13 2023/11/07(311)14:46:49-14:50:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2023/11/07(311)15:07:49-15:11:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1830-210 2023/11/07(311)15:19:04-15:22:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2023/11/07(311)15:45:29-15:48:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1908-20 2023/11/07(311)15:56:13-15:59:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1915-121 2023/11/07(311)16:03:04-16:06:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1928-142 2023/11/07(311)16:16:46-16:20:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1938-15 2023/11/07(311)16:26:25-16:29:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1953-077 2023/11/07(311)16:41:13-16:44:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2012+010 2023/11/07(311)16:59:30-17:02:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2039-229 2023/11/07(311)17:27:50-17:31:16JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2044-185 2023/11/07(311)17:32:15-17:35:41JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

