




TOYOKAWA 1106-227 2023/12/14(348)05:30:04-05:33:30JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1110-217 2023/12/14(348)05:33:44-05:37:10JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1114-220 2023/12/14(348)05:37:48-05:41:14JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1121-119 2023/12/14(348)05:44:50-05:48:16JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1127-14 2023/12/14(348)05:50:58-05:54:24JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1131-171 2023/12/14(348)05:55:15-05:58:41JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2023/12/14(348)06:00:02-06:03:28JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1141-174 2023/12/14(348)06:05:18-06:08:44JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1148-00 2023/12/14(348)06:11:35-06:15:01JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1152-178 2023/12/14(348)06:16:17-06:19:43JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1156-221 2023/12/14(348)06:20:00-06:23:26JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1200+045 2023/12/14(348)06:24:10-06:27:36JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1205-167 2023/12/14(348)06:28:29-06:31:55JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1208-192 2023/12/14(348)06:32:19-06:35:45JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2023/12/14(348)06:36:33-06:39:59JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1217+097 2023/12/14(348)06:41:13-06:44:39JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1222+216 2023/12/14(348)06:45:38-06:49:04JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2023/12/14(348)06:49:50-06:53:16JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1230-244 2023/12/14(348)06:53:28-06:56:54JST 192Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1235-226 2023/12/14(348)06:58:56-07:02:22JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275 2023/12/14(348)07:03:01-07:06:27JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2023/12/14(348)07:09:06-07:12:32JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1249+035 2023/12/14(348)07:13:03-07:16:29JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C279 2023/12/14(348)07:16:50-07:20:16JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1257-230 2023/12/14(348)07:21:07-07:24:33JST 182Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1302-035 2023/12/14(348)07:25:22-07:28:48JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C283 2023/12/14(348)07:32:19-07:35:45JST 178Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+073 2023/12/14(348)07:36:50-07:40:16JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1317+179 2023/12/14(348)07:40:53-07:44:19JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2023/12/14(348)07:46:44-07:50:10JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286 2023/12/14(348)07:51:34-07:55:00JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1334-17 2023/12/14(348)07:58:11-08:01:37JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1338+044 2023/12/14(348)08:01:55-08:05:21JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1345+12 2023/12/14(348)08:08:01-08:11:27JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1355+01 2023/12/14(348)08:18:21-08:21:47JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C298 2023/12/14(348)08:39:32-08:42:58JST 170Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2023/12/14(348)08:51:15-08:54:41JST 151Rs


19394+/- 890




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2023/12/14(348)09:16:20-09:19:46JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1508-05 2023/12/14(348)09:31:12-09:34:38JST 124Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C318 2023/12/14(348)09:40:13-09:43:39JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 1523+03 2023/12/14(348)09:45:59-09:49:25JST 132Rs


16544+/- 269




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1535+139 2023/12/14(348)09:57:39-10:01:05JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545-12 2023/12/14(348)10:08:03-10:11:29JST 89Rs


19428+/- 89




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2023/12/14(348)10:29:07-10:32:33JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1623-228 2023/12/14(348)10:46:36-10:50:02JST 47Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2023/12/14(348)10:55:06-10:58:32JST 40Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1638-025 2023/12/14(348)11:00:44-11:04:10JST 82Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2023/12/14(348)11:07:38-11:11:04JST 54Rs

19169+/- 325




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 1650+004 2023/12/14(348)11:12:59-11:16:25JST 88Rs


19010+/- 456




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1656+053 2023/12/14(348)11:18:31-11:21:57JST 102Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1712-033 2023/12/14(348)11:35:00-11:38:26JST 72Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1730-13 2023/12/14(348)11:53:03-11:56:29JST 38Rs


21348+/- 137




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2023/12/14(348)12:10:28-12:13:54JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1759+13 2023/12/14(348)12:21:21-12:24:47JST 130Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2023/12/14(348)12:42:21-12:45:47JST 70Rs


28207+/- 640




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1829+29 2023/12/14(348)12:50:43-12:54:09JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1835+134 2023/12/14(348)12:57:05-13:00:31JST 138Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2023/12/14(348)13:20:01-13:23:27JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1908-20 2023/12/14(348)13:30:45-13:34:11JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1915-121 2023/12/14(348)13:37:36-13:41:02JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1938-15 2023/12/14(348)14:00:57-14:04:23JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2007+502 2023/12/14(348)14:28:11-14:31:37JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)









TOYOKAWA 3C422 2023/12/14(348)15:06:29-15:09:55JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2023/12/14(348)15:27:07-15:30:33JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2023/12/14(348)15:52:53-15:56:19JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2023/12/14(348)15:57:11-16:00:37JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2147+145 2023/12/14(348)16:09:31-16:12:57JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2156-043 2023/12/14(348)16:18:35-16:22:01JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2203-18 2023/12/14(348)16:25:23-16:28:49JST 192Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2210+016 2023/12/14(348)16:31:46-16:35:12JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2217+128 2023/12/14(348)16:39:09-16:42:35JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C446 2023/12/14(348)16:44:55-16:48:21JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2229-093 2023/12/14(348)16:51:39-16:55:05JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2238-113 2023/12/14(348)17:00:06-17:03:32JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2257-104 2023/12/14(348)17:19:27-17:22:53JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2303-253 2023/12/14(348)17:25:30-17:28:56JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2313-144 2023/12/14(348)17:35:34-17:39:00JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2318-16 2023/12/14(348)17:39:59-17:43:25JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2328-189 2023/12/14(348)17:50:15-17:53:41JST 210Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2341-244 2023/12/14(348)18:03:06-18:06:32JST 210Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

