




TOYOKAWA 1555-246 2024/02/17(048)06:03:16-06:06:42JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1602-174 2024/02/17(048)06:09:46-06:13:12JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1609-141 2024/02/17(048)06:16:50-06:20:16JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1614-172 2024/02/17(048)06:21:43-06:25:09JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1623-228 2024/02/17(048)06:31:03-06:34:29JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2024/02/17(048)06:39:33-06:42:59JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2024/02/17(048)06:45:10-06:48:36JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1644-106 2024/02/17(048)06:52:05-06:55:31JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1650+004 2024/02/17(048)06:57:25-07:00:51JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1656+053 2024/02/17(048)07:02:57-07:06:23JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2024/02/17(048)07:19:27-07:22:53JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1730-13 2024/02/17(048)07:37:29-07:40:55JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2024/02/17(048)07:54:54-07:58:20JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2024/02/17(048)08:05:47-08:09:13JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2024/02/17(048)08:26:47-08:30:13JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1830-210 2024/02/17(048)08:38:02-08:41:28JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1847-016 2024/02/17(048)08:54:08-08:57:34JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2024/02/17(048)09:04:27-09:07:53JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1908-20 2024/02/17(048)09:15:12-09:18:38JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1915-121 2024/02/17(048)09:22:02-09:25:28JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1928-142 2024/02/17(048)09:35:44-09:39:10JST 124Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1938-15 2024/02/17(048)09:45:23-09:48:49JST 117Rs


18153+/- 236




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2007+502 2024/02/17(048)10:12:37-10:16:03JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2014+358 2024/02/17(048)10:20:20-10:23:46JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C422 2024/02/17(048)10:50:56-10:54:22JST 73Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2024/02/17(048)11:11:34-11:15:00JST 50Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2024/02/17(048)11:37:19-11:40:45JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2024/02/17(048)11:41:37-11:45:03JST 36Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2147+145 2024/02/17(048)11:53:57-11:57:23JST 97Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2156-043 2024/02/17(048)12:03:01-12:06:27JST 30Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2203-18 2024/02/17(048)12:09:50-12:13:16JST 24Rs

17597+/- 267




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2210+016 2024/02/17(048)12:16:12-12:19:38JST 53Rs

12231+/- 568




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 2218+395 2024/02/17(048)12:23:53-12:27:19JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C446 2024/02/17(048)12:29:22-12:32:48JST 36Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2229-093 2024/02/17(048)12:36:05-12:39:31JST 32Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2235+511 2024/02/17(048)12:40:39-12:44:05JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2239+333 2024/02/17(048)12:44:51-12:48:17JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2243+394 2024/02/17(048)12:49:08-12:52:34JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C454.3 2024/02/17(048)12:57:22-13:00:48JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2259+481 2024/02/17(048)13:05:04-13:08:30JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C456 2024/02/17(048)13:15:52-13:19:18JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C459

2024/02/17(048)13:19:58-13:23:24JST 90Rs

10191+/- 594




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2318-16 2024/02/17(048)13:24:25-13:27:51JST 73Rs


16179+/- 108




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2325+269 2024/02/17(048)13:31:18-13:34:44JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2344+09 2024/02/17(048)13:49:56-13:53:22JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2347-02 2024/02/17(048)13:53:43-13:57:09JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2354+14 2024/02/17(048)14:00:36-14:04:02JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C2

2024/02/17(048)14:09:39-14:13:05JST 117Rs

12269+/- 346




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0011+344 2024/02/17(048)14:17:01-14:20:27JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0019-00 2024/02/17(048)14:25:37-14:29:03JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C12

2024/02/17(048)14:35:52-14:39:18JST 161Rs


10645+/- 73




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0038+328 2024/02/17(048)14:44:09-14:47:35JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0044-056 2024/02/17(048)14:49:53-14:53:19JST 141Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C26

2024/02/17(048)14:57:15-15:00:41JST 147Rs


13727+/- 179




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0056-00 2024/02/17(048)15:02:13-15:05:39JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0106+01 2024/02/17(048)15:11:55-15:15:21JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0115-01 2024/02/17(048)15:21:18-15:24:44JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0120+405 2024/02/17(048)15:26:39-15:30:05JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0128+03 2024/02/17(048)15:34:18-15:37:44JST 174Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C48

2024/02/17(048)15:40:51-15:44:17JST 198Rs


13890+/- 86




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0148+274 2024/02/17(048)15:54:35-15:58:01JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0155-109 2024/02/17(048)16:00:36-16:04:02JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0202+15 2024/02/17(048)16:07:43-16:11:09JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0213+178 2024/02/17(048)16:19:34-16:23:00JST 199Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C67

2024/02/17(048)16:27:16-16:30:42JST 205Rs

13484+/- 164




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C71

2024/02/17(048)16:45:31-16:48:57JST 200Rs


13069+/- 47




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA CTA21 2024/02/17(048)17:21:50-17:25:16JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0320+05 2024/02/17(048)17:26:07-17:29:33JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0324+119 2024/02/17(048)17:30:12-17:33:38JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0332-187 2024/02/17(048)17:37:38-17:41:04JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0338-196 2024/02/17(048)17:43:39-17:47:05JST 210Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0346-130 2024/02/17(048)17:51:18-17:54:44JST 211Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

