




TOYOKAWA 1915+556 2024/04/15(106)05:32:01-05:35:27JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1931+364 2024/04/15(106)05:49:14-05:52:40JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1936+266 2024/04/15(106)05:54:41-05:58:07JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1941+336 2024/04/15(106)05:59:23-06:02:49JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1945+267 2024/04/15(106)06:03:08-06:06:34JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1949+115 2024/04/15(106)06:07:23-06:10:49JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1954+513 2024/04/15(106)06:11:03-06:14:29JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1958+252 2024/04/15(106)06:15:47-06:19:13JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 2001+003 2024/04/15(106)06:19:29-06:22:55JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2007+502 2024/04/15(106)06:24:34-06:28:00JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2009-162 2024/04/15(106)06:28:38-06:32:04JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2014+358 2024/04/15(106)06:32:18-06:35:44JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2018+231 2024/04/15(106)06:36:43-06:40:09JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2022+119 2024/04/15(106)06:40:25-06:43:51JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2025-155 2024/04/15(106)06:44:04-06:47:30JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2029-018 2024/04/15(106)06:48:16-06:51:42JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 2034-066 2024/04/15(106)06:52:32-06:55:58JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2038-013 2024/04/15(106)06:57:01-07:00:27JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C422 2024/04/15(106)07:02:54-07:06:20JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2049+166 2024/04/15(106)07:07:05-07:10:31JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2054+570 2024/04/15(106)07:11:10-07:14:36JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2056+028 2024/04/15(106)07:14:50-07:18:16JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2101+139 2024/04/15(106)07:19:14-07:22:40JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2105-072 2024/04/15(106)07:23:31-07:26:57JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2109+328 2024/04/15(106)07:27:18-07:30:44JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2114+608 2024/04/15(106)07:31:08-07:34:34JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2116-250 2024/04/15(106)07:34:53-07:38:19JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2120-102 2024/04/15(106)07:38:37-07:42:03JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2124+349 2024/04/15(106)07:42:27-07:45:53JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2024/04/15(106)07:49:17-07:52:43JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2024/04/15(106)07:53:35-07:57:01JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2139+028 2024/04/15(106)07:57:48-08:01:14JST 182Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2147+145 2024/04/15(106)08:05:55-08:09:21JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2152+450 2024/04/15(106)08:09:37-08:13:03JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2156-043 2024/04/15(106)08:14:59-08:18:25JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2203-18 2024/04/15(106)08:21:47-08:25:13JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2210+016 2024/04/15(106)08:28:10-08:31:36JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2217+128 2024/04/15(106)08:35:33-08:38:59JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C446

2024/04/15(106)08:41:20-08:44:46JST 162Rs


10302+/- 362




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2229-093 2024/04/15(106)08:48:03-08:51:29JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 2235+511 2024/04/15(106)08:52:36-08:56:02JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2243+394 2024/04/15(106)09:01:06-09:04:32JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C454.3 2024/04/15(106)09:09:19-09:12:45JST 136Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2259+481 2024/04/15(106)09:17:02-09:20:28JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C456

2024/04/15(106)09:27:50-09:31:16JST 122Rs

10256+/- 30




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C459

2024/04/15(106)09:31:55-09:35:21JST 121Rs


10593+/- 42




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2318-16 2024/04/15(106)09:36:23-09:39:49JST 144Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2325+269 2024/04/15(106)09:43:16-09:46:42JST 121Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 2344+09 2024/04/15(106)10:01:54-10:05:20JST 95Rs


9873+/- 168




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2347-02 2024/04/15(106)10:05:40-10:09:06JST 102Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2354+14 2024/04/15(106)10:12:34-10:16:00JST 87Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C2

2024/04/15(106)10:21:37-10:25:03JST 87Rs


10033+/- 45




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0011+344 2024/04/15(106)10:28:58-10:32:24JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0019-00 2024/04/15(106)10:37:35-10:41:01JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C12


2024/04/15(106)10:47:49-10:51:15JST 66Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0038+328 2024/04/15(106)10:56:07-10:59:33JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 0044-056 2024/04/15(106)11:01:51-11:05:17JST 70Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C26

2024/04/15(106)11:09:12-11:12:38JST 61Rs


9347+/- 88




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0056-00 2024/04/15(106)11:14:11-11:17:37JST 48Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0106+01 2024/04/15(106)11:23:53-11:27:19JST 38Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0115-01 2024/04/15(106)11:33:16-11:36:42JST 44Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0120+405 2024/04/15(106)11:38:37-11:42:03JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0128+03 2024/04/15(106)11:46:16-11:49:42JST 20Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C48

2024/04/15(106)11:52:49-11:56:15JST 85Rs

12526+/- 716




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0148+274 2024/04/15(106)12:06:33-12:09:59JST 68Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0155-109 2024/04/15(106)12:12:34-12:16:00JST 78Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0202+15 2024/04/15(106)12:19:41-12:23:07JST 34Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0213+178 2024/04/15(106)12:31:31-12:34:57JST 49Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0223+341 2024/04/15(106)12:41:05-12:44:31JST 98Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C71

2024/04/15(106)12:57:29-13:00:55JST 72Rs


9509+/- 225




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0258+350 2024/04/15(106)13:16:43-13:20:09JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0308+305 2024/04/15(106)13:26:33-13:29:59JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0320+05 2024/04/15(106)13:38:05-13:41:31JST 99Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0324+119 2024/04/15(106)13:42:09-13:45:35JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0333+32 2024/04/15(106)13:51:26-13:54:52JST 126Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0347+05 2024/04/15(106)14:04:28-14:07:54JST 120Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0355+50 2024/04/15(106)14:14:40-14:18:06JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0403-132 2024/04/15(106)14:20:02-14:23:28JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0411+05 2024/04/15(106)14:29:13-14:32:39JST 138Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0418+236 2024/04/15(106)14:36:07-14:39:33JST 144Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0422+178 2024/04/15(106)14:40:05-14:43:31JST 144Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C119 2024/04/15(106)14:47:34-14:51:00JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C138 2024/04/15(106)15:35:41-15:39:07JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0531+194 2024/04/15(106)15:49:15-15:52:41JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C147 2024/04/15(106)15:57:34-16:01:00JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0548+16 2024/04/15(106)16:05:46-16:09:12JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0552+12 2024/04/15(106)16:09:56-16:13:22JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0556+191 2024/04/15(106)16:14:23-16:17:49JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C152 2024/04/15(106)16:18:56-16:22:22JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C158 2024/04/15(106)16:36:02-16:39:28JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C161

2024/04/15(106)16:41:17-16:44:43JST 207Rs


9722+/- 156




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2024/04/15(106)17:08:50-17:12:16JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0703+138 2024/04/15(106)17:20:26-17:23:52JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0725+244 2024/04/15(106)17:42:46-17:46:12JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0732+33 2024/04/15(106)17:50:15-17:53:41JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0740+474 2024/04/15(106)17:58:58-18:02:24JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

