




TOYOKAWA 1939+408 2024/04/21(112)05:32:49-05:36:15JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1942+374 2024/04/21(112)05:36:33-05:39:59JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1949+409 2024/04/21(112)05:42:42-05:46:08JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1953+354 2024/04/21(112)05:47:02-05:50:28JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1958+252 2024/04/21(112)05:52:12-05:55:38JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2003+386 2024/04/21(112)05:56:46-06:00:12JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2007+502 2024/04/21(112)06:00:59-06:04:25JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2014+358 2024/04/21(112)06:08:42-06:12:08JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2018+231 2024/04/21(112)06:13:07-06:16:33JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2022+119 2024/04/21(112)06:16:49-06:20:15JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2033+375 2024/04/21(112)06:27:11-06:30:37JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2035-203 2024/04/21(112)06:30:52-06:34:18JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2039-236 2024/04/21(112)06:34:40-06:38:06JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C422 2024/04/21(112)06:39:18-06:42:44JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2049+166 2024/04/21(112)06:43:29-06:46:55JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2054+570 2024/04/21(112)06:47:35-06:51:01JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2056+028 2024/04/21(112)06:51:14-06:54:40JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2101+139 2024/04/21(112)06:55:39-06:59:05JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2024/04/21(112)06:59:56-07:03:22JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2109+328 2024/04/21(112)07:03:43-07:07:09JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2114+608 2024/04/21(112)07:07:33-07:10:59JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2116-250 2024/04/21(112)07:11:18-07:14:44JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2120-102 2024/04/21(112)07:15:01-07:18:27JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 2124+349 2024/04/21(112)07:18:52-07:22:18JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2131+379 2024/04/21(112)07:25:42-07:29:08JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2024/04/21(112)07:30:00-07:33:26JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2139+028 2024/04/21(112)07:34:13-07:37:39JST 192Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2147+145 2024/04/21(112)07:42:19-07:45:45JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2152+450 2024/04/21(112)07:46:02-07:49:28JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2156-043 2024/04/21(112)07:51:24-07:54:50JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2203-18 2024/04/21(112)07:58:12-08:01:38JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2210+016 2024/04/21(112)08:04:34-08:08:00JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2217+128 2024/04/21(112)08:11:58-08:15:24JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C446

2024/04/21(112)08:17:44-08:21:10JST 176Rs


10496+/- 2319




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2229-093 2024/04/21(112)08:24:28-08:27:54JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2235+511 2024/04/21(112)08:29:01-08:32:27JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2238-113 2024/04/21(112)08:32:55-08:36:21JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2243+394 2024/04/21(112)08:37:30-08:40:56JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C454.3 2024/04/21(112)08:45:44-08:49:10JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 2259+481 2024/04/21(112)08:53:27-08:56:53JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C456

2024/04/21(112)09:04:15-09:07:41JST 139Rs

9569+/- 50




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C459

2024/04/21(112)09:08:20-09:11:46JST 139Rs


9967+/- 213




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2318-16 2024/04/21(112)09:12:48-09:16:14JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2325+269 2024/04/21(112)09:19:40-09:23:06JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2344+09 2024/04/21(112)09:38:18-09:41:44JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2347-02 2024/04/21(112)09:42:05-09:45:31JST 121Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 2354+14 2024/04/21(112)09:48:58-09:52:24JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C2


2024/04/21(112)09:58:01-10:01:27JST 106Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0011+344 2024/04/21(112)10:05:23-10:08:49JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0019-00 2024/04/21(112)10:14:00-10:17:26JST 94Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C12

2024/04/21(112)10:24:14-10:27:40JST 79Rs


9507+/- 27




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0038+328 2024/04/21(112)10:32:32-10:35:58JST 99Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0044-056 2024/04/21(112)10:38:16-10:41:42JST 89Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C26

2024/04/21(112)10:45:37-10:49:03JST 80Rs


9515+/- 707




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0056-00 2024/04/21(112)10:50:36-10:54:02JST 68Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0106+01 2024/04/21(112)11:00:18-11:03:44JST 58Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0116+31 2024/04/21(112)11:11:07-11:14:33JST 80Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0120+405 2024/04/21(112)11:15:02-11:18:28JST 107Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C43

2024/04/21(112)11:21:30-11:24:56JST 49Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C48

2024/04/21(112)11:29:14-11:32:40JST 79Rs


10494+/- 180




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0148+274 2024/04/21(112)11:42:57-11:46:23JST 59Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0155-109 2024/04/21(112)11:48:59-11:52:25JST 83Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0202+15 2024/04/21(112)11:56:06-11:59:32JST 14Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)









TOYOKAWA 3C67

2024/04/21(112)12:15:38-12:19:04JST 64Rs

10283+/- 126




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C71


2024/04/21(112)12:33:54-12:37:20JST 61Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0258+350 2024/04/21(112)12:53:08-12:56:34JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0308+305 2024/04/21(112)13:02:57-13:06:23JST 93Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0320+05 2024/04/21(112)13:14:29-13:17:55JST 82Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0324+119 2024/04/21(112)13:18:34-13:22:00JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )









TOYOKAWA 0347+05 2024/04/21(112)13:40:52-13:44:18JST 103Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0355+50 2024/04/21(112)13:51:04-13:54:30JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0403-132 2024/04/21(112)13:56:27-13:59:53JST 140Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0411+05 2024/04/21(112)14:05:37-14:09:03JST 122Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0418+236 2024/04/21(112)14:12:31-14:15:57JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0422+178 2024/04/21(112)14:16:30-14:19:56JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C119

2024/04/21(112)14:23:58-14:27:24JST 153Rs


11854+/- 1585




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C138 2024/04/21(112)15:12:06-15:15:32JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0531+194 2024/04/21(112)15:25:39-15:29:05JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C147 2024/04/21(112)15:33:58-15:37:24JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0548+16 2024/04/21(112)15:42:10-15:45:36JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0552+12 2024/04/21(112)15:46:21-15:49:47JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0556+191 2024/04/21(112)15:50:48-15:54:14JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C152 2024/04/21(112)15:55:20-15:58:46JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C158 2024/04/21(112)16:12:26-16:15:52JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C161 2024/04/21(112)16:17:42-16:21:08JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0652-130 2024/04/21(112)16:45:15-16:48:41JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0703+138 2024/04/21(112)16:56:51-17:00:17JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0713-024 2024/04/21(112)17:06:14-17:09:40JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0716+022 2024/04/21(112)17:09:54-17:13:20JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0723+10 2024/04/21(112)17:16:25-17:19:51JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0732+33 2024/04/21(112)17:26:40-17:30:06JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C186

2024/04/21(112)17:35:04-17:38:30JST 212Rs


11780+/- 546




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0749+299 2024/04/21(112)17:43:27-17:46:53JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0800+331 2024/04/21(112)17:54:43-17:58:09JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0806+426 2024/04/21(112)18:00:48-18:04:14JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196 2024/04/21(112)18:04:25-18:07:51JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0816+526 2024/04/21(112)18:10:40-18:14:06JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0820+560 2024/04/21(112)18:15:42-18:19:08JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

