




T20240413061411





BLK: 6,SNR1: 14.899 ,SNR2: 48.251




Frequency (Hz)

F20240413061412




BLK: 6,SNR1: 0.15836 ,SNR2: 1.3807





Frequency (Hz)


1949+409 2024/04/12 21.26UT TOYOKAWA-FUJI



T20240413061411





BLK:10,SNR1: 90.915 ,SNR2: 439.64




Frequency (Hz)

K20240413061410




BLK:10,SNR1: 0.91616 ,SNR2: 3.2973





Frequency (Hz)


1949+409 2024/04/12 21.26UT TOYOKAWA-KISO



F20240413061412





BLK: 7,SNR1:-0.16088 ,SNR2: 0.87226




Frequency (Hz)

K20240413061410




BLK: 7,SNR1: 14.131 ,SNR2: 26.816





Frequency (Hz)


1949+409 2024/04/12 21.26UT FUJI -KISO



T20240413061831




BLK: 8,SNR1: 0.70662 ,SNR2: 2.4988




Frequency (Hz)

F20240413061832




BLK: 8,SNR1: 0.52810 ,SNR2: 3.7107





Frequency (Hz)


1953+354 2024/04/12 21.34UT TOYOKAWA-FUJI



T20240413061831




BLK:15,SNR1: 2.6852 ,SNR2: 8.4265





1953+354 2024/04/12 21.34UT TOYOKAWA-KISO



K20240413061830




BLK:15,SNR1: 3.6138 ,SNR2: 11.697



F20240413061832





BLK: 9,SNR1: 0.43984 ,SNR2: 3.6977




Frequency (Hz)

K20240413061830




BLK: 9,SNR1: 3.3359 ,SNR2: 11.031




Frequency (Hz)


1953+354 2024/04/12 21.34UT FUJI -KISO





T20240413062341




BLK: 2,SNR1: 0.51132 ,SNR2: 4.1106




F20240413062342





BLK: 2,SNR1: 1.7326 ,SNR2: 7.8710




1958+252 2024/04/12 21.42UT TOYOKAWA-FUJI





T20240413062341




No. Good Data




K20240413062340



No. Good Data





1958+252 2024/04/12 21.42UT TOYOKAWA-KISO






F20240413062342





BLK: 4,SNR1: 0.36419 ,SNR2: 6.7679




Frequency (Hz)

K20240413062340




BLK: 4,SNR1: 0.13087 ,SNR2: 1.9784




Frequency (Hz)


1958+252 2024/04/12 21.42UT FUJI -KISO



T20240413063228





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


2007+502 2024/04/12 21.57UT TOYOKAWA-FUJI



T20240413063228





BLK: 4,SNR1: 0.22073 ,SNR2: 4.6179




Frequency (Hz)

K20240413063227




BLK: 4,SNR1:-0.99256E-01,SNR2: 0.84640




Frequency (Hz)

2007+502 2024/04/12 21.57UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240413063227




No.Good Data





Frequency (Hz)


2007+502 2024/04/12 21.57UT FUJI -KISO



T20240413064011




BLK: 3,SNR1: 20.463 ,SNR2: 119.39




Frequency (Hz)

2014+358 2024/04/12 21.70UT TOYOKAWA-FUJI


F20240413064012




BLK: 3,SNR1: 0.59283 ,SNR2: 1.8505




Frequency (Hz)



T20240413064011





BLK: 3,SNR1: 9.4887 ,SNR2: 137.32




Frequency (Hz)

2014+358 2024/04/12 21.70UT TOYOKAWA-KISO


K20240413064010




BLK: 3,SNR1: 0.16467 ,SNR2: 1.9451




Frequency (Hz)




F20240413064012




BLK: 3,SNR1: 0.34965E-01,SNR2: 1.7311




K20240413064010





BLK: 3,SNR1: 0.25631 ,SNR2: 3.4806




2014+358 2024/04/12 21.70UT FUJI -KISO



T20240413064819





BLK: 6,SNR1: 0.36441 ,SNR2: 1.9075




Frequency (Hz)

F20240413064820




BLK: 6,SNR1: 3.5774 ,SNR2: 15.136





Frequency (Hz)

2022+119 2024/04/12 21.83UT TOYOKAWA-FUJI






T20240413064819





BLK:12,SNR1: 0.33080 ,SNR2: 1.1804




Frequency (Hz)

K20240413064818




BLK:12,SNR1: 3.6280 ,SNR2: 15.116





Frequency (Hz)


2022+119 2024/04/12 21.83UT TOYOKAWA-KISO



F20240413064820





BLK: 7,SNR1: 3.7024 ,SNR2: 15.928




Frequency (Hz)

2022+119 2024/04/12 21.83UT FUJI -KISO


K20240413064818




BLK: 7,SNR1: 2.4224 ,SNR2: 10.556




Frequency (Hz)




T20240413065610




BLK: 5,SNR1: 0.77366 ,SNR2: 10.489




F20240413065611





BLK: 5,SNR1: 1.0720 ,SNR2: 3.3084




2029-018 2024/04/12 21.96UT TOYOKAWA-FUJI



T20240413065610





BLK: 5,SNR1: 1.3495 ,SNR2: 7.9255




Frequency (Hz)

2029-018 2024/04/12 21.96UT TOYOKAWA-KISO


K20240413065609





BLK: 5,SNR1: 4.7160 ,SNR2: 10.742




Frequency (Hz)



F20240413065611





BLK: 3,SNR1: 0.83611E-01,SNR2: 1.3032




Frequency (Hz)

K20240413065609




BLK: 3,SNR1: 5.2160 ,SNR2: 19.099




Frequency (Hz)


2029-018 2024/04/12 21.96UT FUJI -KISO



T20240413070026




BLK: 3,SNR1: 2.9196 ,SNR2: 31.698





2034-066 2024/04/12 22.04UT TOYOKAWA-FUJI


F20240413070027




BLK: 3,SNR1:-0.32193 ,SNR2: 0.0000



T20240413070026





BLK: 7,SNR1: 5.4390 ,SNR2: 34.312




Frequency (Hz)

K20240413070025




BLK: 7,SNR1: 0.65128 ,SNR2: 4.6962





Frequency (Hz)


2034-066 2024/04/12 22.04UT TOYOKAWA-KISO





F20240413070027




BLK: 3,SNR1:-0.33370 ,SNR2: 0.27330




K20240413070025



BLK: 3,SNR1:-0.30775E-02,SNR2: 1.1147





2034-066 2024/04/12 22.04UT FUJI -KISO






T20240413070455





BLK: 2,SNR1: 0.36397E-01,SNR2: 0.38180




Frequency (Hz)

F20240413070456




BLK: 2,SNR1:-0.16276 ,SNR2: 0.58012





Frequency (Hz)


2038-013 2024/04/12 22.11UT TOYOKAWA-FUJI



T20240413070455





BLK: 4,SNR1:-0.37286E-01,SNR2: 0.54910




Frequency (Hz)

K20240413070454




BLK: 4,SNR1: 19.261 ,SNR2: 23.004





Frequency (Hz)


2038-013 2024/04/12 22.11UT TOYOKAWA-KISO



F20240413070456





BLK: 3,SNR1: 2.4479 ,SNR2: 6.1837




Frequency (Hz)

K20240413070454




BLK: 3,SNR1: 18.608 ,SNR2: 34.702





Frequency (Hz)


2038-013 2024/04/12 22.11UT FUJI -KISO



T20240413071047




BLK: 2,SNR1: 2.0577 ,SNR2: 20.636





3C422 2024/04/12 22.21UT TOYOKAWA-FUJI



F20240413071048




BLK: 2,SNR1:-0.29199 ,SNR2: 0.39859E-02



T20240413071047




BLK: 6,SNR1: 0.72095 ,SNR2: 6.2709




Frequency (Hz)

K20240413071046




BLK: 6,SNR1: 3.0878 ,SNR2: 6.0835





Frequency (Hz)


3C422 2024/04/12 22.21UT TOYOKAWA-KISO



F20240413071048





BLK: 4,SNR1:-0.28602 ,SNR2: 0.41984




Frequency (Hz)

3C422 2024/04/12 22.21UT FUJI -KISO


K20240413071046





BLK: 4,SNR1: 3.8786 ,SNR2: 8.7154




Frequency (Hz)



T20240413072243





BLK: 5, SNR1: 5.3817 ,SNR2: 53.056




Frequency (Hz)

F20240413072244




BLK: 5, SNR1: 1.8649 ,SNR2: 7.7187





Frequency (Hz)


2056+028 2024/04/12 22.41UT TOYOKAWA-FUJI



T20240413072243





BLK: 4,SNR1: 10.236 ,SNR2: 109.53




Frequency (Hz)

K20240413072242




BLK: 4,SNR1: 0.58092 ,SNR2: 3.0223





Frequency (Hz)

2056+028 2024/04/12 22.41UT TOYOKAWA-KISO








F20240413072244




BLK: 5, SNR1: 1.0984 , SNR2: 10.448




K20240413072242





BLK: 5, SNR1: 2.1052 , SNR2: 3.6742




2056+028 2024/04/12 22.41UT FUJI -KISO



T20240413073125





BLK: 3,SNR1: 0.23453 ,SNR2: 1.4087




Frequency (Hz)

F20240413073125




BLK: 3,SNR1: 0.42714E-01,SNR2: 1.1267





Frequency (Hz)


2105-072 2024/04/12 22.55UT TOYOKAWA-FUJI



T20240413073125





BLK: 2,SNR1: 0.34744 ,SNR2: 2.7142




Frequency (Hz)

K20240413073124




BLK: 2,SNR1: 16.161 ,SNR2: 30.168





Frequency (Hz)


2105-072 2024/04/12 22.55UT TOYOKAWA-KISO



F20240413073125





BLK: 5,SNR1:-0.21440 ,SNR2: 0.13324




Frequency (Hz)

K20240413073124




BLK: 5,SNR1: 7.2743 ,SNR2: 12.384




Frequency (Hz)


2105-072 2024/04/12 22.55UT FUJI -KISO



T20240413074630





BLK: 7,SNR1: 0.29401 ,SNR2: 2.2502





2120-102 2024/04/12 22.80UT TOYOKAWA-FUJI


F20240413074631




BLK: 7,SNR1: 0.75943 ,SNR2: 2.5013




T20240413074630




BLK: 5,SNR1: 0.78247 ,SNR2: 10.044




K20240413074629





BLK: 5,SNR1: 1.4330 ,SNR2: 7.4539




2120-102 2024/04/12 22.80UT TOYOKAWA-KISO



F20240413074631





BLK: 5,SNR1:-0.78334E-01,SNR2: 1.6743




Frequency (Hz)

K20240413074629




BLK: 5,SNR1: 12.858 ,SNR2: 19.479





Frequency (Hz)


2120-102 2024/04/12 22.80UT FUJI -KISO




T20240413075711




No.Good Data




F20240413075712



No.Good Data





2131+379 2024/04/12 22.98UT TOYOKAWA-FUJI








T20240413075711




BLK: 1,SNR1:-0.36364E-01,SNR2: 0.52839




K20240413075710





BLK: 1,SNR1: 0.45342E-01,SNR2: 0.55059




2131+379 2024/04/12 22.98UT TOYOKAWA-KISO





F20240413075712




BLK: 1,SNR1:-0.71132E-01,SNR2: 0.60420




K20240413075710





BLK: 1,SNR1: 1.7782 ,SNR2: 12.541




2131+379 2024/04/12 22.98UT FUJI -KISO



T20240413081349




BLK: 5,SNR1: 0.73097E-01,SNR2: 0.52216





2147+145 2024/04/12 23.26UT TOYOKAWA-FUJI



F20240413081350




BLK: 5,SNR1: 0.56028 ,SNR2: 3.5269





T20240413081349




BLK: 4,SNR1:-0.14826 ,SNR2: 0.49072




K20240413081348




BLK: 4,SNR1: 1.0230 ,SNR2: 3.8331




2147+145 2024/04/12 23.26UT TOYOKAWA-KISO





F20240413081350




BLK: 4,SNR1: 0.73683E-01,SNR2: 3.5578




K20240413081348





BLK: 4,SNR1: 0.12640 ,SNR2: 3.4443




2147+145 2024/04/12 23.26UT FUJI -KISO




T20240413082253




BLK: 3,SNR1: 0.65070 ,SNR2: 3.8075




F20240413082254





BLK: 3,SNR1: 2.1631 ,SNR2: 13.112




2156-043 2024/04/12 23.41UT TOYOKAWA-FUJI



T20240413082253





BLK: 3,SNR1: 0.73170 ,SNR2: 2.2195




Frequency (Hz)

K20240413082252




BLK: 3,SNR1: 1.1414 ,SNR2: 9.2177




Frequency (Hz)


2156-043 2024/04/12 23.41UT TOYOKAWA-KISO





F20240413082254




BLK: 3,SNR1: 3.1405 ,SNR2: 11.295




K20240413082252



BLK: 3,SNR1:-0.55706E-03,SNR2: 0.25186





2156-043 2024/04/12 23.41UT FUJI -KISO







T20240413082941




BLK: 8,SNR1: 0.38690 ,SNR2: 4.3702




F20240413082942





BLK: 8,SNR1:-0.11891 ,SNR2: 0.28535




2203-18 2024/04/12 23.52UT TOYOKAWA-FUJI



T20240413082941





BLK: 4,SNR1: 1.4680 ,SNR2: 7.7075





2203-18 2024/04/12 23.52UT TOYOKAWA-KISO


K20240413082940




BLK: 4,SNR1: 0.87800E-01,SNR2: 2.6331





F20240413082942




BLK: 2,SNR1: 0.85772E-02,SNR2: 0.50170




K20240413082940




BLK: 2,SNR1: 0.58089 ,SNR2: 8.5262




2203-18 2024/04/12 23.52UT FUJI -KISO




T20240413083604




BLK: 5,SNR1: 0.66800E-01,SNR2: 0.99680




F20240413083604





BLK: 5,SNR1: 1.1233 ,SNR2: 3.3410




2210+016 2024/04/12 23.63UT TOYOKAWA-FUJI





T20240413083604




BLK: 3,SNR1:-0.14087E-01,SNR2: 0.61865




K20240413083603





BLK: 3,SNR1:-0.14849 ,SNR2: 1.1401



2210+016 2024/04/12 23.63UT TOYOKAWA-KISO





F20240413083604




No.Good Data




K20240413083603





No.Good Data




2210+016 2024/04/12 23.63UT FUJI -KISO





T20240413084327




BLK: 3,SNR1: 0.14387E-01,SNR2: 0.42721




F20240413084328





BLK: 3,SNR1:-0.18845 ,SNR2: 1.4065




2217+128 2024/04/12 23.75UT TOYOKAWA-FUJI





T20240413084327




BLK: 6,SNR1: 0.14786 ,SNR2: 0.68188




K20240413084326



BLK: 6,SNR1: 0.43747 ,SNR2: 2.2930




2217+128 2024/04/12 23.75UT TOYOKAWA-KISO








F20240413084328




BLK: 4, SNR1: 0.20913 , SNR2: 3.7082




K20240413084326





BLK: 4, SNR1: 1.0572 , SNR2: 7.7360




2217+128 2024/04/12 23.75UT FUJI -KISO



T20240413084913




BLK: 2,SNR1: 0.33034 ,SNR2: 4.9031





3C446 2024/04/12 23.85UT TOYOKAWA-FUJI



F20240413084914




BLK: 2,SNR1:-0.25752 ,SNR2: 0.0000





T20240413084913




BLK: 9, SNR1: 0.28901 , SNR2: 1.8593




K20240413084912





BLK: 9, SNR1: 0.29533 , SNR2: 1.5908




3C446 2024/04/12 23.85UT TOYOKAWA-KISO



F20240413084914





BLK: 4, SNR1: 0.13420 , SNR2: 1.6684




Frequency (Hz)

3C446 2024/04/12 23.85UT FUJI -KISO


K20240413084912





BLK: 4, SNR1: 0.15353 , SNR2: 0.30015




Frequency (Hz)



T20240413090424





BLK: 6,SNR1: 2.8602 ,SNR2: 31.188




Frequency (Hz)

2238-113 2024/04/13 0.10UT TOYOKAWA-FUJI


F20240413090424




BLK: 6,SNR1:-0.24786 ,SNR2: 1.8010




Frequency (Hz)



T20240413090424





BLK: 7, SNR1: 3.4157 ,SNR2: 30.543





2238-113 2024/04/13 0.10UT TOYOKAWA-KISO


K20240413090423




BLK: 7, SNR1: 0.99227 ,SNR2: 4.8082




F20240413090424




BLK: 3,SNR1: 0.19748 ,SNR2: 2.5171




K20240413090423





BLK: 3,SNR1: 0.31111 ,SNR2: 3.9245




2238-113 2024/04/13 0.10UT FUJI -KISO



T20240413091713




BLK:10,SNR1: 1.0944 ,SNR2: 10.422




3C454.3 2024/04/13 0.32UT TOYOKAWA-FUJI


F20240413091714



BLK:10,SNR1:-0.40130 ,SNR2: 0.35490





Frequency (Hz)






T20240413091713





BLK: 5, SNR1: 0.52291 , SNR2: 5.5509





3C454.3 2024/04/13 0.32UT TOYOKAWA-KISO


K20240413091712




BLK: 5, SNR1: 0.11241 , SNR2: 0.50042





F20240413091714




BLK: 8, SNR1: -0.37294 , SNR2: 0.23206




K20240413091712







BLK: 8, SNR1: 0.23322 , SNR2: 2.8570








3C454.3 2024/04/13 0.32UT FUJI -KISO






2259+481 2024/04/13 0.44UT TOYOKAWA-FUJI







2259+481 2024/04/13 0.44UT TOYOKAWA-KISO



F20240413092456





BLK: 4,SNR1: 0.50596 ,SNR2: 3.5666




Frequency (Hz)

K20240413092455




BLK: 4,SNR1: 0.58534E-01,SNR2: 0.39618





Frequency (Hz)


2259+481 2024/04/13 0.44UT FUJI -KISO



T20240413093949




BLK: 8,SNR1: 12.972 ,SNR2: 67.117





3C459 2024/04/13 0.69UT TOYOKAWA-FUJI


F20240413093950




BLK: 8,SNR1:-0.74478E-01,SNR2: 1.5978



T20240413093949




BLK:12,SNR1: 3.8473 ,SNR2: 56.463





3C459 2024/04/13 0.69UT TOYOKAWA-KISO


K20240413093948




BLK:12,SNR1: 1.0979 ,SNR2: 4.4220





F20240413093950




BLK: 5,SNR1: 0.81883E-01,SNR2: 1.9003




K20240413093948







BLK: 5,SNR1: 0.96573 ,SNR2: 2.7848




3C459 2024/04/13 0.69UT FUJI -KISO












2347-02 2024/04/13 1.25UT TOYOKAWA-FUJI







2347-02 2024/04/13 1.25UT TOYOKAWA-KISO





F20240413101334




BLK: 4, SNR1: 1.0003 ,SNR2: 2.7201




K20240413101333





BLK: 4, SNR1: 0.48967 ,SNR2: 1.1783




2347-02 2024/04/13 1.25UT FUJI -KISO



T20240413102028




BLK:16,SNR1: 45.773 ,SNR2: 45.551





2354+14 2024/04/13 1.37UT TOYOKAWA-FUJI



F20240413102028




BLK:16,SNR1: 4.9627 ,SNR2: 12.567



T20240413102028




BLK:12,SNR1: 49.523 ,SNR2: 49.282




2354+14 2024/04/13 1.37UT TOYOKAWA-KISO


K20240413102027





BLK:12,SNR1: 2.9051 ,SNR2: 10.943




Frequency (Hz)



F20240413102028





BLK:15,SNR1: 4.7769 ,SNR2: 12.142




Frequency (Hz)

K20240413102027




BLK:15,SNR1: 2.8110 ,SNR2: 10.326





Frequency (Hz)


2354+14 2024/04/13 1.37UT FUJI -KISO



T20240413102930





BLK:26,SNR1: 2.8967 ,SNR2: 13.521





3C2 2024/04/13 1.52UT TOYOKAWA-FUJI



F20240413102931




BLK:26,SNR1: 7.6721 ,SNR2: 19.868



T20240413102930





BLK:30,SNR1: 2.9122 ,SNR2: 13.578





3C2 2024/04/13 1.52UT TOYOKAWA-KISO

K20240413102929





BLK:30,SNR1: 7.6165 ,SNR2: 20.394






F20240413102931





BLK:30,SNR1: 7.5095 ,SNR2: 19.662




Frequency (Hz)

3C2 2024/04/13 1.52UT FUJI -KISO


K20240413102929







BLK:30,SNR1: 7.6151 ,SNR2: 20.390




Frequency (Hz)










0011+344 2024/04/13 1.64UT TOYOKAWA-FUJI




T20240413103652




K20240413103651




0011+344 2024/04/13 1.64UT TOYOKAWA-KISO




F20240413103653




BLK: 5, SNR1:  $-0.46112E-02$ , SNR2: 1.2520




K20240413103651





BLK: 5, SNR1: 0.44227, SNR2: 1.8208




0011+344 2024/04/13 1.64UT FUJI -KISO



T20240413104529





BLK: 7,SNR1: 0.49862 ,SNR2: 3.9623





0019-00 2024/04/13 1.79UT TOYOKAWA-FUJI


F20240413104529




BLK: 7,SNR1: 0.47302 ,SNR2: 2.3647





T20240413104529




BLK:16,SNR1: 0.55179 ,SNR2: 2.9173




K20240413104528




BLK:16,SNR1: 0.92822 ,SNR2: 4.4111




0019-00 2024/04/13 1.79UT TOYOKAWA-KISO





F20240413104529




BLK: 5, SNR1: 10.184 , SNR2: 20.484




K20240413104528







BLK: 5, SNR1: 0.39823 , SNR2: 2.3130




0019-00 2024/04/13 1.79UT FUJI -KISO










3C12 2024/04/13 1.96UT TOYOKAWA-FUJI









3C12 2024/04/13 1.96UT TOYOKAWA-KISO




F20240413105544




BLK:20,SNR1: 3.8427 ,SNR2: 9.7698




K20240413105542




BLK:20,SNR1: 1.1806 ,SNR2: 4.7330




3C12 2024/04/13 1.96UT FUJI -KISO




T20240413110945




BLK: 3,SNR1: 0.13050 ,SNR2: 1.9843




F20240413110945




BLK: 3,SNR1: 2.1246 ,SNR2: 5.5393




0044-056 2024/04/13 2.19UT TOYOKAWA-FUJI





T20240413110945




BLK: 9,SNR1: 0.29374 ,SNR2: 2.2564




K20240413110944




BLK: 9,SNR1: 0.51198 ,SNR2: 3.1356




0044-056 2024/04/13 2.19UT TOYOKAWA-KISO





F20240413110945




BLK: 5,SNR1: 0.23192 ,SNR2: 2.0413




K20240413110944




BLK: 5,SNR1: 0.18018 ,SNR2: 1.1818




0044-056 2024/04/13 2.19UT FUJI -KISO




T20240413111706




BLK:19,SNR1: 1.3063 ,SNR2: 7.1246




F20240413111707




BLK:19,SNR1: 0.61182 ,SNR2: 6.9201




3C26 2024/04/13 2.31UT TOYOKAWA-FUJI




T20240413111706




BLK:28,SNR1: 1.0307 ,SNR2: 5.8632




K20240413111705




BLK:28,SNR1: 8.4430 ,SNR2: 16.517




3C26 2024/04/13 2.31UT TOYOKAWA-KISO



F20240413111707





BLK:22,SNR1: 0.62189 ,SNR2: 6.9011





3C26 2024/04/13 2.31UT FUJI -KISO

K20240413111705




BLK:22,SNR1: 10.165 ,SNR2: 19.606







T20240413112205




BLK: 9,SNR1: 2.7846 ,SNR2: 16.593




F20240413112206




BLK: 9,SNR1: 2.2642 ,SNR2: 16.547




0056-00 2024/04/13 2.40UT TOYOKAWA-FUJI




T20240413112205




BLK:20,SNR1: 2.6055 ,SNR2: 16.312




K20240413112204




BLK:20,SNR1: 0.31805 ,SNR2: 1.3284




0056-00 2024/04/13 2.40UT TOYOKAWA-KISO



F20240413112206




BLK: 6,SNR1:-0.10435 ,SNR2: 0.20030E-01





0056-00 2024/04/13 2.40UT FUJI -KISO


K20240413112204




BLK: 6,SNR1: 0.28890 ,SNR2: 2.0397




T20240413113147




BLK: 5,SNR1: 0.73604 ,SNR2: 2.1410




F20240413113147




BLK: 5,SNR1: 0.87226E-01,SNR2: 1.5362




0106+01 2024/04/13 2.56UT TOYOKAWA-FUJI




T20240413113147




BLK: 8,SNR1: 0.69300 ,SNR2: 2.5114




K20240413113146




BLK: 8,SNR1: 0.42545 ,SNR2: 2.0422




0106+01 2024/04/13 2.56UT TOYOKAWA-KISO




F20240413113147




BLK: 3,SNR1:-0.25057 ,SNR2: 0.0000




K20240413113146







BLK: 3,SNR1: 0.88559 ,SNR2: 5.1417






0106+01 2024/04/13 2.56UT FUJI -KISO






0115-01 2024/04/13 2.71UT TOYOKAWA-FUJI






0115-01 2024/04/13 2.71UT TOYOKAWA-KISO






F20240413114111





BLK: 3,SNR1:-0.25577E-01,SNR2: 1.0829





0115-01 2024/04/13 2.71UT FUJI -KISO



K20240413114109




BLK: 3,SNR1: 0.85473 ,SNR2: 5.3320




T20240413115409




BLK:15,SNR1: 0.11341 ,SNR2: 1.3704




F20240413115410





BLK:15,SNR1: 0.27754E-02,SNR2: 3.6370




0128+03 2024/04/13 2.93UT TOYOKAWA-FUJI





T20240413115409




BLK: 7,SNR1: 0.49867 ,SNR2: 1.8376




K20240413115408





BLK: 7,SNR1: 0.37395 ,SNR2: 1.3152




0128+03 2024/04/13 2.93UT TOYOKAWA-KISO





F20240413115410




BLK: 7,SNR1: 0.53252 ,SNR2: 3.1696




K20240413115408





BLK: 7,SNR1: 0.71412 ,SNR2: 2.8453




0128+03 2024/04/13 2.93UT FUJI -KISO



T20240413120043




BLK:23,SNR1: 16.678 ,SNR2: 48.480





3C48 2024/04/13 3.04UT TOYOKAWA-FUJI



F20240413120044




BLK:23,SNR1: 0.10939 ,SNR2: 5.5965



T20240413120043




BLK:25,SNR1: 17.638 ,SNR2: 39.323





3C48 2024/04/13 3.04UT TOYOKAWA-KISO


K20240413120042




BLK:25,SNR1: 2.9751 ,SNR2: 11.053



F20240413120044





BLK:22,SNR1: 0.47934 ,SNR2: 2.5281





3C48 2024/04/13 3.04UT FUJI -KISO



K20240413120042




BLK:22,SNR1: 3.2158 ,SNR2: 11.727




T20240413122028




BLK:11,SNR1: 0.36858 ,SNR2: 2.9178




F20240413122029



BLK:11,SNR1: 0.77464 ,SNR2: 2.9459





0155-109 2024/04/13 3.37UT TOYOKAWA-FUJI








T20240413122028




BLK:15,SNR1: 0.66347 ,SNR2: 2.4989




K20240413122027




BLK:15,SNR1: 1.0631 ,SNR2: 4.8298




0155-109 2024/04/13 3.37UT TOYOKAWA-KISO





F20240413122029




BLK: 8,SNR1: 0.13230E-02,SNR2: 2.2514




K20240413122027




BLK: 8,SNR1: 4.3410 ,SNR2: 6.2357




0155-109 2024/04/13 3.37UT FUJI -KISO




T20240413122735




BLK:20,SNR1: 3.4360 ,SNR2: 11.020




F20240413122735





BLK:20,SNR1: 0.16361E-01,SNR2: 2.0132




0202+15 2024/04/13 3.49UT TOYOKAWA-FUJI





T20240413122735




BLK:16,SNR1: 3.7438 ,SNR2: 12.196




K20240413122734




BLK:16,SNR1: 0.94694 ,SNR2: 4.1650




0202+15 2024/04/13 3.49UT TOYOKAWA-KISO





F20240413122735




BLK:11,SNR1: 0.32573E-01,SNR2: 1.2547




K20240413122734





BLK:11,SNR1: 0.77030 ,SNR2: 4.9154




0202+15 2024/04/13 3.49UT FUJI -KISO



T20240413123925





BLK: 1,SNR1: 0.20881 ,SNR2: 0.61327




Frequency (Hz)

F20240413123926




BLK: 1,SNR1:-0.10095 ,SNR2: 1.4730





Frequency (Hz)


0213+178 2024/04/13 3.69UT TOYOKAWA-FUJI





T20240413123925




BLK: 6,SNR1:-0.52974E-01,SNR2: 0.48919




K20240413123924





BLK: 6,SNR1: 0.94951 ,SNR2: 3.9023




0213+178 2024/04/13 3.69UT TOYOKAWA-KISO





F20240413123926




BLK: 8,SNR1: 0.12860 ,SNR2: 3.6816




K20240413123924




BLK: 8,SNR1: 0.67305 ,SNR2: 2.9978





0213+178 2024/04/13 3.69UT FUJI -KISO









BLK:25,SNR1: 1.9092 ,SNR2: 9.9804







BLK:25,SNR1: 3.0755 ,SNR2: 13.549




3C67 2024/04/13 3.81UT TOYOKAWA-FUJI








3C67 2024/04/13 3.81UT TOYOKAWA-KISO



F20240413124707





BLK:20,SNR1: 3.0777 ,SNR2: 13.559





3C67 2024/04/13 3.81UT FUJI -KISO



K20240413124706




BLK:20,SNR1: 7.0421 ,SNR2: 21.644




T20240413130523




BLK: 5,SNR1: 58.227 ,SNR2: 94.710




F20240413130523





BLK: 5,SNR1: 0.93272 ,SNR2: 2.3258




3C71 2024/04/13 4.12UT TOYOKAWA-FUJI





T20240413130523




BLK: 7,SNR1: 58.029 ,SNR2: 94.389




K20240413130522





BLK: 7,SNR1: 154.74 ,SNR2: 165.32




3C71 2024/04/13 4.12UT TOYOKAWA-KISO





F20240413130523




BLK: 8,SNR1: 0.64224 ,SNR2: 1.7010




K20240413130522





BLK: 8,SNR1: 148.97 ,SNR2: 159.16




3C71 2024/04/13 4.12UT FUJI -KISO




T20240413132437




BLK: 6,SNR1: 0.13940 ,SNR2: 0.49698




F20240413132437




BLK: 6,SNR1:-0.20754 ,SNR2: 0.57625




0258+350 2024/04/13 4.44UT TOYOKAWA-FUJI




T20240413132437




BLK: 7,SNR1: 0.23734E-02,SNR2: 0.58042




K20240413132436



BLK: 7,SNR1: 2.3265 ,SNR2: 10.274




0258+350 2024/04/13 4.44UT TOYOKAWA-KISO








F20240413132437




BLK:14,SNR1: 0.85485 ,SNR2: 4.2600




K20240413132436





BLK:14,SNR1: 4.2331 ,SNR2: 11.644




0258+350 2024/04/13 4.44UT FUJI -KISO




T20240413133427




BLK:12,SNR1: 0.44389 ,SNR2: 1.7902




F20240413133427





BLK:12,SNR1: 0.38023E-01,SNR2: 1.1136




0308+305 2024/04/13 4.60UT TOYOKAWA-FUJI





T20240413133427




BLK: 8,SNR1: 0.35851 ,SNR2: 2.6452




K20240413133426







BLK: 8,SNR1: 1.2080 ,SNR2: 4.9809




0308+305 2024/04/13 4.60UT TOYOKAWA-KISO








0308+305 2024/04/13 4.60UT FUJI -KISO



T20240413134559





BLK: 8,SNR1: 0.43282 ,SNR2: 2.8639




Frequency (Hz)

F20240413134559




BLK: 8,SNR1:-0.26887 ,SNR2: 0.42029





Frequency (Hz)


0320+05 2024/04/13 4.79UT TOYOKAWA-FUJI





T20240413134559




BLK:16,SNR1: 0.28066 ,SNR2: 3.0592




K20240413134558







BLK:16,SNR1: 1.0735 ,SNR2: 4.6454




0320+05 2024/04/13 4.79UT TOYOKAWA-KISO







0320+05 2024/04/13 4.79UT FUJI -KISO




T20240413135919




BLK: 2,SNR1:-0.17342E-01,SNR2: 0.58901




F20240413135920



BLK: 2,SNR1:-0.68765E-01,SNR2: 1.8391





0333+32 2024/04/13 5.02UT TOYOKAWA-FUJI








T20240413135919




BLK: 6,SNR1: 0.26005E-01,SNR2: 0.27411




K20240413135918







BLK: 6,SNR1: 0.68551 ,SNR2: 2.9771




0333+32 2024/04/13 5.02UT TOYOKAWA-KISO







0333+32 2024/04/13 5.02UT FUJI -KISO



T20240413141221





BLK: 4,SNR1:-0.60201E-02,SNR2: 0.24389




Frequency (Hz)

F20240413141221




BLK: 4,SNR1:-0.24382E-01,SNR2: 0.94466





Frequency (Hz)


0347+05 2024/04/13 5.23UT TOYOKAWA-FUJI



T20240413141221





BLK: 4,SNR1: 0.15888 ,SNR2: 0.86330




Frequency (Hz)

K20240413141220




BLK: 4,SNR1: 2.8170 ,SNR2: 10.563




Frequency (Hz)


0347+05 2024/04/13 5.23UT TOYOKAWA-KISO



F20240413141221





BLK: 7,SNR1:-0.20319 ,SNR2: 0.25372E-01




Frequency (Hz)

K20240413141220




BLK: 7,SNR1: 2.5681 ,SNR2: 8.4667




Frequency (Hz)


0347+05 2024/04/13 5.23UT FUJI -KISO



T20240413142756





BLK: 8,SNR1: 0.14338 ,SNR2: 2.2168




Frequency (Hz)

F20240413142756




BLK: 8,SNR1:-0.90576E-01,SNR2: 1.0370





Frequency (Hz)


0403-132 2024/04/13 5.49UT TOYOKAWA-FUJI



T20240413142756





BLK: 9,SNR1: 0.21713 ,SNR2: 0.77873




Frequency (Hz)

K20240413142755




BLK: 9,SNR1: 6.7705 ,SNR2: 18.765




Frequency (Hz)


0403-132 2024/04/13 5.49UT TOYOKAWA-KISO





F20240413142756




BLK: 5,SNR1: 0.19734 ,SNR2: 1.6745




K20240413142755



BLK: 5,SNR1: 7.6677 ,SNR2: 21.188





0403-132 2024/04/13 5.49UT FUJI -KISO







T20240413143706




BLK: 5,SNR1: 0.78689E-01,SNR2: 0.58528




F20240413143707





BLK: 5,SNR1: 0.10509 ,SNR2: 3.7016




0411+05 2024/04/13 5.65UT TOYOKAWA-FUJI




T20240413143706




BLK: 7,SNR1: 0.10859 ,SNR2: 1.3205




K20240413143705





BLK: 7,SNR1: 0.78797 ,SNR2: 3.5497





0411+05 2024/04/13 5.65UT TOYOKAWA-KISO




F20240413143707





K20240413143705




0411+05 2024/04/13 5.65UT FUJI -KISO




T20240413144759




BLK: 1,SNR1: 0.13781 ,SNR2: 1.0114




F20240413144759





BLK: 1,SNR1:-0.20695 ,SNR2: 1.7054




0422+178 2024/04/13 5.83UT TOYOKAWA-FUJI




T20240413144759




BLK: 7,SNR1:-0.11191 ,SNR2: 0.11367




K20240413144758







BLK: 7,SNR1: 0.95333 ,SNR2: 4.7437




0422+178 2024/04/13 5.83UT TOYOKAWA-KISO








0422+178 2024/04/13 5.83UT FUJI -KISO



T20240413145527




BLK: 5,SNR1: 0.40980 ,SNR2: 2.4798




Frequency (Hz)

F20240413145528




BLK: 5,SNR1: 0.86074 ,SNR2: 2.8301





Frequency (Hz)


3C119 2024/04/13 5.95UT TOYOKAWA-FUJI





T20240413145527




BLK:15,SNR1: 0.38911 ,SNR2: 2.4163




K20240413145526



BLK:15,SNR1: 0.25343 ,SNR2: 1.4870




3C119 2024/04/13 5.95UT TOYOKAWA-KISO








F20240413145528




BLK: 2,SNR1: 1.3242 ,SNR2: 4.2477




K20240413145526





BLK: 2,SNR1: 0.24413 ,SNR2: 1.8258




3C119 2024/04/13 5.95UT FUJI -KISO



T20240413154335




BLK: 9,SNR1: 0.84383 ,SNR2: 3.1765




Frequency (Hz)

F20240413154336




BLK: 9,SNR1:-0.98528E-01,SNR2: 1.0748






Frequency (Hz)



3C138 2024/04/13 6.75UT TOYOKAWA-FUJI




T20240413154335




K20240413154334




3C138 2024/04/13 6.75UT TOYOKAWA-KISO



F20240413154336




BLK:14,SNR1: 0.82625E-01,SNR2: 1.5696




Frequency (Hz)

K20240413154334




BLK:14,SNR1: 5.0478 ,SNR2: 9.5424





Frequency (Hz)


3C138 2024/04/13 6.75UT FUJI -KISO



T20240413155708




BLK:12,SNR1: 0.49233 ,SNR2: 4.3033




Frequency (Hz)

F20240413155708




BLK:12,SNR1: 0.68612 ,SNR2: 3.0969





Frequency (Hz)


0531+194 2024/04/13 6.98UT TOYOKAWA-FUJI



T20240413155708




BLK:17,SNR1: 0.40277 ,SNR2: 1.5160




Frequency (Hz)

K20240413155707




BLK:17,SNR1: 2.0820 ,SNR2: 7.3653




Frequency (Hz)


0531+194 2024/04/13 6.98UT TOYOKAWA-KISO



F20240413155708





BLK:12,SNR1: 1.1747 ,SNR2: 9.5913




Frequency (Hz)

K20240413155707




BLK:12,SNR1: 1.7378 ,SNR2: 6.5137





Frequency (Hz)


0531+194 2024/04/13 6.98UT FUJI -KISO




T20240413160527




BLK:23,SNR1: 2.3977 ,SNR2: 14.837




F20240413160528



BLK:23,SNR1: 0.84669E-01,SNR2: 1.7694





3C147 2024/04/13 7.12UT TOYOKAWA-FUJI








T20240413160527




BLK:29,SNR1: 2.2743 ,SNR2: 20.235




K20240413160526




BLK:29,SNR1: 0.28958 ,SNR2: 2.6196




3C147 2024/04/13 7.12UT TOYOKAWA-KISO




F20240413160528




BLK:16,SNR1: 0.79190E-02,SNR2: 2.6956




K20240413160526





BLK:16,SNR1: 0.49740 ,SNR2: 2.8243




3C147 2024/04/13 7.12UT FUJI -KISO



T20240413161339




BLK: 2,SNR1: 0.79243E-01,SNR2: 1.6695




Frequency (Hz)

F20240413161340




BLK: 2,SNR1:-0.28593 ,SNR2: 0.29386





Frequency (Hz)


0548+16 2024/04/13 7.26UT TOYOKAWA-FUJI





T20240413161339




BLK: 9,SNR1: 0.60781E-01,SNR2: 0.37106




K20240413161338





BLK: 9,SNR1: 9.4270 ,SNR2: 17.294




0548+16 2024/04/13 7.26UT TOYOKAWA-KISO



F20240413161340





BLK: 5, SNR1: 0.13206 , SNR2: 1.2953




Frequency (Hz)

K20240413161338






BLK: 5, SNR1: 7.6421 , SNR2: 14.886




Frequency (Hz)

0548+16 2024/04/13 7.26UT FUJI -KISO







0552+12 2024/04/13 7.33UT TOYOKAWA-FUJI



T20240413161750





BLK: 8,SNR1: 0.20442 ,SNR2: 1.8260




Frequency (Hz)

K20240413161749






BLK: 8,SNR1: 0.41967 ,SNR2: 1.7170




Frequency (Hz)

0552+12 2024/04/13 7.33UT TOYOKAWA-KISO







0552+12 2024/04/13 7.33UT FUJI -KISO






T20240413162217




BLK: 6,SNR1: 0.18383E-01,SNR2: 0.34448




Frequency (Hz)

F20240413162218




BLK: 6,SNR1: 0.32602 ,SNR2: 4.5705





Frequency (Hz)


0556+191 2024/04/13 7.40UT TOYOKAWA-FUJI



T20240413162217





BLK:12,SNR1: 0.22449E-01,SNR2: 0.74286




Frequency (Hz)

K20240413162216




BLK:12,SNR1: 3.3886 ,SNR2: 10.979




Frequency (Hz)


0556+191 2024/04/13 7.40UT TOYOKAWA-KISO



F20240413162218




BLK:12,SNR1: 2.1619 ,SNR2: 8.1546




Frequency (Hz)

K20240413162216




BLK:12,SNR1: 4.6566 ,SNR2: 9.2426




Frequency (Hz)


0556+191 2024/04/13 7.40UT FUJI -KISO




T20240413162650




BLK: 4,SNR1:-0.74565E-01,SNR2: 0.49884




F20240413162650





BLK: 4,SNR1: 0.44741 ,SNR2: 2.1439




3C152 2024/04/13 7.48UT TOYOKAWA-FUJI



T20240413162650





BLK: 3,SNR1: 0.22811 ,SNR2: 0.59805




Frequency (Hz)

K20240413162649





BLK: 3,SNR1: 1.6250 ,SNR2: 3.5147





Frequency (Hz)

3C152 2024/04/13 7.48UT TOYOKAWA-KISO







BLK: 4, SNR1: 0.73104 , SNR2: 2.1852





BLK: 4, SNR1: 0.25658 , SNR2: 1.1207




3C152 2024/04/13 7.48UT FUJI -KISO



T20240413164911




BLK: 5,SNR1: 0.18067E-01,SNR2: 2.9279




Frequency (Hz)

F20240413164912




BLK: 5,SNR1:-0.30876 ,SNR2: 0.76529





Frequency (Hz)


3C161 2024/04/13 7.85UT TOYOKAWA-FUJI



T20240413164911




BLK: 7,SNR1: 0.34522 ,SNR2: 5.0156




Frequency (Hz)

K20240413164910




BLK: 7,SNR1: 0.17800 ,SNR2: 0.92796




Frequency (Hz)

3C161 2024/04/13 7.85UT TOYOKAWA-KISO






F20240413164912





BLK: 4, SNR1: 0.15493 , SNR2: 1.7731




Frequency (Hz)

K20240413164910



BLK: 4, SNR1: 0.25160 , SNR2: 1.1472



Frequency (Hz)

3C161 2024/04/13 7.85UT FUJI -KISO

