




T20240426060733





BLK: 2, SNR1: 3.7082 ,SNR2: 11.973




Frequency (Hz)

2033+375 2024/04/25 21.15UT TOYOKAWA-FUJI


F20240426060734





BLK: 2, SNR1: 0.25005E-01, SNR2: 2.0009




Frequency (Hz)



T20240426060733





BLK: 5, SNR1: 8.3743 , SNR2: 54.869




Frequency (Hz)

K20240426060732




BLK: 5, SNR1: 0.48290 , SNR2: 2.3031




Frequency (Hz)

2033+375 2024/04/25 21.15UT TOYOKAWA-KISO






F20240426060734





BLK: 5, SNR1: -0.24275 , SNR2: 0.86038E-02




Frequency (Hz)

K20240426060732




BLK: 5, SNR1: 2.5858 , SNR2: 11.116





Frequency (Hz)


2033+375 2024/04/25 21:15UT FUJI -KISO



T20240426062352





BLK:19,SNR1: 11.084 ,SNR2: 21.584




Frequency (Hz)

F20240426062353




BLK:19,SNR1: 5.6301 ,SNR2: 14.072





Frequency (Hz)


2049+166 2024/04/25 21.43UT TOYOKAWA-FUJI



T20240426062352





BLK:24,SNR1: 10.806 ,SNR2: 20.311




Frequency (Hz)

K20240426062351




BLK:24,SNR1: 2.8224 ,SNR2: 13.444





Frequency (Hz)


2049+166 2024/04/25 21.43UT TOYOKAWA-KISO



F20240426062353





BLK:21,SNR1: 3.9674 ,SNR2: 13.517




Frequency (Hz)

2049+166 2024/04/25 21.43UT FUJI -KISO


K20240426062351





BLK:21,SNR1: 2.8370 ,SNR2: 13.501




Frequency (Hz)



T20240426063137





BLK: 5,SNR1: 6.8398 ,SNR2: 52.284




Frequency (Hz)

F20240426063138




BLK: 5,SNR1:-0.12629 ,SNR2: 0.72230




Frequency (Hz)


2056+028 2024/04/25 21.56UT TOYOKAWA-FUJI



T20240426063137





BLK: 8,SNR1: 24.567 ,SNR2: 172.78




Frequency (Hz)

2056+028 2024/04/25 21.56UT TOYOKAWA-KISO


K20240426063136




BLK: 8,SNR1: 0.47539 ,SNR2: 2.3448




Frequency (Hz)




F20240426063138




BLK:11,SNR1:-0.87498E-01,SNR2: 0.87460




K20240426063136





BLK:11,SNR1: 1.6452 ,SNR2: 3.3658




2056+028 2024/04/25 21.56UT FUJI -KISO



T20240426064018





BLK:17,SNR1: 11.324 ,SNR2: 20.046




Frequency (Hz)

2105-072 2024/04/25 21.70UT TOYOKAWA-FUJI


F20240426064019







BLK:17,SNR1: 0.62355 ,SNR2: 2.2242




Frequency (Hz)









2105-072 2024/04/25 21.70UT TOYOKAWA-KISO




F20240426064019




BLK:21,SNR1: 0.76944 ,SNR2: 2.8591




K20240426064017





BLK:21,SNR1: 2.7248 ,SNR2: 6.7365




2105-072 2024/04/25 21.70UT FUJI -KISO



T20240426065524





BLK: 9,SNR1: 0.32799 ,SNR2: 2.0815




Frequency (Hz)

F20240426065524




BLK: 9,SNR1: 0.40981 ,SNR2: 2.4126





Frequency (Hz)


2120-102 2024/04/25 21.95UT TOYOKAWA-FUJI



T20240426065524





BLK:14,SNR1: 0.29483 ,SNR2: 2.9045




Frequency (Hz)

K20240426065523




BLK:14,SNR1: 0.67572 ,SNR2: 3.2523





Frequency (Hz)


2120-102 2024/04/25 21.95UT TOYOKAWA-KISO



F20240426065524





BLK:14,SNR1: 0.21190 ,SNR2: 1.5791




Frequency (Hz)

K20240426065523




BLK:14,SNR1: 0.87800 ,SNR2: 3.3302





Frequency (Hz)


2120-102 2024/04/25 21.95UT FUJI -KISO



T20240426070604





BLK: 8,SNR1: 1.6332 ,SNR2: 4.4791




Frequency (Hz)

F20240426070604




BLK: 8,SNR1:-0.87549E-01,SNR2: 0.69699





Frequency (Hz)


2131+379 2024/04/25 22.13UT TOYOKAWA-FUJI





T20240426070604




BLK: 9,SNR1: 1.9016 ,SNR2: 5.1938




K20240426070603




BLK: 9,SNR1: 0.33251 ,SNR2: 1.4784




2131+379 2024/04/25 22.13UT TOYOKAWA-KISO



F20240426070604




BLK: 2,SNR1: 0.92594 ,SNR2: 3.2918




Frequency (Hz)

K20240426070603




BLK: 2,SNR1: 1.3957 ,SNR2: 7.4992





Frequency (Hz)

2131+379 2024/04/25 22.13UT FUJI -KISO






T20240426072242




BLK:13,SNR1: 0.75899 ,SNR2: 2.7043




Frequency (Hz)

2147+145 2024/04/25 22.41UT TOYOKAWA-FUJI


F20240426072243





BLK:13,SNR1: 8.3548 ,SNR2: 18.041




Frequency (Hz)



T20240426072242





BLK:13,SNR1: 0.75168 ,SNR2: 2.1743




Frequency (Hz)

K20240426072241




BLK:13,SNR1: 22.210 ,SNR2: 29.105





Frequency (Hz)


2147+145 2024/04/25 22.41UT TOYOKAWA-KISO





F20240426072243




BLK:27,SNR1: 7.6097 ,SNR2: 16.430




K20240426072241





BLK:27,SNR1: 10.571 ,SNR2: 18.733




2147+145 2024/04/25 22.41UT FUJI -KISO



T20240426073146




BLK:18,SNR1: 1.0942 ,SNR2: 9.2941




Frequency (Hz)

F20240426073147




BLK:18,SNR1: 0.69156E-01,SNR2: 1.1576





Frequency (Hz)


2156-043 2024/04/25 22.56UT TOYOKAWA-FUJI



T20240426073146





BLK:21,SNR1: 0.99750 ,SNR2: 8.7501




Frequency (Hz)

K20240426073145




BLK:21,SNR1: 1.9157 ,SNR2: 5.0371




Frequency (Hz)


2156-043 2024/04/25 22.56UT TOYOKAWA-KISO



F20240426073147





BLK:16,SNR1: 0.92668E-01,SNR2: 1.2348




Frequency (Hz)

K20240426073145




BLK:16,SNR1: 2.2575 ,SNR2: 8.5395




Frequency (Hz)


2156-043 2024/04/25 22.56UT FUJI -KISO



T20240426073834





BLK: 5,SNR1: 0.11035 ,SNR2: 1.8739




Frequency (Hz)

F20240426073834




BLK: 5,SNR1: 0.40529E-01,SNR2: 0.83321




Frequency (Hz)


2203-18 2024/04/25 22.67UT TOYOKAWA-FUJI



T20240426073834





BLK: 3,SNR1: 0.39651 ,SNR2: 1.9375




Frequency (Hz)

K20240426073833




BLK: 3,SNR1: 1.5211 ,SNR2: 11.985





Frequency (Hz)

2203-18 2024/04/25 22.67UT TOYOKAWA-KISO






F20240426073834





BLK: 4,SNR1: 0.38050 ,SNR2: 4.5536




Frequency (Hz)

K20240426073833




BLK: 4,SNR1: 0.90980E-01,SNR2: 0.89720





Frequency (Hz)


2203-18 2024/04/25 22.67UT FUJI -KISO




T20240426074457




BLK:12,SNR1: 1.1545 ,SNR2: 2.7626




F20240426074457





BLK:12,SNR1: 1.8474 ,SNR2: 8.6434




2210+016 2024/04/25 22.78UT TOYOKAWA-FUJI





T20240426074457




BLK:10,SNR1: 0.98298 ,SNR2: 2.1907




K20240426074456





BLK:10,SNR1: 1.3812 ,SNR2: 2.8271




2210+016 2024/04/25 22.78UT TOYOKAWA-KISO





F20240426074457




BLK:20,SNR1: 1.4614 ,SNR2: 7.0499




K20240426074456




BLK:20,SNR1: 1.5176 ,SNR2: 2.9607




2210+016 2024/04/25 22.78UT FUJI -KISO





T20240426075220




BLK: 5,SNR1:-0.22186E-01,SNR2: 0.23833




F20240426075221




BLK: 5,SNR1: 0.63502 ,SNR2: 6.8665




2217+128 2024/04/25 22.90UT TOYOKAWA-FUJI




T20240426075220




BLK: 4,SNR1: 0.35724E-01,SNR2: 0.67394




K20240426075219





BLK: 4,SNR1: 2.9004 ,SNR2: 12.971




2217+128 2024/04/25 22.90UT TOYOKAWA-KISO



F20240426075221





BLK:15,SNR1: 1.1761 ,SNR2: 9.1822




Frequency (Hz)

K20240426075219




BLK:15,SNR1: 2.0501 ,SNR2: 9.4739




Frequency (Hz)


2217+128 2024/04/25 22.90UT FUJI -KISO



T20240426075807




BLK:11,SNR1: 0.35171 ,SNR2: 2.9490





3C446 2024/04/25 23.00UT TOYOKAWA-FUJI

F20240426075808





BLK:11,SNR1: 0.37532E-01,SNR2: 2.2694






T20240426075807





BLK:16,SNR1: 0.51719 ,SNR2: 3.7631





3C446 2024/04/25 23.00UT TOYOKAWA-KISO


K20240426075806




BLK:16,SNR1: 2.9680 ,SNR2: 13.158



F20240426075808





BLK:18,SNR1: 2.6236 ,SNR2: 11.497





3C446 2024/04/25 23.00UT FUJI -KISO



K20240426075806




BLK:18,SNR1: 3.0295 ,SNR2: 13.389



T20240426080450





BLK: 5, SNR1: 0.10126 , SNR2: 0.38168




Frequency (Hz)

F20240426080450




BLK: 5, SNR1: 0.98049 , SNR2: 2.5947






Frequency (Hz)




2229-093 2024/04/25 23.11UT TOYOKAWA-FUJI




T20240426080450





K20240426080449




2229-093 2024/04/25 23.11UT TOYOKAWA-KISO



F20240426080450




BLK:14,SNR1: 0.32925 ,SNR2: 3.5481




Frequency (Hz)

K20240426080449




BLK:14,SNR1: 0.73710 ,SNR2: 3.1448





Frequency (Hz)


2229-093 2024/04/25 23.11UT FUJI -KISO



T20240426081317





BLK: 3,SNR1: 4.1280 ,SNR2: 61.167




Frequency (Hz)

2238-113 2024/04/25 23.25UT TOYOKAWA-FUJI


F20240426081317





BLK: 3,SNR1:-0.17711 ,SNR2: 0.91579




Frequency (Hz)



T20240426081317





BLK: 3,SNR1: 2.5035 ,SNR2: 16.946




Frequency (Hz)

2238-113 2024/04/25 23.25UT TOYOKAWA-KISO


K20240426081316





BLK: 3,SNR1: 0.43028 ,SNR2: 4.7156




Frequency (Hz)



F20240426081317





BLK: 4, SNR1: -0.14864 , SNR2: 0.42509




Frequency (Hz)

K20240426081316




BLK: 4, SNR1: 0.29404 , SNR2: 5.6963





Frequency (Hz)

2238-113 2024/04/25 23.25UT FUJI -KISO






T20240426082606




BLK: 9,SNR1: 0.36126 ,SNR2: 1.8042




Frequency (Hz)

F20240426082606




BLK: 9,SNR1: 0.27154 ,SNR2: 3.0750





Frequency (Hz)


3C454.3 2024/04/25 23.46UT TOYOKAWA-FUJI





T20240426082606




BLK: 9,SNR1: 0.18332 ,SNR2: 1.5368




K20240426082605




BLK: 9,SNR1: 0.63210 ,SNR2: 2.7215




3C454.3 2024/04/25 23.46UT TOYOKAWA-KISO



F20240426082606





BLK:17,SNR1: 0.32366 ,SNR2: 3.7333




Frequency (Hz)

K20240426082605





BLK:17,SNR1: 0.60764 ,SNR2: 2.8328





Frequency (Hz)

3C454.3 2024/04/25 23.46UT FUJI -KISO







BLK:11,SNR1: 0.48759 ,SNR2: 1.5680




BLK:11,SNR1: 1.3159 ,SNR2: 6.4353





2259+481 2024/04/25 23.59UT TOYOKAWA-FUJI







BLK:11,SNR1: 0.48749 ,SNR2: 3.4502




BLK:11,SNR1: 0.89244 ,SNR2: 2.6155




2259+481 2024/04/25 23.59UT TOYOKAWA-KISO



F20240426083349




BLK:13,SNR1: 0.99157 ,SNR2: 5.1999




Frequency (Hz)

K20240426083348




BLK:13,SNR1: 0.97097 ,SNR2: 4.7496






Frequency (Hz)




2259+481 2024/04/25 23.59UT FUJI -KISO





T20240426084843




F20240426084843




T20240426084843




BLK:19,SNR1: 2.5914 ,SNR2: 11.072




K20240426084842



BLK:19,SNR1: 4.1523 ,SNR2: 17.400





3C459 2024/04/25 23.84UT TOYOKAWA-KISO






F20240426084843





BLK:17,SNR1: 4.1171 ,SNR2: 17.259




Frequency (Hz)

3C459 2024/04/25 23.84UT FUJI -KISO


K20240426084842





BLK:17,SNR1: 4.1170 ,SNR2: 17.264




Frequency (Hz)




T20240426092228




BLK:13,SNR1: 0.13902 ,SNR2: 1.1604




F20240426092229




BLK:13,SNR1: 2.7735 ,SNR2: 12.884




2347-02 2024/04/26 0.40UT TOYOKAWA-FUJI





T20240426092228




BLK:11,SNR1: 0.12711 ,SNR2: 1.3857




K20240426092227




BLK:11,SNR1: 0.22205 ,SNR2: 0.68677




2347-02 2024/04/26 0.40UT TOYOKAWA-KISO



F20240426092229





BLK:19,SNR1: 2.4023 ,SNR2: 8.3418




Frequency (Hz)

K20240426092227




BLK:19,SNR1: 0.15757 ,SNR2: 1.2718





Frequency (Hz)


2347-02 2024/04/26 0.40UT FUJI -KISO



T20240426092921




BLK: 9,SNR1: 0.12401 ,SNR2: 0.87395





2354+14 2024/04/26 0.52UT TOYOKAWA-FUJI



F20240426092921




BLK: 9,SNR1: 23.785 ,SNR2: 35.760



T20240426092921





BLK:18,SNR1: 0.92850E-01,SNR2: 0.57391





2354+14 2024/04/26 0.52UT TOYOKAWA-KISO


K20240426092920




BLK:18,SNR1: 11.495 ,SNR2: 22.188




F20240426092921




BLK:38,SNR1: 25.982 ,SNR2: 28.060




K20240426092920




BLK:38,SNR1: 16.243 ,SNR2: 20.619




2354+14 2024/04/26 0.52UT FUJI -KISO




T20240426093824




BLK:10,SNR1: 0.35676 ,SNR2: 2.1513




F20240426093824



BLK:10,SNR1:-0.18852 ,SNR2: 1.6325





3C2 2024/04/26 0.67UT TOYOKAWA-FUJI






T20240426093824





BLK:15,SNR1: 0.20241 ,SNR2: 2.2379




Frequency (Hz)

3C2 2024/04/26 0.67UT TOYOKAWA-KISO


K20240426093823





BLK:15,SNR1: 2.5162 ,SNR2: 9.4158




Frequency (Hz)



F20240426093824





BLK:12,SNR1:-0.84724E-01,SNR2: 0.61906




Frequency (Hz)

3C2 2024/04/26 0.67UT FUJI -KISO


K20240426093823





BLK:12,SNR1: 2.6759 ,SNR2: 10.439




Frequency (Hz)



T20240426094545





BLK: 5, SNR1: 48.171 , SNR2: 70.850




Frequency (Hz)

F20240426094545




BLK: 5, SNR1: -0.34326 , SNR2: 0.48129





Frequency (Hz)


0011+344 2024/04/26 0.79UT TOYOKAWA-FUJI



T20240426094545





BLK: 6, SNR1: 64.577 , SNR2: 88.562




Frequency (Hz)

K20240426094544




BLK: 6, SNR1: 0.26069 , SNR2: 0.79346





Frequency (Hz)


0011+344 2024/04/26 0.79UT TOYOKAWA-KISO





F20240426094545




BLK: 6,SNR1:-0.29169 ,SNR2: 1.4762




K20240426094544





BLK: 6,SNR1: 0.25019 ,SNR2: 0.86258




0011+344 2024/04/26 0.79UT FUJI -KISO





T20240426095422




BLK: 7,SNR1: 0.18162 ,SNR2: 0.91068




F20240426095422





BLK: 7,SNR1:-0.24755 ,SNR2: 0.16607




0019-00 2024/04/26 0.93UT TOYOKAWA-FUJI



T20240426095422





BLK: 8,SNR1: 0.20654 ,SNR2: 2.3309




Frequency (Hz)

0019-00 2024/04/26 0.93UT TOYOKAWA-KISO


K20240426095421




BLK: 8,SNR1: 0.39406 ,SNR2: 4.0542




Frequency (Hz)



F20240426095422





BLK: 7,SNR1:-0.26450 ,SNR2: 0.46640




Frequency (Hz)

K20240426095421




BLK: 7,SNR1: 0.42789 ,SNR2: 4.3283





Frequency (Hz)

0019-00 2024/04/26 0.93UT FUJI -KISO








T20240426100436




BLK:10,SNR1: 0.63092 ,SNR2: 2.7872




F20240426100436





BLK:10,SNR1:-0.89218E-01,SNR2: 1.1032




3C12 2024/04/26 1.10UT TOYOKAWA-FUJI





T20240426100436




BLK:14,SNR1: 0.51995 ,SNR2: 2.1680




K20240426100435




BLK:14,SNR1: 1.0492 ,SNR2: 4.6225




3C12 2024/04/26 1.10UT TOYOKAWA-KISO




F20240426100436




BLK:20,SNR1: 0.14808 ,SNR2: 2.4399




K20240426100435





BLK:20,SNR1: 0.66860 ,SNR2: 2.7871




3C12 2024/04/26 1.10UT FUJI -KISO



T20240426101838




BLK:16,SNR1: 2.7919 ,SNR2: 17.474





0044-056 2024/04/26 1.34UT TOYOKAWA-FUJI


F20240426101838




BLK:16,SNR1: 0.52463E-01,SNR2: 1.9040



T20240426101838




BLK:10,SNR1: 3.0507 ,SNR2: 15.443





0044-056 2024/04/26 1.34UT TOYOKAWA-KISO


K20240426101837




BLK:10,SNR1: 0.79081 ,SNR2: 2.7574





F20240426101838




BLK:16,SNR1: 0.88483E-01,SNR2: 2.1693




K20240426101837




BLK:16,SNR1: 0.27608 ,SNR2: 1.4185




0044-056 2024/04/26 1.34UT FUJI -KISO




T20240426102559




BLK: 8,SNR1: 0.23578 ,SNR2: 2.6325




F20240426102559




BLK: 8,SNR1:-0.26364 ,SNR2: 1.4997




3C26 2024/04/26 1.46UT TOYOKAWA-FUJI




T20240426102559




BLK:14,SNR1: 0.36149 ,SNR2: 1.1477




K20240426102558



BLK:14,SNR1: 0.25029 ,SNR2: 0.96143




3C26 2024/04/26 1.46UT TOYOKAWA-KISO







F20240426102559




BLK: 9,SNR1: 0.87109E-01,SNR2: 1.3526




K20240426102558




BLK: 9,SNR1: 0.62771 ,SNR2: 2.6686




3C26 2024/04/26 1.46UT FUJI -KISO



T20240426103058




BLK:16,SNR1: 0.70870 ,SNR2: 3.3560





0056-00 2024/04/26 1.54UT TOYOKAWA-FUJI


F20240426103059




BLK:16,SNR1: 0.87155 ,SNR2: 3.8946



T20240426103058




BLK:20,SNR1: 0.61559 ,SNR2: 3.0423





0056-00 2024/04/26 1.54UT TOYOKAWA-KISO


K20240426103057




BLK:20,SNR1: 0.63944 ,SNR2: 3.2431




F20240426103059




BLK:21,SNR1: 1.7689 ,SNR2: 9.9870




K20240426103057





BLK:21,SNR1: 1.0789 ,SNR2: 3.2267




0056-00 2024/04/26 1.54UT FUJI -KISO



T20240426104040





BLK: 7,SNR1: 0.30203 ,SNR2: 1.4869




0106+01 2024/04/26 1.71UT TOYOKAWA-FUJI


F20240426104040




BLK: 7,SNR1:-0.24518 ,SNR2: 0.46103




Frequency (Hz)




T20240426104040




BLK:10,SNR1: 0.37340 ,SNR2: 1.8522




K20240426104039




BLK:10,SNR1: 0.37335 ,SNR2: 1.3388




0106+01 2024/04/26 1.71UT TOYOKAWA-KISO



F20240426104040





BLK: 3,SNR1: 0.75062E-02,SNR2: 0.48409




Frequency (Hz)

K20240426104039




BLK: 3,SNR1: 0.15846 ,SNR2: 2.3043




Frequency (Hz)


0106+01 2024/04/26 1.71UT FUJI -KISO




T20240426105130




BLK: 8,SNR1: 0.39943 ,SNR2: 4.0313




F20240426105131



BLK: 8,SNR1: 0.80062 ,SNR2: 4.2262




0116+31 2024/04/26 1.89UT TOYOKAWA-FUJI






T20240426105130





BLK: 9, SNR1: 0.33273 , SNR2: 1.8096




Frequency (Hz)

K20240426105129




BLK: 9, SNR1: 0.34352 , SNR2: 1.9387




Frequency (Hz)


0116+31 2024/04/26 1.89UT TOYOKAWA-KISO



F20240426105131





BLK:12,SNR1: 0.52330 ,SNR2: 2.9951




Frequency (Hz)

K20240426105129




BLK:12,SNR1: 0.32989 ,SNR2: 2.2855





Frequency (Hz)


0116+31 2024/04/26 1.89UT FUJI -KISO





T20240426110152




BLK:13,SNR1: 0.81127 ,SNR2: 2.9024




F20240426110152




BLK:13,SNR1: 0.12638 ,SNR2: 2.1568




3C43 2024/04/26 2.06UT TOYOKAWA-FUJI




T20240426110152




BLK:24,SNR1: 1.3875 ,SNR2: 5.0320




K20240426110151




BLK:24,SNR1: 0.23991 ,SNR2: 1.5662




3C43 2024/04/26 2.06UT TOYOKAWA-KISO



F20240426110152




BLK:14,SNR1: 0.23711E-01,SNR2: 1.4089





3C43 2024/04/26 2.06UT FUJI -KISO


K20240426110151




BLK:14,SNR1: 0.40657 ,SNR2: 1.7415



T20240426110936





BLK:24,SNR1: 17.976 ,SNR2: 110.41





3C48 2024/04/26 2.19UT TOYOKAWA-FUJI



F20240426110937




BLK:24,SNR1: 19.726 ,SNR2: 52.258



T20240426110936




BLK:33,SNR1: 17.201 ,SNR2: 102.53





3C48 2024/04/26 2.19UT TOYOKAWA-KISO



K20240426110935




BLK:33,SNR1: 3.5135 ,SNR2: 12.104



F20240426110937





BLK:24,SNR1: 19.326 ,SNR2: 51.886





3C48 2024/04/26 2.19UT FUJI -KISO

K20240426110935




BLK:24,SNR1: 2.2890 ,SNR2: 8.6567







T20240426112921




BLK:10,SNR1: 0.24337 ,SNR2: 1.3959




F20240426112922




BLK:10,SNR1: 0.72001E-01,SNR2: 2.1327




0155-109 2024/04/26 2.52UT TOYOKAWA-FUJI





T20240426112921




BLK: 6,SNR1: 0.53958 ,SNR2: 2.0846




K20240426112920




BLK: 6,SNR1: 0.55268 ,SNR2: 3.1514




0155-109 2024/04/26 2.52UT TOYOKAWA-KISO




F20240426112922




BLK: 9,SNR1: 0.90883E-01,SNR2: 2.2112




K20240426112920




BLK: 9,SNR1: 0.52814 ,SNR2: 1.9251




0155-109 2024/04/26 2.52UT FUJI -KISO





T20240426113628




BLK:32,SNR1: 22.008 ,SNR2: 25.239




F20240426113628





BLK:32,SNR1: 3.8871 ,SNR2: 8.0666




0202+15 2024/04/26 2.64UT TOYOKAWA-FUJI





T20240426113628




BLK:28,SNR1: 21.703 ,SNR2: 25.180




K20240426113627




BLK:28,SNR1: 18.136 ,SNR2: 24.545




0202+15 2024/04/26 2.64UT TOYOKAWA-KISO




F20240426113628




BLK:28,SNR1: 6.1240 ,SNR2: 6.1556




K20240426113627




BLK:28,SNR1: 21.147 ,SNR2: 26.186




0202+15 2024/04/26 2.64UT FUJI -KISO




T20240426114818




BLK:18,SNR1: 28.725 ,SNR2: 48.990




F20240426114819





BLK:18,SNR1: 11.083 ,SNR2: 29.344




0213+178 2024/04/26 2.83UT TOYOKAWA-FUJI





T20240426114818




BLK:26,SNR1: 18.534 ,SNR2: 37.664




K20240426114817



BLK:26,SNR1: 27.974 ,SNR2: 45.101




0213+178 2024/04/26 2.83UT TOYOKAWA-KISO







F20240426114819




BLK:16,SNR1: 15.471 ,SNR2: 25.367




K20240426114817





BLK:16,SNR1: 26.635 ,SNR2: 47.893




0213+178 2024/04/26 2.83UT FUJI -KISO



T20240426115601





BLK:26,SNR1: 1.0805 ,SNR2: 3.9287





3C67 2024/04/26 2.96UT TOYOKAWA-FUJI



F20240426115601




BLK:26,SNR1: 0.63672 ,SNR2: 2.3884





T20240426115601




BLK:21,SNR1: 1.5661 ,SNR2: 6.7746




K20240426115600





BLK:21,SNR1: 1.4499 ,SNR2: 5.7855




3C67 2024/04/26 2.96UT TOYOKAWA-KISO



F20240426115601





BLK:26,SNR1: 0.66368 ,SNR2: 2.4653




Frequency (Hz)

3C67 2024/04/26 2.96UT FUJI -KISO


K20240426115600





BLK:26,SNR1: 1.4181 ,SNR2: 5.7482




Frequency (Hz)



T20240426121416




BLK: 9,SNR1: 14.845 ,SNR2: 28.990





3C71 2024/04/26 3.27UT TOYOKAWA-FUJI



F20240426121416




BLK: 9,SNR1:-0.70259E-01,SNR2: 1.4079



T20240426121416




BLK:10,SNR1: 14.946 ,SNR2: 29.148





3C71 2024/04/26 3.27UT TOYOKAWA-KISO


K20240426121415




BLK:10,SNR1: 0.82561 ,SNR2: 3.1319



F20240426121416





BLK:10,SNR1:-0.67858E-01,SNR2: 1.6502





3C71 2024/04/26 3.27UT FUJI -KISO



K20240426121415




BLK:10,SNR1: 0.73427 ,SNR2: 5.2182




T20240426123331




BLK: 3,SNR1: 0.32258 ,SNR2: 2.5713




F20240426123331



BLK: 3,SNR1:-0.49413E-01,SNR2: 3.0280





0258+350 2024/04/26 3.59UT TOYOKAWA-FUJI








T20240426123331




BLK:10,SNR1: 0.65503E-01,SNR2: 0.48679




K20240426123330




BLK:10,SNR1: 32.867 ,SNR2: 74.360




0258+350 2024/04/26 3.59UT TOYOKAWA-KISO



F20240426123331





BLK: 5,SNR1:-0.53981E-01,SNR2: 1.2883




Frequency (Hz)

K20240426123330




BLK: 5,SNR1: 28.890 ,SNR2: 66.896





Frequency (Hz)


0258+350 2024/04/26 3.59UT FUJI -KISO




T20240426124320




BLK:16,SNR1: 2.7134 ,SNR2: 13.034




F20240426124320





BLK:16,SNR1: 1.3817 ,SNR2: 4.4701




0308+305 2024/04/26 3.75UT TOYOKAWA-FUJI





T20240426124320




BLK:18,SNR1: 2.7672 ,SNR2: 13.247




K20240426124319





BLK:18,SNR1: 4.5288 ,SNR2: 8.8315




0308+305 2024/04/26 3.75UT TOYOKAWA-KISO





F20240426124320




BLK:15,SNR1: 1.4347 ,SNR2: 4.7265




K20240426124319




BLK:15,SNR1: 1.9904 ,SNR2: 7.7654




0308+305 2024/04/26 3.75UT FUJI -KISO



T20240426125452





BLK:23,SNR1: 3.5252 ,SNR2: 12.921




Frequency (Hz)

F20240426125452




BLK:23,SNR1: 1.3146 ,SNR2: 4.3049




Frequency (Hz)


0320+05 2024/04/26 3.94UT TOYOKAWA-FUJI




T20240426125452




BLK:29,SNR1: 2.9618 ,SNR2: 11.956




K20240426125451





BLK:29,SNR1: 0.65504 ,SNR2: 2.5546




0320+05 2024/04/26 3.94UT TOYOKAWA-KISO





F20240426125452




BLK:16,SNR1: 1.4805 ,SNR2: 4.7720




K20240426125451



BLK:16,SNR1: 0.98429 ,SNR2: 4.8284





0320+05 2024/04/26 3.94UT FUJI -KISO







T20240426130813




BLK: 8,SNR1: 0.83864E-01,SNR2: 0.95040




F20240426130813





BLK: 8,SNR1:-0.22824 ,SNR2: 1.6355




0333+32 2024/04/26 4.17UT TOYOKAWA-FUJI





T20240426130813




BLK: 4,SNR1: 0.22331E-01,SNR2: 1.0993




K20240426130812





BLK: 4,SNR1: 0.15469 ,SNR2: 1.0916




0333+32 2024/04/26 4.17UT TOYOKAWA-KISO





F20240426130813




BLK: 7,SNR1:-0.30992 ,SNR2: 0.78463




K20240426130812





BLK: 7,SNR1: 0.27969 ,SNR2: 2.5891




0333+32 2024/04/26 4.17UT FUJI -KISO





T20240426132115




BLK:23,SNR1: 1.4842 ,SNR2: 3.7384




F20240426132115




BLK:23,SNR1: 1.1125 ,SNR2: 3.2617




0347+05 2024/04/26 4.38UT TOYOKAWA-FUJI




T20240426132115




BLK:25,SNR1: 1.0374 ,SNR2: 2.6917




K20240426132114





BLK:25,SNR1: 0.57170 ,SNR2: 3.0156




0347+05 2024/04/26 4.38UT TOYOKAWA-KISO





F20240426132115




BLK:20,SNR1: 1.3618 ,SNR2: 3.8433




K20240426132114





BLK:20,SNR1: 0.62925 ,SNR2: 2.6912




0347+05 2024/04/26 4.38UT FUJI -KISO





T20240426133649




BLK:32,SNR1: 7.9556 ,SNR2: 19.980




F20240426133649





BLK:32,SNR1: 8.0556 ,SNR2: 20.393




0403-132 2024/04/26 4.64UT TOYOKAWA-FUJI





T20240426133649




BLK:34,SNR1: 9.7725 ,SNR2: 18.194




K20240426133648



BLK:34,SNR1: 2.6880 ,SNR2: 12.912





0403-132 2024/04/26 4.64UT TOYOKAWA-KISO








F20240426133649




BLK:36,SNR1: 8.1528 ,SNR2: 20.629




K20240426133648




BLK:36,SNR1: 2.6622 ,SNR2: 12.811





0403-132 2024/04/26 4.64UT FUJI -KISO







BLK:25,SNR1: 7.2620 ,SNR2: 12.876




BLK:25,SNR1: 7.8621 ,SNR2: 13.903





0411+05 2024/04/26 4.79UT TOYOKAWA-FUJI







BLK:25,SNR1: 5.4489 ,SNR2: 13.756





BLK:25,SNR1: 7.9714 ,SNR2: 20.380




0411+05 2024/04/26 4.79UT TOYOKAWA-KISO





F20240426134600




BLK:30,SNR1: 7.2305 ,SNR2: 12.802




K20240426134559





BLK:30,SNR1: 7.9581 ,SNR2: 20.347




0411+05 2024/04/26 4.79UT FUJI -KISO





T20240426135653




BLK:24,SNR1: 0.82727 ,SNR2: 2.1624




F20240426135653




BLK:24,SNR1: 2.8759 ,SNR2: 6.5143




0422+178 2024/04/26 4.98UT TOYOKAWA-FUJI





T20240426135653




BLK:21,SNR1: 0.93661 ,SNR2: 3.2427




K20240426135652




BLK:21,SNR1: 5.3283 ,SNR2: 10.249




0422+178 2024/04/26 4.98UT TOYOKAWA-KISO





F20240426135653




BLK:27,SNR1: 3.0279 ,SNR2: 6.9088




K20240426135652





BLK:27,SNR1: 3.2142 ,SNR2: 6.2675




0422+178 2024/04/26 4.98UT FUJI -KISO



T20240426140429





BLK:15,SNR1: 0.17417 ,SNR2: 1.1284




Frequency (Hz)

F20240426140429




BLK:15,SNR1: 0.64689 ,SNR2: 4.1743




Frequency (Hz)

3C120 2024/04/26 5.10UT TOYOKAWA-FUJI








T20240426140429




BLK:15,SNR1: 0.23183 ,SNR2: 1.3271




K20240426140428





BLK:15,SNR1: 0.73521 ,SNR2: 4.4148




3C120 2024/04/26 5.10UT TOYOKAWA-KISO





F20240426140429




BLK:12,SNR1: 0.67872 ,SNR2: 5.2543




K20240426140428





BLK:12,SNR1: 0.77901 ,SNR2: 5.2076




3C120 2024/04/26 5.10UT FUJI -KISO



T20240426145228





BLK:18,SNR1: 2.9085 ,SNR2: 9.3563




Frequency (Hz)

F20240426145229




BLK:18,SNR1:-0.12530 ,SNR2: 2.5111






Frequency (Hz)




3C138 2024/04/26 5.90UT TOYOKAWA-FUJI




T20240426145228





K20240426145227




3C138 2024/04/26 5.90UT TOYOKAWA-KISO





F20240426145229




BLK:18,SNR1: 0.57025E-01,SNR2: 2.7283




K20240426145227





BLK:18,SNR1: 2.2152 ,SNR2: 3.3992




3C138 2024/04/26 5.90UT FUJI -KISO



T20240426150602





BLK:18,SNR1: 13.375 ,SNR2: 23.876




Frequency (Hz)

F20240426150603




BLK:18,SNR1: 9.2218 ,SNR2: 15.715





Frequency (Hz)


0531+194 2024/04/26 6.13UT TOYOKAWA-FUJI





T20240426150602




BLK:26,SNR1: 10.297 ,SNR2: 18.228




K20240426150601





BLK:26,SNR1: 12.804 ,SNR2: 21.710




0531+194 2024/04/26 6.13UT TOYOKAWA-KISO





F20240426150603




BLK:21,SNR1: 11.474 ,SNR2: 18.839




K20240426150601



BLK:21,SNR1: 13.985 ,SNR2: 23.753




0531+194 2024/04/26 6.13UT FUJI -KISO







T20240426151421




BLK:25,SNR1: 114.96 ,SNR2: 119.67




F20240426151421





BLK:25,SNR1:-0.22966 ,SNR2: 1.2440




3C147 2024/04/26 6.27UT TOYOKAWA-FUJI





T20240426151421




BLK:20,SNR1: 109.94 ,SNR2: 111.60




K20240426151420





BLK:20,SNR1: 0.53082 ,SNR2: 3.5115




3C147 2024/04/26 6.27UT TOYOKAWA-KISO



F20240426151421





BLK:20,SNR1:-0.86933E-01,SNR2: 1.4049




Frequency (Hz)

K20240426151420




BLK:20,SNR1: 0.45575 ,SNR2: 2.1741





Frequency (Hz)


3C147 2024/04/26 6.27UT FUJI -KISO



T20240426152233




BLK: 9,SNR1: 1.4589 ,SNR2: 6.9772




Frequency (Hz)

F20240426152233




BLK: 9,SNR1:-0.16122 ,SNR2: 1.1560





Frequency (Hz)


0548+16 2024/04/26 6.40UT TOYOKAWA-FUJI



T20240426152233





BLK: 8,SNR1: 7.3765 ,SNR2: 62.793




Frequency (Hz)

K20240426152232




BLK: 8,SNR1: 0.48599 ,SNR2: 4.0329




Frequency (Hz)


0548+16 2024/04/26 6.40UT TOYOKAWA-KISO



F20240426152233





BLK: 4,SNR1:-0.24330E-01,SNR2: 0.63834




Frequency (Hz)

K20240426152232





BLK: 4,SNR1: 1.3667 ,SNR2: 4.1807





Frequency (Hz)

0548+16 2024/04/26 6.40UT FUJI -KISO







BLK:18,SNR1: 24.567 ,SNR2: 54.645







BLK:18,SNR1: 1.2332 ,SNR2: 2.4515




0552+12 2024/04/26 6.47UT TOYOKAWA-FUJI






0552+12 2024/04/26 6.47UT TOYOKAWA-KISO








F20240426152645




BLK:17,SNR1: 1.2525 ,SNR2: 2.5421




K20240426152643





BLK:17,SNR1: 3.6255 ,SNR2: 6.0949




0552+12 2024/04/26 6.47UT FUJI -KISO





T20240426153110




BLK:28,SNR1: 19.061 ,SNR2: 33.503




F20240426153111





BLK:28,SNR1: 12.673 ,SNR2: 17.032




0556+191 2024/04/26 6.55UT TOYOKAWA-FUJI



T20240426153110





BLK:27,SNR1: 19.251 ,SNR2: 33.818




Frequency (Hz)

K20240426153109




BLK:27,SNR1: 20.008 ,SNR2: 33.894




Frequency (Hz)


0556+191 2024/04/26 6.55UT TOYOKAWA-KISO





F20240426153111




BLK:28,SNR1: 11.850 ,SNR2: 16.029




K20240426153109





BLK:28,SNR1: 18.800 ,SNR2: 32.239




0556+191 2024/04/26 6.55UT FUJI -KISO




T20240426153543




BLK: 6,SNR1: 5.6607 ,SNR2: 17.898




F20240426153543





BLK: 6,SNR1: 5.5718 ,SNR2: 13.673




3C152 2024/04/26 6.62UT TOYOKAWA-FUJI





T20240426153543




BLK:12,SNR1: 6.9580 ,SNR2: 24.830




K20240426153542





BLK:12,SNR1: 3.3639 ,SNR2: 5.2620




3C152 2024/04/26 6.62UT TOYOKAWA-KISO



F20240426153543





BLK: 9,SNR1: 4.9694 ,SNR2: 12.226




Frequency (Hz)

K20240426153542




BLK: 9,SNR1: 3.3213 ,SNR2: 7.3151




Frequency (Hz)


3C152 2024/04/26 6.62UT FUJI -KISO



T20240426155804





BLK:15,SNR1: 1.7006 ,SNR2: 12.689




Frequency (Hz)

F20240426155805




BLK:15,SNR1:-0.22842 ,SNR2: 1.3359





Frequency (Hz)

3C161 2024/04/26 7.00UT TOYOKAWA-FUJI








T20240426155804




BLK:19,SNR1: 2.0724 ,SNR2: 14.926




K20240426155803




BLK:19,SNR1: 0.12652 ,SNR2: 4.0817




3C161 2024/04/26 7.00UT TOYOKAWA-KISO





F20240426155805




BLK:12,SNR1:-0.21771 ,SNR2: 1.1531




K20240426155803




BLK:12,SNR1: 0.43016 ,SNR2: 2.9615




3C161 2024/04/26 7.00UT FUJI -KISO



T20240426162537




BLK:10,SNR1: 1.0973 ,SNR2: 2.1370




Frequency (Hz)

F20240426162537




BLK:10,SNR1: 6.7522 ,SNR2: 11.054




Frequency (Hz)


0652-130 2024/04/26 7.46UT TOYOKAWA-FUJI





T20240426162537




BLK:10,SNR1: 1.4576 ,SNR2: 2.5163




K20240426162536




BLK:10,SNR1: 6.4016 ,SNR2: 10.367




0652-130 2024/04/26 7.46UT TOYOKAWA-KISO



F20240426162537





BLK:15,SNR1: 5.5986 ,SNR2: 9.0729




Frequency (Hz)

K20240426162536





BLK:15,SNR1: 3.7666 ,SNR2: 6.2897





Frequency (Hz)

0652-130 2024/04/26 7.46UT FUJI -KISO







BLK:16,SNR1: 0.75980 ,SNR2: 1.3641




BLK:16,SNR1: 3.0839 ,SNR2: 6.3872





0703+138 2024/04/26 7.65UT TOYOKAWA-FUJI







BLK:19,SNR1: 0.68627 ,SNR2: 1.4750




BLK:19,SNR1: 3.7498 ,SNR2: 6.2008




0703+138 2024/04/26 7.65UT TOYOKAWA-KISO



F20240426163713




BLK:23,SNR1: 3.1025 ,SNR2: 6.3365




Frequency (Hz)

K20240426163712




BLK:23,SNR1: 5.4353 ,SNR2: 8.2729





Frequency (Hz)

0703+138 2024/04/26 7.65UT FUJI -KISO






T20240426164636




BLK: 3,SNR1:-0.26719 ,SNR2: 0.39993




Frequency (Hz)

F20240426164637




BLK: 3,SNR1: 0.40621 ,SNR2: 2.3765





Frequency (Hz)


0713-024 2024/04/26 7.80UT TOYOKAWA-FUJI



T20240426164636





BLK: 7,SNR1: 0.52666E-01,SNR2: 0.77946




Frequency (Hz)

K20240426164635




BLK: 7,SNR1: 0.54114 ,SNR2: 2.6559




Frequency (Hz)


0713-024 2024/04/26 7.80UT TOYOKAWA-KISO



F20240426164637





BLK: 8,SNR1: 1.7077 ,SNR2: 3.7000




Frequency (Hz)

K20240426164635




BLK: 8,SNR1: 0.20900 ,SNR2: 1.3867





Frequency (Hz)


0713-024 2024/04/26 7.80UT FUJI -KISO



T20240426165648





BLK: 2,SNR1: 0.22384 ,SNR2: 0.52662




Frequency (Hz)

F20240426165648




BLK: 2,SNR1:-0.39311E-01,SNR2: 0.54958





Frequency (Hz)


0723+10 2024/04/26 7.97UT TOYOKAWA-FUJI



T20240426165648




No.Good Data




Frequency (Hz)

K20240426165647




No.Good Data




Frequency (Hz)


0723+10 2024/04/26 7.97UT TOYOKAWA-KISO





F20240426165648




BLK: 4,SNR1: 0.37403 ,SNR2: 1.1103




K20240426165647





BLK: 4,SNR1:-0.70696E-02,SNR2: 0.32938




0723+10 2024/04/26 7.97UT FUJI -KISO



T20240426170702





BLK: 1,SNR1:-0.12125 ,SNR2: 0.31994




Frequency (Hz)

F20240426170703




BLK: 1,SNR1: 0.27442 ,SNR2: 2.2046





Frequency (Hz)


0732+33 2024/04/26 8.15UT TOYOKAWA-FUJI



T20240426170702





BLK: 2,SNR1: 0.22609 ,SNR2: 2.0360




Frequency (Hz)

K20240426170701




BLK: 2,SNR1: 0.86138 ,SNR2: 5.3199




Frequency (Hz)

0732+33 2024/04/26 8.15UT TOYOKAWA-KISO






F20240426170703




BLK: 4,SNR1:-0.29837E-01,SNR2: 2.5207




Frequency (Hz)

K20240426170701




BLK: 4,SNR1: 0.58851 ,SNR2: 3.7899





Frequency (Hz)


0732+33 2024/04/26 8.15UT FUJI -KISO



T20240426174448




BLK: 6,SNR1: 0.53409E-02,SNR2: 1.0436




Frequency (Hz)

F20240426174448




BLK: 6,SNR1:-0.55887E-01,SNR2: 1.4052





Frequency (Hz)


3C196 2024/04/26 8.77UT TOYOKAWA-FUJI



T20240426174448





BLK: 8,SNR1: 0.95441E-01,SNR2: 1.6190




Frequency (Hz)

K20240426174447





BLK: 8,SNR1: 0.33654 ,SNR2: 1.3302





Frequency (Hz)

3C196 2024/04/26 8.77UT TOYOKAWA-KISO






BLK:13,SNR1:-0.75814E-01,SNR2: 1.2233



BLK:13,SNR1: 0.44196 ,SNR2: 1.4935



3C196 2024/04/26 8.77UT FUJI -KISO

