




T20240511060016





BLK: 4,SNR1: 0.40068E-01,SNR2: 0.54215




Frequency (Hz)

F20240511060016




BLK: 4,SNR1: 0.53522 ,SNR2: 2.1007





Frequency (Hz)


2124+349 2024/05/10 21.03UT TOYOKAWA-FUJI



T20240511060016





BLK: 6,SNR1: 0.14222 ,SNR2: 0.83835




Frequency (Hz)

K20240511060013




BLK: 6,SNR1: 1.5195 ,SNR2: 6.0024




Frequency (Hz)


2124+349 2024/05/10 21.03UT TOYOKAWA-KISO



F20240511060016





BLK: 4, SNR1: 0.22337 , SNR2: 6.2085




Frequency (Hz)

K20240511060013




BLK: 4, SNR1: 0.46906 , SNR2: 6.2807




Frequency (Hz)


2124+349 2024/05/10 21.03UT FUJI -KISO



T20240511060706





BLK: 5,SNR1:-0.33652E-02,SNR2: 1.2319




Frequency (Hz)

F20240511060707




BLK: 5,SNR1: 0.70802 ,SNR2: 4.2546





Frequency (Hz)




2131+379 2024/05/10 21.15UT TOYOKAWA-FUJI




T20240511060706





K20240511060703




2131+379 2024/05/10 21.15UT TOYOKAWA-KISO



F20240511060707





BLK:16,SNR1: 0.56069 ,SNR2: 2.6167




Frequency (Hz)

K20240511060703




BLK:16,SNR1: 1.0435 ,SNR2: 2.7754





Frequency (Hz)


2131+379 2024/05/10 21.15UT FUJI -KISO





T20240511062343




BLK: 5,SNR1: 0.21528 ,SNR2: 1.2374




F20240511062344





BLK: 5,SNR1: 0.43158E-01,SNR2: 3.3360




2147+145 2024/05/10 21.42UT TOYOKAWA-FUJI



T20240511062343





BLK:10,SNR1: 0.70363 ,SNR2: 2.3035




Frequency (Hz)

K20240511062340




BLK:10,SNR1: 0.74781 ,SNR2: 2.4625




Frequency (Hz)

2147+145 2024/05/10 21.42UT TOYOKAWA-KISO








F20240511062344




BLK: 4,SNR1: 0.16710 ,SNR2: 5.5557




K20240511062340





BLK: 4,SNR1: 7.7139 ,SNR2: 22.746




2147+145 2024/05/10 21.42UT FUJI -KISO



T20240511064558





BLK: 7,SNR1: 0.82003E-01,SNR2: 0.98441




Frequency (Hz)

F20240511064559




BLK: 7,SNR1: 0.13538 ,SNR2: 1.2446





Frequency (Hz)


2210+016 2024/05/10 21.79UT TOYOKAWA-FUJI




T20240511064558




No.Good Data




K20240511064558




No.Good Data




2210+016 2024/05/10 21.79UT TOYOKAWA-KISO




F20240511064559




BLK: 2,SNR1: 0.72461E-01,SNR2: 5.2915




K20240511064556





BLK: 2,SNR1: 0.16473 ,SNR2: 1.0934




2210+016 2024/05/10 21.79UT FUJI -KISO





T20240511065322




BLK:14,SNR1: 0.28753 ,SNR2: 1.5913




F20240511065323





BLK:14,SNR1: 4.2686 ,SNR2: 11.477




2217+128 2024/05/10 21.92UT TOYOKAWA-FUJI



T20240511065322





BLK:20,SNR1: 0.59232 ,SNR2: 2.0933




Frequency (Hz)

K20240511065320




BLK:20,SNR1: 5.8546 ,SNR2: 14.449





Frequency (Hz)


2217+128 2024/05/10 21.92UT TOYOKAWA-KISO



F20240511065323





BLK:20,SNR1: 2.6151 ,SNR2: 8.1100




Frequency (Hz)

K20240511065320




BLK:20,SNR1: 5.6779 ,SNR2: 14.175




Frequency (Hz)


2217+128 2024/05/10 21.92UT FUJI -KISO



T20240511065908




BLK:18,SNR1: 3.3601 ,SNR2: 6.3877




Frequency (Hz)

3C446 2024/05/10 22.01UT TOYOKAWA-FUJI


F20240511065908



BLK:18,SNR1: 0.66794 ,SNR2: 2.8239




Frequency (Hz)






T20240511065908





BLK:22,SNR1: 2.7157 ,SNR2: 5.1516




Frequency (Hz)

3C446 2024/05/10 22.01UT TOYOKAWA-KISO


K20240511065905




BLK:22,SNR1: 1.1203 ,SNR2: 4.0013




Frequency (Hz)



F20240511065908





BLK:15,SNR1: 0.72027 ,SNR2: 3.8825





3C446 2024/05/10 22.01UT FUJI -KISO


K20240511065905




BLK:15,SNR1: 2.8560 ,SNR2: 6.8613



T20240511070552




BLK:15,SNR1: 1.9936 ,SNR2: 5.0205




Frequency (Hz)

F20240511070553




BLK:15,SNR1: 0.80426 ,SNR2: 2.4410




Frequency (Hz)


2229-093 2024/05/10 22.13UT TOYOKAWA-FUJI



T20240511070552




BLK:17,SNR1: 1.3335 ,SNR2: 6.6334




Frequency (Hz)

K20240511070550




BLK:17,SNR1: 1.1314 ,SNR2: 2.9257





Frequency (Hz)


2229-093 2024/05/10 22.13UT TOYOKAWA-KISO



F20240511070553




BLK:14,SNR1: 0.86841 ,SNR2: 3.0022




Frequency (Hz)

2229-093 2024/05/10 22.13UT FUJI -KISO


K20240511070550





BLK:14,SNR1: 1.0958 ,SNR2: 3.1714




Frequency (Hz)





T20240511071419




BLK:32,SNR1: 8.0288 ,SNR2: 20.090




F20240511071420





BLK:32,SNR1: 3.4017 ,SNR2: 15.480




2238-113 2024/05/10 22.27UT TOYOKAWA-FUJI



T20240511071419





BLK:30,SNR1: 8.1527 ,SNR2: 20.405




Frequency (Hz)

K20240511071417




BLK:30,SNR1: 8.1857 ,SNR2: 20.500




Frequency (Hz)


2238-113 2024/05/10 22.27UT TOYOKAWA-KISO




F20240511071420



Time (sec)




BLK:34,SNR1: 3.4005 ,SNR2: 15.475




Frequency (Hz)


K20240511071417



Time (sec)




BLK:34,SNR1: 8.1506 ,SNR2: 20.408





Frequency (Hz)

2238-113 2024/05/10 22:27UT FUJI -KISO






T20240511072708





BLK:24,SNR1: 2.8275 ,SNR2: 12.648




Frequency (Hz)

3C454.3 2024/05/10 22.48UT TOYOKAWA-FUJI


F20240511072709





BLK:24,SNR1: 8.9780 ,SNR2: 16.731




Frequency (Hz)



T20240511072708





BLK:23,SNR1: 2.8280 ,SNR2: 12.650




Frequency (Hz)

3C454.3 2024/05/10 22.48UT TOYOKAWA-KISO


K20240511072706





BLK:23,SNR1: 8.4660 ,SNR2: 21.212




Frequency (Hz)



F20240511072709





BLK:24,SNR1: 8.0568 ,SNR2: 20.616




Frequency (Hz)

3C454.3 2024/05/10 22.48UT FUJI -KISO


K20240511072706





BLK:24,SNR1: 8.7693 ,SNR2: 21.950




Frequency (Hz)



T20240511073450





BLK:25,SNR1: 7.5536 ,SNR2: 22.284





2259+481 2024/05/10 22.61UT TOYOKAWA-FUJI



F20240511073451




BLK:25,SNR1: 10.410 ,SNR2: 19.362



T20240511073450





BLK:23,SNR1: 7.5519 ,SNR2: 22.279




Frequency (Hz)

2259+481 2024/05/10 22.61UT TOYOKAWA-KISO


K20240511073447





BLK:23,SNR1: 7.6820 ,SNR2: 24.177




Frequency (Hz)





F20240511073451




BLK:23,SNR1: 10.433 ,SNR2: 19.404




K20240511073447





BLK:23,SNR1: 7.6806 ,SNR2: 24.171




2259+481 2024/05/10 22.61UT FUJI -KISO



T20240511074944





BLK:25,SNR1: 6.7465 ,SNR2: 23.626




Frequency (Hz)

3C459 2024/05/10 22.86UT TOYOKAWA-FUJI


F20240511074945





BLK:25,SNR1: 19.301 ,SNR2: 35.264




Frequency (Hz)



T20240511074944





BLK:29,SNR1: 14.679 ,SNR2: 35.371




Frequency (Hz)

3C459 2024/05/10 22.86UT TOYOKAWA-KISO


K20240511074942



BLK:29,SNR1: 20.058 ,SNR2: 36.322





Frequency (Hz)






F20240511074945





BLK:34,SNR1: 19.271 ,SNR2: 35.208




Frequency (Hz)

3C459 2024/05/10 22.86UT FUJI -KISO


K20240511074942





BLK:34,SNR1: 20.039 ,SNR2: 36.287




Frequency (Hz)




T20240511082329




BLK:30,SNR1: 44.762 ,SNR2: 44.987




F20240511082329





BLK:30,SNR1: 2.4748 ,SNR2: 10.953




2347-02 2024/05/10 23.42UT TOYOKAWA-FUJI



T20240511082329




BLK:29,SNR1: 45.876 ,SNR2: 46.106




Frequency (Hz)

2347-02 2024/05/10 23.42UT TOYOKAWA-KISO


K20240511082326





BLK:29,SNR1: 7.3156 ,SNR2: 18.237




Frequency (Hz)



F20240511082329





BLK:29,SNR1: 2.5517 ,SNR2: 11.247




Frequency (Hz)

2347-02 2024/05/10 23.42UT FUJI -KISO


K20240511082326






BLK:29,SNR1: 7.7130 ,SNR2: 19.197



Frequency (Hz)






T20240511083022





2354+14 2024/05/10 23.53UT TOYOKAWA-FUJI


F20240511083022





T20240511083022




BLK:12,SNR1: 0.32138 ,SNR2: 1.3385




K20240511083020





BLK:12,SNR1: 1.1379 ,SNR2: 4.5141




2354+14 2024/05/10 23.53UT TOYOKAWA-KISO



F20240511083022





BLK: 6, SNR1: 2.4384 , SNR2: 11.536




Frequency (Hz)

K20240511083020




BLK: 6, SNR1: 1.4799 , SNR2: 5.2111





Frequency (Hz)


2354+14 2024/05/10 23.53UT FUJI -KISO



T20240511083925




BLK: 9,SNR1: 0.26321 ,SNR2: 2.2635




Frequency (Hz)

F20240511083926




BLK: 9,SNR1:-0.74044E-01,SNR2: 2.1336





Frequency (Hz)

3C2 2024/05/10 23.69UT TOYOKAWA-FUJI






T20240511083925





BLK:11,SNR1: 0.22262 ,SNR2: 2.0436





3C2

2024/05/10 23.69UT TOYOKAWA-KISO



K20240511083923




BLK:11,SNR1: 0.44793 ,SNR2: 1.9254





F20240511083926




BLK:11,SNR1: 0.20493 ,SNR2: 2.5285




K20240511083923




BLK:11,SNR1: 0.49388 ,SNR2: 2.0185




3C2 2024/05/10 23.69UT FUJI -KISO



T20240511084647




BLK:25,SNR1: 15.452 ,SNR2: 28.184





0011+344 2024/05/10 23.81UT TOYOKAWA-FUJI



F20240511084648




BLK:25,SNR1: 2.5705 ,SNR2: 6.4531





T20240511084647




BLK:28,SNR1: 14.434 ,SNR2: 26.331




K20240511084644




BLK:28,SNR1: 6.3187 ,SNR2: 15.349




0011+344 2024/05/10 23.81UT TOYOKAWA-KISO





F20240511084648




BLK:30,SNR1: 7.4238 ,SNR2: 11.256




K20240511084644






BLK:30,SNR1: 5.5967 ,SNR2: 13.654






0011+344 2024/05/10 23.81UT FUJI -KISO




T20240511085422





F20240511085423




0018+241 2024/05/10 23.93UT TOYOKAWA-FUJI




T20240511085422




BLK:17,SNR1: 0.74623 ,SNR2: 3.1883




K20240511085420





BLK:17,SNR1: 17.367 ,SNR2: 17.123




0018+241 2024/05/10 23.93UT TOYOKAWA-KISO





F20240511085423




BLK:37,SNR1: 13.886 ,SNR2: 15.486




K20240511085420



BLK:37,SNR1: 18.801 ,SNR2: 18.447





0018+241 2024/05/10 23.93UT FUJI -KISO








T20240511090538




BLK:13,SNR1: 0.61975 ,SNR2: 1.4597




F20240511090539





BLK:13,SNR1: 2.6347 ,SNR2: 7.9424




3C12 2024/05/11 0.12UT TOYOKAWA-FUJI




T20240511090538




BLK:23,SNR1: 0.48361 ,SNR2: 1.2292




K20240511090536





BLK:23,SNR1: 0.75197 ,SNR2: 2.9762




3C12 2024/05/11 0.12UT TOYOKAWA-KISO



F20240511090539





BLK:19,SNR1: 1.8396 ,SNR2: 6.4290




Frequency (Hz)

3C12 2024/05/11 0.12UT FUJI -KISO


K20240511090536





BLK:19,SNR1: 0.78466 ,SNR2: 3.1085




Frequency (Hz)



T20240511091940





BLK:21,SNR1: 14.590 ,SNR2: 26.766




Frequency (Hz)

F20240511091940




BLK:21,SNR1: 7.8029 ,SNR2: 19.792





Frequency (Hz)


0044-056 2024/05/11 0.36UT TOYOKAWA-FUJI





T20240511091940




BLK:31,SNR1: 14.569 ,SNR2: 26.728




K20240511091937





BLK:31,SNR1: 8.9832 ,SNR2: 22.496




0044-056 2024/05/11 0.36UT TOYOKAWA-KISO





F20240511091940




BLK:18,SNR1: 8.0231 ,SNR2: 20.137




K20240511091937




BLK:18,SNR1: 2.6643 ,SNR2: 12.841




0044-056 2024/05/11 0.36UT FUJI -KISO



T20240511092701




BLK: 2,SNR1:-0.28302E-01,SNR2: 2.5931





3C26 2024/05/11 0.48UT TOYOKAWA-FUJI


F20240511092702




BLK: 2,SNR1:-0.18544 ,SNR2: 1.2061



T20240511092701





BLK:11,SNR1: 3.7480 ,SNR2: 6.9364





3C26 2024/05/11 0.48UT TOYOKAWA-KISO

K20240511092659




BLK:11,SNR1: 0.23538 ,SNR2: 1.4735






F20240511092702





BLK: 2, SNR1: 0.11263 , SNR2: 1.5162





3C26 2024/05/11 0.48UT FUJI -KISO



K20240511092659




BLK: 2, SNR1: 0.97459 , SNR2: 4.8821



T20240511093200




BLK:30,SNR1: 7.8495 ,SNR2: 19.737





0056-00 2024/05/11 0.56UT TOYOKAWA-FUJI



F20240511093201




BLK:30,SNR1: 6.0502 ,SNR2: 15.378



T20240511093200





BLK:36,SNR1: 7.9437 ,SNR2: 19.985





0056-00 2024/05/11 0.56UT TOYOKAWA-KISO


K20240511093158




BLK:36,SNR1: 8.8908 ,SNR2: 22.261



F20240511093201





BLK:31,SNR1: 6.0120 ,SNR2: 15.287





0056-00 2024/05/11 0.56UT FUJI -KISO



K20240511093158




BLK:31,SNR1: 8.8917 ,SNR2: 22.264



T20240511094142





BLK: 3,SNR1: 0.31324 ,SNR2: 1.4926




Frequency (Hz)

0106+01 2024/05/11 0.72UT TOYOKAWA-FUJI


F20240511094142





BLK: 3,SNR1:-0.10039 ,SNR2: 1.7506




Frequency (Hz)



T20240511094142





BLK: 1,SNR1:-0.89681E-02,SNR2: 2.4790





0106+01 2024/05/11 0.72UT TOYOKAWA-KISO



K20240511094140




BLK: 1,SNR1: 1.2978 ,SNR2: 4.6352



F20240511094142





BLK: 2,SNR1:-0.16304 ,SNR2: 2.5128




Frequency (Hz)

K20240511094140




BLK: 2,SNR1: 0.84050 ,SNR2: 4.0577




Frequency (Hz)


0106+01 2024/05/11 0.72UT FUJI -KISO



T20240511095231




BLK:18,SNR1: 6.4735 ,SNR2: 15.928





0116+31 2024/05/11 0.90UT TOYOKAWA-FUJI

F20240511095231




BLK:18,SNR1: 7.2331 ,SNR2: 12.890






T20240511095231





BLK:23,SNR1: 5.8381 ,SNR2: 14.217





0116+31 2024/05/11 0.90UT TOYOKAWA-KISO



K20240511095229




BLK:23,SNR1: 2.8850 ,SNR2: 13.695





F20240511095231




BLK:24,SNR1: 6.7327 ,SNR2: 12.003




K20240511095229




BLK:24,SNR1: 2.8843 ,SNR2: 13.692




0116+31 2024/05/11 0.90UT FUJI -KISO



T20240511100254




BLK:16,SNR1: 4.1274 ,SNR2: 10.232





3C43 2024/05/11 1.08UT TOYOKAWA-FUJI


F20240511100255




BLK:16,SNR1: 0.48024 ,SNR2: 5.0591



T20240511100254




BLK:22,SNR1: 3.2405 ,SNR2: 14.066





3C43 2024/05/11 1.08UT TOYOKAWA-KISO


K20240511100251




BLK:22,SNR1: 2.9639 ,SNR2: 7.2282





F20240511100255




BLK:27,SNR1: 0.99547 ,SNR2: 5.2522




K20240511100251




BLK:27,SNR1: 2.9145 ,SNR2: 7.1549




3C43 2024/05/11 1.08UT FUJI -KISO



T20240511101038




BLK:16,SNR1: 11.148 ,SNR2: 21.667





3C48 2024/05/11 1.21UT TOYOKAWA-FUJI


F20240511101038




BLK:16,SNR1: 0.21039 ,SNR2: 3.7952



T20240511101038




BLK:22,SNR1: 11.580 ,SNR2: 22.426





3C48 2024/05/11 1.21UT TOYOKAWA-KISO


K20240511101036




BLK:22,SNR1: 1.7851 ,SNR2: 5.8761



F20240511101038




BLK:30,SNR1: 0.21217 ,SNR2: 3.6958





3C48 2024/05/11 1.21UT FUJI -KISO

K20240511101036




BLK:30,SNR1: 1.4547 ,SNR2: 4.8366








T20240511103023




BLK:34,SNR1: 3.7249 ,SNR2: 6.7255




F20240511103023




BLK:34,SNR1: 8.2534 ,SNR2: 8.9749




0155-109 2024/05/11 1.53UT TOYOKAWA-FUJI



T20240511103023





BLK:27,SNR1: 4.1120 ,SNR2: 7.6243









0155-109 2024/05/11 1.53UT TOYOKAWA-KISO

K20240511103021




BLK:27,SNR1: 7.0005 ,SNR2: 17.325







0155-109 2024/05/11 1.53UT FUJI -KISO



T20240511103730





BLK:19,SNR1: 3.0710 ,SNR2: 14.676





0202+15 2024/05/11 1.65UT TOYOKAWA-FUJI


F20240511103731




BLK:19,SNR1: 115.10 ,SNR2: 113.43



T20240511103730





BLK:22,SNR1: 3.5956 ,SNR2: 12.795




0202+15 2024/05/11 1.65UT TOYOKAWA-KISO


K20240511103727




BLK:22,SNR1: 1.7378 ,SNR2: 3.4146




Frequency (Hz)




F20240511103731




BLK:27,SNR1: 59.255 ,SNR2: 59.843




K20240511103727





BLK:27,SNR1: 2.1238 ,SNR2: 3.8172




0202+15 2024/05/11 1.65UT FUJI -KISO





T20240511104920




BLK:33,SNR1: 0.93028 ,SNR2: 3.4289




F20240511104921





BLK:33,SNR1: 53.247 ,SNR2: 57.500




0213+178 2024/05/11 1.85UT TOYOKAWA-FUJI




T20240511104920




BLK:33,SNR1: 0.90910 ,SNR2: 2.7421




K20240511104918



BLK:33,SNR1: 24.032 ,SNR2: 23.570





0213+178 2024/05/11 1.85UT TOYOKAWA-KISO







F20240511104921




BLK:32,SNR1: 54.941 ,SNR2: 72.463




K20240511104918





BLK:32,SNR1: 22.050 ,SNR2: 21.425




0213+178 2024/05/11 1.85UT FUJI -KISO



T20240511105702




BLK:22,SNR1: 0.78344 ,SNR2: 2.8048





3C67 2024/05/11 1.98UT TOYOKAWA-FUJI



F20240511105702




BLK:22,SNR1: 0.67711 ,SNR2: 2.9953



T20240511105702




BLK:24,SNR1: 0.83143 ,SNR2: 2.9348





3C67 2024/05/11 1.98UT TOYOKAWA-KISO


K20240511105700




BLK:24,SNR1: 0.63024 ,SNR2: 2.9376



F20240511105702




BLK:26,SNR1: 1.2888 ,SNR2: 1.7003




Frequency (Hz)

3C67 2024/05/11 1.98UT FUJI -KISO


K20240511105700




BLK:26,SNR1: 0.61585 ,SNR2: 2.8771




Frequency (Hz)



T20240511111518




BLK:17,SNR1: 12.553 ,SNR2: 23.862




3C71 2024/05/11 2.28UT TOYOKAWA-FUJI


F20240511111519




BLK:17,SNR1: 2.7329 ,SNR2: 12.226




Frequency (Hz)



T20240511111518




BLK:23,SNR1: 10.084 ,SNR2: 19.179





3C71 2024/05/11 2.28UT TOYOKAWA-KISO



K20240511111516




BLK:23,SNR1: 1.4016 ,SNR2: 6.3898



F20240511111519




BLK:23,SNR1: 2.6023 ,SNR2: 11.721





3C71 2024/05/11 2.28UT FUJI -KISO



K20240511111516




BLK:23,SNR1: 0.76548 ,SNR2: 3.4205




T20240511113432




BLK:31,SNR1: 2.0993 ,SNR2: 4.2722




F20240511113433



BLK:31,SNR1: 0.60560 ,SNR2: 4.8567





0258+350 2024/05/11 2.60UT TOYOKAWA-FUJI







T20240511113432




BLK:33,SNR1: 1.6674 ,SNR2: 3.9907




K20240511113430




BLK:33,SNR1: 1.6557 ,SNR2: 7.2696




0258+350 2024/05/11 2.60UT TOYOKAWA-KISO





F20240511113433




BLK:31,SNR1: 0.55069 ,SNR2: 4.7229




K20240511113430




BLK:31,SNR1: 1.6979 ,SNR2: 7.3784




0258+350 2024/05/11 2.60UT FUJI -KISO




T20240511114421




BLK:30,SNR1: 14.955 ,SNR2: 32.030




F20240511114422




BLK:30,SNR1: 95.759 ,SNR2: 111.71




0308+305 2024/05/11 2.77UT TOYOKAWA-FUJI




T20240511114421




BLK:36,SNR1: 12.440 ,SNR2: 22.406




K20240511114419




BLK:36,SNR1: 53.578 ,SNR2: 71.557




0308+305 2024/05/11 2.77UT TOYOKAWA-KISO





F20240511114422




BLK:31,SNR1: 97.608 ,SNR2: 107.10




K20240511114419




BLK:31,SNR1: 62.419 ,SNR2: 83.362




0308+305 2024/05/11 2.77UT FUJI -KISO





T20240511115553




BLK:19,SNR1: 43.147 ,SNR2: 85.105




F20240511115554





BLK:19,SNR1: 2.0418 ,SNR2: 4.1965




0320+05 2024/05/11 2.96UT TOYOKAWA-FUJI





T20240511115553




BLK:31,SNR1: 28.938 ,SNR2: 57.090




K20240511115551




BLK:31,SNR1: 0.71439 ,SNR2: 2.4830




0320+05 2024/05/11 2.96UT TOYOKAWA-KISO




F20240511115554




BLK:18,SNR1: 1.2416 ,SNR2: 5.3139




K20240511115551



BLK:18,SNR1: 0.88016 ,SNR2: 3.0138




0320+05 2024/05/11 2.96UT FUJI -KISO







T20240511120914




BLK:28,SNR1: 4.2898 ,SNR2: 9.7005




F20240511120914




BLK:28,SNR1: 1.1254 ,SNR2: 6.5340




0333+32 2024/05/11 3.18UT TOYOKAWA-FUJI




T20240511120914




BLK:23,SNR1: 5.0560 ,SNR2: 11.692




K20240511120912




BLK:23,SNR1: 1.1875 ,SNR2: 5.2585




0333+32 2024/05/11 3.18UT TOYOKAWA-KISO





F20240511120914




BLK:18,SNR1: 1.7151 ,SNR2: 9.0522




K20240511120912





BLK:18,SNR1: 1.7025 ,SNR2: 5.9801




0333+32 2024/05/11 3.18UT FUJI -KISO



T20240511122216





BLK:10,SNR1: 0.28134 ,SNR2: 1.9668





0347+05 2024/05/11 3.40UT TOYOKAWA-FUJI



F20240511122217




BLK:10,SNR1: 2.3833 ,SNR2: 10.463



T20240511122216





BLK:12,SNR1: 0.54709 ,SNR2: 3.4377





0347+05 2024/05/11 3.40UT TOYOKAWA-KISO




K20240511122213





BLK:12,SNR1: 1.2189 ,SNR2: 5.0873




F20240511122217




K20240511122213




0347+05 2024/05/11 3.40UT FUJI -KISO




T20240511123751




BLK: 8,SNR1: 0.26860 ,SNR2: 1.5823




F20240511123752




BLK: 8,SNR1:-0.41337E-01,SNR2: 1.6702




0403-132 2024/05/11 3.66UT TOYOKAWA-FUJI





T20240511123751




BLK:10,SNR1: 0.31345 ,SNR2: 2.4451




K20240511123749



BLK:10,SNR1: 0.58779 ,SNR2: 3.9061




0403-132 2024/05/11 3.66UT TOYOKAWA-KISO






F20240511123752




BLK: 3,SNR1: 0.65998E-01,SNR2: 0.82939




K20240511123749





BLK: 3,SNR1: 0.89801E-01,SNR2: 1.8063




0403-132 2024/05/11 3.66UT FUJI -KISO





T20240511124701




BLK: 7,SNR1: 0.11400 ,SNR2: 2.2681




F20240511124701





BLK: 7,SNR1: 1.1453 ,SNR2: 4.4149




0411+05 2024/05/11 3.81UT TOYOKAWA-FUJI





T20240511124701




BLK:18,SNR1: 0.22747 ,SNR2: 2.8767




K20240511124658




BLK:18,SNR1: 0.54079 ,SNR2: 3.6993




0411+05 2024/05/11 3.81UT TOYOKAWA-KISO



F20240511124701




BLK:13,SNR1: 0.89988 ,SNR2: 3.1742




Frequency (Hz)

K20240511124658




BLK:13,SNR1: 0.49245 ,SNR2: 1.5813





Frequency (Hz)


0411+05 2024/05/11 3.81UT FUJI -KISO





T20240511125754




BLK:19,SNR1: 0.21051 ,SNR2: 2.1248




F20240511125755





BLK:19,SNR1: 9.3135 ,SNR2: 32.783




0422+178 2024/05/11 3.99UT TOYOKAWA-FUJI





T20240511125754




BLK:18,SNR1: 0.23862 ,SNR2: 1.9399




K20240511125752





BLK:18,SNR1: 50.871 ,SNR2: 62.965




0422+178 2024/05/11 3.99UT TOYOKAWA-KISO





F20240511125755




BLK:25,SNR1: 8.2615 ,SNR2: 28.741




K20240511125752





BLK:25,SNR1: 16.627 ,SNR2: 27.706




0422+178 2024/05/11 3.99UT FUJI -KISO





T20240511130530




BLK: 7,SNR1: 0.94223E-01,SNR2: 1.3520




F20240511130531



BLK: 7,SNR1: 0.35084 ,SNR2: 1.7600





3C120 2024/05/11 4.12UT TOYOKAWA-FUJI








T20240511130530




BLK: 8,SNR1: 0.26790 ,SNR2: 1.1307




K20240511130528




BLK: 8,SNR1: 0.43527 ,SNR2: 2.0417




3C120 2024/05/11 4.12UT TOYOKAWA-KISO



F20240511130531




BLK: 3,SNR1: 0.19754 ,SNR2: 0.76034





3C120 2024/05/11 4.12UT FUJI -KISO



K20240511130528




BLK: 3,SNR1: 0.98256E-01,SNR2: 0.55960



T20240511135330





BLK:20,SNR1: 3.0295 ,SNR2: 10.728




Frequency (Hz)

F20240511135331




BLK:20,SNR1: 0.14808 ,SNR2: 3.1097





Frequency (Hz)


3C138 2024/05/11 4.92UT TOYOKAWA-FUJI




T20240511135330




BLK:26,SNR1: 3.2237 ,SNR2: 14.300




K20240511135328





BLK:26,SNR1: 1.4690 ,SNR2: 5.0522






3C138 2024/05/11 4.92UT TOYOKAWA-KISO




F20240511135331




K20240511135328




3C138 2024/05/11 4.92UT FUJI -KISO





T20240511140703




BLK:21,SNR1: 1.7557 ,SNR2: 4.9995




F20240511140704





BLK:21,SNR1: 10.009 ,SNR2: 33.230




0531+194 2024/05/11 5.15UT TOYOKAWA-FUJI





T20240511140703




BLK:20,SNR1: 1.7570 ,SNR2: 4.6016




K20240511140701





BLK:20,SNR1: 1.6114 ,SNR2: 6.2041




0531+194 2024/05/11 5.15UT TOYOKAWA-KISO




F20240511140704




BLK:20,SNR1: 7.6129 ,SNR2: 22.920




K20240511140701



BLK:20,SNR1: 1.8716 ,SNR2: 9.7725





0531+194 2024/05/11 5.15UT FUJI -KISO







T20240511141522




BLK:34,SNR1: 38.341 ,SNR2: 60.804




F20240511141523







BLK:34,SNR1: 0.15262 ,SNR2: 3.6146




3C147 2024/05/11 5.28UT TOYOKAWA-FUJI







3C147 2024/05/11 5.28UT TOYOKAWA-KISO



F20240511141523





BLK:22,SNR1: 0.21389 ,SNR2: 4.0224





3C147 2024/05/11 5.28UT FUJI -KISO



K20240511141520




BLK:22,SNR1: 3.6132 ,SNR2: 14.148



T20240511142334




BLK:17,SNR1: 0.63022 ,SNR2: 4.5327




Frequency (Hz)

F20240511142334




BLK:17,SNR1: 0.57343 ,SNR2: 5.1788





Frequency (Hz)


0548+16 2024/05/11 5.42UT TOYOKAWA-FUJI





T20240511142334




BLK:19,SNR1: 0.82761 ,SNR2: 3.1109




K20240511142332





BLK:19,SNR1: 8.7220 ,SNR2: 11.084






0548+16 2024/05/11 5.42UT TOYOKAWA-KISO




F20240511142334





K20240511142332




0548+16 2024/05/11 5.42UT FUJI -KISO




T20240511142745




BLK:16,SNR1: 3.8400 ,SNR2: 16.167




F20240511142745





BLK:16,SNR1: 2.5143 ,SNR2: 6.5222




0552+12 2024/05/11 5.49UT TOYOKAWA-FUJI





T20240511142745




BLK:13,SNR1: 7.2175 ,SNR2: 48.800




K20240511142742



BLK:13,SNR1: 3.1140 ,SNR2: 7.7254





0552+12 2024/05/11 5.49UT TOYOKAWA-KISO








F20240511142745




BLK:27,SNR1: 2.2693 ,SNR2: 5.5470




K20240511142742





BLK:27,SNR1: 3.1791 ,SNR2: 7.2853




0552+12 2024/05/11 5.49UT FUJI -KISO





T20240511143212




BLK: 7,SNR1: 0.62581E-01,SNR2: 0.41495




F20240511143212





BLK: 7,SNR1: 1.4525 ,SNR2: 5.8959




0556+191 2024/05/11 5.56UT TOYOKAWA-FUJI





T20240511143212




BLK: 7,SNR1: 0.27869 ,SNR2: 0.61308




K20240511143209




BLK: 7,SNR1: 0.82641 ,SNR2: 3.7533




0556+191 2024/05/11 5.56UT TOYOKAWA-KISO





F20240511143212




BLK:13,SNR1: 0.87169 ,SNR2: 3.7977




K20240511143209





BLK:13,SNR1: 0.83562 ,SNR2: 3.8753




0556+191 2024/05/11 5.56UT FUJI -KISO





T20240511143958




BLK:14,SNR1: 0.19967 ,SNR2: 1.5734




F20240511143958





BLK:14,SNR1: 0.99575 ,SNR2: 3.6727




0605-08 2024/05/11 5.69UT TOYOKAWA-FUJI





T20240511143958




BLK:14,SNR1: 0.18857 ,SNR2: 1.5768




K20240511143956





BLK:14,SNR1: 1.1214 ,SNR2: 5.2104




0605-08 2024/05/11 5.69UT TOYOKAWA-KISO





F20240511143958




BLK:19,SNR1: 1.0861 ,SNR2: 3.7429




K20240511143956





BLK:19,SNR1: 0.93659 ,SNR2: 4.4108




0605-08 2024/05/11 5.69UT FUJI -KISO





T20240511145906




BLK:13,SNR1: 3.6391 ,SNR2: 14.462




F20240511145906



BLK:13,SNR1: 0.11242E-01,SNR2: 2.7444




3C161 2024/05/11 6.01UT TOYOKAWA-FUJI








T20240511145906




BLK:29,SNR1: 5.3373 ,SNR2: 10.113




K20240511145903




BLK:29,SNR1: 1.5512 ,SNR2: 5.8021




3C161 2024/05/11 6.01UT TOYOKAWA-KISO



F20240511145906





BLK:15,SNR1: 0.44687E-01,SNR2: 2.4511




Frequency (Hz)

K20240511145903




BLK:15,SNR1: 1.6529 ,SNR2: 6.1595





Frequency (Hz)


3C161 2024/05/11 6.01UT FUJI -KISO





T20240511152639




BLK:17,SNR1: 4.7666 ,SNR2: 9.2596




F20240511152639






BLK:17,SNR1: 0.87840 ,SNR2: 2.1298






0652-130 2024/05/11 6.47UT TOYOKAWA-FUJI




T20240511152639





K20240511152637




0652-130 2024/05/11 6.47UT TOYOKAWA-KISO



F20240511152639





BLK:13,SNR1: 1.1471 ,SNR2: 2.9037




Frequency (Hz)

K20240511152637




BLK:13,SNR1: 0.90276 ,SNR2: 3.3139





Frequency (Hz)


0652-130 2024/05/11 6.47UT FUJI -KISO



T20240511153815




BLK:17,SNR1: 1.7747 ,SNR2: 6.2882




Frequency (Hz)

F20240511153815




BLK:17,SNR1: 1.1153 ,SNR2: 4.4294





Frequency (Hz)


0703+138 2024/05/11 6.67UT TOYOKAWA-FUJI





T20240511153815




BLK:13,SNR1: 2.0001 ,SNR2: 7.1710




K20240511153813




BLK:13,SNR1: 0.49075 ,SNR2: 2.6183




0703+138 2024/05/11 6.67UT TOYOKAWA-KISO



F20240511153815





BLK:20,SNR1: 1.1318 ,SNR2: 4.4151




Frequency (Hz)

K20240511153813




BLK:20,SNR1: 0.44518 ,SNR2: 2.1258





Frequency (Hz)

0703+138 2024/05/11 6.67UT FUJI -KISO






T20240511154738




BLK:22,SNR1: 12.184 ,SNR2: 29.406




Frequency (Hz)

F20240511154738




BLK:22,SNR1: 4.7277 ,SNR2: 12.090





Frequency (Hz)


0713-024 2024/05/11 6.82UT TOYOKAWA-FUJI





T20240511154738




BLK:26,SNR1: 11.857 ,SNR2: 28.623




K20240511154736




BLK:26,SNR1: 2.8377 ,SNR2: 13.467




0713-024 2024/05/11 6.82UT TOYOKAWA-KISO



F20240511154738




BLK:30,SNR1: 4.3480 ,SNR2: 14.578




Frequency (Hz)

K20240511154736




BLK:30,SNR1: 2.8335 ,SNR2: 13.441




Frequency (Hz)


0713-024 2024/05/11 6.82UT FUJI -KISO



T20240511155749





BLK:29,SNR1: 8.2458 ,SNR2: 20.618




Frequency (Hz)

F20240511155749




BLK:29,SNR1: 10.776 ,SNR2: 24.932




Frequency (Hz)


0723+10 2024/05/11 6.99UT TOYOKAWA-FUJI



T20240511155749





BLK:32,SNR1: 8.1240 ,SNR2: 20.309




Frequency (Hz)

K20240511155746




BLK:32,SNR1: 2.7489 ,SNR2: 12.901





Frequency (Hz)


0723+10 2024/05/11 6.99UT TOYOKAWA-KISO





F20240511155749




BLK:34,SNR1: 10.765 ,SNR2: 24.917




K20240511155746





BLK:34,SNR1: 8.4033 ,SNR2: 21.087




0723+10 2024/05/11 6.99UT FUJI -KISO





T20240511160804




BLK:23,SNR1: 10.097 ,SNR2: 17.842




F20240511160804





BLK:23,SNR1: 6.8118 ,SNR2: 15.342




0732+33 2024/05/11 7.16UT TOYOKAWA-FUJI





T20240511160804




BLK:29,SNR1: 10.802 ,SNR2: 19.089




K20240511160802



BLK:29,SNR1: 14.827 ,SNR2: 26.491





0732+33 2024/05/11 7.16UT TOYOKAWA-KISO






F20240511160804





BLK:31,SNR1: 8.2709 ,SNR2: 19.283




Frequency (Hz)

K20240511160802




BLK:31,SNR1: 14.879 ,SNR2: 26.586





Frequency (Hz)


0732+33 2024/05/11 7.16UT FUJI -KISO



T20240511161606




BLK:10,SNR1: 1.9451 ,SNR2: 2.6163




Frequency (Hz)

F20240511161607




BLK:10,SNR1: 1.4877 ,SNR2: 3.8925




Frequency (Hz)


0741-06 2024/05/11 7.30UT TOYOKAWA-FUJI



T20240511161606





BLK:11,SNR1: 1.0400 ,SNR2: 4.4419




Frequency (Hz)

K20240511161603




BLK:11,SNR1: 0.77550 ,SNR2: 4.7386





Frequency (Hz)


0741-06 2024/05/11 7.30UT TOYOKAWA-KISO





F20240511161607




BLK:12,SNR1: 1.4960 ,SNR2: 3.8301




K20240511161603




BLK:12,SNR1: 1.1290 ,SNR2: 4.5726





0741-06 2024/05/11 7.30UT FUJI -KISO







BLK:14,SNR1: 0.22555E-01,SNR2: 1.4753





BLK:14,SNR1: 4.7257 ,SNR2: 11.451






0752-200 2024/05/11 7.46UT TOYOKAWA-FUJI







BLK: 9,SNR1: 0.58036E-01,SNR2: 1.7904





BLK: 9,SNR1: 0.85098 ,SNR2: 4.2339




0752-200 2024/05/11 7.46UT TOYOKAWA-KISO





F20240511162552




BLK: 8,SNR1: 6.2033 ,SNR2: 14.669




K20240511162549





BLK: 8,SNR1: 0.49753 ,SNR2: 3.0061




0752-200 2024/05/11 7.46UT FUJI -KISO




T20240511163325




BLK: 7,SNR1: 0.44514 ,SNR2: 1.9614




F20240511163325



BLK: 7,SNR1: 0.21015 ,SNR2: 1.7131





3C190 2024/05/11 7.59UT TOYOKAWA-FUJI






T20240511163325





BLK: 9,SNR1: 0.41290 ,SNR2: 1.9617




Frequency (Hz)

K20240511163323




BLK: 9,SNR1: 0.40718 ,SNR2: 3.8440




Frequency (Hz)


3C190 2024/05/11 7.59UT TOYOKAWA-KISO



F20240511163325




BLK: 2,SNR1: 0.54130 ,SNR2: 2.4576




Frequency (Hz)

K20240511163323




BLK: 2,SNR1:-0.20384E-01,SNR2: 0.82077





Frequency (Hz)


3C190 2024/05/11 7.59UT FUJI -KISO



T20240511164549




BLK:18,SNR1: 0.90936 ,SNR2: 2.6079




Frequency (Hz)

F20240511164550




BLK:18,SNR1: 4.1801 ,SNR2: 9.5300





Frequency (Hz)


3C196 2024/05/11 7.79UT TOYOKAWA-FUJI



T20240511164549





BLK:12,SNR1: 1.0710 ,SNR2: 2.0496




Frequency (Hz)

K20240511164546




BLK:12,SNR1: 7.0410 ,SNR2: 7.2623





Frequency (Hz)


3C196 2024/05/11 7.79UT TOYOKAWA-KISO



F20240511164550





BLK:23,SNR1: 6.8372 ,SNR2: 17.154




Frequency (Hz)

K20240511164546




BLK:23,SNR1: 5.8688 ,SNR2: 6.5050





Frequency (Hz)


3C196 2024/05/11 7.79UT FUJI -KISO



T20240511165659




BLK:14,SNR1: 3.1583 ,SNR2: 5.4194




Frequency (Hz)

F20240511165659




BLK:14,SNR1: 1.1405 ,SNR2: 4.9518





Frequency (Hz)


0821+394 2024/05/11 7.98UT TOYOKAWA-FUJI



T20240511165659




BLK:18,SNR1: 2.1722 ,SNR2: 6.9953




Frequency (Hz)

K20240511165657






BLK:18,SNR1: 4.1373 ,SNR2: 10.738




Frequency (Hz)

0821+394 2024/05/11 7.98UT TOYOKAWA-KISO







0821+394 2024/05/11 7.98UT FUJI -KISO






T20240511174127





BLK: 9,SNR1: 0.44473 ,SNR2: 2.2903




Frequency (Hz)

F20240511174127




BLK: 9,SNR1:-0.99300E-02,SNR2: 1.0489





Frequency (Hz)


3C216 2024/05/11 8.72UT TOYOKAWA-FUJI





T20240511174127




BLK:11,SNR1: 1.0863 ,SNR2: 2.2064




K20240511174125





BLK:11,SNR1: 0.54873 ,SNR2: 2.4580




3C216 2024/05/11 8.72UT TOYOKAWA-KISO



F20240511174127





BLK:10,SNR1: 0.22405 ,SNR2: 1.7003




Frequency (Hz)

K20240511174125



BLK:10,SNR1: 0.56817 ,SNR2: 2.2080



Frequency (Hz)

3C216 2024/05/11 8.72UT FUJI -KISO

