




TOYOKAWA 2327+568 2024/07/07(189)04:18:49-04:22:15JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2341+535 2024/07/07(189)04:32:44-04:36:10JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0010+405 2024/07/07(189)05:02:25-05:05:51JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0017+565 2024/07/07(189)05:08:49-05:12:15JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0025+373 2024/07/07(189)05:17:07-05:20:33JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0031+391 2024/07/07(189)05:23:08-05:26:34JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0038+328 2024/07/07(189)05:29:47-05:33:13JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0044+301 2024/07/07(189)05:35:58-05:39:24JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0049+379 2024/07/07(189)05:41:10-05:44:36JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0100+146 2024/07/07(189)05:51:36-05:55:02JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0103+422 2024/07/07(189)05:55:36-05:59:02JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0108+258 2024/07/07(189)06:00:10-06:03:36JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0116+31 2024/07/07(189)06:08:23-06:11:49JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0120+405 2024/07/07(189)06:12:17-06:15:43JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0128+03 2024/07/07(189)06:19:56-06:23:22JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C48

2024/07/07(189)06:26:29-06:29:55JST 207Rs

7127+/- 442




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0148+274 2024/07/07(189)06:40:13-06:43:39JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0155-109 2024/07/07(189)06:46:14-06:49:40JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0202+15 2024/07/07(189)06:53:21-06:56:47JST 206Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C67

2024/07/07(189)07:12:54-07:16:20JST 194Rs

6027+/- 156




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C71

2024/07/07(189)07:31:09-07:34:35JST 202Rs


6439+/- 42




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0258+350 2024/07/07(189)07:50:24-07:53:50JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0308+305 2024/07/07(189)08:00:13-08:03:39JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0320+05 2024/07/07(189)08:11:45-08:15:11JST 181Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0324+119 2024/07/07(189)08:15:50-08:19:16JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0333+32 2024/07/07(189)08:25:06-08:28:32JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0347+05 2024/07/07(189)08:38:08-08:41:34JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0355+50 2024/07/07(189)08:48:20-08:51:46JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0403-132 2024/07/07(189)08:53:42-08:57:08JST 182Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0411+05 2024/07/07(189)09:02:53-09:06:19JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0418+236 2024/07/07(189)09:09:47-09:13:13JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0422+178 2024/07/07(189)09:13:46-09:17:12JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C119 2024/07/07(189)09:21:14-09:24:40JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C138 2024/07/07(189)10:09:22-10:12:48JST 93Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0531+194 2024/07/07(189)10:22:55-10:26:21JST 79Rs


5671+/- 701




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C147 2024/07/07(189)10:31:14-10:34:40JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0548+16 2024/07/07(189)10:39:26-10:42:52JST 69Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0552+12 2024/07/07(189)10:43:37-10:47:03JST 72Rs


5624+/- 337




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0556+191 2024/07/07(189)10:48:03-10:51:29JST 59Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0605-08 2024/07/07(189)10:55:50-10:59:16JST 122Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C158 2024/07/07(189)11:09:42-11:13:08JST 49Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C161


2024/07/07(189)11:14:57-11:18:23JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2024/07/07(189)11:42:30-11:45:56JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0703+138 2024/07/07(189)11:54:07-11:57:33JST 33Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0713-024 2024/07/07(189)12:03:29-12:06:55JST 93Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2024/07/07(189)12:07:09-12:10:35JST 77Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0723+10 2024/07/07(189)12:13:41-12:17:07JST 49Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0732+33 2024/07/07(189)12:23:56-12:27:22JST 47Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0741-06 2024/07/07(189)12:31:58-12:35:24JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0752-200 2024/07/07(189)12:41:42-12:45:08JST 152Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190 2024/07/07(189)12:49:17-12:52:43JST 58Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0806-103 2024/07/07(189)12:56:22-12:59:48JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196


2024/07/07(189)13:01:41-13:05:07JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2024/07/07(189)13:08:26-13:11:52JST 67Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0821+394 2024/07/07(189)13:12:51-13:16:17JST 87Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0834-19 2024/07/07(189)13:24:31-13:27:57JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0839-071 2024/07/07(189)13:29:37-13:33:03JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208 2024/07/07(189)13:40:38-13:44:04JST 98Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0857-191 2024/07/07(189)13:46:58-13:50:24JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C216 2024/07/07(189)13:57:19-14:00:45JST 117Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2024/07/07(189)14:02:03-14:05:29JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0919-142 2024/07/07(189)14:09:30-14:12:56JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0926+117 2024/07/07(189)14:16:09-14:19:35JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C222 2024/07/07(189)14:23:54-14:27:20JST 142Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0941-08 2024/07/07(189)14:30:54-14:34:20JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230 2024/07/07(189)14:39:16-14:42:42JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C237 2024/07/07(189)14:55:17-14:58:43JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1011+110 2024/07/07(189)15:01:33-15:04:59JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C241 2024/07/07(189)15:09:14-15:12:40JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1031-11 2024/07/07(189)15:20:43-15:24:09JST 192Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1035-058 2024/07/07(189)15:25:17-15:28:43JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1044-008 2024/07/07(189)15:34:29-15:37:55JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1055+01 2024/07/07(189)15:45:34-15:49:00JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1059-010 2024/07/07(189)15:49:10-15:52:36JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1107+109 2024/07/07(189)15:56:51-16:00:17JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C255 2024/07/07(189)16:06:29-16:09:55JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2024/07/07(189)16:17:06-16:20:32JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2024/07/07(189)16:26:10-16:29:36JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C263.1 2024/07/07(189)16:30:27-16:33:53JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C267 2024/07/07(189)16:36:54-16:40:20JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1154+552 2024/07/07(189)16:44:18-16:47:44JST 192Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2024/07/07(189)16:56:08-16:59:34JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C273 2024/07/07(189)17:15:59-17:19:25JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1236+055 2024/07/07(189)17:25:59-17:29:25JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1256+215 2024/07/07(189)17:45:19-17:48:45JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1303+192 2024/07/07(189)17:52:30-17:55:56JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1308+277 2024/07/07(189)17:57:46-18:01:12JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1313+453 2024/07/07(189)18:02:46-18:06:12JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1323+32 2024/07/07(189)18:12:52-18:16:18JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286


2024/07/07(189)18:17:42-18:21:08JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1335+479 2024/07/07(189)18:24:05-18:27:31JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1339+472 2024/07/07(189)18:28:11-18:31:37JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1351+586 2024/07/07(189)18:39:10-18:42:36JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1358+538 2024/07/07(189)18:46:35-18:50:01JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1448+634 2024/07/07(189)19:35:07-19:38:33JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

