




T20240714054448





BLK: 7,SNR1: 0.26989 ,SNR2: 5.9079




Frequency (Hz)

F20240714054450




BLK: 7,SNR1: 0.98981 ,SNR2: 3.7590





Frequency (Hz)


0120+405 2024/07/13 20.77UT TOYOKAWA-FUJI



T20240714054448





BLK: 4,SNR1: 0.22784E-01,SNR2: 1.4312




Frequency (Hz)

K20240714054445




BLK: 4,SNR1: 0.25172 ,SNR2: 1.7396




Frequency (Hz)

0120+405 2024/07/13 20.77UT TOYOKAWA-KISO






F20240714054450





BLK:15,SNR1: 0.80548 ,SNR2: 2.6957




Frequency (Hz)

K20240714054445




BLK:15,SNR1: 1.4648 ,SNR2: 4.5266





Frequency (Hz)


0120+405 2024/07/13 20.77UT FUJI -KISO



T20240714055900



BLK:18,SNR1: 0.40812 ,SNR2: 1.9885




Frequency (Hz)


3C48

2024/07/13 21.01UT TOYOKAWA-FUJI


F20240714055902





BLK:18,SNR1: 0.29429 ,SNR2: 1.4899




Frequency (Hz)



T20240714055900



BLK:21,SNR1: 0.33639 ,SNR2: 2.6941





Frequency (Hz)


3C48

2024/07/13 21.01UT TOYOKAWA-KISO


K20240714055857





BLK:21,SNR1: 0.10212 ,SNR2: 1.4855




Frequency (Hz)



F20240714055902





BLK:10,SNR1: 0.37263 ,SNR2: 1.6837




Frequency (Hz)

3C48 2024/07/13 21.01UT FUJI -KISO


K20240714055857




BLK:10,SNR1: 0.24859 ,SNR2: 1.2871




Frequency (Hz)



T20240714061244





BLK: 2,SNR1:-0.24801E-01,SNR2: 0.46290




Frequency (Hz)

F20240714061246




BLK: 2,SNR1:-0.57480E-02,SNR2: 0.73389





Frequency (Hz)


0148+274 2024/07/13 21.24UT TOYOKAWA-FUJI



T20240714061244





BLK: 2,SNR1: 0.21049 ,SNR2: 0.99502




Frequency (Hz)

K20240714061241




BLK: 2,SNR1: 0.76793E-02,SNR2: 1.8790




Frequency (Hz)


0148+274 2024/07/13 21.24UT TOYOKAWA-KISO



F20240714061246




BLK: 3,SNR1: 0.11569 ,SNR2: 1.1626




Frequency (Hz)

K20240714061241




BLK: 3,SNR1: 0.13686E-01,SNR2: 0.88158





Frequency (Hz)


0148+274 2024/07/13 21.24UT FUJI -KISO



T20240714062552





BLK: 1,SNR1: 0.16907 ,SNR2: 1.6350




Frequency (Hz)

F20240714062554




BLK: 1,SNR1:-0.52527E-01,SNR2: 0.38060





Frequency (Hz)

0202+15 2024/07/13 21.46UT TOYOKAWA-FUJI








T20240714062552




BLK: 1,SNR1: 0.85174E-01,SNR2: 2.3947




K20240714062549





BLK: 1,SNR1:-0.17614 ,SNR2: 0.32618




0202+15 2024/07/13 21.46UT TOYOKAWA-KISO



F20240714062554





BLK: 1,SNR1: -0.28866 ,SNR2: 0.37287




Frequency (Hz)

K20240714062549




BLK: 1,SNR1: 1.0122 ,SNR2: 3.2748





Frequency (Hz)


0202+15 2024/07/13 21.46UT FUJI -KISO



T20240714063742





BLK: 3,SNR1: 0.60882 ,SNR2: 1.6619




Frequency (Hz)

F20240714063744




BLK: 3,SNR1: 0.11957 ,SNR2: 2.0030





Frequency (Hz)


0213+178 2024/07/13 21.66UT TOYOKAWA-FUJI



T20240714063742




BLK: 5,SNR1: 0.21607 ,SNR2: 1.5024




Frequency (Hz)

K20240714063739




BLK: 5,SNR1: 0.42647 ,SNR2: 1.3604





Frequency (Hz)


0213+178 2024/07/13 21.66UT TOYOKAWA-KISO



F20240714063744





BLK: 7,SNR1: 1.4846 ,SNR2: 2.8010




Frequency (Hz)

K20240714063739




BLK: 7,SNR1: 3.4550 ,SNR2: 10.766





Frequency (Hz)


0213+178 2024/07/13 21.66UT FUJI -KISO



T20240714064525



BLK: 6,SNR1: 0.27312 ,SNR2: 1.6098





Frequency (Hz)


3C67

2024/07/13 21.79UT TOYOKAWA-FUJI


F20240714064527





BLK: 6,SNR1: 0.35743 ,SNR2: 1.4383




Frequency (Hz)



T20240714064525



BLK: 7,SNR1: 0.39428 ,SNR2: 1.4640





Frequency (Hz)


3C67

2024/07/13 21.79UT TOYOKAWA-KISO


K20240714064522




BLK: 7,SNR1: -0.20463E-02,SNR2: 0.90047




Frequency (Hz)



F20240714064527





BLK: 6,SNR1: 0.42534E-01,SNR2: 1.4582




Frequency (Hz)

3C67 2024/07/13 21.79UT FUJI -KISO


K20240714064522



BLK: 6,SNR1: 0.21679 ,SNR2: 2.3636





Frequency (Hz)






T20240714070340





BLK:26,SNR1: 8.1890 ,SNR2: 23.016




Frequency (Hz)

3C71 2024/07/13 22.09UT TOYOKAWA-FUJI


F20240714070342





BLK:26,SNR1: 12.131 ,SNR2: 21.523




Frequency (Hz)



T20240714070340



BLK:27,SNR1: 8.2336 ,SNR2: 23.123





Frequency (Hz)


3C71

2024/07/13 22.09UT TOYOKAWA-KISO


K20240714070337





BLK:27,SNR1: 8.9477 ,SNR2: 22.404




Frequency (Hz)



F20240714070342





BLK:33,SNR1: 11.907 ,SNR2: 21.128




Frequency (Hz)

3C71 2024/07/13 22.09UT FUJI -KISO


K20240714070337





BLK:33,SNR1: 8.9294 ,SNR2: 22.355




Frequency (Hz)



T20240714072255





BLK:12,SNR1: 0.12538 ,SNR2: 0.34760




Frequency (Hz)

F20240714072257




BLK:12,SNR1: 0.54007 ,SNR2: 1.9956





Frequency (Hz)


0258+350 2024/07/13 22.41UT TOYOKAWA-FUJI



T20240714072255





BLK: 9,SNR1: 0.13460 ,SNR2: 0.46619




Frequency (Hz)

K20240714072252




BLK: 9,SNR1: 0.37128 ,SNR2: 1.4850





Frequency (Hz)


0258+350 2024/07/13 22.41UT TOYOKAWA-KISO



F20240714072257





BLK:11,SNR1: 0.94915 ,SNR2: 3.5932




Frequency (Hz)

K20240714072252




BLK:11,SNR1: 0.35998 ,SNR2: 1.1934





Frequency (Hz)


0258+350 2024/07/13 22.41UT FUJI -KISO



T20240714073244




BLK: 3,SNR1: 0.26277E-01,SNR2: 0.69835




Frequency (Hz)

F20240714073246




BLK: 3,SNR1: 0.25919 ,SNR2: 2.7824





Frequency (Hz)


0308+305 2024/07/13 22.57UT TOYOKAWA-FUJI



T20240714073244





BLK: 5,SNR1: 0.83034E-01,SNR2: 0.58590




Frequency (Hz)

K20240714073241




BLK: 5,SNR1: 0.46836 ,SNR2: 4.6297




Frequency (Hz)

0308+305 2024/07/13 22.57UT TOYOKAWA-KISO








F20240714073246




BLK: 3,SNR1: 0.24892 ,SNR2: 1.9781




K20240714073241





BLK: 3,SNR1: 0.60545 ,SNR2: 5.8141




0308+305 2024/07/13 22.57UT FUJI -KISO



T20240714074416





BLK: 1,SNR1: 0.41822 ,SNR2: 1.3428




Frequency (Hz)

F20240714074418




BLK: 1,SNR1: 0.93894E-01,SNR2: 0.18300





Frequency (Hz)


0320+05 2024/07/13 22.77UT TOYOKAWA-FUJI



T20240714074416





BLK:12,SNR1: 0.20413 ,SNR2: 0.58094





0320+05 2024/07/13 22.77UT TOYOKAWA-KISO



K20240714074413




BLK:12,SNR1: 0.50418 ,SNR2: 2.2105



F20240714074418





BLK: 1,SNR1:-0.72660E-01,SNR2: 0.15970E-01




Frequency (Hz)

K20240714074413




BLK: 1,SNR1: 0.62162E-02,SNR2: 0.61524





Frequency (Hz)


0320+05 2024/07/13 22.77UT FUJI -KISO



T20240714075737




BLK:13,SNR1: 2.6778 ,SNR2: 12.621




Frequency (Hz)

0333+32 2024/07/13 22.99UT TOYOKAWA-FUJI


F20240714075739





BLK:13,SNR1: 5.5238 ,SNR2: 9.7580




Frequency (Hz)



T20240714075737





BLK:16,SNR1: 2.6769 ,SNR2: 12.610




Frequency (Hz)

0333+32 2024/07/13 22.99UT TOYOKAWA-KISO


K20240714075735





BLK:16,SNR1: 2.5749 ,SNR2: 12.486




Frequency (Hz)



F20240714075739





BLK:19,SNR1: 4.2232 ,SNR2: 7.4652




Frequency (Hz)

K20240714075735




BLK:19,SNR1: 2.5754 ,SNR2: 12.479





Frequency (Hz)


0333+32 2024/07/13 22.99UT FWJ -KISO



T20240714081038





BLK:20,SNR1: 8.0556 ,SNR2: 19.926




Frequency (Hz)

0347+05 2024/07/13 23.21UT TOYOKAWA-FUJI


F20240714081040



BLK:20,SNR1: 5.7599 ,SNR2: 16.363





Frequency (Hz)






T20240714081038





BLK:27,SNR1: 7.5312 ,SNR2: 18.858




Frequency (Hz)

0347+05 2024/07/13 23.21UT TOYOKAWA-KISO


K20240714081035





BLK:27,SNR1: 2.4756 ,SNR2: 11.752




Frequency (Hz)



F20240714081040





BLK:27,SNR1: 5.6167 ,SNR2: 15.960




Frequency (Hz)

K20240714081035




BLK:27,SNR1: 2.7463 ,SNR2: 13.138





Frequency (Hz)


0347+05 2024/07/13 23.21UT FUJI -KISO



T20240714082613





BLK: 4,SNR1: 5.9465 ,SNR2: 14.357




Frequency (Hz)

F20240714082615




BLK: 4,SNR1: 0.95511 ,SNR2: 2.4879




Frequency (Hz)


0403-132 2024/07/13 23.47UT TOYOKAWA-FUJI




T20240714082613




BLK:10,SNR1: 3.1658 ,SNR2: 8.9762




K20240714082610





BLK:10,SNR1: 4.3579 ,SNR2: 10.954




0403-132 2024/07/13 23.47UT TOYOKAWA-KISO



F20240714082615





BLK: 5,SNR1:-0.32506E-01,SNR2: 1.9864




Frequency (Hz)

K20240714082610




BLK: 5,SNR1: 5.3711 ,SNR2: 13.622




Frequency (Hz)


0403-132 2024/07/13 23.47UT FUJI -KISO



T20240714083523





BLK:23,SNR1: 2.7083 ,SNR2: 6.7344




Frequency (Hz)

F20240714083525




BLK:23,SNR1: 8.6241 ,SNR2: 20.131




Frequency (Hz)


0411+05 2024/07/13 23.62UT TOYOKAWA-FUJI



T20240714083523





BLK:28,SNR1: 2.4802 ,SNR2: 6.1739




Frequency (Hz)

K20240714083520




BLK:28,SNR1: 5.3861 ,SNR2: 13.400





Frequency (Hz)


0411+05 2024/07/13 23.62UT TOYOKAWA-KISO



F20240714083525





BLK:28,SNR1: 8.4636 ,SNR2: 19.768





0411+05 2024/07/13 23.62UT FUJI -KISO

K20240714083520





BLK:28,SNR1: 2.8200 ,SNR2: 13.192






T20240714084218




BLK: 9,SNR1: 9.0520 ,SNR2: 21.478





0418+236 2024/07/13 23.73UT TOYOKAWA-FUJI



F20240714084220




BLK: 9,SNR1: 0.17432 ,SNR2: 1.6165



T20240714084218




BLK: 6,SNR1: 9.2765 ,SNR2: 22.072





0418+236 2024/07/13 23.73UT TOYOKAWA-KISO


K20240714084215




BLK: 6,SNR1: 2.4953 ,SNR2: 6.3265



F20240714084220





BLK: 4,SNR1: 0.10432 ,SNR2: 2.4851




Frequency (Hz)

K20240714084215




BLK: 4,SNR1: 1.9410 ,SNR2: 8.3501





Frequency (Hz)


0418+236 2024/07/13 23.73UT FUJI -KISO





T20240714085345




BLK:20,SNR1: 1.1774 ,SNR2: 3.6892




F20240714085347





BLK:20,SNR1: 0.26770 ,SNR2: 1.7645




3C119 2024/07/13 23.92UT TOYOKAWA-FUJI





T20240714085345




BLK:25,SNR1: 0.94432 ,SNR2: 4.4481




K20240714085342




BLK:25,SNR1: 2.6722 ,SNR2: 4.9692




3C119 2024/07/13 23.92UT TOYOKAWA-KISO





F20240714085347




BLK:24,SNR1: 0.28699 ,SNR2: 2.8669




K20240714085342





BLK:24,SNR1: 0.24235 ,SNR2: 1.5773




3C119 2024/07/13 23.92UT FUJI -KISO



T20240714094152





BLK:23,SNR1: 3.0144 ,SNR2: 13.337




Frequency (Hz)

F20240714094154




BLK:23,SNR1: 7.5266 ,SNR2: 19.104





Frequency (Hz)


3C138 2024/07/14 0.73UT TOYOKAWA-FUJI





T20240714094152




BLK:28,SNR1: 4.0942 ,SNR2: 10.282




K20240714094149



BLK:28,SNR1: 14.805 ,SNR2: 26.160





3C138 2024/07/14 0.73UT TOYOKAWA-KISO






F20240714094154





BLK:28,SNR1: 7.3810 ,SNR2: 18.517









3C138 2024/07/14 0.73UT FUJI -KISO

K20240714094149








BLK:28,SNR1: 14.819 ,SNR2: 26.186






0531+194 2024/07/14 0.95UT TOYOKAWA-FUJI








0531+194 2024/07/14 0.95UT TOYOKAWA-KISO




F20240714095528




BLK:34,SNR1: 9.3968 ,SNR2: 21.039




K20240714095523





BLK:34,SNR1: 13.303 ,SNR2: 23.474




0531+194 2024/07/14 0.95UT FUJI -KISO



T20240714100345




BLK:17,SNR1: 19.803 ,SNR2: 61.779





3C147 2024/07/14 1.09UT TOYOKAWA-FUJI


F20240714100347




BLK:17,SNR1: 0.50748 ,SNR2: 2.3532



T20240714100345





BLK:31,SNR1: 19.775 ,SNR2: 100.15





3C147 2024/07/14 1.09UT TOYOKAWA-KISO


K20240714100342




BLK:31,SNR1: 2.5000 ,SNR2: 7.3366





F20240714100347




BLK:25,SNR1: 0.32194 ,SNR2: 4.1879




K20240714100342




BLK:25,SNR1: 2.5453 ,SNR2: 10.335




3C147 2024/07/14 1.09UT FUJI -KISO



T20240714101157




BLK:10,SNR1: 0.59226 ,SNR2: 5.7708





0548+16 2024/07/14 1.23UT TOYOKAWA-FUJI

F20240714101159




BLK:10,SNR1:-0.24545 ,SNR2: 0.0000






T20240714101157





BLK:13,SNR1: 0.85734 ,SNR2: 7.6011





0548+16 2024/07/14 1.23UT TOYOKAWA-KISO



K20240714101154




BLK:13,SNR1: 0.20210 ,SNR2: 1.0502





F20240714101159




BLK: 7,SNR1:-0.11434 ,SNR2: 2.3358




K20240714101154




BLK: 7,SNR1: 0.77600 ,SNR2: 4.5348




0548+16 2024/07/14 1.23UT FUJI -KISO



T20240714101607





BLK:14,SNR1: 5.8154 ,SNR2: 40.067





0552+12 2024/07/14 1.30UT TOYOKAWA-FUJI



F20240714101609




BLK:14,SNR1: 3.3725 ,SNR2: 11.572



T20240714101607





BLK:20,SNR1: 6.3262 ,SNR2: 21.955




Frequency (Hz)

0552+12 2024/07/14 1.30UT TOYOKAWA-KISO


K20240714101604




BLK:20,SNR1: 5.9360 ,SNR2: 14.790




Frequency (Hz)





F20240714101609




BLK:18,SNR1: 5.0152 ,SNR2: 12.703




K20240714101604





BLK:18,SNR1: 7.9005 ,SNR2: 19.592




0552+12 2024/07/14 1.30UT FUJI -KISO





T20240714102034




BLK:15,SNR1: 0.19592 ,SNR2: 2.3820




F20240714102036





BLK:15,SNR1: 0.40993 ,SNR2: 3.5455




0556+191 2024/07/14 1.37UT TOYOKAWA-FUJI



T20240714102034





BLK:11,SNR1: 0.10812 ,SNR2: 1.3633




Frequency (Hz)

K20240714102031




BLK:11,SNR1: 0.38206 ,SNR2: 1.9321





Frequency (Hz)


0556+191 2024/07/14 1.37UT TOYOKAWA-KISO





F20240714102036




BLK:13,SNR1: 0.95177 ,SNR2: 4.2684




K20240714102031



BLK:13,SNR1: 0.36121 ,SNR2: 2.7770





0556+191 2024/07/14 1.37UT FUJI -KISO






T20240714102820





BLK:27,SNR1: 3.0093 ,SNR2: 7.4355




Frequency (Hz)

F20240714102822




BLK:27,SNR1: 3.0191 ,SNR2: 10.152





Frequency (Hz)


0605-08 2024/07/14 1.50UT TOYOKAWA-FUJI



T20240714102820





BLK:28,SNR1: 4.3433 ,SNR2: 9.8790




Frequency (Hz)

0605-08 2024/07/14 1.50UT TOYOKAWA-KISO


K20240714102817




BLK:28,SNR1: 6.3167 ,SNR2: 17.932




Frequency (Hz)




F20240714102822




BLK:31,SNR1: 2.9737 ,SNR2: 10.157




K20240714102817




BLK:31,SNR1: 6.7709 ,SNR2: 18.907




0605-08 2024/07/14 1.50UT FUJI -KISO




T20240714104728




BLK:19,SNR1: 1.6287 ,SNR2: 13.062




F20240714104730




BLK:19,SNR1: 0.26224 ,SNR2: 3.2220




3C161 2024/07/14 1.82UT TOYOKAWA-FUJI



T20240714104728




BLK:36,SNR1: 1.4518 ,SNR2: 11.499




3C161 2024/07/14 1.82UT TOYOKAWA-KISO


K20240714104725




BLK:36,SNR1: 0.67223 ,SNR2: 5.5674




Frequency (Hz)




F20240714104730




BLK:19,SNR1: 0.28015 ,SNR2: 3.2733




K20240714104725




BLK:19,SNR1: 0.79534 ,SNR2: 4.3977




3C161 2024/07/14 1.82UT FUJI -KISO



T20240714111501




BLK: 4,SNR1: 0.43814 ,SNR2: 2.4520




0652-130 2024/07/14 2.28UT TOYOKAWA-FUJI


F20240714111503





BLK: 4,SNR1: 8.2108 ,SNR2: 19.709




Frequency (Hz)



T20240714111501





BLK:13,SNR1: 0.21308 ,SNR2: 0.81614




Frequency (Hz)

K20240714111458




BLK:13,SNR1: 1.3093 ,SNR2: 6.0320




Frequency (Hz)

0652-130 2024/07/14 2.28UT TOYOKAWA-KISO








F20240714111503




BLK:14,SNR1: 1.9987 ,SNR2: 9.3043




K20240714111458





BLK:14,SNR1: 3.0228 ,SNR2: 7.7398




0652-130 2024/07/14 2.28UT FUJI -KISO





T20240714112637




BLK:21,SNR1: 0.40776 ,SNR2: 1.9788




F20240714112639





BLK:21,SNR1: 1.7881 ,SNR2: 6.1762




0703+138 2024/07/14 2.47UT TOYOKAWA-FUJI




T20240714112637




BLK:15,SNR1: 0.31886 ,SNR2: 3.2255




K20240714112634





BLK:15,SNR1: 0.98004 ,SNR2: 4.2337




0703+138 2024/07/14 2.47UT TOYOKAWA-KISO





F20240714112639




BLK:18,SNR1: 1.3649 ,SNR2: 3.1521




K20240714112634




BLK:18,SNR1: 1.0042 ,SNR2: 4.0583




0703+138 2024/07/14 2.47UT FUJI -KISO





T20240714113600




BLK:21,SNR1: 1.7416 ,SNR2: 12.715




F20240714113602




BLK:21,SNR1: 0.59994 ,SNR2: 5.5217




0713-024 2024/07/14 2.63UT TOYOKAWA-FUJI



T20240714113600




BLK:29,SNR1: 1.5638 ,SNR2: 11.471





0713-024 2024/07/14 2.63UT TOYOKAWA-KISO


K20240714113557




BLK:29,SNR1: 0.77341 ,SNR2: 3.2688




F20240714113602




BLK:19,SNR1: 1.2132 ,SNR2: 4.1190




K20240714113557




BLK:19,SNR1: 3.2335 ,SNR2: 11.213




0713-024 2024/07/14 2.63UT FUJI -KISO




T20240714114612




BLK:30,SNR1: 29.181 ,SNR2: 141.02




F20240714114614



BLK:30,SNR1: -0.59525E-01,SNR2: 2.6251




0723+10 2024/07/14 2.80UT TOYOKAWA-FUJI







T20240714114612




BLK:24,SNR1: 25.866 ,SNR2: 124.90




K20240714114609




BLK:24,SNR1: 0.50011 ,SNR2: 2.3010




0723+10 2024/07/14 2.80UT TOYOKAWA-KISO




F20240714114614




BLK:21,SNR1:-0.61925E-01,SNR2: 2.6209




K20240714114609





BLK:21,SNR1: 0.38731 ,SNR2: 2.3188




0723+10 2024/07/14 2.80UT FUJI -KISO





T20240714115626




BLK:30,SNR1: 13.912 ,SNR2: 47.015




F20240714115628




BLK:30,SNR1: 2.5061 ,SNR2: 8.6969




0732+33 2024/07/14 2.97UT TOYOKAWA-FUJI



T20240714115626




BLK:28,SNR1: 14.613 ,SNR2: 49.461





0732+33 2024/07/14 2.97UT TOYOKAWA-KISO



K20240714115624




BLK:28,SNR1: 9.7241 ,SNR2: 19.106



F20240714115628





BLK:23,SNR1: 3.5610 ,SNR2: 7.7962





0732+33 2024/07/14 2.97UT FUJI -KISO


K20240714115624




BLK:23,SNR1: 7.7772 ,SNR2: 27.421




T20240714120428




BLK:28,SNR1: 50.831 ,SNR2: 115.93




F20240714120430




BLK:28,SNR1: 0.39420 ,SNR2: 4.2186




0741-06 2024/07/14 3.10UT TOYOKAWA-FUJI




T20240714120428




BLK:24,SNR1: 59.463 ,SNR2: 137.09




K20240714120425




BLK:24,SNR1: 0.56895 ,SNR2: 2.9461




0741-06 2024/07/14 3.10UT TOYOKAWA-KISO





F20240714120430




BLK:19,SNR1: 0.90463 ,SNR2: 6.7442




K20240714120425



BLK:19,SNR1: 0.70076 ,SNR2: 3.7304




0741-06 2024/07/14 3.10UT FUJI -KISO







T20240714121413




BLK: 7,SNR1: 0.15636 ,SNR2: 1.9132




F20240714121415




BLK: 7,SNR1: 0.12235 ,SNR2: 1.3138




0752-200 2024/07/14 3.27UT TOYOKAWA-FUJI



T20240714121413





BLK:12,SNR1: 0.21225 ,SNR2: 1.5563





0752-200 2024/07/14 3.27UT TOYOKAWA-KISO


K20240714121410




BLK:12,SNR1: 0.38130 ,SNR2: 4.2033



F20240714121415




BLK: 5,SNR1: 0.19195 ,SNR2: 1.1357





0752-200 2024/07/14 3.27UT FUJI -KISO



K20240714121410




BLK: 5,SNR1: 0.19515 ,SNR2: 0.79642





T20240714122148




BLK:15,SNR1: 0.66545 ,SNR2: 3.3656




F20240714122150




BLK:15,SNR1: 0.28681 ,SNR2: 3.5103




3C190 2024/07/14 3.39UT TOYOKAWA-FUJI





T20240714122148




BLK:24,SNR1: 0.95176 ,SNR2: 4.9317




K20240714122145





BLK:24,SNR1: 0.55612 ,SNR2: 4.0254




3C190 2024/07/14 3.39UT TOYOKAWA-KISO





F20240714122150




BLK:16,SNR1: 1.5136 ,SNR2: 7.1925




K20240714122145





BLK:16,SNR1: 0.29975 ,SNR2: 1.5884




3C190 2024/07/14 3.39UT FUJI -KISO




T20240714123412




BLK:12,SNR1: 297.76 ,SNR2: 279.85




F20240714123414





BLK:12,SNR1: 0.15351 ,SNR2: 2.0482




3C196 2024/07/14 3.60UT TOYOKAWA-FUJI




T20240714123412




BLK:19,SNR1: 320.70 ,SNR2: 301.41




K20240714123409



BLK:19,SNR1: 4.5203 ,SNR2: 8.9185




3C196 2024/07/14 3.60UT TOYOKAWA-KISO






F20240714123414




BLK: 8,SNR1: 4.0180 ,SNR2: 9.6719





3C196 2024/07/14 3.60UT FUJI -KISO


K20240714123409




BLK: 8,SNR1: 7.5058 ,SNR2: 14.821




T20240714124522




BLK:21,SNR1: 31.384 ,SNR2: 43.336




F20240714124524




BLK:21,SNR1: 72.712 ,SNR2: 80.232




0821+394 2024/07/14 3.78UT TOYOKAWA-FUJI




T20240714124522




BLK:18,SNR1: 12.793 ,SNR2: 26.810




K20240714124519




BLK:18,SNR1: 0.52500 ,SNR2: 2.2092




0821+394 2024/07/14 3.78UT TOYOKAWA-KISO




F20240714124524




BLK:11,SNR1: 38.707 ,SNR2: 63.013




K20240714124519





BLK:11,SNR1: 0.41279 ,SNR2: 3.6465




0821+394 2024/07/14 3.78UT FUJI -KISO





T20240714125702




BLK:10,SNR1:-0.20362E-01,SNR2: 0.98802




F20240714125704





BLK:10,SNR1: 0.61557 ,SNR2: 3.7593




0834-19 2024/07/14 3.98UT TOYOKAWA-FUJI





T20240714125702




BLK: 8,SNR1: 0.30707 ,SNR2: 1.8618




K20240714125659




BLK: 8,SNR1: 0.83964 ,SNR2: 3.4214




0834-19 2024/07/14 3.98UT TOYOKAWA-KISO





F20240714125704




BLK: 6,SNR1: 0.27725 ,SNR2: 1.3579




K20240714125659





BLK: 6,SNR1: 0.27697 ,SNR2: 0.92506




0834-19 2024/07/14 3.98UT FUJI -KISO





T20240714130207




BLK: 6,SNR1: 4.4406 ,SNR2: 27.053




F20240714130209







BLK: 6,SNR1: 0.57498 ,SNR2: 1.2749




0839-071 2024/07/14 4.06UT TOYOKAWA-FUJI










0839-071 2024/07/14 4.06UT TOYOKAWA-KISO



F20240714130209





BLK: 1,SNR1: 0.41924 ,SNR2: 5.7859




Frequency (Hz)

K20240714130204




BLK: 1,SNR1: 0.25184 ,SNR2: 1.0796





Frequency (Hz)


0839-071 2024/07/14 4.06UT FUJI -KISO





T20240714131308




BLK:24,SNR1: 1.0905 ,SNR2: 3.0537




F20240714131310




BLK:24,SNR1: 14.462 ,SNR2: 65.316




3C208 2024/07/14 4.25UT TOYOKAWA-FUJI





T20240714131308




BLK:32,SNR1: 0.96269 ,SNR2: 8.5686




K20240714131305





BLK:32,SNR1: 1.2717 ,SNR2: 4.2261




3C208 2024/07/14 4.25UT TOYOKAWA-KISO



F20240714131310





BLK:19,SNR1: 15.184 ,SNR2: 59.567





3C208 2024/07/14 4.25UT FUJI -KISO



K20240714131305




BLK:19,SNR1: 2.0067 ,SNR2: 6.6542




T20240714132949




BLK: 9,SNR1: 0.21762 ,SNR2: 3.3626




F20240714132951





BLK: 9,SNR1: 0.34414 ,SNR2: 1.5890




3C216 2024/07/14 4.53UT TOYOKAWA-FUJI





T20240714132949




BLK:19,SNR1: 0.23578 ,SNR2: 0.74358




K20240714132947





BLK:19,SNR1: 0.12891 ,SNR2: 1.1785




3C216 2024/07/14 4.53UT TOYOKAWA-KISO





F20240714132951




BLK: 3,SNR1:-0.90332E-02,SNR2: 1.0405




K20240714132947



BLK: 3,SNR1: 0.23899 ,SNR2: 1.6906





3C216 2024/07/14 4.53UT FUJI -KISO






T20240714134201





BLK: 2,SNR1:-0.42386E-01,SNR2: 0.53865




Frequency (Hz)

F20240714134203




BLK: 2,SNR1:-0.19832 ,SNR2: 0.76569





Frequency (Hz)


0919-142 2024/07/14 4.73UT TOYOKAWA-FUJI





T20240714134201




BLK: 7,SNR1:-0.13088E-01,SNR2: 0.55297




K20240714134158





BLK: 7,SNR1: 0.48604 ,SNR2: 2.4291




0919-142 2024/07/14 4.73UT TOYOKAWA-KISO





F20240714134203




BLK: 5,SNR1: 0.10177 ,SNR2: 2.5442




K20240714134158





BLK: 5,SNR1: 1.2311 ,SNR2: 4.9334




0919-142 2024/07/14 4.73UT FUJI -KISO




T20240714134840




BLK: 4,SNR1: 0.12961 ,SNR2: 0.80623




F20240714134842





BLK: 4,SNR1: 0.31425 ,SNR2: 1.1606




0926+117 2024/07/14 4.84UT TOYOKAWA-FUJI





T20240714134840




BLK: 2,SNR1:-0.79076E-01,SNR2: 0.93469




K20240714134837




BLK: 2,SNR1: 0.63746 ,SNR2: 3.2475




0926+117 2024/07/14 4.84UT TOYOKAWA-KISO





F20240714134842




BLK: 3,SNR1: 0.67105 ,SNR2: 2.4163




K20240714134837





BLK: 3,SNR1: 0.85494 ,SNR2: 7.0330




0926+117 2024/07/14 4.84UT FUJI -KISO




T20240714135625




BLK: 7,SNR1: 0.77728 ,SNR2: 12.090




F20240714135627





BLK: 7,SNR1: 0.37332E-01,SNR2: 2.4619




3C222 2024/07/14 4.97UT TOYOKAWA-FUJI





T20240714135625




BLK:13,SNR1: 0.40479 ,SNR2: 2.4021




K20240714135622



BLK:13,SNR1: 0.49795 ,SNR2: 2.4567




3C222 2024/07/14 4.97UT TOYOKAWA-KISO








F20240714135627




BLK:11,SNR1: 0.23830 ,SNR2: 3.9205




K20240714135622





BLK:11,SNR1: 1.2032 ,SNR2: 4.7072




3C222 2024/07/14 4.97UT FUJI -KISO




T20240714140325




BLK:10,SNR1: 0.21628 ,SNR2: 1.3533




F20240714140327





BLK:10,SNR1: 1.8502 ,SNR2: 7.4408




0941-08 2024/07/14 5.09UT TOYOKAWA-FUJI





T20240714140325




BLK: 7,SNR1: 0.26473 ,SNR2: 1.7300




K20240714140322




BLK: 7,SNR1: 3.0304 ,SNR2: 13.237




0941-08 2024/07/14 5.09UT TOYOKAWA-KISO





F20240714140327




BLK:12,SNR1: 2.0934 ,SNR2: 9.7344




K20240714140322





BLK:12,SNR1: 2.8501 ,SNR2: 12.460




0941-08 2024/07/14 5.09UT FUJI -KISO




T20240714141147




BLK: 7,SNR1: 0.19333 ,SNR2: 2.0624




F20240714141149





BLK: 7,SNR1: 0.15466 ,SNR2: 1.6637




3C230 2024/07/14 5.22UT TOYOKAWA-FUJI





T20240714141147




BLK:16,SNR1: 0.24209 ,SNR2: 3.7601




K20240714141144




BLK:16,SNR1: 0.31085 ,SNR2: 2.9964




3C230 2024/07/14 5.22UT TOYOKAWA-KISO





F20240714141149




BLK: 5,SNR1: 0.94731E-02,SNR2: 1.1637




K20240714141144





BLK: 5,SNR1: 0.20578 ,SNR2: 0.77405




3C230 2024/07/14 5.22UT FUJI -KISO



T20240714142747




BLK:15,SNR1: 0.93310 ,SNR2: 6.8774




Frequency (Hz)

F20240714142749




BLK:15,SNR1: 1.3790 ,SNR2: 6.1755





Frequency (Hz)

3C237 2024/07/14 5.49UT TOYOKAWA-FUJI








T20240714142747




BLK:28,SNR1: 0.94505 ,SNR2: 7.4824




K20240714142744




BLK:28,SNR1: 0.53579 ,SNR2: 4.3957




3C237 2024/07/14 5.49UT TOYOKAWA-KISO





F20240714142749




BLK:15,SNR1: 4.8747 ,SNR2: 10.682




K20240714142744





BLK:15,SNR1: 0.86064 ,SNR2: 6.5269




3C237 2024/07/14 5.49UT FUJI -KISO





T20240714143404




BLK: 4,SNR1:-0.85894E-01,SNR2: 0.79905




F20240714143406





BLK: 4,SNR1: 2.2703 ,SNR2: 10.655




1011+110 2024/07/14 5.60UT TOYOKAWA-FUJI





T20240714143404




BLK: 1,SNR1: 0.11787 ,SNR2: 0.53164




K20240714143401




BLK: 1,SNR1: 0.84475 ,SNR2: 2.9599




1011+110 2024/07/14 5.60UT TOYOKAWA-KISO




F20240714143406




BLK:10,SNR1: 0.70271 ,SNR2: 5.4433




K20240714143401





BLK:10,SNR1: 0.17840 ,SNR2: 0.63850




1011+110 2024/07/14 5.60UT FUJI -KISO




T20240714144144




BLK:16,SNR1: 0.27521 ,SNR2: 2.2047




F20240714144146





BLK:16,SNR1: 0.99538 ,SNR2: 10.099




3C241 2024/07/14 5.72UT TOYOKAWA-FUJI




T20240714144144




BLK:10,SNR1: 0.37943 ,SNR2: 2.4932




K20240714144141




BLK:10,SNR1: 2.5498 ,SNR2: 16.670




3C241 2024/07/14 5.72UT TOYOKAWA-KISO



F20240714144146





BLK:15,SNR1: 0.58077 ,SNR2: 8.2514




Frequency (Hz)

K20240714144141




BLK:15,SNR1: 1.7063 ,SNR2: 7.4349





Frequency (Hz)

3C241 2024/07/14 5.72UT FUJI -KISO







T20240714145314




BLK: 7,SNR1: 1.1310 ,SNR2: 2.5599




F20240714145316





BLK: 7,SNR1: 0.30653E-01,SNR2: 0.94150




1031-11 2024/07/14 5.92UT TOYOKAWA-FUJI





T20240714145314




BLK:12,SNR1: 0.97927 ,SNR2: 3.2838




K20240714145311




BLK:12,SNR1: 1.2232 ,SNR2: 4.6249




1031-11 2024/07/14 5.92UT TOYOKAWA-KISO





F20240714145316




BLK: 7,SNR1:-0.36563E-01,SNR2: 1.3106




K20240714145311





BLK: 7,SNR1: 0.97559 ,SNR2: 3.3163




1031-11 2024/07/14 5.92UT FUJI -KISO





T20240714145747




BLK: 8,SNR1: 1.0830 ,SNR2: 3.6584




F20240714145749




BLK: 8,SNR1: 0.15293 ,SNR2: 1.3147




1035-058 2024/07/14 5.99UT TOYOKAWA-FUJI





T20240714145747




BLK: 7,SNR1: 0.86761 ,SNR2: 6.3710




K20240714145744





BLK: 7,SNR1: 1.7260 ,SNR2: 6.9307




1035-058 2024/07/14 5.99UT TOYOKAWA-KISO





F20240714145749




BLK: 6,SNR1: 0.24021 ,SNR2: 1.9810




K20240714145744




BLK: 6,SNR1: 0.49739 ,SNR2: 3.6316




1035-058 2024/07/14 5.99UT FUJI -KISO



T20240714150700





BLK: 3,SNR1: 0.12603 ,SNR2: 1.1654




Frequency (Hz)

F20240714150702




BLK: 3,SNR1: 2.3405 ,SNR2: 11.290





Frequency (Hz)


1044-008 2024/07/14 6.14UT TOYOKAWA-FUJI





T20240714150700




BLK: 1,SNR1: 0.36753 ,SNR2: 2.6405




K20240714150657



BLK: 1,SNR1: 0.11047 ,SNR2: 0.97879




1044-008 2024/07/14 6.14UT TOYOKAWA-KISO








F20240714150702




BLK: 2,SNR1:-0.20601 ,SNR2: 0.55319




K20240714150657





BLK: 2,SNR1: 0.13164 ,SNR2: 3.3329




1044-008 2024/07/14 6.14UT FUJI -KISO





T20240714151804




BLK: 2,SNR1: 0.14127 ,SNR2: 0.64205




F20240714151806





BLK: 2,SNR1: 0.78641 ,SNR2: 1.9993




1055+01 2024/07/14 6.33UT TOYOKAWA-FUJI





T20240714151804




BLK: 5,SNR1: 0.89375E-01,SNR2: 0.45731




K20240714151801





BLK: 5,SNR1: 0.13218E-01,SNR2: 0.45081




1055+01 2024/07/14 6.33UT TOYOKAWA-KISO





F20240714151806




BLK: 2,SNR1:-0.10147 ,SNR2: 0.75117




K20240714151801





BLK: 2,SNR1: 0.48806 ,SNR2: 2.0410




1055+01 2024/07/14 6.33UT FUJI -KISO




T20240714152922




BLK: 5,SNR1: 0.74698E-01,SNR2: 1.0786




F20240714152924





BLK: 5,SNR1: 0.95583 ,SNR2: 3.2470




1107+109 2024/07/14 6.52UT TOYOKAWA-FUJI





T20240714152922




BLK: 3,SNR1: 0.10459 ,SNR2: 0.34647




K20240714152919




BLK: 3,SNR1: 1.1617 ,SNR2: 4.8421




1107+109 2024/07/14 6.52UT TOYOKAWA-KISO





F20240714152924




BLK: 5,SNR1: 1.4654 ,SNR2: 6.6777




K20240714152919





BLK: 5,SNR1: 0.92897 ,SNR2: 5.1914




1107+109 2024/07/14 6.52UT FUJI -KISO





T20240714153859




BLK: 7,SNR1: 0.30530 ,SNR2: 1.2273




F20240714153901



BLK: 7,SNR1: 0.27457 ,SNR2: 1.2462





3C255 2024/07/14 6.68UT TOYOKAWA-FUJI








T20240714153859




BLK: 6,SNR1: 0.27641 ,SNR2: 1.7579




K20240714153856




BLK: 6,SNR1: 0.91998 ,SNR2: 3.9515




3C255 2024/07/14 6.68UT TOYOKAWA-KISO





F20240714153901




BLK: 7,SNR1: 0.22603 ,SNR2: 1.2233




K20240714153856





BLK: 7,SNR1: 0.79807 ,SNR2: 4.9654




3C255 2024/07/14 6.68UT FUJI -KISO




T20240714154937




BLK:13,SNR1: 0.32600 ,SNR2: 1.4625




F20240714154939





BLK:13,SNR1: 1.2808 ,SNR2: 6.6043




1127-14 2024/07/14 6.86UT TOYOKAWA-FUJI





T20240714154937




BLK:12,SNR1: 0.35529 ,SNR2: 1.4704




K20240714154934




BLK:12,SNR1: 0.67482 ,SNR2: 3.1566




1127-14 2024/07/14 6.86UT TOYOKAWA-KISO



F20240714154939





BLK:13,SNR1: 2.5719 ,SNR2: 6.1246




Frequency (Hz)

K20240714154934




BLK:13,SNR1: 1.1932 ,SNR2: 4.5808





Frequency (Hz)


1127-14 2024/07/14 6.86UT FUJI -KISO



T20240714160257





BLK: 2,SNR1:-0.51774E-01,SNR2: 0.56535E-01




Frequency (Hz)

F20240714160259




BLK: 2,SNR1: 0.77366 ,SNR2: 6.6861





Frequency (Hz)


3C263.1 2024/07/14 7.08UT TOYOKAWA-FUJI





T20240714160257




BLK: 5,SNR1: 0.98331E-01,SNR2: 0.59902




K20240714160254





BLK: 5,SNR1: 0.22176 ,SNR2: 1.2559




3C263.1 2024/07/14 7.08UT TOYOKAWA-KISO



F20240714160259





BLK: 1,SNR1: 0.55442 ,SNR2: 4.4275




Frequency (Hz)

K20240714160254




BLK: 1,SNR1: 0.12461 ,SNR2: 0.61804





Frequency (Hz)

3C263.1 2024/07/14 7.08UT FUJI -KISO






T20240714160924





BLK:38,SNR1: 16.877 ,SNR2: 23.226




Frequency (Hz)

F20240714160926








BLK:38,SNR1: 17.395 ,SNR2: 31.007




Frequency (Hz)

3C267 2024/07/14 7.18UT TOYOKAWA-FUJI








3C267 2024/07/14 7.18UT TOYOKAWA-KISO



F20240714160926





BLK:37,SNR1: 17.499 ,SNR2: 31.192




Frequency (Hz)

K20240714160921




BLK:37,SNR1: 13.771 ,SNR2: 33.568





Frequency (Hz)


3C267 2024/07/14 7.18UT FUJI -KISO



T20240714162839





BLK:12,SNR1: 1.0032 ,SNR2: 3.2491




Frequency (Hz)

F20240714162841




BLK:12,SNR1: 2.1583 ,SNR2: 5.2489





Frequency (Hz)


1206+439 2024/07/14 7.51UT TOYOKAWA-FUJI



T20240714162839





BLK:13,SNR1: 0.28701 ,SNR2: 3.7685




Frequency (Hz)

K20240714162836




BLK:13,SNR1: 4.1636 ,SNR2: 7.9106





Frequency (Hz)


1206+439 2024/07/14 7.51UT TOYOKAWA-KISO



F20240714162841





BLK:14,SNR1: 3.4197 ,SNR2: 8.6859




Frequency (Hz)

K20240714162836




BLK:14,SNR1: 4.8189 ,SNR2: 9.3022





Frequency (Hz)


1206+439 2024/07/14 7.51UT FUJI -KISO



T20240714164829




BLK: 6,SNR1: 0.46684E-01,SNR2: 0.45376




Frequency (Hz)

F20240714164831




BLK: 6,SNR1: 1.9012 ,SNR2: 12.175





Frequency (Hz)


3C273 2024/07/14 7.84UT TOYOKAWA-FUJI





T20240714164829




BLK: 7,SNR1: 0.17839 ,SNR2: 1.6250




K20240714164826



BLK: 7,SNR1: 5.0945 ,SNR2: 20.005




3C273 2024/07/14 7.84UT TOYOKAWA-KISO






F20240714164831





BLK: 5, SNR1: 1.2030 , SNR2: 7.9715




Frequency (Hz)

K20240714164826




BLK: 5, SNR1: 2.8577 , SNR2: 11.081





Frequency (Hz)


3C273 2024/07/14 7.84UT FUJI -KISO



T20240714173517





BLK: 4,SNR1: 0.44928 ,SNR2: 3.4964




Frequency (Hz)

F20240714173519




BLK: 4,SNR1:-0.49872E-01,SNR2: 0.70056





Frequency (Hz)


1313+453 2024/07/14 8.62UT TOYOKAWA-FUJI



T20240714173517





BLK: 3,SNR1: 0.20750 ,SNR2: 1.3128




Frequency (Hz)

K20240714173514




BLK: 3,SNR1: 0.52950E-01,SNR2: 2.1683




Frequency (Hz)


1313+453 2024/07/14 8.62UT TOYOKAWA-KISO



F20240714173519




BLK: 3,SNR1:-0.11445 ,SNR2: 0.92054




Frequency (Hz)

K20240714173514




BLK: 3,SNR1: 2.4089 ,SNR2: 11.497




Frequency (Hz)


1313+453 2024/07/14 8.62UT FUJI -KISO



T20240714174523




BLK: 3,SNR1: 0.23731E-01,SNR2: 1.3224




Frequency (Hz)

F20240714174525




BLK: 3,SNR1:-0.11651 ,SNR2: 1.3305





Frequency (Hz)


1323+32 2024/07/14 8.78UT TOYOKAWA-FUJI



T20240714174523




BLK: 5,SNR1: 0.16774 ,SNR2: 2.4431




Frequency (Hz)

K20240714174520




BLK: 5,SNR1: 4.0870 ,SNR2: 10.639




Frequency (Hz)


1323+32 2024/07/14 8.78UT TOYOKAWA-KISO



F20240714174525




BLK: 6,SNR1:-0.69015E-01,SNR2: 1.7214




Frequency (Hz)

K20240714174520




BLK: 6,SNR1: 6.0568 ,SNR2: 22.153





Frequency (Hz)


1323+32 2024/07/14 8.78UT FUJI -KISO



T20240714175013




BLK:20,SNR1: 0.67183 ,SNR2: 1.8885




Frequency (Hz)

F20240714175015




BLK:20,SNR1: 0.13006 ,SNR2: 2.0854




Frequency (Hz)

3C286 2024/07/14 8.87UT TOYOKAWA-FUJI






T20240714175013





BLK:23,SNR1: 0.53149 ,SNR2: 1.4799




Frequency (Hz)

K20240714175010




BLK:23,SNR1: 3.0347 ,SNR2: 11.325




Frequency (Hz)


3C286 2024/07/14 8.87UT TOYOKAWA-KISO



F20240714175015




BLK:15,SNR1: 0.16224 ,SNR2: 1.2696




Frequency (Hz)

K20240714175010




BLK:15,SNR1: 8.0091 ,SNR2: 15.485





Frequency (Hz)


3C286 2024/07/14 8.87UT FUJI -KISO



T20240714175636




BLK: 3,SNR1: 0.70438 ,SNR2: 4.4677




Frequency (Hz)

1335+479 2024/07/14 8.97UT TOYOKAWA-FUJI


F20240714175638





BLK: 3,SNR1:-0.32631E-01,SNR2: 1.3399




Frequency (Hz)



T20240714175636





BLK: 2,SNR1: 0.66660 ,SNR2: 12.312




Frequency (Hz)

K20240714175633




BLK: 2,SNR1: 0.31556E-01,SNR2: 0.37144





Frequency (Hz)


1335+479 2024/07/14 8.97UT TOYOKAWA-KISO



F20240714175638





BLK: 5,SNR1:-0.95324E-02,SNR2: 0.77988




Frequency (Hz)

K20240714175633




BLK: 5,SNR1: 0.29667 ,SNR2: 4.0283





Frequency (Hz)


1335+479 2024/07/14 8.97UT FUJI -KISO



T20240714180041





BLK: 4,SNR1: 0.20169 ,SNR2: 1.1609




Frequency (Hz)

F20240714180043




BLK: 4,SNR1: 0.25714E-01,SNR2: 1.2273





Frequency (Hz)


1339+472 2024/07/14 9.04UT TOYOKAWA-FUJI



T20240714180041





BLK: 5,SNR1: 0.15439 ,SNR2: 0.81783




Frequency (Hz)

K20240714180039




BLK: 5,SNR1: 0.30727 ,SNR2: 2.0673





Frequency (Hz)


1339+472 2024/07/14 9.04UT TOYOKAWA-KISO



F20240714180043





BLK: 7,SNR1: 0.15248 ,SNR2: 1.0724




Frequency (Hz)

K20240714180039



BLK: 7,SNR1: 0.50843 ,SNR2: 2.2448



Frequency (Hz)

1339+472 2024/07/14 9.04UT FWJ -KISO

