




T20240716060452




BLK:16,SNR1: 4.3734 ,SNR2: 10.884




F20240716060454




BLK:16,SNR1: 5.9066 ,SNR2: 14.775




0148+274 2024/07/15 21.11UT TOYOKAWA-FUJI



T20240716060452




BLK:25,SNR1: 3.6454 ,SNR2: 9.2941




Frequency (Hz)

K20240716060449




BLK:25,SNR1: 7.4307 ,SNR2: 18.550





Frequency (Hz)

0148+274 2024/07/15 21.11UT TOYOKAWA-KISO






F20240716060454





BLK:27,SNR1: 5.0434 ,SNR2: 12.762




Frequency (Hz)

K20240716060449




BLK:27,SNR1: 7.5317 ,SNR2: 18.839





Frequency (Hz)


0148+274 2024/07/15 21.11UT FUJI -KISO



T20240716061329





BLK: 7,SNR1: 3.5218 ,SNR2: 59.506




Frequency (Hz)

F20240716061331




BLK: 7,SNR1: 0.36017 ,SNR2: 3.6221




Frequency (Hz)


0157+217 2024/07/15 21.25UT TOYOKAWA-FUJI



T20240716061329





BLK: 9,SNR1: 4.9968 ,SNR2: 23.936




Frequency (Hz)

K20240716061326




BLK: 9,SNR1: 2.5355 ,SNR2: 6.4532





Frequency (Hz)


0157+217 2024/07/15 21.25UT TOYOKAWA-KISO



F20240716061331





BLK: 9,SNR1: 0.55013 ,SNR2: 2.8411




Frequency (Hz)

K20240716061326




BLK: 9,SNR1: 0.63299 ,SNR2: 3.4181





Frequency (Hz)


0157+217 2024/07/15 21.25UT FUJI -KISO



T20240716062951





BLK:21,SNR1: 5.0726 ,SNR2: 12.148




Frequency (Hz)

F20240716062953




BLK:21,SNR1: 8.4657 ,SNR2: 21.595




Frequency (Hz)


0213+178 2024/07/15 21.53UT TOYOKAWA-FUJI



T20240716062951





BLK:27,SNR1: 7.6458 ,SNR2: 18.205




Frequency (Hz)

K20240716062949




BLK:27,SNR1: 7.8192 ,SNR2: 14.614





Frequency (Hz)


0213+178 2024/07/15 21.53UT TOYOKAWA-KISO





F20240716062953




BLK:20,SNR1: 6.8963 ,SNR2: 17.297




K20240716062949





BLK:20,SNR1: 7.0742 ,SNR2: 17.598




0213+178 2024/07/15 21.53UT FUJI -KISO



T20240716063733



BLK:14,SNR1: 2.4800 ,SNR2: 6.1531





Frequency (Hz)


3C67

2024/07/15 21.65UT TOYOKAWA-FUJI


F20240716063735



BLK:14,SNR1: 1.0552 ,SNR2: 3.8711





Frequency (Hz)






T20240716063733



BLK:15,SNR1: 2.3191 ,SNR2: 5.7731





Frequency (Hz)


3C67

2024/07/15 21.65UT TOYOKAWA-KISO


K20240716063730




BLK:15,SNR1: 13.307 ,SNR2: 12.877




Frequency (Hz)



F20240716063735





BLK:19,SNR1: 0.82855 ,SNR2: 3.2720




Frequency (Hz)

3C67 2024/07/15 21.65UT FUJI -KISO


K20240716063730





BLK:19,SNR1: 11.813 ,SNR2: 11.431




Frequency (Hz)



T20240716065548



BLK: 5, SNR1: 0.36731 ,SNR2: 3.7835





Frequency (Hz)


3C71

2024/07/15 21.96UT TOYOKAWA-FUJI


F20240716065550





BLK: 5, SNR1: 1.4437 ,SNR2: 3.7524




Frequency (Hz)



T20240716065548



BLK: 6,SNR1: 0.34610 ,SNR2: 3.6819





Frequency (Hz)


3C71

2024/07/15 21.96UT TOYOKAWA-KISO


K20240716065546





BLK: 6,SNR1: 0.39440 ,SNR2: 3.6940




Frequency (Hz)



F20240716065550





BLK: 8,SNR1: 0.92687 ,SNR2: 4.5148




Frequency (Hz)

K20240716065546




BLK: 8,SNR1: 0.42758 ,SNR2: 2.1808





Frequency (Hz)


3C71 2024/07/15 21.96UT FUJI -KISO



T20240716071503





BLK:28,SNR1: 20.347 ,SNR2: 38.151




Frequency (Hz)

F20240716071505




BLK:28,SNR1: 9.8982 ,SNR2: 23.768





Frequency (Hz)


0258+350 2024/07/15 22.28UT TOYOKAWA-FUJI



T20240716071503





BLK:27,SNR1: 20.378 ,SNR2: 38.210




Frequency (Hz)

K20240716071500




BLK:27,SNR1: 8.8820 ,SNR2: 21.724





Frequency (Hz)


0258+350 2024/07/15 22.28UT TOYOKAWA-KISO



F20240716071505





BLK:30,SNR1: 12.611 ,SNR2: 30.604




Frequency (Hz)

K20240716071500




BLK:30,SNR1: 8.5952 ,SNR2: 21.020





Frequency (Hz)

0258+350 2024/07/15 22.28UT FUJI -KISO






T20240716072452





BLK:24,SNR1: 12.013 ,SNR2: 27.407




Frequency (Hz)

F20240716072454




BLK:24,SNR1: 4.1221 ,SNR2: 9.5195





Frequency (Hz)


0308+305 2024/07/15 22.44UT TOYOKAWA-FUJI



T20240716072452





BLK:33,SNR1: 11.701 ,SNR2: 26.695




Frequency (Hz)

K20240716072449




BLK:33,SNR1: 5.9215 ,SNR2: 14.317




Frequency (Hz)


0308+305 2024/07/15 22.44UT TOYOKAWA-KISO



F20240716072454





BLK:29,SNR1: 3.7963 ,SNR2: 6.7661




Frequency (Hz)

K20240716072449




BLK:29,SNR1: 4.6495 ,SNR2: 11.624





Frequency (Hz)


0308+305 2024/07/15 22.44UT FUJI -KISO



T20240716073624




BLK:26,SNR1: 2.5914 ,SNR2: 4.5604




Frequency (Hz)

F20240716073626




BLK:26,SNR1: 2.5191 ,SNR2: 11.207





Frequency (Hz)


0320+05 2024/07/15 22.63UT TOYOKAWA-FUJI



T20240716073624





BLK:33,SNR1: 2.4333 ,SNR2: 4.2083




Frequency (Hz)

K20240716073621




BLK:33,SNR1: 10.875 ,SNR2: 19.665




Frequency (Hz)


0320+05 2024/07/15 22.63UT TOYOKAWA-KISO



F20240716073626





BLK:29,SNR1: 6.5565 ,SNR2: 15.552




Frequency (Hz)

K20240716073621




BLK:29,SNR1: 11.107 ,SNR2: 20.459





Frequency (Hz)


0320+05 2024/07/15 22.63UT FUJI -KISO



T20240716074945





BLK:28,SNR1: 6.4648 ,SNR2: 15.476




Frequency (Hz)

F20240716074947




BLK:28,SNR1: 2.2006 ,SNR2: 5.3573





Frequency (Hz)


0333+32 2024/07/15 22.86UT TOYOKAWA-FUJI



T20240716074945





BLK:30,SNR1: 6.4397 ,SNR2: 15.412




Frequency (Hz)

K20240716074943




BLK:30,SNR1: 3.6297 ,SNR2: 9.1315





Frequency (Hz)

0333+32 2024/07/15 22.86UT TOYOKAWA-KISO








F20240716074947




BLK:29,SNR1: 2.3351 ,SNR2: 5.7350




K20240716074943





BLK:29,SNR1: 3.6520 ,SNR2: 9.0782




0333+32 2024/07/15 22.86UT FUJI -KISO



T20240716080247





BLK:20,SNR1: 2.9144 ,SNR2: 13.822




Frequency (Hz)

0347+05 2024/07/15 23.07UT TOYOKAWA-FUJI


F20240716080249





BLK:20,SNR1: 19.195 ,SNR2: 35.375




Frequency (Hz)



T20240716080247





BLK:29,SNR1: 2.9131 ,SNR2: 13.816





0347+05 2024/07/15 23.07UT TOYOKAWA-KISO



K20240716080244




BLK:29,SNR1: 10.062 ,SNR2: 25.084



F20240716080249





BLK:28,SNR1: 17.096 ,SNR2: 31.833




Frequency (Hz)

0347+05 2024/07/15 23.07UT FUJI -KISO


K20240716080244




BLK:28,SNR1: 13.371 ,SNR2: 32.603




Frequency (Hz)



T20240716081821




BLK: 7,SNR1: 0.67180 ,SNR2: 1.8021




Frequency (Hz)

F20240716081823




BLK: 7,SNR1: 0.10271 ,SNR2: 1.0588




Frequency (Hz)


0403-132 2024/07/15 23.33UT TOYOKAWA-FUJI





T20240716081821




BLK:13,SNR1: 5.1921 ,SNR2: 9.2521




K20240716081819




BLK:13,SNR1: 1.6262 ,SNR2: 6.4367




0403-132 2024/07/15 23.33UT TOYOKAWA-KISO



F20240716081823





BLK: 2,SNR1: 1.1999 ,SNR2: 2.0666




Frequency (Hz)

K20240716081819




BLK: 2,SNR1: 0.41232 ,SNR2: 1.6789




Frequency (Hz)


0403-132 2024/07/15 23.33UT FUJI -KISO



T20240716082732




BLK:13,SNR1: 3.6808 ,SNR2: 9.5372





0411+05 2024/07/15 23.49UT TOYOKAWA-FUJI

F20240716082734




BLK:13,SNR1: 2.0248 ,SNR2: 4.5948







T20240716082732




BLK: 8,SNR1: 4.9120 ,SNR2: 12.137




K20240716082729





BLK: 8,SNR1: 3.0755 ,SNR2: 6.0893




0411+05 2024/07/15 23.49UT TOYOKAWA-KISO



F20240716082734





BLK:11,SNR1: 1.6535 ,SNR2: 5.6934




Frequency (Hz)

K20240716082729




BLK:11,SNR1: 2.5258 ,SNR2: 4.9883





Frequency (Hz)


0411+05 2024/07/15 23.49UT FUJI -KISO



T20240716083426





BLK:32,SNR1: 2.4453 ,SNR2: 11.961




Frequency (Hz)

F20240716083428




BLK:32,SNR1: 7.4319 ,SNR2: 21.188





Frequency (Hz)


0418+236 2024/07/15 23.60UT TOYOKAWA-FUJI



T20240716083426





BLK:34,SNR1: 2.4453 ,SNR2: 11.961




Frequency (Hz)

K20240716083423




BLK:34,SNR1: 8.6832 ,SNR2: 16.205





Frequency (Hz)


0418+236 2024/07/15 23.60UT TOYOKAWA-KISO



F20240716083428





BLK:32,SNR1: 7.4323 ,SNR2: 21.189




Frequency (Hz)

K20240716083423




BLK:32,SNR1: 8.6825 ,SNR2: 16.204




Frequency (Hz)


0418+236 2024/07/15 23.60UT FUJI -KISO



T20240716084553




BLK:21,SNR1: 2.7738 ,SNR2: 15.239




Frequency (Hz)

F20240716084555




BLK:21,SNR1: 0.18732 ,SNR2: 3.2226





Frequency (Hz)


3C119 2024/07/15 23.79UT TOYOKAWA-FUJI



T20240716084553





BLK:22,SNR1: 2.9130 ,SNR2: 14.422




Frequency (Hz)

K20240716084551




BLK:22,SNR1: 0.62678 ,SNR2: 2.9343





Frequency (Hz)


3C119 2024/07/15 23.79UT TOYOKAWA-KISO



F20240716084555





BLK:32,SNR1: 0.17924 ,SNR2: 2.6350




Frequency (Hz)

K20240716084551




BLK:32,SNR1: 0.70808 ,SNR2: 6.0336





Frequency (Hz)

3C119 2024/07/15 23.79UT FUJI -KISO






T20240716085307





BLK:10,SNR1: 3.0797 ,SNR2: 13.569




Frequency (Hz)

F20240716085309




BLK:10,SNR1: 0.91761 ,SNR2: 2.4791





Frequency (Hz)


0437+114 2024/07/15 23.91UT TOYOKAWA-FUJI



T20240716085307





BLK:14,SNR1: 2.9902 ,SNR2: 13.230




Frequency (Hz)

K20240716085304




BLK:14,SNR1: 0.54887 ,SNR2: 2.1726





Frequency (Hz)


0437+114 2024/07/15 23.91UT TOYOKAWA-KISO





F20240716085309




BLK: 4, SNR1: 1.0229 , SNR2: 3.5491




K20240716085304





BLK: 4, SNR1: 0.96832 , SNR2: 3.7971




0437+114 2024/07/15 23.91UT FUJI -KISO



T20240716093400





BLK:21,SNR1: 1.3539 ,SNR2: 6.2297




Frequency (Hz)

F20240716093402




BLK:21,SNR1: 2.4783 ,SNR2: 6.7789





Frequency (Hz)


3C138 2024/07/16 0.59UT TOYOKAWA-FUJI





T20240716093400




BLK:24,SNR1: 1.4123 ,SNR2: 6.4791




K20240716093357





BLK:24,SNR1: 1.3050 ,SNR2: 4.9106




3C138 2024/07/16 0.59UT TOYOKAWA-KISO



F20240716093402





BLK:22,SNR1: 2.1330 ,SNR2: 5.7476




Frequency (Hz)

3C138 2024/07/16 0.59UT FUJI -KISO


K20240716093357





BLK:22,SNR1: 2.5087 ,SNR2: 11.683




Frequency (Hz)




T20240716094734




BLK:21,SNR1: 1.6064 ,SNR2: 12.146




F20240716094736





BLK:21,SNR1: 0.31832 ,SNR2: 2.6590




0531+194 2024/07/16 0.82UT TOYOKAWA-FUJI




T20240716094734




BLK:28,SNR1: 1.7533 ,SNR2: 12.719




K20240716094731



BLK:28,SNR1: 0.66338 ,SNR2: 3.1965




0531+194 2024/07/16 0.82UT TOYOKAWA-KISO








F20240716094736




BLK:16,SNR1: 0.45233 ,SNR2: 3.1919




K20240716094731





BLK:16,SNR1: 0.27544 ,SNR2: 2.1508




0531+194 2024/07/16 0.82UT FUJI -KISO



T20240716095553





BLK:24,SNR1: 7.3212 ,SNR2: 17.245




Frequency (Hz)

3C147 2024/07/16 0.96UT TOYOKAWA-FUJI


F20240716095555




BLK:24,SNR1: 0.78690 ,SNR2: 3.3539




Frequency (Hz)





T20240716095553




BLK:32,SNR1: 7.2913 ,SNR2: 25.108




K20240716095550





BLK:32,SNR1: 2.0502 ,SNR2: 4.1138




3C147 2024/07/16 0.96UT TOYOKAWA-KISO





F20240716095555




BLK:27,SNR1: 0.90804 ,SNR2: 3.0916




K20240716095550





BLK:27,SNR1: 2.8418 ,SNR2: 5.6626




3C147 2024/07/16 0.96UT FUJI -KISO





T20240716100405




BLK:14,SNR1: 1.1970 ,SNR2: 2.0512




F20240716100407




BLK:14,SNR1: 2.2453 ,SNR2: 5.9190




0548+16 2024/07/16 1.10UT TOYOKAWA-FUJI



T20240716100405




BLK:15,SNR1: 0.62866 ,SNR2: 2.9348





0548+16 2024/07/16 1.10UT TOYOKAWA-KISO



K20240716100402




BLK:15,SNR1: 1.8719 ,SNR2: 8.7073





F20240716100407




BLK:24,SNR1: 2.3322 ,SNR2: 6.0648




K20240716100402





BLK:24,SNR1: 2.5079 ,SNR2: 8.9120




0548+16 2024/07/16 1.10UT FUJI -KISO



T20240716100816





BLK:14,SNR1: 6.6592 ,SNR2: 53.842




Frequency (Hz)

F20240716100818




BLK:14,SNR1: 2.9982 ,SNR2: 13.075





Frequency (Hz)

0552+12 2024/07/16 1.17UT TOYOKAWA-FUJI






T20240716100816





BLK:14,SNR1: 13.444 ,SNR2: 55.390




Frequency (Hz)

K20240716100813




BLK:14,SNR1: 0.67503 ,SNR2: 3.3884





Frequency (Hz)


0552+12 2024/07/16 1.17UT TOYOKAWA-KISO




F20240716100818




BLK:21,SNR1: 2.9638 ,SNR2: 12.939




K20240716100813





BLK:21,SNR1: 2.9126 ,SNR2: 10.395




0552+12 2024/07/16 1.17UT FUJI -KISO





T20240716101242




BLK: 8,SNR1: 0.23767 ,SNR2: 1.5280




F20240716101244





BLK: 8,SNR1: 0.90967 ,SNR2: 4.2582




0556+191 2024/07/16 1.24UT TOYOKAWA-FUJI



T20240716101242





BLK: 9,SNR1: 0.19836 ,SNR2: 2.2235





0556+191 2024/07/16 1.24UT TOYOKAWA-KISO


K20240716101239




BLK: 9,SNR1: 0.11639 ,SNR2: 1.3032



F20240716101244




BLK: 6,SNR1: 0.43277 ,SNR2: 2.6171




Frequency (Hz)

K20240716101239




BLK: 6,SNR1: 0.36994 ,SNR2: 1.5426





Frequency (Hz)


0556+191 2024/07/16 1.24UT FUJI -KISO





T20240716102028




BLK: 3,SNR1: 0.52022 ,SNR2: 3.3916




F20240716102030





BLK: 3,SNR1: 0.75097 ,SNR2: 6.9154




0605-08 2024/07/16 1.37UT TOYOKAWA-FUJI



T20240716102028





BLK: 3,SNR1: 0.26013 ,SNR2: 1.3796




0605-08 2024/07/16 1.37UT TOYOKAWA-KISO


K20240716102025





BLK: 3,SNR1: 0.46171 ,SNR2: 1.8861




Frequency (Hz)



F20240716102030




BLK: 9,SNR1: 0.81039 ,SNR2: 2.0040




Frequency (Hz)

K20240716102025




BLK: 9,SNR1: 0.80014 ,SNR2: 3.8483





Frequency (Hz)

0605-08 2024/07/16 1.37UT FUJI -KISO








T20240716103936




BLK:17,SNR1: 57.564 ,SNR2: 73.509




F20240716103938





BLK:17,SNR1: 62.817 ,SNR2: 82.269




3C161 2024/07/16 1.69UT TOYOKAWA-FUJI



T20240716103936





BLK:22,SNR1: 50.913 ,SNR2: 72.770




Frequency (Hz)

3C161 2024/07/16 1.69UT TOYOKAWA-KISO


K20240716103933





BLK:22,SNR1: 1.0757 ,SNR2: 4.8865




Frequency (Hz)




F20240716103938




BLK:21,SNR1: 62.435 ,SNR2: 81.242




K20240716103933





BLK:21,SNR1: 6.0158 ,SNR2: 10.806




3C161 2024/07/16 1.69UT FUJI -KISO



T20240716110709




BLK: 3,SNR1: 0.36735 ,SNR2: 3.2211




0652-130 2024/07/16 2.15UT TOYOKAWA-FUJI


F20240716110711





BLK: 3,SNR1:-0.33305 ,SNR2: 0.32441




Frequency (Hz)



T20240716110709




BLK: 7,SNR1: 59.318 ,SNR2: 59.913




0652-130 2024/07/16 2.15UT TOYOKAWA-KISO


K20240716110706







BLK: 7,SNR1: 0.12480 ,SNR2: 0.47909




Frequency (Hz)







0652-130 2024/07/16 2.15UT FUJI -KISO




T20240716111845




BLK:20,SNR1: 2.9646 ,SNR2: 10.423




F20240716111847




BLK:20,SNR1: 0.86086E-01,SNR2: 1.0889




0703+138 2024/07/16 2.34UT TOYOKAWA-FUJI




T20240716111845




BLK:10,SNR1: 0.94355 ,SNR2: 3.3289




K20240716111842



BLK:10,SNR1: 0.29978 ,SNR2: 0.85407




0703+138 2024/07/16 2.34UT TOYOKAWA-KISO







F20240716111847




BLK:16,SNR1: 0.38849 ,SNR2: 2.5499




K20240716111842




BLK:16,SNR1: 2.5523 ,SNR2: 11.171




0703+138 2024/07/16 2.34UT FUJI -KISO




T20240716112808




BLK:13,SNR1: 38.163 ,SNR2: 73.194




F20240716112810




BLK:13,SNR1: 0.32273 ,SNR2: 1.7657




0713-024 2024/07/16 2.50UT TOYOKAWA-FUJI



T20240716112808




BLK:23,SNR1: 23.920 ,SNR2: 90.084





0713-024 2024/07/16 2.50UT TOYOKAWA-KISO


K20240716112805




BLK:23,SNR1: 0.21435 ,SNR2: 1.2713




F20240716112810




BLK:17,SNR1: 0.46460E-01,SNR2: 1.5184




K20240716112805





BLK:17,SNR1: 0.44762 ,SNR2: 1.3259




0713-024 2024/07/16 2.50UT FUJI -KISO



T20240716113820




BLK:27,SNR1: 5.2505 ,SNR2: 19.048




0723+10 2024/07/16 2.67UT TOYOKAWA-FUJI


F20240716113822





BLK:27,SNR1: 0.11445 ,SNR2: 2.3212




Frequency (Hz)



T20240716113820




BLK:25,SNR1: 4.9979 ,SNR2: 15.777





0723+10 2024/07/16 2.67UT TOYOKAWA-KISO



K20240716113817




BLK:25,SNR1: 0.27241 ,SNR2: 1.1296





F20240716113822




BLK:15,SNR1: 0.27168 ,SNR2: 2.7705




K20240716113817




BLK:15,SNR1: 0.27398 ,SNR2: 0.73346




0723+10 2024/07/16 2.67UT FUJI -KISO





T20240716114834




BLK:21,SNR1: 18.416 ,SNR2: 93.413




F20240716114836



BLK:21,SNR1: 2.6951 ,SNR2: 12.016





0732+33 2024/07/16 2.84UT TOYOKAWA-FUJI








T20240716114834




BLK:29,SNR1: 19.122 ,SNR2: 90.369




K20240716114831





BLK:29,SNR1: 1.7329 ,SNR2: 6.8258




0732+33 2024/07/16 2.84UT TOYOKAWA-KISO





F20240716114836




BLK:29,SNR1: 2.6115 ,SNR2: 11.461




K20240716114831





BLK:29,SNR1: 4.1360 ,SNR2: 10.117




0732+33 2024/07/16 2.84UT FUJI -KISO



T20240716115637




BLK:13,SNR1: 1.4193 ,SNR2: 11.399





0741-06 2024/07/16 2.97UT TOYOKAWA-FUJI



F20240716115639




BLK:13,SNR1: 0.59222 ,SNR2: 3.5031




T20240716115637




BLK:23,SNR1: 1.3191 ,SNR2: 7.1163




K20240716115634




BLK:23,SNR1: 0.67246 ,SNR2: 2.0497




0741-06 2024/07/16 2.97UT TOYOKAWA-KISO




F20240716115639




BLK:14,SNR1: 0.98560 ,SNR2: 4.3232




K20240716115634




BLK:14,SNR1: 0.83257 ,SNR2: 4.7486




0741-06 2024/07/16 2.97UT FUJI -KISO





T20240716120621




BLK: 4,SNR1: 0.48496 ,SNR2: 3.9291




F20240716120623





BLK: 4,SNR1:-0.13294 ,SNR2: 0.67551




0752-200 2024/07/16 3.13UT TOYOKAWA-FUJI



T20240716120621




BLK: 5,SNR1: 0.22387 ,SNR2: 2.9378





0752-200 2024/07/16 3.13UT TOYOKAWA-KISO



K20240716120618




BLK: 5,SNR1: 0.18181 ,SNR2: 0.77808



F20240716120623




BLK: 1,SNR1: 1.3452 ,SNR2: 6.3236





0752-200 2024/07/16 3.13UT FUJI -KISO

K20240716120618





BLK: 1,SNR1: 0.35335 ,SNR2: 1.0895






T20240716121356




BLK:16,SNR1: 15.320 ,SNR2: 81.673





3C190 2024/07/16 3.26UT TOYOKAWA-FUJI



F20240716121358




BLK:16,SNR1: 6.5936 ,SNR2: 31.424



T20240716121356





BLK:16,SNR1: 14.811 ,SNR2: 78.975





3C190 2024/07/16 3.26UT TOYOKAWA-KISO


K20240716121353




BLK:16,SNR1: 0.91303 ,SNR2: 4.1728



F20240716121358





BLK:13,SNR1: 6.4498 ,SNR2: 18.114





3C190 2024/07/16 3.26UT FUJI -KISO



K20240716121353




BLK:13,SNR1: 1.1065 ,SNR2: 4.9392



T20240716122620




BLK:16,SNR1: 4.6930 ,SNR2: 9.7641




Frequency (Hz)

F20240716122622




BLK:16,SNR1: 0.67336 ,SNR2: 4.3387





Frequency (Hz)


3C196 2024/07/16 3.47UT TOYOKAWA-FUJI





T20240716122620




BLK:23,SNR1: 3.5587 ,SNR2: 7.6565




K20240716122617





BLK:23,SNR1: 0.15975 ,SNR2: 0.46455




3C196 2024/07/16 3.47UT TOYOKAWA-KISO



F20240716122622




BLK: 7,SNR1: 2.7978 ,SNR2: 9.4087




Frequency (Hz)

3C196 2024/07/16 3.47UT FUJI -KISO


K20240716122617




BLK: 7,SNR1: 0.80378E-01,SNR2: 1.9245




Frequency (Hz)





T20240716123730




BLK: 9,SNR1: 0.31508 ,SNR2: 2.0633




F20240716123732





BLK: 9,SNR1: 0.87935E-01,SNR2: 0.53084




0821+394 2024/07/16 3.65UT TOYOKAWA-FUJI



T20240716123730





BLK:17,SNR1: 0.43413 ,SNR2: 1.7171





0821+394 2024/07/16 3.65UT TOYOKAWA-KISO

K20240716123727





BLK:17,SNR1: 0.11025 ,SNR2: 0.90912








F20240716123732




BLK: 8,SNR1: 0.30336 ,SNR2: 0.76315




K20240716123727




BLK: 8,SNR1: 0.15421 ,SNR2: 0.42844




0821+394 2024/07/16 3.65UT FUJI -KISO




T20240716124910




BLK: 9,SNR1: 83.767 ,SNR2: 128.82




F20240716124912





BLK: 9,SNR1:-0.65551E-01,SNR2: 1.5843




0834-19 2024/07/16 3.85UT TOYOKAWA-FUJI




T20240716124910




BLK:11,SNR1: 71.894 ,SNR2: 110.60




K20240716124907




BLK:11,SNR1: 0.13648 ,SNR2: 2.2035




0834-19 2024/07/16 3.85UT TOYOKAWA-KISO




F20240716124912




BLK: 1,SNR1:-0.62371E-01,SNR2: 2.2364




K20240716124907





BLK: 1,SNR1: 0.20878 ,SNR2: 1.0954




0834-19 2024/07/16 3.85UT FUJI -KISO



T20240716125416





BLK: 4,SNR1: 5.2648 ,SNR2: 43.568





0839-071 2024/07/16 3.93UT TOYOKAWA-FUJI



F20240716125418




BLK: 4,SNR1:-0.13097 ,SNR2: 0.82715



T20240716125416





BLK: 7,SNR1: 4.6895 ,SNR2: 43.616





0839-071 2024/07/16 3.93UT TOYOKAWA-KISO


K20240716125413




BLK: 7,SNR1: 1.2459 ,SNR2: 5.9361





F20240716125418




BLK: 5,SNR1: 3.4846 ,SNR2: 12.182




K20240716125413





BLK: 5,SNR1: 2.9720 ,SNR2: 13.028




0839-071 2024/07/16 3.93UT FUJI -KISO





T20240716130516




BLK:10,SNR1: 0.32371 ,SNR2: 2.7399




F20240716130518



BLK:10,SNR1: 0.46211 ,SNR2: 5.3831





3C208 2024/07/16 4.12UT TOYOKAWA-FUJI








T20240716130516




BLK:15,SNR1: 0.27130 ,SNR2: 2.4926




K20240716130513




BLK:15,SNR1: 0.36628 ,SNR2: 2.1134




3C208 2024/07/16 4.12UT TOYOKAWA-KISO





F20240716130518




BLK:19,SNR1: 0.51867 ,SNR2: 2.4540




K20240716130513





BLK:19,SNR1: 0.38409 ,SNR2: 2.3077




3C208 2024/07/16 4.12UT FUJI -KISO





T20240716132158




BLK: 3,SNR1:-0.14408E-02,SNR2: 0.77619




F20240716132200





BLK: 3,SNR1: 0.46315 ,SNR2: 1.5732




3C216 2024/07/16 4.39UT TOYOKAWA-FUJI





T20240716132158




BLK: 8,SNR1: 0.26031 ,SNR2: 2.3042




K20240716132155





BLK: 8,SNR1: 0.22984 ,SNR2: 2.7773




3C216 2024/07/16 4.39UT TOYOKAWA-KISO



F20240716132200





BLK: 1,SNR1: 0.15852 ,SNR2: 2.3603





3C216 2024/07/16 4.39UT FUJI -KISO



K20240716132155




BLK: 1,SNR1: 0.23899 ,SNR2: 0.84318





T20240716133409




BLK: 4,SNR1: 0.28742E-01,SNR2: 2.1291




F20240716133411





BLK: 4,SNR1: 0.43446 ,SNR2: 2.3415




0919-142 2024/07/16 4.60UT TOYOKAWA-FUJI





T20240716133409




BLK: 8,SNR1: 0.26017 ,SNR2: 1.1435




K20240716133406




BLK: 8,SNR1: 0.52472 ,SNR2: 5.4910




0919-142 2024/07/16 4.60UT TOYOKAWA-KISO





F20240716133411




BLK: 3,SNR1: 2.0438 ,SNR2: 6.4244




K20240716133406



BLK: 3,SNR1: 0.29622 ,SNR2: 2.7702





0919-142 2024/07/16 4.60UT FUJI -KISO








T20240716134048




BLK: 3,SNR1: 0.12876 ,SNR2: 1.4211




F20240716134050





BLK: 3,SNR1:-0.71213E-01,SNR2: 1.6382




0926+117 2024/07/16 4.71UT TOYOKAWA-FUJI





T20240716134048




BLK: 4,SNR1:-0.17708E-01,SNR2: 2.2506




K20240716134045




BLK: 4,SNR1: 0.23758 ,SNR2: 3.5736




0926+117 2024/07/16 4.71UT TOYOKAWA-KISO





F20240716134050




BLK: 1,SNR1: 0.12300 ,SNR2: 3.1021




K20240716134045





BLK: 1,SNR1: 0.20313E-01,SNR2: 0.64815




0926+117 2024/07/16 4.71UT FUJI -KISO





T20240716134833




BLK:10,SNR1: 0.30274 ,SNR2: 4.9784




F20240716134835





BLK:10,SNR1: 0.19606 ,SNR2: 1.3043




3C222 2024/07/16 4.84UT TOYOKAWA-FUJI





T20240716134833




BLK:13,SNR1: 0.36121 ,SNR2: 3.8703




K20240716134830




BLK:13,SNR1: 0.16761 ,SNR2: 0.32146




3C222 2024/07/16 4.84UT TOYOKAWA-KISO





F20240716134835




BLK: 6,SNR1: 0.11852 ,SNR2: 3.0735




K20240716134830





BLK: 6,SNR1: 0.74484 ,SNR2: 2.8493




3C222 2024/07/16 4.84UT FUJI -KISO




T20240716135533




BLK: 3,SNR1: 0.75271E-01,SNR2: 2.3584




F20240716135535




BLK: 3,SNR1:-0.15081 ,SNR2: 0.69739




0941-08 2024/07/16 4.95UT TOYOKAWA-FUJI





T20240716135533




BLK: 4,SNR1: 0.39818 ,SNR2: 2.5208




K20240716135530



BLK: 4,SNR1: 0.18032 ,SNR2: 0.51837




0941-08 2024/07/16 4.95UT TOYOKAWA-KISO







F20240716135535




BLK: 2,SNR1:-0.19456 ,SNR2: 0.49513




K20240716135530





BLK: 2,SNR1: 1.0271 ,SNR2: 11.201




0941-08 2024/07/16 4.95UT FUJI -KISO





T20240716140355




BLK:15,SNR1: 4.7083 ,SNR2: 11.875




F20240716140357





BLK:15,SNR1: 4.0509 ,SNR2: 10.698




3C230 2024/07/16 5.09UT TOYOKAWA-FUJI





T20240716140355




BLK:23,SNR1: 3.0766 ,SNR2: 7.4983




K20240716140352




BLK:23,SNR1: 3.3172 ,SNR2: 11.707




3C230 2024/07/16 5.09UT TOYOKAWA-KISO





F20240716140357




BLK:21,SNR1: 6.5507 ,SNR2: 15.887




K20240716140352





BLK:21,SNR1: 3.8330 ,SNR2: 13.238




3C230 2024/07/16 5.09UT FUJI -KISO





T20240716141802




BLK: 9,SNR1: 14.213 ,SNR2: 26.107




F20240716141804





BLK: 9,SNR1: 0.83628 ,SNR2: 3.2681




3C236 2024/07/16 5.33UT TOYOKAWA-FUJI





T20240716141802




BLK:11,SNR1: 10.815 ,SNR2: 24.624




K20240716141759





BLK:11,SNR1: 0.98070E-01,SNR2: 0.87735




3C236 2024/07/16 5.33UT TOYOKAWA-KISO





F20240716141804




BLK: 6,SNR1: 1.2331 ,SNR2: 2.9091




K20240716141759





BLK: 6,SNR1: 1.2882 ,SNR2: 5.5885




3C236 2024/07/16 5.33UT FUJI -KISO





T20240716142612




BLK:19,SNR1: 0.79082 ,SNR2: 2.9750




F20240716142614



BLK:19,SNR1: 7.3476 ,SNR2: 21.192





1011+110 2024/07/16 5.46UT TOYOKAWA-FUJI








T20240716142612




BLK:27,SNR1: 0.64892 ,SNR2: 2.4137




K20240716142609





BLK:27,SNR1: 2.6536 ,SNR2: 5.2840




1011+110 2024/07/16 5.46UT TOYOKAWA-KISO




F20240716142614




BLK:29,SNR1: 5.2665 ,SNR2: 12.723




K20240716142609





BLK:29,SNR1: 3.0508 ,SNR2: 11.178




1011+110 2024/07/16 5.46UT FUJI -KISO



T20240716143353




BLK: 6,SNR1: 0.23961 ,SNR2: 0.85188




Frequency (Hz)

F20240716143355




BLK: 6,SNR1: 0.18261 ,SNR2: 2.7802





Frequency (Hz)


3C241 2024/07/16 5.59UT TOYOKAWA-FUJI





T20240716143353




BLK:11,SNR1: 0.30791 ,SNR2: 1.4182




K20240716143350




BLK:11,SNR1: 3.9221 ,SNR2: 10.630




3C241 2024/07/16 5.59UT TOYOKAWA-KISO



F20240716143355





BLK:15,SNR1: 0.37647 ,SNR2: 3.7859




Frequency (Hz)

K20240716143350




BLK:15,SNR1: 1.4547 ,SNR2: 6.6240





Frequency (Hz)


3C241 2024/07/16 5.59UT FUJI -KISO




T20240716144522




BLK:12,SNR1: 1.6851 ,SNR2: 8.2395




F20240716144524





BLK:12,SNR1: 2.9744 ,SNR2: 8.9200




1031-11 2024/07/16 5.78UT TOYOKAWA-FUJI





T20240716144522




BLK:12,SNR1: 1.8876 ,SNR2: 9.2454




K20240716144519





BLK:12,SNR1: 1.6938 ,SNR2: 6.3821




1031-11 2024/07/16 5.78UT TOYOKAWA-KISO



F20240716144524





BLK:13,SNR1: 0.98761 ,SNR2: 4.2372




Frequency (Hz)

K20240716144519




BLK:13,SNR1: 2.3034 ,SNR2: 9.0161





Frequency (Hz)

1031-11 2024/07/16 5.78UT FUJI -KISO








T20240716144956




BLK:26,SNR1: 9.3991 ,SNR2: 22.754




F20240716144958





BLK:26,SNR1: 18.580 ,SNR2: 33.363




1035-058 2024/07/16 5.86UT TOYOKAWA-FUJI





T20240716144956




BLK:28,SNR1: 9.2224 ,SNR2: 22.319




K20240716144953





BLK:28,SNR1: 10.190 ,SNR2: 19.554




1035-058 2024/07/16 5.86UT TOYOKAWA-KISO



F20240716144958





BLK:38,SNR1: 17.423 ,SNR2: 31.293




Frequency (Hz)

K20240716144953




BLK:38,SNR1: 10.288 ,SNR2: 19.742





Frequency (Hz)


1035-058 2024/07/16 5.86UT FUJI -KISO





T20240716145908




BLK:29,SNR1: 31.877 ,SNR2: 57.549




F20240716145910





BLK:29,SNR1: 6.9639 ,SNR2: 17.468




1044-008 2024/07/16 6.01UT TOYOKAWA-FUJI





T20240716145908




BLK:23,SNR1: 25.713 ,SNR2: 45.255




K20240716145905





BLK:23,SNR1: 7.6420 ,SNR2: 19.210




1044-008 2024/07/16 6.01UT TOYOKAWA-KISO




F20240716145910




BLK:24,SNR1: 10.702 ,SNR2: 18.957




K20240716145905





BLK:24,SNR1: 7.5603 ,SNR2: 19.013




1044-008 2024/07/16 6.01UT FUJI -KISO



T20240716151013





BLK:21,SNR1: 15.799 ,SNR2: 27.858




Frequency (Hz)

F20240716151015




BLK:21,SNR1: 7.6947 ,SNR2: 19.050





Frequency (Hz)


1055+01 2024/07/16 6.20UT TOYOKAWA-FUJI





T20240716151013




BLK:20,SNR1: 15.991 ,SNR2: 28.195




K20240716151010







BLK:20,SNR1: 8.5772 ,SNR2: 21.521




1055+01 2024/07/16 6.20UT TOYOKAWA-KISO










1055+01 2024/07/16 6.20UT FUJI -KISO





T20240716152130




BLK:32,SNR1: 12.085 ,SNR2: 21.463




F20240716152132





BLK:32,SNR1: 2.6355 ,SNR2: 12.702




1107+109 2024/07/16 6.39UT TOYOKAWA-FUJI





T20240716152130




BLK:34,SNR1: 12.071 ,SNR2: 21.438




K20240716152127





BLK:34,SNR1: 8.8524 ,SNR2: 22.177




1107+109 2024/07/16 6.39UT TOYOKAWA-KISO





F20240716152132




BLK:37,SNR1: 2.5914 ,SNR2: 12.519




K20240716152127




BLK:37,SNR1: 8.8811 ,SNR2: 22.248




1107+109 2024/07/16 6.39UT FUJI -KISO



T20240716153108





BLK: 2,SNR1: 27.217 ,SNR2: 39.280




Frequency (Hz)

F20240716153110




BLK: 2,SNR1: 0.28000 ,SNR2: 2.1082




Frequency (Hz)


3C255 2024/07/16 6.55UT TOYOKAWA-FUJI





T20240716153108




BLK: 6,SNR1: 21.053 ,SNR2: 30.358




K20240716153105




BLK: 6,SNR1: 0.41908 ,SNR2: 1.2888




3C255 2024/07/16 6.55UT TOYOKAWA-KISO





F20240716153110




BLK: 2,SNR1: 2.6653 ,SNR2: 7.6364




K20240716153105




BLK: 2,SNR1: 0.54084E-01,SNR2: 1.0710




3C255 2024/07/16 6.55UT FUJI -KISO



T20240716154145





BLK:17,SNR1: 4.2313 ,SNR2: 10.588




Frequency (Hz)

F20240716154147




BLK:17,SNR1: 4.0227 ,SNR2: 11.121




Frequency (Hz)

1127-14 2024/07/16 6.72UT TOYOKAWA-FUJI






T20240716154145





BLK:21,SNR1: 4.7259 ,SNR2: 11.611




Frequency (Hz)

K20240716154142




BLK:21,SNR1: 5.7829 ,SNR2: 14.505





Frequency (Hz)


1127-14 2024/07/16 6.72UT TOYOKAWA-KISO





F20240716154147




BLK:23,SNR1: 5.3993 ,SNR2: 14.919




K20240716154142





BLK:23,SNR1: 6.0303 ,SNR2: 16.074




1127-14 2024/07/16 6.72UT FUJI -KISO



T20240716155506





BLK:29,SNR1: 20.575 ,SNR2: 23.089




Frequency (Hz)

F20240716155508




BLK:29,SNR1: 11.542 ,SNR2: 26.490





Frequency (Hz)


3C263.1 2024/07/16 6.95UT TOYOKAWA-FUJI



T20240716155506





BLK:28,SNR1: 20.586 ,SNR2: 23.101




Frequency (Hz)

K20240716155503




BLK:28,SNR1: 20.603 ,SNR2: 28.746





Frequency (Hz)


3C263.1 2024/07/16 6.95UT TOYOKAWA-KISO





F20240716155508




BLK:32,SNR1: 11.544 ,SNR2: 26.497




K20240716155503





BLK:32,SNR1: 20.610 ,SNR2: 28.755




3C263.1 2024/07/16 6.95UT FUJI -KISO




T20240716160133




BLK:11,SNR1: 0.93261 ,SNR2: 9.3381




F20240716160135




BLK:11,SNR1: 0.65689E-01,SNR2: 0.89645




3C267 2024/07/16 7.05UT TOYOKAWA-FUJI



T20240716160133





BLK: 2,SNR1: 4.6382 ,SNR2: 22.679





3C267 2024/07/16 7.05UT TOYOKAWA-KISO


K20240716160130




BLK: 2,SNR1: 0.77838 ,SNR2: 10.618



F20240716160135





BLK: 3,SNR1: 0.99805E-01,SNR2: 0.95858




Frequency (Hz)

K20240716160130




BLK: 3,SNR1: 0.49334 ,SNR2: 1.8099





Frequency (Hz)

3C267 2024/07/16 7.05UT FUJI -KISO






T20240716162720





BLK:12,SNR1: 67.943 ,SNR2: 85.694




Frequency (Hz)

F20240716162722




BLK:12,SNR1: 0.15402 ,SNR2: 1.2156





Frequency (Hz)


1213-17 2024/07/16 7.48UT TOYOKAWA-FUJI



T20240716162720





BLK:16,SNR1: 42.744 ,SNR2: 67.273




Frequency (Hz)

K20240716162717




BLK:16,SNR1: 1.4678 ,SNR2: 5.6839





Frequency (Hz)


1213-17 2024/07/16 7.48UT TOYOKAWA-KISO



F20240716162722





BLK:14,SNR1: 0.71727 ,SNR2: 1.5697




Frequency (Hz)

K20240716162717




BLK:14,SNR1: 1.8493 ,SNR2: 7.1883





Frequency (Hz)


1213-17 2024/07/16 7.48UT FUJI -KISO



T20240716164038





BLK:21,SNR1: 2.8074 ,SNR2: 13.363




Frequency (Hz)

F20240716164040




BLK:21,SNR1: 1.9725 ,SNR2: 8.8851





Frequency (Hz)


3C273 2024/07/16 7.71UT TOYOKAWA-FUJI



T20240716164038





BLK:23,SNR1: 2.7979 ,SNR2: 13.323




Frequency (Hz)

3C273 2024/07/16 7.71UT TOYOKAWA-KISO


K20240716164035





BLK:23,SNR1: 3.5095 ,SNR2: 5.3790




Frequency (Hz)



F20240716164040





BLK:27,SNR1: 0.75461 ,SNR2: 3.8690




Frequency (Hz)

K20240716164035




BLK:27,SNR1: 4.4378 ,SNR2: 11.240





Frequency (Hz)


3C273 2024/07/16 7.71UT FUJI -KISO



T20240716165348





BLK:10,SNR1: 1.5469 ,SNR2: 4.4474




Frequency (Hz)

F20240716165350




BLK:10,SNR1: 0.28613 ,SNR2: 3.3642





Frequency (Hz)


3C275 2024/07/16 7.92UT TOYOKAWA-FUJI



T20240716165348





BLK:10,SNR1: 2.9266 ,SNR2: 13.019




Frequency (Hz)

K20240716165345




BLK:10,SNR1: 1.3192 ,SNR2: 4.5874




Frequency (Hz)

3C275 2024/07/16 7.92UT TOYOKAWA-KISO






F20240716165350





BLK:15,SNR1: 0.30952 ,SNR2: 3.9954




Frequency (Hz)

K20240716165345




BLK:15,SNR1: 1.6116 ,SNR2: 5.6422





Frequency (Hz)


3C275 2024/07/16 7.92UT FUJI -KISO



T20240716172725





BLK: 4,SNR1: 0.16486 ,SNR2: 1.4035




Frequency (Hz)

F20240716172727




BLK: 4,SNR1: 0.27625 ,SNR2: 1.1523




Frequency (Hz)


1313+453 2024/07/16 8.49UT TOYOKAWA-FUJI



T20240716172725




BLK: 6,SNR1:-0.53462E-02,SNR2: 0.56203




Frequency (Hz)

K20240716172722




BLK: 6,SNR1: 0.29364 ,SNR2: 1.6805




Frequency (Hz)


1313+453 2024/07/16 8.49UT TOYOKAWA-KISO



F20240716172727




BLK: 5,SNR1: 0.17941 ,SNR2: 1.0369




Frequency (Hz)

K20240716172722




BLK: 5,SNR1: 0.33435 ,SNR2: 4.4566




Frequency (Hz)


1313+453 2024/07/16 8.49UT FUJI -KISO



T20240716173731




BLK: 2,SNR1: 0.13391 ,SNR2: 2.8019




Frequency (Hz)

F20240716173733




BLK: 2,SNR1: 0.79493E-01,SNR2: 2.0370





Frequency (Hz)


1323+32 2024/07/16 8.65UT TOYOKAWA-FUJI



T20240716173731





BLK: 8,SNR1: 0.52744E-01,SNR2: 1.2803




Frequency (Hz)

K20240716173728




BLK: 8,SNR1: 1.5045 ,SNR2: 6.8267





Frequency (Hz)


1323+32 2024/07/16 8.65UT TOYOKAWA-KISO



F20240716173733





BLK: 6,SNR1: 0.92525E-01,SNR2: 2.3474




Frequency (Hz)

K20240716173728




BLK: 6,SNR1: 1.7693 ,SNR2: 7.5316




Frequency (Hz)


1323+32 2024/07/16 8.65UT FUJI -KISO



T20240716174221





BLK:21,SNR1: 0.55354 ,SNR2: 3.6789




Frequency (Hz)

F20240716174223




BLK:21,SNR1:-0.36031E-01,SNR2: 1.6327




Frequency (Hz)

3C286 2024/07/16 8.73UT TOYOKAWA-FUJI






T20240716174221





BLK:17,SNR1: 0.54612 ,SNR2: 3.6500




Frequency (Hz)

K20240716174218




BLK:17,SNR1: 0.25413 ,SNR2: 1.2402





Frequency (Hz)


3C286 2024/07/16 8.73UT TOYOKAWA-KISO



F20240716174223





BLK:14,SNR1: 0.26512E-01,SNR2: 1.9611




Frequency (Hz)

K20240716174218




BLK:14,SNR1: 0.37698 ,SNR2: 1.7614





Frequency (Hz)


3C286 2024/07/16 8.73UT FUJI -KISO



T20240716174844





BLK: 1,SNR1: 0.18956 ,SNR2: 1.3738




Frequency (Hz)

F20240716174846




BLK: 1,SNR1:-0.86070E-01,SNR2: 0.30099





Frequency (Hz)


1335+479 2024/07/16 8.84UT TOYOKAWA-FUJI



T20240716174844




BLK: 5,SNR1: 0.15504 ,SNR2: 1.0639




Frequency (Hz)

K20240716174841




BLK: 5,SNR1: 6.3848 ,SNR2: 11.993




Frequency (Hz)


1335+479 2024/07/16 8.84UT TOYOKAWA-KISO



F20240716174846




BLK: 6,SNR1:-0.12841E-01,SNR2: 0.65512




Frequency (Hz)

K20240716174841




BLK: 6,SNR1: 1.6261 ,SNR2: 6.0726





Frequency (Hz)


1335+479 2024/07/16 8.84UT FWJI -KISO



T20240716175250




BLK: 4,SNR1: 0.78872E-01,SNR2: 0.56757




Frequency (Hz)

F20240716175252




BLK: 4,SNR1: 0.17195 ,SNR2: 1.3960





Frequency (Hz)


1339+472 2024/07/16 8.91UT TOYOKAWA-FUJI



T20240716175250





BLK: 2,SNR1: 0.27998 ,SNR2: 0.72301




Frequency (Hz)

K20240716175247




BLK: 2,SNR1: 2.3356 ,SNR2: 2.9720




Frequency (Hz)


1339+472 2024/07/16 8.91UT TOYOKAWA-KISO



F20240716175252





BLK: 3,SNR1: 0.22973E-02,SNR2: 1.7468




Frequency (Hz)

K20240716175247



BLK: 3,SNR1: 0.73233 ,SNR2: 4.1465



Frequency (Hz)

1339+472 2024/07/16 8.91UT FWJ -KISO

