



T20240725063940




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0258+350 2024/07/24 21.69UT TOYOKAWA-FUJI



T20240725063940





BLK: 5,SNR1: 0.28158E-01,SNR2: 1.4461




Frequency (Hz)

K20240725063937




BLK: 5,SNR1: 0.58656 ,SNR2: 3.6556





Frequency (Hz)


0258+350 2024/07/24 21.69UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20240725063937



No.Good Data





Frequency (Hz)


0258+350 2024/07/24 21.69UT FUJI -KISO



T20240725064929





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

0308+305 2024/07/24 21.85UT TOYOKAWA-FUJI






T20240725064929





BLK: 1,SNR1:-0.26580E-01,SNR2: 0.99792




Frequency (Hz)

K20240725064926




BLK: 1,SNR1: 3.5146 ,SNR2: 6.8299



Frequency (Hz)

0308+305 2024/07/24 21.85UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20240725064926



No.Good Data





Frequency (Hz)


0308+305 2024/07/24 21.85UT FUJI -KISO





T20240725070101




No.Good Data




FUJI





No.Good Data




0320+05 2024/07/24 22.05UT TOYOKAWA-FUJI



T20240725070101





BLK: 7,SNR1: 0.34620 ,SNR2: 4.4414




Frequency (Hz)

K20240725070059




BLK: 7,SNR1: 0.24485 ,SNR2: 1.4983




Frequency (Hz)


0320+05 2024/07/24 22.05UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240725070059




No.Good Data





Frequency (Hz)


0320+05 2024/07/24 22.05UT FUJI -KISO



T20240725071422





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0333+32 2024/07/24 22.27UT TOYOKAWA-FUJI



T20240725071422





BLK: 1,SNR1:-0.13209E-01,SNR2: 0.21311




Frequency (Hz)

K20240725071419




BLK: 1,SNR1: 0.96964 ,SNR2: 5.8076




Frequency (Hz)


0333+32 2024/07/24 22.27UT TOYOKAWA-KISO




FUJI




No.Good Data



K20240725071419



No.Good Data





0333+32 2024/07/24 22.27UT FUJI -KISO






T20240725072724





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0347+05 2024/07/24 22.48UT TOYOKAWA-FUJI



T20240725072724





BLK:10,SNR1: 0.31229E-01,SNR2: 1.0087




Frequency (Hz)

K20240725072721




BLK:10,SNR1: 3.5879 ,SNR2: 5.3257




Frequency (Hz)


0347+05 2024/07/24 22.48UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240725072721




No.Good Data




0347+05 2024/07/24 22.48UT FUJI -KISO





T20240725074258




No.Good Data




FUJI





No.Good Data




0403-132 2024/07/24 22.74UT TOYOKAWA-FUJI



T20240725074258





BLK:14,SNR1: 0.11714 ,SNR2: 0.80252




Frequency (Hz)

K20240725074256




BLK:14,SNR1: 0.63317 ,SNR2: 2.9445



Frequency (Hz)

0403-132 2024/07/24 22.74UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240725074256





No.Good Data




0403-132 2024/07/24 22.74UT FUJI -KISO



T20240725075209





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0411+05 2024/07/24 22.90UT TOYOKAWA-FUJI



T20240725075209




BLK:10,SNR1: 0.16842 ,SNR2: 1.1954




Frequency (Hz)

K20240725075207




BLK:10,SNR1: 6.3380 ,SNR2: 10.797





Frequency (Hz)

0411+05 2024/07/24 22.90UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240725075207




No.Good Data





Frequency (Hz)


0411+05 2024/07/24 22.90UT FUJI -KISO



T20240725075903





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0418+236 2024/07/24 23.01UT TOYOKAWA-FUJI



T20240725075903





BLK: 4,SNR1: 0.53383E-01,SNR2: 0.0000




Frequency (Hz)

K20240725075901




BLK: 4,SNR1: 0.22654 ,SNR2: 2.1589





Frequency (Hz)


0418+236 2024/07/24 23.01UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20240725075901




No.Good Data





Frequency (Hz)


0418+236 2024/07/24 23.01UT FUJI -KISO




T20240725081030




No.Good Data




FUJI





No.Good Data




3C119 2024/07/24 23.20UT TOYOKAWA-FUJI



T20240725081030





BLK:11,SNR1: 0.50326 ,SNR2: 4.6410




Frequency (Hz)

K20240725081028




BLK:11,SNR1: 0.35987 ,SNR2: 1.6460




Frequency (Hz)


3C119 2024/07/24 23.20UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240725081028




No.Good Data





Frequency (Hz)


3C119 2024/07/24 23.20UT FUJI -KISO





T20240725085412




No.Good Data




FUJI



No.Good Data





0514+109 2024/07/24 23.93UT TOYOKAWA-FUJI








T20240725085412




BLK: 6,SNR1: 0.78580E-01,SNR2: 1.2624




K20240725085409





BLK: 6,SNR1: 1.6117 ,SNR2: 8.6678




0514+109 2024/07/24 23.93UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240725085409





No.Good Data




0514+109 2024/07/24 23.93UT FUJI -KISO





T20240725091211




No.Good Data




FUJI




No.Good Data




0531+194 2024/07/25 0.23UT TOYOKAWA-FUJI



T20240725091211




BLK:15,SNR1: 0.38930 ,SNR2: 2.3710





0531+194 2024/07/25 0.23UT TOYOKAWA-KISO



K20240725091209




BLK:15,SNR1: 0.49215 ,SNR2: 1.2268



FUJI





No.Good Data




Frequency (Hz)

K20240725091209




No.Good Data





Frequency (Hz)


0531+194 2024/07/25 0.23UT FUJI -KISO





T20240725092030




No.Good Data




FUJI





No.Good Data




3C147 2024/07/25 0.37UT TOYOKAWA-FUJI



T20240725092030





BLK:32,SNR1: 7.9311 ,SNR2: 37.402




Frequency (Hz)

3C147 2024/07/25 0.37UT TOYOKAWA-KISO


K20240725092027





BLK:32,SNR1: 0.94582 ,SNR2: 4.6280




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240725092027




No.Good Data





Frequency (Hz)

3C147 2024/07/25 0.37UT FUJI -KISO








T20240725092842




No. Good Data




FUJI





No. Good Data




0548+16 2024/07/25 0.51UT TOYOKAWA-FUJI





T20240725092842




BLK:10,SNR1: 0.65729E-01,SNR2: 2.3413




K20240725092839



BLK:10,SNR1: 28.527 ,SNR2: 41.236




0548+16 2024/07/25 0.51UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240725092839




No.Good Data





Frequency (Hz)


0548+16 2024/07/25 0.51UT FUJI -KISO




T20240725093252




No.Good Data




FUJI




No.Good Data




0552+12 2024/07/25 0.58UT TOYOKAWA-FUJI



T20240725093252





BLK:11,SNR1:-0.77346E-02,SNR2: 0.88850





0552+12 2024/07/25 0.58UT TOYOKAWA-KISO

K20240725093249




BLK:11,SNR1: 126.96 ,SNR2: 139.30



FUJI





No.Good Data




Frequency (Hz)

K20240725093249




No.Good Data



Frequency (Hz)

0552+12 2024/07/25 0.58UT FUJI -KISO



T20240725093719



No.Good Data




FUJI





No.Good Data




0556+191 2024/07/25 0.65UT TOYOKAWA-FUJI



T20240725093719




BLK: 9,SNR1: 0.16756E-02,SNR2: 1.2154





0556+191 2024/07/25 0.65UT TOYOKAWA-KISO

K20240725093716



BLK: 9,SNR1: 2.7835 ,SNR2: 4.7240






FUJI





No.Good Data




Frequency (Hz)

K20240725093716




No.Good Data




Frequency (Hz)

0556+191 2024/07/25 0.65UT FUJI -KISO




T20240725094152




No.Good Data



FUJI





No.Good Data




3C152 2024/07/25 0.73UT TOYOKAWA-FUJI





T20240725094152




BLK:16,SNR1: 0.34383 ,SNR2: 5.9289




K20240725094149



BLK:16,SNR1: 2.3628 ,SNR2: 4.4684



3C152 2024/07/25 0.73UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20240725094149



No.Good Data




Frequency (Hz)


3C152 2024/07/25 0.73UT FUJI -KISO




T20240725100413




No.Good Data



FUJI




No.Good Data




3C161 2024/07/25 1.10UT TOYOKAWA-FUJI





T20240725100413




BLK:34,SNR1: 1.6461 ,SNR2: 14.484




K20240725100410





BLK:34,SNR1: 0.72356 ,SNR2: 1.9369




3C161 2024/07/25 1.10UT TOYOKAWA-KISO



FUJI




No.Good Data



Frequency (Hz)

K20240725100410




No.Good Data



Frequency (Hz)

3C161 2024/07/25 1.10UT FUJI -KISO




T20240725103146



No.Good Data




FUJI



No.Good Data





0652-130 2024/07/25 1.56UT TOYOKAWA-FUJI








T20240725103146




BLK:10,SNR1: 1.9795 ,SNR2: 3.7900




K20240725103143





BLK:10,SNR1: 2.0769 ,SNR2: 4.0851




0652-130 2024/07/25 1.56UT TOYOKAWA-KISO



FUJI



No. Good Data




Frequency (Hz)

K20240725103143




No. Good Data



Frequency (Hz)


0652-130 2024/07/25 1.56UT FUJI -KISO



T20240725104322




No. Good Data




FUJI





No. Good Data




0703+138 2024/07/25 1.75UT TOYOKAWA-FUJI




T20240725104322




BLK: 6,SNR1: 0.81574E-01,SNR2: 0.53752




K20240725104319




BLK: 6,SNR1: 0.74020 ,SNR2: 1.3069




0703+138 2024/07/25 1.75UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20240725104319




No.Good Data



Frequency (Hz)

0703+138 2024/07/25 1.75UT FUJI -KISO




T20240725105245



No. Good Data



FUJI




No. Good Data




0713-024 2024/07/25 1.91UT TOYOKAWA-FUJI



T20240725105245




BLK:21,SNR1: 1.1327 ,SNR2: 2.4247




Frequency (Hz)

K20240725105242




BLK:21,SNR1: 8.1041 ,SNR2: 11.913





Frequency (Hz)


0713-024 2024/07/25 1.91UT TOYOKAWA-KISO



FUJI



No. Good Data




Frequency (Hz)

K20240725105242




No. Good Data



Frequency (Hz)

0713-024 2024/07/25 1.91UT FUJI -KISO






T20240725110257





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0723+10 2024/07/25 2.08UT TOYOKAWA-FUJI



T20240725110257




BLK:26,SNR1: 1.8216 ,SNR2: 3.4988





0723+10 2024/07/25 2.08UT TOYOKAWA-KISO


K20240725110254




BLK:26,SNR1: 6.3263 ,SNR2: 10.513



FUJI





No. Good Data




Frequency (Hz)

K20240725110254




No. Good Data



Frequency (Hz)


0723+10 2024/07/25 2.08UT FUJI -KISO



T20240725111311





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0732+33 2024/07/25 2.25UT TOYOKAWA-FUJI



T20240725111311





BLK:10,SNR1:-0.18636 ,SNR2: 2.1929





0732+33 2024/07/25 2.25UT TOYOKAWA-KISO



K20240725111308




BLK:10,SNR1: 99.645 ,SNR2: 135.73



FUJI





No.Good Data




Frequency (Hz)

K20240725111308




No.Good Data





Frequency (Hz)


0732+33 2024/07/25 2.25UT FUJI -KISO



T20240725112113





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0741-06 2024/07/25 2.38UT TOYOKAWA-FUJI



T20240725112113





BLK:27,SNR1: 1.1544 ,SNR2: 6.6340





0741-06 2024/07/25 2.38UT TOYOKAWA-KISO

K20240725112110





BLK:27,SNR1: 0.24783 ,SNR2: 1.7556





FUJI





No. Good Data



Frequency (Hz)

K20240725112110




No. Good Data





Frequency (Hz)


0741-06 2024/07/25 2.38UT FUJI -KISO



T20240725113058





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0752-200 2024/07/25 2.54UT TOYOKAWA-FUJI



T20240725113058





BLK: 3,SNR1: 24.908 ,SNR2: 45.087





0752-200 2024/07/25 2.54UT TOYOKAWA-KISO

K20240725113055



BLK: 3,SNR1: 0.82615 ,SNR2: 3.1913



FUJI



No. Good Data



Frequency (Hz)

K20240725113055



No. Good Data



Frequency (Hz)

0752-200 2024/07/25 2.54UT FUJI -KISO





T20240725113833




No. Good Data




FUJI




No. Good Data




3C190 2024/07/25 2.67UT TOYOKAWA-FUJI



T20240725113833





BLK:11,SNR1: 8.3663 ,SNR2: 13.356





3C190 2024/07/25 2.67UT TOYOKAWA-KISO

K20240725113830



BLK:11,SNR1: 22.990 ,SNR2: 32.166



FUJI





No.Good Data




Frequency (Hz)

K20240725113830




No.Good Data



Frequency (Hz)


3C190 2024/07/25 2.67UT FUJI -KISO



T20240725115057



No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C196 2024/07/25 2.88UT TOYOKAWA-FUJI






T20240725115057





BLK:17,SNR1:-0.40019 ,SNR2: 0.72183





3C196 2024/07/25 2.88UT TOYOKAWA-KISO



K20240725115054




BLK:17,SNR1:-0.16176 ,SNR2: 2.1112



FUJI





No.Good Data




Frequency (Hz)

K20240725115054




No.Good Data



Frequency (Hz)

3C196 2024/07/25 2.88UT FUJI -KISO



T20240725120207





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0821+394 2024/07/25 3.06UT TOYOKAWA-FUJI




T20240725120207




BLK:20,SNR1: 11.362 ,SNR2: 27.121




K20240725120204





BLK:20,SNR1: 0.16025 ,SNR2: 0.99150




0821+394 2024/07/25 3.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240725120204




No.Good Data



Frequency (Hz)

0821+394 2024/07/25 3.06UT FUJI -KISO



T20240725121347



No.Good Data



Frequency (Hz)

FUJI



No.Good Data




Frequency (Hz)


0834-19 2024/07/25 3.26UT TOYOKAWA-FUJI



T20240725121347





BLK:20,SNR1: 6.5113 ,SNR2: 12.195





0834-19 2024/07/25 3.26UT TOYOKAWA-KISO

K20240725121344




BLK:20,SNR1: 8.2457 ,SNR2: 22.408



FUJI



No.Good Data




Frequency (Hz)

K20240725121344



No.Good Data




Frequency (Hz)

0834-19 2024/07/25 3.26UT FUJI -KISO





T20240725121852




No.Good Data



Frequency (Hz)

FUJI



No.Good Data





Frequency (Hz)


0839-071 2024/07/25 3.34UT TOYOKAWA-FUJI



T20240725121852




BLK: 8,SNR1: 0.31730E-01,SNR2: 2.9854





0839-071 2024/07/25 3.34UT TOYOKAWA-KISO

K20240725121849



BLK: 8,SNR1: 1.8460 ,SNR2: 10.638



FUJI



No.Good Data



Frequency (Hz)

K20240725121849



No.Good Data





Frequency (Hz)

0839-071 2024/07/25 3.34UT FUJI -KISO



T20240725122953





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C208 2024/07/25 3.53UT TOYOKAWA-FUJI





T20240725122953




BLK:22,SNR1: 0.22319 ,SNR2: 2.8851




K20240725122950



BLK:22,SNR1: 96.352 ,SNR2: 105.16



3C208 2024/07/25 3.53UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20240725122950



No.Good Data




Frequency (Hz)

3C208 2024/07/25 3.53UT FUJI -KISO





T20240725124635




No. Good Data




FUJI





No. Good Data




3C216 2024/07/25 3.80UT TOYOKAWA-FUJI




T20240725124635




BLK:17,SNR1: 11.828 ,SNR2: 17.847




K20240725124633



BLK:17,SNR1: 19.475 ,SNR2: 19.196



3C216 2024/07/25 3.80UT TOYOKAWA-KISO






FUJI




No. Good Data




Frequency (Hz)

K20240725124633




No. Good Data




Frequency (Hz)

3C216 2024/07/25 3.80UT FUJI -KISO



T20240725125846




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0919-142 2024/07/25 4.01UT TOYOKAWA-FUJI



T20240725125846





BLK:13,SNR1: 14.810 ,SNR2: 26.347





0919-142 2024/07/25 4.01UT TOYOKAWA-KISO


K20240725125844



BLK:13,SNR1: 12.204 ,SNR2: 25.300



FUJI





No.Good Data




Frequency (Hz)

K20240725125844




No.Good Data



Frequency (Hz)

0919-142 2024/07/25 4.01UT FUJI -KISO



T20240725130525





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0926+117 2024/07/25 4.12UT TOYOKAWA-FUJI



T20240725130525





BLK:13,SNR1: 20.441 ,SNR2: 30.811





0926+117 2024/07/25 4.12UT TOYOKAWA-KISO



K20240725130522




BLK:13,SNR1: 3.0843 ,SNR2: 2.9390



FUJI





No.Good Data




Frequency (Hz)

K20240725130522




No.Good Data



Frequency (Hz)

0926+117 2024/07/25 4.12UT FUJI -KISO



T20240725131310



No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C222 2024/07/25 4.25UT TOYOKAWA-FUJI






T20240725131310





BLK:18,SNR1: 12.699 ,SNR2: 19.546





3C222 2024/07/25 4.25UT TOYOKAWA-KISO



K20240725131307




BLK:18,SNR1: 4.6729 ,SNR2: 5.2364



FUJI





No.Good Data




Frequency (Hz)

K20240725131307




No.Good Data



Frequency (Hz)


3C222 2024/07/25 4.25UT FUJI -KISO



T20240725132010



No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


0941-08 2024/07/25 4.36UT TOYOKAWA-FUJI



T20240725132010




BLK:13,SNR1: 30.643 ,SNR2: 41.468





0941-08 2024/07/25 4.36UT TOYOKAWA-KISO



K20240725132007



BLK:13,SNR1: 4.3963 ,SNR2: 9.5187



FUJI





No.Good Data




Frequency (Hz)

K20240725132007



No.Good Data





Frequency (Hz)


0941-08 2024/07/25 4.36UT FUJI -KISO



T20240725132832





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C230 2024/07/25 4.50UT TOYOKAWA-FUJI



T20240725132832





BLK:18,SNR1: 9.2424 ,SNR2: 15.976





3C230 2024/07/25 4.50UT TOYOKAWA-KISO



K20240725132829




BLK:18,SNR1: 3.1304 ,SNR2: 3.1026



FUJI





No.Good Data




Frequency (Hz)

K20240725132829




No.Good Data





Frequency (Hz)

3C230 2024/07/25 4.50UT FUJI -KISO






T20240725134239





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C236 2024/07/25 4.74UT TOYOKAWA-FUJI





T20240725134239




BLK:15,SNR1: 0.42714 ,SNR2: 1.3332




K20240725134236





BLK:15,SNR1: 1.0064 ,SNR2: 2.0933




3C236 2024/07/25 4.74UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20240725134236




No.Good Data






Frequency (Hz)




3C236 2024/07/25 4.74UT FUJI -KISO




T20240725135049




FUJI




1011+110 2024/07/25 4.88UT TOYOKAWA-FUJI





T20240725135049




BLK:11,SNR1: 0.27248 ,SNR2: 1.8267




K20240725135046





BLK:11,SNR1: 1.6858 ,SNR2: 3.0378



1011+110 2024/07/25 4.88UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240725135046




No.Good Data




Frequency (Hz)


1011+110 2024/07/25 4.88UT FUJI -KISO





T20240725135830




BLK:22,SNR1: 1.5787 ,SNR2: 8.5929




F20240725135832




BLK:22,SNR1: 7.6175 ,SNR2: 14.359




3C241 2024/07/25 5.00UT TOYOKAWA-FUJI





T20240725135830




BLK:15,SNR1: 1.4774 ,SNR2: 9.7289




K20240725135827



BLK:15,SNR1: 5.1975 ,SNR2: 15.547




3C241 2024/07/25 5.00UT TOYOKAWA-KISO






F20240725135832





BLK:18,SNR1: 11.825 ,SNR2: 34.429





3C241 2024/07/25 5.00UT FUJI -KISO



K20240725135827




BLK:18,SNR1: 3.7170 ,SNR2: 11.298





T20240725140959




BLK: 6,SNR1: 0.50209 ,SNR2: 1.8176




F20240725140959





BLK: 6,SNR1:-0.18414 ,SNR2: 0.39077




1031-11 2024/07/25 5.19UT TOYOKAWA-FUJI





T20240725140959




BLK:14,SNR1: 0.40986 ,SNR2: 2.0418




K20240725140956





BLK:14,SNR1:-0.12107 ,SNR2: 0.55777




1031-11 2024/07/25 5.19UT TOYOKAWA-KISO



F20240725140959





BLK: 8,SNR1:-0.18335 ,SNR2: 0.39304





1031-11 2024/07/25 5.19UT FUJI -KISO


K20240725140956




BLK: 8,SNR1: 1.3453 ,SNR2: 2.9788





T20240725141432




BLK: 8,SNR1: 1.1258 ,SNR2: 2.7101




F20240725141432





BLK: 8,SNR1:-0.11568 ,SNR2: 1.3610




1035-058 2024/07/25 5.27UT TOYOKAWA-FUJI



T20240725141432





BLK: 4,SNR1: 0.73791 ,SNR2: 3.1421




Frequency (Hz)

K20240725141429




BLK: 4,SNR1: 0.30319 ,SNR2: 1.9955





Frequency (Hz)


1035-058 2024/07/25 5.27UT TOYOKAWA-KISO





F20240725141432




BLK: 6,SNR1: 4.2105 ,SNR2: 7.8426




K20240725141429





BLK: 6,SNR1: 1.0381 ,SNR2: 2.6576




1035-058 2024/07/25 5.27UT FUJI -KISO




T20240725142345




BLK: 9,SNR1: 0.15348 ,SNR2: 1.2365




F20240725142345



BLK: 9,SNR1: 0.25328 ,SNR2: 1.3034





1044-008 2024/07/25 5.42UT TOYOKAWA-FUJI








T20240725142345




BLK: 8,SNR1: 0.24901 ,SNR2: 1.0510




K20240725142342





BLK: 8,SNR1: 2.2184 ,SNR2: 3.6681




1044-008 2024/07/25 5.42UT TOYOKAWA-KISO





F20240725142345




BLK:15,SNR1: 0.88325 ,SNR2: 2.6557




K20240725142342





BLK:15,SNR1: 12.375 ,SNR2: 11.944




1044-008 2024/07/25 5.42UT FUJI -KISO



T20240725143450





BLK: 8,SNR1: 1.3553 ,SNR2: 7.2724




Frequency (Hz)

F20240725143450




BLK: 8,SNR1: 1.9948 ,SNR2: 7.3835





Frequency (Hz)


1055+01 2024/07/25 5.61UT TOYOKAWA-FUJI



T20240725143450





BLK:18,SNR1: 3.5555 ,SNR2: 5.4301




Frequency (Hz)

K20240725143448




BLK:18,SNR1: 4.1347 ,SNR2: 8.5746





Frequency (Hz)


1055+01 2024/07/25 5.61UT TOYOKAWA-KISO



F20240725143450





BLK: 7,SNR1: 9.4013 ,SNR2: 25.094




Frequency (Hz)

K20240725143448




BLK: 7,SNR1: 7.7354 ,SNR2: 21.961





Frequency (Hz)


1055+01 2024/07/25 5.61UT FUJI -KISO





T20240725144607




BLK: 7,SNR1: 3.2918 ,SNR2: 7.2790




F20240725144607





BLK: 7,SNR1: 3.7223 ,SNR2: 3.6566




1107+109 2024/07/25 5.80UT TOYOKAWA-FUJI





T20240725144607




BLK:13,SNR1: 1.0001 ,SNR2: 1.5179




K20240725144605





BLK:13,SNR1:-0.15285 ,SNR2: 0.27340




1107+109 2024/07/25 5.80UT TOYOKAWA-KISO





F20240725144607




BLK:11,SNR1:-0.31678 ,SNR2: 0.52992




K20240725144605



BLK:11,SNR1: 1.4438 ,SNR2: 1.3801





1107+109 2024/07/25 5.80UT FUJI -KISO






T20240725145544





BLK:10,SNR1: 4.3236 ,SNR2: 4.2656




Frequency (Hz)

F20240725145545




BLK:10,SNR1: 0.25824E-01,SNR2: 1.7720





Frequency (Hz)


3C255 2024/07/25 5.96UT TOYOKAWA-FUJI





T20240725145544




BLK:10,SNR1:-0.17608E-01,SNR2: 0.78895




K20240725145542





BLK:10,SNR1: 1.6030 ,SNR2: 3.4517




3C255 2024/07/25 5.96UT TOYOKAWA-KISO





F20240725145545




BLK: 8,SNR1: 0.52324 ,SNR2: 2.3138




K20240725145542




BLK: 8,SNR1:-0.27604E-01,SNR2: 1.0162




3C255 2024/07/25 5.96UT FUJI -KISO





T20240725150622




BLK:13,SNR1: 10.161 ,SNR2: 10.066




F20240725150622





BLK:13,SNR1: 1.8747 ,SNR2: 1.8539




1127-14 2024/07/25 6.13UT TOYOKAWA-FUJI





T20240725150622




BLK:23,SNR1: 5.1962 ,SNR2: 4.8312




K20240725150620





BLK:23,SNR1: 0.21964 ,SNR2: 1.9174




1127-14 2024/07/25 6.13UT TOYOKAWA-KISO





F20240725150622




BLK:13,SNR1:-0.10036 ,SNR2: 0.61471




K20240725150620




BLK:13,SNR1: 1.5203 ,SNR2: 4.0948




1127-14 2024/07/25 6.13UT FUJI -KISO





T20240725151942




BLK:11,SNR1: 0.80480 ,SNR2: 7.0333




F20240725151943





BLK:11,SNR1: 1.1910 ,SNR2: 3.1285




3C263.1 2024/07/25 6.36UT TOYOKAWA-FUJI



T20240725151942





BLK:17,SNR1: 0.64559 ,SNR2: 6.3518




Frequency (Hz)

K20240725151940




BLK:17,SNR1: 0.28950 ,SNR2: 2.0175





Frequency (Hz)

3C263.1 2024/07/25 6.36UT TOYOKAWA-KISO







F20240725151943




BLK: 9,SNR1: 0.85306 ,SNR2: 2.3440




K20240725151940




BLK: 9,SNR1:-0.34113 ,SNR2: 1.0804





3C263.1 2024/07/25 6.36UT FUJI -KISO







BLK:11,SNR1: 0.91140 ,SNR2: 4.7575




BLK:11,SNR1: 2.4472 ,SNR2: 4.6630





3C267 2024/07/25 6.46UT TOYOKAWA-FUJI







BLK:19,SNR1: 8.7051 ,SNR2: 8.4997





BLK:19,SNR1: 3.2223 ,SNR2: 5.3317




3C267 2024/07/25 6.46UT TOYOKAWA-KISO





F20240725152609




BLK:11,SNR1: 0.25523 ,SNR2: 1.1216




K20240725152607




BLK:11,SNR1:-0.20960 ,SNR2: 0.58806




3C267 2024/07/25 6.46UT FUJI -KISO



T20240725155157





BLK: 9,SNR1: 3.3678 ,SNR2: 4.8018




Frequency (Hz)

F20240725155158




BLK: 9,SNR1: 0.97298 ,SNR2: 6.5428




Frequency (Hz)


1213-17 2024/07/25 6.89UT TOYOKAWA-FUJI



T20240725155157




BLK:30,SNR1: 1.2250 ,SNR2: 4.1876




Frequency (Hz)

K20240725155155




BLK:30,SNR1: 2.0929 ,SNR2: 3.0638





Frequency (Hz)


1213-17 2024/07/25 6.89UT TOYOKAWA-KISO





F20240725155158




BLK:10,SNR1: 0.46792 ,SNR2: 4.0426




K20240725155155




BLK:10,SNR1: 1.9432 ,SNR2: 2.8449




1213-17 2024/07/25 6.89UT FUJI -KISO



T20240725160514




BLK:11,SNR1: 1.8509 ,SNR2: 3.0729




Frequency (Hz)

F20240725160514




BLK:11,SNR1: 0.27864 ,SNR2: 3.4397




Frequency (Hz)



3C273 2024/07/25 7.12UT TOYOKAWA-FUJI









BLK:31,SNR1: 2.4289 ,SNR2: 4.7887




BLK:31,SNR1: 0.62306E-01,SNR2: 3.1604




3C273 2024/07/25 7.12UT TOYOKAWA-KISO



F20240725160514





BLK: 8,SNR1: 0.23472 ,SNR2: 3.7800




Frequency (Hz)

K20240725160512




BLK: 8,SNR1: 6.3894 ,SNR2: 6.3894




Frequency (Hz)


3C273 2024/07/25 7.12UT FUJI -KISO



T20240725161825




BLK: 9,SNR1: 2.3557 ,SNR2: 5.7927




Frequency (Hz)

F20240725161826




BLK: 9,SNR1: 0.51230 ,SNR2: 4.4012




Frequency (Hz)


3C275 2024/07/25 7.34UT TOYOKAWA-FUJI





T20240725161825




BLK:31,SNR1: 1.8602 ,SNR2: 4.3147




K20240725161823




BLK:31,SNR1: 3.5471 ,SNR2: 7.5047




3C275 2024/07/25 7.34UT TOYOKAWA-KISO





F20240725161826




BLK:11,SNR1: 1.4255 ,SNR2: 4.7771




K20240725161823




BLK:11,SNR1: 5.1757 ,SNR2: 10.343




3C275 2024/07/25 7.34UT FUJI -KISO



T20240725162430




BLK:16,SNR1: 1.2167 ,SNR2: 8.9725




Frequency (Hz)

F20240725162430




BLK:16,SNR1: 0.85885 ,SNR2: 2.5578




Frequency (Hz)


1245-19 2024/07/25 7.44UT TOYOKAWA-FUJI



T20240725162430





BLK:35,SNR1: 0.98346 ,SNR2: 7.5837




Frequency (Hz)

K20240725162427




BLK:35,SNR1: 6.2273 ,SNR2: 9.6626




Frequency (Hz)


1245-19 2024/07/25 7.44UT TOYOKAWA-KISO



F20240725162430





BLK:12,SNR1: 1.1594 ,SNR2: 2.9337




Frequency (Hz)

K20240725162427




BLK:12,SNR1: 6.4874 ,SNR2: 10.065





Frequency (Hz)

1245-19 2024/07/25 7.44UT FUJI -KISO






T20240725163214




BLK:11,SNR1: 68.254 ,SNR2: 65.113




Frequency (Hz)

F20240725163215




BLK:11,SNR1: 0.30739 ,SNR2: 2.3155





Frequency (Hz)


3C279 2024/07/25 7.57UT TOYOKAWA-FUJI



T20240725163214




BLK:37,SNR1: 61.924 ,SNR2: 59.351




Frequency (Hz)

K20240725163212




BLK:37,SNR1:-0.12495 ,SNR2: 1.7683




Frequency (Hz)


3C279 2024/07/25 7.57UT TOYOKAWA-KISO



F20240725163215





BLK:13,SNR1: 0.61018 ,SNR2: 2.9551




Frequency (Hz)

K20240725163212




BLK:13,SNR1: 2.8434 ,SNR2: 5.0950




Frequency (Hz)


3C279 2024/07/25 7.57UT FUJI -KISO



T20240725165202




BLK:17,SNR1: 10.444 ,SNR2: 10.258




Frequency (Hz)

F20240725165202




BLK:17,SNR1: 3.2422 ,SNR2: 2.9575





Frequency (Hz)


1313+453 2024/07/25 7.90UT TOYOKAWA-FUJI



T20240725165202




BLK:31,SNR1: 6.7365 ,SNR2: 6.6736




Frequency (Hz)

K20240725165159




BLK:31,SNR1: 26.870 ,SNR2: 35.854




Frequency (Hz)


1313+453 2024/07/25 7.90UT TOYOKAWA-KISO



F20240725165202





BLK:16,SNR1: 2.9906 ,SNR2: 3.4345




Frequency (Hz)

K20240725165159




BLK:16,SNR1: 26.691 ,SNR2: 35.616





Frequency (Hz)


1313+453 2024/07/25 7.90UT FUJI -KISO





T20240725170208




BLK:20,SNR1: 15.692 ,SNR2: 16.671




F20240725170208





BLK:20,SNR1: 74.190 ,SNR2: 103.87




1323+32 2024/07/25 8.06UT TOYOKAWA-FUJI





T20240725170208




BLK:27,SNR1: 7.9686 ,SNR2: 7.0796




K20240725170205



BLK:27,SNR1: 0.34900E-02,SNR2: 1.1028





1323+32 2024/07/25 8.06UT TOYOKAWA-KISO






F20240725170208





BLK:10,SNR1: 0.47877 ,SNR2: 2.7594




Frequency (Hz)

K20240725170205




BLK:10,SNR1: 15.199 ,SNR2: 20.168





Frequency (Hz)


1323+32 2024/07/25 8.06UT FUJI -KISO



T20240725170658





BLK:17,SNR1: 12.516 ,SNR2: 12.074




Frequency (Hz)

F20240725170658




BLK:17,SNR1: 1.0001 ,SNR2: 3.2760





Frequency (Hz)


3C286 2024/07/25 8.14UT TOYOKAWA-FUJI



T20240725170658





BLK:30,SNR1: 12.122 ,SNR2: 11.693




Frequency (Hz)

K20240725170655




BLK:30,SNR1: 1.2723 ,SNR2: 3.5502





Frequency (Hz)


3C286 2024/07/25 8.14UT TOYOKAWA-KISO



F20240725170658





BLK:13,SNR1: 1.5135 ,SNR2: 5.9142




Frequency (Hz)

K20240725170655



BLK:13,SNR1: 1.2432 ,SNR2: 3.7480



Frequency (Hz)

3C286 2024/07/25 8.14UT FUJI -KISO

