




T20240726063544





BLK: 3,SNR1: 0.17288E-02,SNR2: 0.81728




Frequency (Hz)

F20240726063544




BLK: 3,SNR1: 1.3077 ,SNR2: 4.1941





Frequency (Hz)


0258+350 2024/07/25 21.62UT TOYOKAWA-FUJI



T20240726063544





BLK: 3,SNR1:-0.20385E-01,SNR2: 0.50864




Frequency (Hz)

K20240726063541




BLK: 3,SNR1: 1.5177 ,SNR2: 2.2927





Frequency (Hz)

0258+350 2024/07/25 21.62UT TOYOKAWA-KISO






F20240726063544





BLK: 4,SNR1: 3.8177 ,SNR2: 10.819




Frequency (Hz)

K20240726063541




BLK: 4,SNR1: 0.29695 ,SNR2: 5.2055





Frequency (Hz)


0258+350 2024/07/25 21.62UT FUJI -KISO



T20240726064533





BLK: 4,SNR1: 0.24936E-02,SNR2: 0.23977




Frequency (Hz)

F20240726064533




BLK: 4,SNR1: 2.2284 ,SNR2: 7.3780





Frequency (Hz)


0308+305 2024/07/25 21.79UT TOYOKAWA-FUJI



T20240726064533





BLK: 5,SNR1: 0.16347 ,SNR2: 0.38412




Frequency (Hz)

K20240726064530




BLK: 5,SNR1: 1.3847 ,SNR2: 4.2983





Frequency (Hz)


0308+305 2024/07/25 21.79UT TOYOKAWA-KISO



F20240726064533





BLK:11,SNR1: 1.5721 ,SNR2: 3.8162




Frequency (Hz)

K20240726064530




BLK:11,SNR1: 0.71212 ,SNR2: 3.6931




Frequency (Hz)


0308+305 2024/07/25 21.79UT FUJI -KISO





T20240726065705




BLK: 9,SNR1: 0.19814 ,SNR2: 0.88509




F20240726065705





BLK: 9,SNR1: 0.66114E-02,SNR2: 2.2890




0320+05 2024/07/25 21.98UT TOYOKAWA-FUJI



T20240726065705





BLK: 9,SNR1: 0.15799 ,SNR2: 1.7788




Frequency (Hz)

K20240726065702




BLK: 9,SNR1: 0.72279 ,SNR2: 4.2976




Frequency (Hz)


0320+05 2024/07/25 21.98UT TOYOKAWA-KISO



F20240726065705





BLK: 6,SNR1: 0.11549 ,SNR2: 3.1471




Frequency (Hz)

K20240726065702




BLK: 6,SNR1: 0.96604 ,SNR2: 5.0987





Frequency (Hz)


0320+05 2024/07/25 21.98UT FUJI -KISO



T20240726071026





BLK: 1,SNR1: 0.13243 ,SNR2: 0.79981




Frequency (Hz)

F20240726071027




BLK: 1,SNR1: 2.0851 ,SNR2: 10.879





Frequency (Hz)

0333+32 2024/07/25 22.20UT TOYOKAWA-FUJI






T20240726071026





BLK: 1,SNR1:-0.35258E-01,SNR2: 3.0902




Frequency (Hz)

K20240726071023




BLK: 1,SNR1:-0.17940 ,SNR2: 0.40180




Frequency (Hz)


0333+32 2024/07/25 22.20UT TOYOKAWA-KISO



F20240726071027




BLK: 5,SNR1: 0.89794 ,SNR2: 6.4573




Frequency (Hz)

K20240726071023




BLK: 5,SNR1: 0.98065 ,SNR2: 7.5703





Frequency (Hz)


0333+32 2024/07/25 22.20UT FUJI -KISO



T20240726072328





BLK: 5, SNR1: 1.0228 , SNR2: 8.7036




Frequency (Hz)

F20240726072328




BLK: 5, SNR1: -0.56838E-01, SNR2: 3.4314





Frequency (Hz)


0347+05 2024/07/25 22.42UT TOYOKAWA-FUJI



T20240726072328





BLK: 6, SNR1: 0.93220 ,SNR2: 6.6621




Frequency (Hz)

0347+05 2024/07/25 22.42UT TOYOKAWA-KISO


K20240726072325





BLK: 6, SNR1: 0.32369 ,SNR2: 2.5750




Frequency (Hz)



F20240726072328





BLK: 5,SNR1: 0.79175 ,SNR2: 3.3139




Frequency (Hz)

K20240726072325




BLK: 5,SNR1: 0.16141 ,SNR2: 2.9917





Frequency (Hz)


0347+05 2024/07/25 22.42UT FUJI -KISO



T20240726073902




BLK: 7,SNR1: 0.26634 ,SNR2: 1.2702




Frequency (Hz)

F20240726073902




BLK: 7,SNR1:-0.18826E-01,SNR2: 1.7235





Frequency (Hz)


0403-132 2024/07/25 22.68UT TOYOKAWA-FUJI



T20240726073902




BLK:10,SNR1: 0.18220 ,SNR2: 1.3167




Frequency (Hz)

K20240726073859




BLK:10,SNR1: 8.0557 ,SNR2: 14.272





Frequency (Hz)


0403-132 2024/07/25 22.68UT TOYOKAWA-KISO



F20240726073902





BLK:11,SNR1:-0.89551E-01,SNR2: 1.4867




Frequency (Hz)

K20240726073859




BLK:11,SNR1: 6.3504 ,SNR2: 13.427





Frequency (Hz)

0403-132 2024/07/25 22.68UT FUJI -KISO








T20240726074813




BLK: 5,SNR1:-0.38320E-01,SNR2: 0.77324




F20240726074813





BLK: 5,SNR1:-0.14796 ,SNR2: 2.0605




0411+05 2024/07/25 22.83UT TOYOKAWA-FUJI



T20240726074813




BLK: 6,SNR1:-0.44243E-01,SNR2: 0.90511




Frequency (Hz)

K20240726074811




BLK: 6,SNR1: 1.4026 ,SNR2: 3.2847





Frequency (Hz)


0411+05 2024/07/25 22.83UT TOYOKAWA-KISO



F20240726074813





BLK: 8,SNR1:-0.16439 ,SNR2: 1.9591




Frequency (Hz)

K20240726074811




BLK: 8,SNR1: 0.69214 ,SNR2: 1.3895





Frequency (Hz)


0411+05 2024/07/25 22.83UT FUJI -KISO



T20240726075507




BLK: 5,SNR1: 0.79800 ,SNR2: 11.218




Frequency (Hz)

F20240726075507




BLK: 5,SNR1:-0.51436E-01,SNR2: 1.2357





Frequency (Hz)


0418+236 2024/07/25 22.95UT TOYOKAWA-FUJI





T20240726075507




BLK: 1,SNR1:-0.25837 ,SNR2: 0.50352




K20240726075504





BLK: 1,SNR1: 0.55107E-01,SNR2: 0.28422




0418+236 2024/07/25 22.95UT TOYOKAWA-KISO



F20240726075507





BLK: 4,SNR1: 0.65479 ,SNR2: 3.7650




Frequency (Hz)

K20240726075504




BLK: 4,SNR1: 0.10910E-01,SNR2: 0.74315





Frequency (Hz)


0418+236 2024/07/25 22.95UT FUJI -KISO



T20240726080634




BLK:13,SNR1: 0.26163 ,SNR2: 4.2328




Frequency (Hz)

F20240726080634




BLK:13,SNR1: 0.43490 ,SNR2: 3.7931





Frequency (Hz)


3C119 2024/07/25 23.14UT TOYOKAWA-FUJI



T20240726080634





BLK:19,SNR1: 0.24725 ,SNR2: 0.94738




Frequency (Hz)

K20240726080632




BLK:19,SNR1: 0.31431 ,SNR2: 2.2403




Frequency (Hz)

3C119 2024/07/25 23.14UT TOYOKAWA-KISO







F20240726080634




BLK: 6,SNR1: 1.2711 ,SNR2: 4.6845




K20240726080632





BLK: 6,SNR1: 0.16377 ,SNR2: 0.70989




3C119 2024/07/25 23.14UT FUJI -KISO



T20240726085420





BLK: 4,SNR1: 0.13181 ,SNR2: 2.3247




Frequency (Hz)

F20240726085420




BLK: 4,SNR1: 0.25739 ,SNR2: 3.4673





Frequency (Hz)


0517+141 2024/07/25 23.93UT TOYOKAWA-FUJI



T20240726085420





BLK: 3,SNR1: 0.22591 ,SNR2: 3.0428




Frequency (Hz)

K20240726085417




BLK: 3,SNR1: 3.3697 ,SNR2: 10.366




Frequency (Hz)


0517+141 2024/07/25 23.93UT TOYOKAWA-KISO





F20240726085420




BLK: 5,SNR1: 0.79302 ,SNR2: 1.7964




K20240726085417




BLK: 5,SNR1: 0.58672E-01,SNR2: 2.1046




0517+141 2024/07/25 23.93UT FUJI -KISO




T20240726090815




BLK:11,SNR1: 0.30520 ,SNR2: 2.0405




F20240726090815





BLK:11,SNR1: 0.78199 ,SNR2: 3.6522




0531+194 2024/07/26 0.17UT TOYOKAWA-FUJI



T20240726090815





BLK:14,SNR1: 0.46293 ,SNR2: 2.6793




Frequency (Hz)

K20240726090812




BLK:14,SNR1:-0.51286E-01,SNR2: 0.73434




Frequency (Hz)


0531+194 2024/07/26 0.17UT TOYOKAWA-KISO




F20240726090815




BLK:10,SNR1: 0.79963 ,SNR2: 3.7157




K20240726090812




BLK:10,SNR1: 1.3983 ,SNR2: 6.1691




0531+194 2024/07/26 0.17UT FWJ -KISO



T20240726091634




BLK:16,SNR1: 5.1836 ,SNR2: 33.112




Frequency (Hz)

3C147 2024/07/26 0.30UT TOYOKAWA-FUJI


F20240726091634



BLK:16,SNR1: 0.14703 ,SNR2: 1.1848




Frequency (Hz)






T20240726091634




BLK:25,SNR1: 5.9443 ,SNR2: 36.588




Frequency (Hz)

3C147 2024/07/26 0.30UT TOYOKAWA-KISO


K20240726091632





BLK:25,SNR1: 0.73568 ,SNR2: 4.6678




Frequency (Hz)



F20240726091634





BLK:26,SNR1: 0.12444 ,SNR2: 0.93896




Frequency (Hz)

3C147 2024/07/26 0.30UT FUJI -KISO


K20240726091632





BLK:26,SNR1: 0.90337 ,SNR2: 8.2243




Frequency (Hz)



T20240726092446





BLK: 7,SNR1: 0.32211 ,SNR2: 1.3000




Frequency (Hz)

F20240726092446




BLK: 7,SNR1: 0.23291 ,SNR2: 3.0091





Frequency (Hz)


0548+16 2024/07/26 0.44UT TOYOKAWA-FUJI



T20240726092446





BLK: 9,SNR1: 0.18980 ,SNR2: 1.5434




Frequency (Hz)

K20240726092443




BLK: 9,SNR1: 3.4316 ,SNR2: 12.483




Frequency (Hz)


0548+16 2024/07/26 0.44UT TOYOKAWA-KISO




F20240726092446




BLK: 8,SNR1: 0.95094 ,SNR2: 5.0555




K20240726092443





BLK: 8,SNR1: 2.1108 ,SNR2: 7.4925




0548+16 2024/07/26 0.44UT FUJI -KISO



T20240726092857





BLK: 6,SNR1: 0.22629E-01,SNR2: 0.71634




Frequency (Hz)

F20240726092857




BLK: 6,SNR1:-0.12820 ,SNR2: 0.72102





Frequency (Hz)


0552+12 2024/07/26 0.51UT TOYOKAWA-FUJI



T20240726092857





BLK: 5,SNR1: 0.18627 ,SNR2: 0.84690




Frequency (Hz)

0552+12 2024/07/26 0.51UT TOYOKAWA-KISO


K20240726092854




BLK: 5,SNR1: 36.032 ,SNR2: 124.90




Frequency (Hz)





F20240726092857




BLK: 6,SNR1: 0.17492 ,SNR2: 1.0044




K20240726092854



BLK: 6,SNR1: 45.854 ,SNR2: 124.86





0552+12 2024/07/26 0.51UT FUJI -KISO








T20240726093323




BLK: 3,SNR1: 0.82264E-01,SNR2: 0.44556




F20240726093323





BLK: 3,SNR1: 2.5212 ,SNR2: 11.804




0556+191 2024/07/26 0.58UT TOYOKAWA-FUJI




T20240726093323




BLK: 2,SNR1: 0.23502 ,SNR2: 0.63371




K20240726093320





BLK: 2,SNR1: 7.6208 ,SNR2: 17.846




0556+191 2024/07/26 0.58UT TOYOKAWA-KISO





F20240726093323




BLK: 6,SNR1: 0.62452 ,SNR2: 3.7410




K20240726093320





BLK: 6,SNR1: 0.36313 ,SNR2: 1.0556




0556+191 2024/07/26 0.58UT FUJI -KISO




T20240726093756




BLK: 7,SNR1: 0.37358 ,SNR2: 0.85904




F20240726093756





BLK: 7,SNR1: 0.28861E-01,SNR2: 1.6004




3C152 2024/07/26 0.66UT TOYOKAWA-FUJI



T20240726093756





BLK:17,SNR1: 0.22537 ,SNR2: 1.4189




Frequency (Hz)

K20240726093754




BLK:17,SNR1: 0.11717 ,SNR2: 1.5180




Frequency (Hz)


3C152 2024/07/26 0.66UT TOYOKAWA-KISO




F20240726093756




No. Good Data




K20240726093754





No. Good Data




3C152 2024/07/26 0.66UT FUJI -KISO



T20240726100017





BLK:16,SNR1: 1.4300 ,SNR2: 14.283




Frequency (Hz)

3C161 2024/07/26 1.03UT TOYOKAWA-FUJI


F20240726100017




BLK:16,SNR1:-0.70619E-01,SNR2: 2.3573




Frequency (Hz)



T20240726100017





BLK:32,SNR1: 1.1729 ,SNR2: 10.765





3C161 2024/07/26 1.03UT TOYOKAWA-KISO

K20240726100014





BLK:32,SNR1: 0.24974 ,SNR2: 2.9299






F20240726100017





BLK: 8,SNR1:-0.13155 ,SNR2: 1.5697




Frequency (Hz)

K20240726100014




BLK: 8,SNR1: 0.38432 ,SNR2: 2.1239





Frequency (Hz)


3C161 2024/07/26 1.03UT FUJI -KISO



T20240726102750





BLK:10,SNR1: 0.24585 ,SNR2: 1.5586




Frequency (Hz)

F20240726102750




BLK:10,SNR1: 86.947 ,SNR2: 90.983





Frequency (Hz)


0652-130 2024/07/26 1.49UT TOYOKAWA-FUJI



T20240726102750





BLK:12,SNR1: 0.32915 ,SNR2: 1.6951





0652-130 2024/07/26 1.49UT TOYOKAWA-KISO



K20240726102747




BLK:12,SNR1: 4.1836 ,SNR2: 17.517



F20240726102750





BLK: 5,SNR1: 14.038 ,SNR2: 43.557





0652-130 2024/07/26 1.49UT FUJI -KISO


K20240726102747




BLK: 5,SNR1: 4.2124 ,SNR2: 17.634





T20240726103926




BLK:18,SNR1: 1.5979 ,SNR2: 2.2193




F20240726103926




BLK:18,SNR1: 11.765 ,SNR2: 26.530




0703+138 2024/07/26 1.69UT TOYOKAWA-FUJI




T20240726103926




BLK:26,SNR1: 1.1593 ,SNR2: 1.6007




K20240726103924




BLK:26,SNR1: 12.622 ,SNR2: 20.125




0703+138 2024/07/26 1.69UT TOYOKAWA-KISO




F20240726103926




BLK:22,SNR1: 13.359 ,SNR2: 30.143




K20240726103924





BLK:22,SNR1: 11.647 ,SNR2: 18.272




0703+138 2024/07/26 1.69UT FUJI -KISO





T20240726104849




BLK:12,SNR1: 1.2938 ,SNR2: 5.4619




F20240726104849



BLK:12,SNR1: 20.713 ,SNR2: 68.920




0713-024 2024/07/26 1.84UT TOYOKAWA-FUJI







T20240726104849




BLK:14,SNR1: 1.2050 ,SNR2: 5.0736




K20240726104846





BLK:14,SNR1: 0.22352 ,SNR2: 2.0546




0713-024 2024/07/26 1.84UT TOYOKAWA-KISO




F20240726104849




BLK: 7,SNR1: 81.231 ,SNR2: 105.70




K20240726104846





BLK: 7,SNR1: 2.5675 ,SNR2: 4.3368




0713-024 2024/07/26 1.84UT FUJI -KISO



T20240726105901




BLK:10,SNR1: 7.6271 ,SNR2: 45.268





0723+10 2024/07/26 2.01UT TOYOKAWA-FUJI



F20240726105901




BLK:10,SNR1:-0.87026E-01,SNR2: 2.0291



T20240726105901





BLK:15,SNR1: 1.5803 ,SNR2: 3.1451




Frequency (Hz)

0723+10 2024/07/26 2.01UT TOYOKAWA-KISO


K20240726105858




BLK:15,SNR1: 0.52604 ,SNR2: 2.9687




Frequency (Hz)





F20240726105901




BLK:11,SNR1: 2.7505 ,SNR2: 4.4984




K20240726105858




BLK:11,SNR1: 118.87 ,SNR2: 113.82




0723+10 2024/07/26 2.01UT FUJI -KISO



T20240726110916




BLK:11,SNR1: 2.3653 ,SNR2: 13.915




Frequency (Hz)

0732+33 2024/07/26 2.18UT TOYOKAWA-FUJI


F20240726110916





BLK:11,SNR1:-0.79658E-02,SNR2: 0.94879




Frequency (Hz)



T20240726110916





BLK:16,SNR1: 1.9710 ,SNR2: 9.7114





0732+33 2024/07/26 2.18UT TOYOKAWA-KISO



K20240726110913




BLK:16,SNR1: 1.8504 ,SNR2: 3.6819



F20240726110916





BLK:12,SNR1: 0.15055 ,SNR2: 1.3471




Frequency (Hz)

K20240726110913




BLK:12,SNR1: 6.5544 ,SNR2: 22.245




Frequency (Hz)

0732+33 2024/07/26 2.18UT FUJI -KISO






T20240726111718




BLK:19,SNR1: 2.1380 ,SNR2: 3.4641





0741-06 2024/07/26 2.32UT TOYOKAWA-FUJI


F20240726111718




BLK:19,SNR1: 0.79255 ,SNR2: 2.0320



T20240726111718




BLK:28,SNR1: 1.0543 ,SNR2: 4.4021





0741-06 2024/07/26 2.32UT TOYOKAWA-KISO


K20240726111715




BLK:28,SNR1: 0.30751 ,SNR2: 1.8373





F20240726111718




BLK:15,SNR1: 1.1160 ,SNR2: 2.3012




K20240726111715




BLK:15,SNR1: 0.60111 ,SNR2: 2.5795




0741-06 2024/07/26 2.32UT FUJI -KISO



T20240726112702





BLK:14,SNR1: 10.594 ,SNR2: 15.019





0752-200 2024/07/26 2.48UT TOYOKAWA-FUJI


F20240726112702




BLK:14,SNR1:-0.18198 ,SNR2: 3.7785



T20240726112702




BLK: 7, SNR1: 1.1021 , SNR2: 2.2636





0752-200 2024/07/26 2.48UT TOYOKAWA-KISO



K20240726112859




BLK: 7, SNR1: 1.0324 , SNR2: 3.6994



F20240726112702




BLK:13,SNR1:-0.15781 ,SNR2: 3.8328





0752-200 2024/07/26 2.48UT FUJI -KISO



K20240726112859




BLK:13,SNR1: 13.073 ,SNR2: 20.715



T20240726113437




BLK:12,SNR1:-0.10612 ,SNR2: 2.4128





3C190 2024/07/26 2.61UT TOYOKAWA-FUJI



F20240726113437




BLK:12,SNR1: 16.692 ,SNR2: 28.061



T20240726113437





BLK:12,SNR1:-0.92021E-01,SNR2: 2.4798





3C190 2024/07/26 2.61UT TOYOKAWA-KISO

K20240726113434




BLK:12,SNR1: 10.976 ,SNR2: 19.030








F20240726113437




BLK:11,SNR1: 16.188 ,SNR2: 27.207




K20240726113434





BLK:11,SNR1: 12.569 ,SNR2: 17.710




3C190 2024/07/26 2.61UT FUJI -KISO



T20240726114701





BLK:13,SNR1: 17.198 ,SNR2: 24.647





3C196 2024/07/26 2.81UT TOYOKAWA-FUJI



F20240726114701




BLK:13,SNR1: 15.760 ,SNR2: 28.258



T20240726114701





BLK:20,SNR1: 13.510 ,SNR2: 22.300




3C196 2024/07/26 2.81UT TOYOKAWA-KISO


K20240726114658





BLK:20,SNR1: 9.3325 ,SNR2: 15.224




Frequency (Hz)



F20240726114701




BLK:14,SNR1: 15.683 ,SNR2: 28.124





3C196 2024/07/26 2.81UT FUJI -KISO



K20240726114658




BLK:14,SNR1: 10.047 ,SNR2: 17.267



T20240726115811





BLK:15,SNR1: 9.3951 ,SNR2: 14.800





0821+394 2024/07/26 3.00UT TOYOKAWA-FUJI



F20240726115811




BLK:15,SNR1: 21.010 ,SNR2: 30.124



T20240726115811




BLK: 9,SNR1: 10.896 ,SNR2: 14.889





0821+394 2024/07/26 3.00UT TOYOKAWA-KISO



K20240726115808




BLK: 9,SNR1: 16.473 ,SNR2: 28.202



F20240726115811




BLK: 8,SNR1: 19.240 ,SNR2: 34.907





0821+394 2024/07/26 3.00UT FUJI -KISO


K20240726115808




BLK: 8,SNR1: 8.4917 ,SNR2: 15.927





T20240726120951




BLK:13,SNR1: 3.9418 ,SNR2: 9.8968




F20240726120951



BLK:13,SNR1: 0.39386 ,SNR2: 2.3689




0834-19 2024/07/26 3.19UT TOYOKAWA-FUJI






T20240726120951





BLK:19,SNR1: 3.2613 ,SNR2: 8.2047





0834-19 2024/07/26 3.19UT TOYOKAWA-KISO


K20240726120948




BLK:19,SNR1: 0.51968 ,SNR2: 4.0543





F20240726120951




BLK:14,SNR1: 0.37080 ,SNR2: 3.5761




K20240726120948





BLK:14,SNR1: 0.17138 ,SNR2: 2.1624




0834-19 2024/07/26 3.19UT FUJI -KISO



T20240726121457




BLK: 8,SNR1: 6.1047 ,SNR2: 16.422




Frequency (Hz)

0839-071 2024/07/26 3.28UT TOYOKAWA-FUJI


F20240726121457





BLK: 8,SNR1:-0.96875E-01,SNR2: 2.3927




Frequency (Hz)



T20240726121457




BLK:13,SNR1: 5.2610 ,SNR2: 14.347





0839-071 2024/07/26 3.28UT TOYOKAWA-KISO


K20240726121454




BLK:13,SNR1: 3.1167 ,SNR2: 8.8101



F20240726121457





BLK: 7,SNR1:-0.22012 ,SNR2: 0.89219





0839-071 2024/07/26 3.28UT FUJI -KISO



K20240726121454




BLK: 7,SNR1: 9.1409 ,SNR2: 25.046




T20240726122557




BLK:16,SNR1: 76.321 ,SNR2: 221.33




F20240726122557





BLK:16,SNR1: 2.1564 ,SNR2: 7.3429




3C208 2024/07/26 3.46UT TOYOKAWA-FUJI




T20240726122557




BLK:17,SNR1: 69.501 ,SNR2: 381.41




K20240726122554




BLK:17,SNR1: 2.1117 ,SNR2: 21.181




3C208 2024/07/26 3.46UT TOYOKAWA-KISO





F20240726122557




BLK: 9,SNR1: 3.2958 ,SNR2: 21.189




K20240726122554



BLK: 9,SNR1: 3.9658 ,SNR2: 37.554




3C208 2024/07/26 3.46UT FUJI -KISO







T20240726124239




BLK: 9,SNR1: 11.291 ,SNR2: 19.480




F20240726124239




BLK: 9,SNR1: 0.65711E-01,SNR2: 3.5448




3C216 2024/07/26 3.74UT TOYOKAWA-FUJI



T20240726124239





BLK:16,SNR1:-0.49510 ,SNR2: 0.0000





3C216 2024/07/26 3.74UT TOYOKAWA-KISO


K20240726124236




BLK:16,SNR1: 46.824 ,SNR2: 72.757





F20240726124239




BLK: 8,SNR1: 0.11887E-01,SNR2: 3.2822




K20240726124236





BLK: 8,SNR1: 24.930 ,SNR2: 43.817




3C216 2024/07/26 3.74UT FUJI -KISO



T20240726125450




BLK: 9,SNR1:-0.32341 ,SNR2: 1.2661





0919-142 2024/07/26 3.94UT TOYOKAWA-FUJI



F20240726125450




BLK: 9,SNR1:-0.11271 ,SNR2: 2.0469



T20240726125450




BLK: 7, SNR1: 7.4388 , SNR2: 11.819





0919-142 2024/07/26 3.94UT TOYOKAWA-KISO



K20240726125447




BLK: 7, SNR1: 17.529 , SNR2: 30.745





F20240726125450




BLK: 9,SNR1:-0.10926 ,SNR2: 2.0533




K20240726125447





BLK: 9,SNR1: 0.40205 ,SNR2: 4.6556




0919-142 2024/07/26 3.94UT FUJI -KISO




T20240726130129




BLK: 3,SNR1: 0.13540 ,SNR2: 1.2329




F20240726130129





BLK: 3,SNR1: 0.14243 ,SNR2: 3.1736




0926+117 2024/07/26 4.05UT TOYOKAWA-FUJI





T20240726130129




BLK: 3,SNR1: 0.29839E-01,SNR2: 0.54960




K20240726130126



BLK: 3,SNR1: 0.96481E-02,SNR2: 0.24761




0926+117 2024/07/26 4.05UT TOYOKAWA-KISO







F20240726130129




BLK: 4,SNR1: 0.24911E-01,SNR2: 0.83325




K20240726130126





BLK: 4,SNR1: 0.14096 ,SNR2: 0.60884




0926+117 2024/07/26 4.05UT FUJI -KISO



T20240726130914




BLK:15,SNR1: 0.43776 ,SNR2: 2.9172





3C222 2024/07/26 4.18UT TOYOKAWA-FUJI


F20240726130914




BLK:15,SNR1: 0.14976 ,SNR2: 3.1673



T20240726130914




BLK:14,SNR1: 0.33477 ,SNR2: 4.6669





3C222 2024/07/26 4.18UT TOYOKAWA-KISO



K20240726130911




BLK:14,SNR1: 6.6031 ,SNR2: 18.131





F20240726130914




BLK:20,SNR1: 0.57506 ,SNR2: 5.3809




K20240726130911





BLK:20,SNR1: 7.1914 ,SNR2: 19.447




3C222 2024/07/26 4.18UT FUJI -KISO



T20240726131614




BLK: 7,SNR1: 0.11498 ,SNR2: 3.8016





0941-08 2024/07/26 4.30UT TOYOKAWA-FUJI



F20240726131614




BLK: 7,SNR1: 0.59292E-01,SNR2: 2.0995



T20240726131614





BLK:16,SNR1: 0.11532 ,SNR2: 3.7798





0941-08 2024/07/26 4.30UT TOYOKAWA-KISO


K20240726131611




BLK:16,SNR1: 1.1423 ,SNR2: 5.5437





F20240726131614




BLK: 8,SNR1: 0.17558 ,SNR2: 3.3555




K20240726131611





BLK: 8,SNR1: 1.1932 ,SNR2: 5.7371




0941-08 2024/07/26 4.30UT FUJI -KISO




T20240726132436




BLK:11,SNR1: 0.37667 ,SNR2: 2.9647




F20240726132436



BLK:11,SNR1:-0.12196 ,SNR2: 2.3183





3C230 2024/07/26 4.44UT TOYOKAWA-FUJI






T20240726132436




BLK:21,SNR1: 0.25916 ,SNR2: 1.4350





3C230 2024/07/26 4.44UT TOYOKAWA-KISO


K20240726132433




BLK:21,SNR1: 0.26415 ,SNR2: 1.1126





F20240726132436




BLK: 6,SNR1:-0.22898 ,SNR2: 0.59819




K20240726132433




BLK: 6,SNR1: 0.41927E-01,SNR2: 0.61860




3C230 2024/07/26 4.44UT FUJI -KISO



T20240726133843




BLK:18,SNR1: 0.34648 ,SNR2: 1.2603




Frequency (Hz)

F20240726133843




BLK:18,SNR1: 0.60512 ,SNR2: 5.6382




Frequency (Hz)


3C236 2024/07/26 4.67UT TOYOKAWA-FUJI




T20240726133843




BLK:21,SNR1: 2.9012 ,SNR2: 7.8583




K20240726133840




BLK:21,SNR1: 6.7580 ,SNR2: 19.158




3C236 2024/07/26 4.67UT TOYOKAWA-KISO



F20240726133843





BLK:23,SNR1: 1.6597 ,SNR2: 4.4162





3C236 2024/07/26 4.67UT FUJI -KISO



K20240726133840




BLK:23,SNR1: 10.743 ,SNR2: 20.712





T20240726134653




BLK: 4,SNR1:-0.81180E-01,SNR2: 0.53846




F20240726134653





BLK: 4,SNR1: 1.4789 ,SNR2: 3.4760




1011+110 2024/07/26 4.81UT TOYOKAWA-FUJI





T20240726134653




BLK: 2,SNR1: 0.15839 ,SNR2: 0.70451




K20240726134650





BLK: 2,SNR1: 2.1762 ,SNR2: 10.053




1011+110 2024/07/26 4.81UT TOYOKAWA-KISO




F20240726134653




BLK: 5,SNR1: 1.5901 ,SNR2: 2.5382




K20240726134650



BLK: 5,SNR1: 0.18610 ,SNR2: 0.63470





1011+110 2024/07/26 4.81UT FUJI -KISO







T20240726135434




BLK:12,SNR1: 0.10524 ,SNR2: 1.0431




F20240726135434




BLK:12,SNR1: 7.1341 ,SNR2: 14.519




3C241 2024/07/26 4.94UT TOYOKAWA-FUJI





T20240726135434




BLK:13,SNR1: 0.23695 ,SNR2: 1.8212




K20240726135431




BLK:13,SNR1: 1.1126 ,SNR2: 3.9464




3C241 2024/07/26 4.94UT TOYOKAWA-KISO



F20240726135434





BLK:19,SNR1: 6.1103 ,SNR2: 14.846





3C241 2024/07/26 4.94UT FUJI -KISO



K20240726135431




BLK:19,SNR1: 4.8220 ,SNR2: 7.8969




T20240726140603




BLK: 4,SNR1: 0.13694 ,SNR2: 0.84770




F20240726140603





BLK: 4,SNR1: 1.7426 ,SNR2: 13.636




1031-11 2024/07/26 5.13UT TOYOKAWA-FUJI





T20240726140603




BLK:15,SNR1: 4.2982 ,SNR2: 8.3918




K20240726140600




BLK:15,SNR1: 5.5955 ,SNR2: 16.029




1031-11 2024/07/26 5.13UT TOYOKAWA-KISO





F20240726140603




BLK:12,SNR1: 0.76487 ,SNR2: 8.5086




K20240726140600





BLK:12,SNR1: 2.4549 ,SNR2: 9.5593




1031-11 2024/07/26 5.13UT FUJI -KISO





T20240726141037




BLK: 9,SNR1: 3.5918 ,SNR2: 52.490




F20240726141037




BLK: 9,SNR1: 1.1194 ,SNR2: 3.1411




1035-058 2024/07/26 5.21UT TOYOKAWA-FUJI





T20240726141037




BLK: 6,SNR1: 6.2809 ,SNR2: 46.530




K20240726141035



BLK: 6,SNR1: 1.1600 ,SNR2: 5.4193




1035-058 2024/07/26 5.21UT TOYOKAWA-KISO








F20240726141037




BLK: 6,SNR1: 0.74619 ,SNR2: 4.7692




K20240726141035





BLK: 6,SNR1: 0.57869E-02,SNR2: 0.69359




1035-058 2024/07/26 5.21UT FUJI -KISO



T20240726141949





BLK: 6,SNR1: 0.31277 ,SNR2: 1.8537




Frequency (Hz)

F20240726141949




BLK: 6,SNR1: 0.20008 ,SNR2: 1.4069





Frequency (Hz)


1044-008 2024/07/26 5.36UT TOYOKAWA-FUJI





T20240726141949




BLK: 2,SNR1: 0.27707 ,SNR2: 1.6800




K20240726141947




BLK: 2,SNR1: 2.5991 ,SNR2: 8.5772




1044-008 2024/07/26 5.36UT TOYOKAWA-KISO





F20240726141949




BLK: 5,SNR1: 0.52628 ,SNR2: 1.7354




K20240726141947





BLK: 5,SNR1: 0.48819 ,SNR2: 2.2483




1044-008 2024/07/26 5.36UT FUJI -KISO




T20240726143054




BLK:11,SNR1: 0.63420 ,SNR2: 4.2329




F20240726143054





BLK:11,SNR1: 1.0625 ,SNR2: 6.8417




1055+01 2024/07/26 5.54UT TOYOKAWA-FUJI





T20240726143054




BLK:15,SNR1: 0.41312 ,SNR2: 2.6327




K20240726143051




BLK:15,SNR1: 3.9091 ,SNR2: 31.843




1055+01 2024/07/26 5.54UT TOYOKAWA-KISO





F20240726143054




BLK: 7,SNR1: 1.5613 ,SNR2: 9.6328




K20240726143051





BLK: 7,SNR1: 7.5197 ,SNR2: 48.117




1055+01 2024/07/26 5.54UT FUJI -KISO





T20240726144211




BLK:10,SNR1: 0.24333 ,SNR2: 1.7983




F20240726144211



BLK:10,SNR1: 16.213 ,SNR2: 53.214





1107+109 2024/07/26 5.73UT TOYOKAWA-FUJI








T20240726144211




BLK: 9,SNR1: 0.25852 ,SNR2: 1.2836




K20240726144208




BLK: 9,SNR1: 0.24322 ,SNR2: 1.0985




1107+109 2024/07/26 5.73UT TOYOKAWA-KISO




F20240726144211




BLK:11,SNR1: 7.6514 ,SNR2: 31.310




K20240726144208





BLK:11,SNR1: 0.86810E-01,SNR2: 0.78977




1107+109 2024/07/26 5.73UT FUJI -KISO




T20240726145149




BLK: 8,SNR1: 0.79336 ,SNR2: 5.4880




F20240726145149





BLK: 8,SNR1: 0.67613 ,SNR2: 3.0506




3C255 2024/07/26 5.89UT TOYOKAWA-FUJI





T20240726145149




BLK: 8,SNR1: 1.4099 ,SNR2: 5.3330




K20240726145146





BLK: 8,SNR1: 0.87656E-01,SNR2: 0.97106




3C255 2024/07/26 5.89UT TOYOKAWA-KISO



F20240726145149





BLK: 5,SNR1: 0.56328 ,SNR2: 2.5619




Frequency (Hz)

K20240726145146




BLK: 5,SNR1: 0.14995 ,SNR2: 1.3398





Frequency (Hz)


3C255 2024/07/26 5.89UT FUJI -KISO




T20240726150226




BLK: 5,SNR1: 0.17129 ,SNR2: 0.49574




F20240726150226






BLK: 5,SNR1: 0.95206 ,SNR2: 1.7824






1127-14 2024/07/26 6.07UT TOYOKAWA-FUJI




T20240726150226






KISO






1127-14 2024/07/26 6.07UT TOYOKAWA-KISO




F20240726150226



KISO





1127-14 2024/07/26 6.07UT FUJI -KISO








T20240726151547




BLK:13,SNR1: 4.6414 ,SNR2: 20.289




F20240726151547





BLK:13,SNR1: 2.6163 ,SNR2: 2.8873




3C263.1 2024/07/26 6.29UT TOYOKAWA-FUJI





T20240726151547




No.Good Data




KISO






No.Good Data






3C263.1 2024/07/26 6.29UT TOYOKAWA-KISO




F20240726151547




KISO




3C263.1 2024/07/26 6.29UT FUJI -KISO





T20240726152214




BLK:11,SNR1: 62.111 ,SNR2: 155.70




F20240726152215




BLK:11,SNR1:-0.15826 ,SNR2: 2.1074




3C267 2024/07/26 6.40UT TOYOKAWA-FUJI





T20240726152214




BLK:13,SNR1: 78.021 ,SNR2: 188.57




K20240726152211




BLK:13,SNR1: 0.91587 ,SNR2: 3.7669




3C267 2024/07/26 6.40UT TOYOKAWA-KISO



F20240726152215





BLK:19,SNR1: 1.3685 ,SNR2: 1.3216




Frequency (Hz)

K20240726152211




BLK:19,SNR1: 1.5563 ,SNR2: 3.8913





Frequency (Hz)


3C267 2024/07/26 6.40UT FUJI -KISO



T20240726154801





BLK: 6,SNR1: 0.57959 ,SNR2: 2.8971




Frequency (Hz)

F20240726154801




BLK: 6,SNR1: 0.77970 ,SNR2: 2.4404





Frequency (Hz)


1213-17 2024/07/26 6.83UT TOYOKAWA-FUJI



T20240726154801





BLK:10,SNR1: 0.66160 ,SNR2: 3.0057




Frequency (Hz)

K20240726154758




BLK:10,SNR1: 0.91213 ,SNR2: 4.8758





Frequency (Hz)

1213-17 2024/07/26 6.83UT TOYOKAWA-KISO







F20240726154801




BLK:23,SNR1: 0.98863E-01,SNR2: 1.5720




K20240726154758





BLK:23,SNR1: 2.0884 ,SNR2: 3.9935




1213-17 2024/07/26 6.83UT FUJI -KISO



T20240726160119




BLK:10,SNR1: 0.66365 ,SNR2: 3.7372




Frequency (Hz)

F20240726160119




BLK:10,SNR1: 0.72525 ,SNR2: 2.6718





Frequency (Hz)


3C273 2024/07/26 7.05UT TOYOKAWA-FUJI




T20240726160119




BLK:16,SNR1: 0.69643 ,SNR2: 3.4288




K20240726160116





BLK:16,SNR1: 0.49140 ,SNR2: 4.1541




3C273 2024/07/26 7.05UT TOYOKAWA-KISO



F20240726160119





BLK:28,SNR1: 1.2825 ,SNR2: 3.5887




Frequency (Hz)

K20240726160116




BLK:28,SNR1: 5.9904 ,SNR2: 5.8795





Frequency (Hz)


3C273 2024/07/26 7.05UT FUJI -KISO



T20240726161429




BLK: 9,SNR1: 0.36625E-01,SNR2: 1.0133




Frequency (Hz)

F20240726161429




BLK: 9,SNR1: 1.7496 ,SNR2: 2.8759





Frequency (Hz)


3C275 2024/07/26 7.27UT TOYOKAWA-FUJI




T20240726161429




BLK:10,SNR1: 0.47933E-01,SNR2: 0.90761




K20240726161426




BLK:10,SNR1: 1.2780 ,SNR2: 6.1416




3C275 2024/07/26 7.27UT TOYOKAWA-KISO



F20240726161429




BLK:23,SNR1: 0.21001 ,SNR2: 2.0095




Frequency (Hz)

K20240726161426




BLK:23,SNR1: 2.1033 ,SNR2: 4.1308




Frequency (Hz)


3C275 2024/07/26 7.27UT FUJI -KISO



T20240726162034





BLK:12,SNR1: 0.18508 ,SNR2: 2.1679




Frequency (Hz)

F20240726162034




BLK:12,SNR1:-0.15924 ,SNR2: 0.69204




Frequency (Hz)

1245-19 2024/07/26 7.37UT TOYOKAWA-FUJI






T20240726162034





BLK:10,SNR1: 0.40846 ,SNR2: 3.3033




Frequency (Hz)

K20240726162031




BLK:10,SNR1: 2.2886 ,SNR2: 3.6060





Frequency (Hz)


1245-19 2024/07/26 7.37UT TOYOKAWA-KISO



F20240726162034





BLK:21,SNR1: 2.9245 ,SNR2: 4.4016




Frequency (Hz)

K20240726162031




BLK:21,SNR1: 3.6260 ,SNR2: 4.1667




Frequency (Hz)


1245-19 2024/07/26 7.37UT FUJI -KISO



T20240726162818




BLK:15,SNR1: 0.94659 ,SNR2: 4.5847




Frequency (Hz)

F20240726162818




BLK:15,SNR1: 2.8101 ,SNR2: 3.1700




Frequency (Hz)


3C279 2024/07/26 7.50UT TOYOKAWA-FUJI



T20240726162818




BLK:12,SNR1: 0.16528 ,SNR2: 1.2644




Frequency (Hz)

K20240726162815




BLK:12,SNR1: 6.6859 ,SNR2: 11.780




Frequency (Hz)


3C279 2024/07/26 7.50UT TOYOKAWA-KISO



F20240726162818





BLK:28,SNR1: 3.1272 ,SNR2: 3.3230




Frequency (Hz)

K20240726162815




BLK:28,SNR1: 8.0438 ,SNR2: 10.074




Frequency (Hz)


3C279 2024/07/26 7.50UT FUJI -KISO





T20240726164806




BLK:12,SNR1: 0.10100 ,SNR2: 1.1895




F20240726164807





BLK:12,SNR1: 1.2245 ,SNR2: 3.1326




1313+453 2024/07/26 7.83UT TOYOKAWA-FUJI



T20240726164806





BLK:11,SNR1: 0.12551 ,SNR2: 1.1722




Frequency (Hz)

K20240726164803




BLK:11,SNR1: 8.6682 ,SNR2: 9.1163





Frequency (Hz)


1313+453 2024/07/26 7.83UT TOYOKAWA-KISO



F20240726164807





BLK:25,SNR1: 0.84167 ,SNR2: 1.1745




Frequency (Hz)

K20240726164803




BLK:25,SNR1: 6.6098 ,SNR2: 6.6425




Frequency (Hz)

1313+453 2024/07/26 7.83UT FUJI -KISO






T20240726165812





BLK: 8,SNR1: 0.58019 ,SNR2: 3.9889




Frequency (Hz)

F20240726165812




BLK: 8,SNR1: 1.9674 ,SNR2: 1.8950





Frequency (Hz)


1323+32 2024/07/26 8.00UT TOYOKAWA-FUJI



T20240726165812




BLK: 9,SNR1: 0.40159 ,SNR2: 1.6340




Frequency (Hz)

K20240726165809




BLK: 9,SNR1: 2.2128 ,SNR2: 4.1628





Frequency (Hz)


1323+32 2024/07/26 8.00UT TOYOKAWA-KISO



F20240726165812




BLK:22,SNR1: 0.85224 ,SNR2: 1.6102




Frequency (Hz)

K20240726165809




BLK:22,SNR1: 3.3342 ,SNR2: 6.4363




Frequency (Hz)


1323+32 2024/07/26 8.00UT FUJI -KISO



T20240726170302





BLK: 8,SNR1:-0.19987 ,SNR2: 1.7760




Frequency (Hz)

F20240726170302




BLK: 8,SNR1: 3.0006 ,SNR2: 2.8923





Frequency (Hz)


3C286 2024/07/26 8.08UT TOYOKAWA-FUJI



T20240726170302





BLK:10,SNR1:-0.19222 ,SNR2: 1.8466




Frequency (Hz)

K20240726170259




BLK:10,SNR1: 1.3579 ,SNR2: 5.4223





Frequency (Hz)


3C286 2024/07/26 8.08UT TOYOKAWA-KISO



F20240726170302





BLK:21,SNR1: 3.8018 ,SNR2: 3.6407




Frequency (Hz)

K20240726170259




BLK:21,SNR1: 0.48751 ,SNR2: 2.3844





Frequency (Hz)


3C286 2024/07/26 8.08UT FUJI -KISO



T20240726171929





BLK:13,SNR1: 0.79727 ,SNR2: 3.2348




Frequency (Hz)

F20240726171929




BLK:13,SNR1: 0.43094 ,SNR2: 1.5734





Frequency (Hz)


1345+12 2024/07/26 8.35UT TOYOKAWA-FUJI



T20240726171929





BLK:22,SNR1: 2.6783 ,SNR2: 11.167




Frequency (Hz)

K20240726171926




BLK:22,SNR1: 8.6447 ,SNR2: 24.474





Frequency (Hz)

1345+12 2024/07/26 8.35UT TOYOKAWA-KISO






F20240726171929





BLK:19,SNR1: 0.44898 ,SNR2: 1.6250




Frequency (Hz)

K20240726171926



BLK:19,SNR1: 4.0584 ,SNR2: 11.257



Frequency (Hz)

1345+12 2024/07/26 8.35UT FUJI -KISO

