




T20240728062752





BLK: 4,SNR1:-0.40761E-01,SNR2: 0.93704




Frequency (Hz)

F20240728062752




BLK: 4,SNR1: 0.82245E-01,SNR2: 3.0390





Frequency (Hz)


0258+350 2024/07/27 21.49UT TOYOKAWA-FUJI



T20240728062752





BLK: 6,SNR1:-0.28682E-02,SNR2: 0.91916




Frequency (Hz)

K20240728062749




BLK: 6,SNR1: 0.50212 ,SNR2: 2.1251




Frequency (Hz)

0258+350 2024/07/27 21.49UT TOYOKAWA-KISO






F20240728062752




BLK: 7,SNR1: 0.12396 ,SNR2: 2.9465




Frequency (Hz)

0258+350 2024/07/27 21.49UT FUJI -KISO


K20240728062749





BLK: 7,SNR1: 0.64176 ,SNR2: 2.5152




Frequency (Hz)



T20240728063741





BLK: 7,SNR1:-0.37809E-01,SNR2: 0.66055




Frequency (Hz)

F20240728063742




BLK: 7,SNR1: 0.29034 ,SNR2: 5.5442





Frequency (Hz)


0308+305 2024/07/27 21.66UT TOYOKAWA-FUJI



T20240728063741





BLK: 1,SNR1: 0.47080E-01,SNR2: 0.94143




Frequency (Hz)

K20240728063738




BLK: 1,SNR1:-0.14099E-02,SNR2: 1.6045





Frequency (Hz)


0308+305 2024/07/27 21.66UT TOYOKAWA-KISO



F20240728063742





BLK: 6,SNR1: 0.20923 ,SNR2: 4.2141




Frequency (Hz)

K20240728063738




BLK: 6,SNR1:-0.33431E-01,SNR2: 2.8502





Frequency (Hz)


0308+305 2024/07/27 21.66UT FUJI -KISO



T20240728064913





BLK: 6,SNR1: 0.13028 ,SNR2: 0.96559




Frequency (Hz)

F20240728064913




BLK: 6,SNR1: 0.17639 ,SNR2: 1.8945




Frequency (Hz)


0320+05 2024/07/27 21.85UT TOYOKAWA-FUJI




T20240728064913




BLK: 8,SNR1: 0.97452E-01,SNR2: 1.3875




K20240728064910





BLK: 8,SNR1: 0.52837E-01,SNR2: 1.6499




0320+05 2024/07/27 21.85UT TOYOKAWA-KISO





F20240728064913




BLK: 6,SNR1: 0.71274E-02,SNR2: 1.6515




K20240728064910




BLK: 6,SNR1: 0.35354E-01,SNR2: 2.7406




0320+05 2024/07/27 21.85UT FUJI -KISO



T20240728070234





BLK: 5,SNR1:-0.30162E-01,SNR2: 0.48746




Frequency (Hz)

F20240728070234




BLK: 5,SNR1: 7.7518 ,SNR2: 13.186




Frequency (Hz)

0333+32 2024/07/27 22.07UT TOYOKAWA-FUJI






T20240728070234





BLK: 6,SNR1: 0.21378 ,SNR2: 0.68202




Frequency (Hz)

K20240728070231




BLK: 6,SNR1: 6.6118 ,SNR2: 14.118





Frequency (Hz)


0333+32 2024/07/27 22.07UT TOYOKAWA-KISO



F20240728070234





BLK:10,SNR1: 6.1952 ,SNR2: 10.107




Frequency (Hz)

K20240728070231




BLK:10,SNR1: 6.5429 ,SNR2: 13.976





Frequency (Hz)


0333+32 2024/07/27 22.07UT FUJI -KISO



T20240728071536





BLK: 1,SNR1: 0.25599 ,SNR2: 1.2037




Frequency (Hz)

F20240728071536




BLK: 1,SNR1: 0.31248 ,SNR2: 1.8167





Frequency (Hz)


0347+05 2024/07/27 22.29UT TOYOKAWA-FUJI




T20240728071536




BLK: 5,SNR1:-0.57503E-01,SNR2: 0.30850




K20240728071533




BLK: 5,SNR1: 1.0637 ,SNR2: 3.1975




0347+05 2024/07/27 22.29UT TOYOKAWA-KISO



F20240728071536




BLK: 7,SNR1: 0.42700 ,SNR2: 2.0058




Frequency (Hz)

K20240728071533




BLK: 7,SNR1: 0.14489 ,SNR2: 1.9429




Frequency (Hz)


0347+05 2024/07/27 22.29UT FUJI -KISO




T20240728073110



Time (sec)




BLK: 2,SNR1: 0.41885 ,SNR2: 1.5168




Frequency (Hz)


F20240728073110



Time (sec)




BLK: 2,SNR1:-0.19935 ,SNR2: 0.68557





Frequency (Hz)


0403-132 2024/07/27 22.55UT TOYOKAWA-FUJI



T20240728073110





BLK: 3,SNR1: 0.31814E-01,SNR2: 1.0396




Frequency (Hz)

K20240728073107




BLK: 3,SNR1: 0.85869 ,SNR2: 4.8327





Frequency (Hz)


0403-132 2024/07/27 22.55UT TOYOKAWA-KISO



F20240728073110





BLK: 1,SNR1:-0.34898 ,SNR2: 0.71154




Frequency (Hz)

K20240728073107




BLK: 1,SNR1: 0.66524 ,SNR2: 2.4504





Frequency (Hz)

0403-132 2024/07/27 22.55UT FUJI -KISO






T20240728074021





BLK: 2,SNR1:-0.68298E-01,SNR2: 0.46707




Frequency (Hz)

F20240728074021




BLK: 2,SNR1:-0.12962 ,SNR2: 2.4764




Frequency (Hz)


0411+05 2024/07/27 22.70UT TOYOKAWA-FUJI



T20240728074021




BLK: 2,SNR1:-0.24537E-01,SNR2: 1.0181




Frequency (Hz)

K20240728074018




BLK: 2,SNR1: 0.23492 ,SNR2: 1.6521





Frequency (Hz)


0411+05 2024/07/27 22.70UT TOYOKAWA-KISO



F20240728074021





BLK: 2,SNR1: 1.3152 ,SNR2: 5.2282




Frequency (Hz)

K20240728074018




BLK: 2,SNR1: 0.30560 ,SNR2: 1.4254





Frequency (Hz)


0411+05 2024/07/27 22.70UT FUJI -KISO



T20240728074715





BLK: 3,SNR1: 0.13659 ,SNR2: 0.17835




Frequency (Hz)

F20240728074715




BLK: 3,SNR1: 0.68219E-01,SNR2: 2.3710





Frequency (Hz)


0418+236 2024/07/27 22.82UT TOYOKAWA-FUJI



T20240728074715





BLK: 6,SNR1: 0.69332E-01,SNR2: 0.24508




Frequency (Hz)

K20240728074712




BLK: 6,SNR1: 0.81642 ,SNR2: 2.7137




Frequency (Hz)


0418+236 2024/07/27 22.82UT TOYOKAWA-KISO



F20240728074715




BLK: 3,SNR1:-0.28522E-01,SNR2: 0.57912




Frequency (Hz)

K20240728074712




BLK: 3,SNR1: 0.21706 ,SNR2: 0.75987





Frequency (Hz)


0418+236 2024/07/27 22.82UT FUJI -KISO



T20240728075842





BLK: 9,SNR1: 0.76830 ,SNR2: 8.0700




Frequency (Hz)

3C119 2024/07/27 23.01UT TOYOKAWA-FUJI


F20240728075842




BLK: 9,SNR1: 13.680 ,SNR2: 25.401




Frequency (Hz)



T20240728075842





BLK:20,SNR1: 0.39386 ,SNR2: 3.7320




Frequency (Hz)

K20240728075840




BLK:20,SNR1: 0.14907 ,SNR2: 1.3676





Frequency (Hz)

3C119 2024/07/27 23.01UT TOYOKAWA-KISO






F20240728075842





BLK: 5,SNR1: 9.4876 ,SNR2: 20.004




Frequency (Hz)

3C119 2024/07/27 23.01UT FUJI -KISO


K20240728075840




BLK: 5,SNR1:-0.11649 ,SNR2: 2.4079




Frequency (Hz)



T20240728084650





BLK:22,SNR1: 1.5062 ,SNR2: 6.3048




Frequency (Hz)

3C138 2024/07/27 23.81UT TOYOKAWA-FUJI


F20240728084650




BLK:22,SNR1: 0.95319 ,SNR2: 3.4272




Frequency (Hz)





T20240728084650




BLK:28,SNR1: 1.4443 ,SNR2: 6.4417




K20240728084647





BLK:28,SNR1: 0.67304 ,SNR2: 2.8636




3C138 2024/07/27 23.81UT TOYOKAWA-KISO



F20240728084650




BLK:18,SNR1: 2.1312 ,SNR2: 7.3481




Frequency (Hz)

3C138 2024/07/27 23.81UT FUJI -KISO


K20240728084647





BLK:18,SNR1: 1.0797 ,SNR2: 4.2555




Frequency (Hz)





T20240728085413




BLK: 3,SNR1:-0.16942E-01,SNR2: 0.52690




F20240728085413





BLK: 3,SNR1: 2.0505 ,SNR2: 3.2730




0525+215 2024/07/27 23.93UT TOYOKAWA-FUJI





T20240728085413




BLK: 6,SNR1: 0.67933E-01,SNR2: 0.88650




K20240728085410





BLK: 6,SNR1: 0.57605 ,SNR2: 3.6227




0525+215 2024/07/27 23.93UT TOYOKAWA-KISO





F20240728085413




BLK: 9,SNR1: 0.47443 ,SNR2: 4.0030




K20240728085410




BLK: 9,SNR1: 0.58376 ,SNR2: 2.8567




0525+215 2024/07/27 23.93UT FUJI -KISO



T20240728090023




BLK:10,SNR1: 1.2994 ,SNR2: 13.309




Frequency (Hz)

F20240728090024




BLK:10,SNR1:-0.28423E-01,SNR2: 1.7104




Frequency (Hz)

0531+194 2024/07/28 0.03UT TOYOKAWA-FUJI






T20240728090023




BLK:30,SNR1: 0.96094 ,SNR2: 7.0160





0531+194 2024/07/28 0.03UT TOYOKAWA-KISO


K20240728090020




BLK:30,SNR1: 0.18266 ,SNR2: 2.5697



F20240728090024




BLK: 9,SNR1:-0.68297E-01,SNR2: 0.76884




Frequency (Hz)

K20240728090020




BLK: 9,SNR1: 0.31143 ,SNR2: 4.0298





Frequency (Hz)


0531+194 2024/07/28 0.03UT FUJI -KISO



T20240728090842





BLK:21,SNR1: 6.4704 ,SNR2: 45.506




Frequency (Hz)

3C147 2024/07/28 0.17UT TOYOKAWA-FUJI


F20240728090842




BLK:21,SNR1:-0.31625E-01,SNR2: 1.4345




Frequency (Hz)



T20240728090842




BLK:26,SNR1: 6.3943 ,SNR2: 44.892




Frequency (Hz)

3C147 2024/07/28 0.17UT TOYOKAWA-KISO


K20240728090839




BLK:26,SNR1: 0.97102 ,SNR2: 9.9314




Frequency (Hz)



F20240728090842




BLK:25,SNR1: 0.16430E-01,SNR2: 1.9794




Frequency (Hz)

3C147 2024/07/28 0.17UT FUJI -KISO


K20240728090839





BLK:25,SNR1: 1.0974 ,SNR2: 8.1981




Frequency (Hz)



T20240728091654




BLK:15,SNR1: 0.20065 ,SNR2: 1.2921




Frequency (Hz)

F20240728091655




BLK:15,SNR1: 4.3247 ,SNR2: 5.7645





Frequency (Hz)


0548+16 2024/07/28 0.31UT TOYOKAWA-FUJI




T20240728091654




BLK:17,SNR1: 0.22038 ,SNR2: 3.0385




K20240728091651




BLK:17,SNR1: 1.1988 ,SNR2: 2.4517




0548+16 2024/07/28 0.31UT TOYOKAWA-KISO




F20240728091655




BLK:16,SNR1: 1.6866 ,SNR2: 3.4415




K20240728091651



BLK:16,SNR1: 0.95619 ,SNR2: 3.6379





0548+16 2024/07/28 0.31UT FUJI -KISO






T20240728092105





BLK: 9,SNR1: 0.18365 ,SNR2: 1.5478




Frequency (Hz)

F20240728092106




BLK: 9,SNR1: 0.41182 ,SNR2: 2.1190





Frequency (Hz)


0552+12 2024/07/28 0.38UT TOYOKAWA-FUJI





T20240728092105




BLK:14,SNR1: 0.18647 ,SNR2: 1.3160




K20240728092102





BLK:14,SNR1: 0.39021 ,SNR2: 2.3656




0552+12 2024/07/28 0.38UT TOYOKAWA-KISO





F20240728092106




BLK:16,SNR1: 1.2327 ,SNR2: 1.9257




K20240728092102





BLK:16,SNR1: 0.43395 ,SNR2: 1.8207




0552+12 2024/07/28 0.38UT FUJI -KISO





T20240728092532




BLK: 6,SNR1: 0.54049E-02,SNR2: 0.40062




F20240728092532





BLK: 6,SNR1: 0.57247 ,SNR2: 4.8981




0556+191 2024/07/28 0.45UT TOYOKAWA-FUJI





T20240728092532




BLK: 8,SNR1: 0.10582 ,SNR2: 0.59434




K20240728092529




BLK: 8,SNR1: 0.11212 ,SNR2: 0.92080




0556+191 2024/07/28 0.45UT TOYOKAWA-KISO





F20240728092532




BLK:12,SNR1: 0.90644 ,SNR2: 3.4682




K20240728092529




BLK:12,SNR1:-0.18118E-01,SNR2: 0.93676




0556+191 2024/07/28 0.45UT FUJI -KISO





T20240728093004




BLK:15,SNR1: 0.38953 ,SNR2: 1.2987




F20240728093004




BLK:15,SNR1: 2.7172 ,SNR2: 9.5999




3C152 2024/07/28 0.53UT TOYOKAWA-FUJI





T20240728093004




BLK:21,SNR1: 0.36818 ,SNR2: 1.5462




K20240728093001



BLK:21,SNR1: 0.28133 ,SNR2: 1.6938




3C152 2024/07/28 0.53UT TOYOKAWA-KISO






F20240728093004





BLK:15,SNR1: 2.5992 ,SNR2: 9.4773





3C152 2024/07/28 0.53UT FUJI -KISO


K20240728093001




BLK:15,SNR1: 0.29761 ,SNR2: 1.3718





T20240728095225




BLK:16,SNR1: 17.901 ,SNR2: 22.861




F20240728095225




BLK:16,SNR1: 45.397 ,SNR2: 52.063




3C161 2024/07/28 0.90UT TOYOKAWA-FUJI



T20240728095225




BLK:23,SNR1: 6.5876 ,SNR2: 11.115




Frequency (Hz)

3C161 2024/07/28 0.90UT TOYOKAWA-KISO


K20240728095222





BLK:23,SNR1: 4.9587 ,SNR2: 7.9538




Frequency (Hz)




F20240728095225




BLK:20,SNR1: 24.802 ,SNR2: 35.682




K20240728095222





BLK:20,SNR1: 6.2053 ,SNR2: 9.8160




3C161 2024/07/28 0.90UT FUJI -KISO





T20240728101958




BLK: 6,SNR1: 0.12774 ,SNR2: 1.5692




F20240728101958




BLK: 6,SNR1:-0.29577 ,SNR2: 0.58209




0652-130 2024/07/28 1.36UT TOYOKAWA-FUJI





T20240728101958




BLK: 4,SNR1: 0.97717E-01,SNR2: 1.2028




K20240728101955




BLK: 4,SNR1: 2.2406 ,SNR2: 11.484




0652-130 2024/07/28 1.36UT TOYOKAWA-KISO





F20240728101958




BLK: 7,SNR1: 0.64750 ,SNR2: 3.4000




K20240728101955





BLK: 7,SNR1: 0.85107E-01,SNR2: 1.0477




0652-130 2024/07/28 1.36UT FUJI -KISO





T20240728103135




BLK:10,SNR1: 0.82121E-01,SNR2: 0.33689




F20240728103135



BLK:10,SNR1: 0.25066 ,SNR2: 1.1234





0703+138 2024/07/28 1.55UT TOYOKAWA-FUJI






T20240728103135





BLK: 4,SNR1: 0.13937 ,SNR2: 2.1905





0703+138 2024/07/28 1.55UT TOYOKAWA-KISO


K20240728103132




BLK: 4,SNR1: 0.65125 ,SNR2: 6.3573





F20240728103135




BLK: 9,SNR1: 0.76083 ,SNR2: 5.0814




K20240728103132




BLK: 9,SNR1: 0.42293 ,SNR2: 2.2590




0703+138 2024/07/28 1.55UT FUJI -KISO




T20240728104057




BLK:18,SNR1: 2.5952 ,SNR2: 6.1477




F20240728104057




BLK:18,SNR1: 2.2733 ,SNR2: 5.5834




0713-024 2024/07/28 1.71UT TOYOKAWA-FUJI



T20240728104057





BLK:13,SNR1: 0.71552 ,SNR2: 3.2759




Frequency (Hz)

K20240728104054




BLK:13,SNR1: 1.7106 ,SNR2: 3.3850





Frequency (Hz)


0713-024 2024/07/28 1.71UT TOYOKAWA-KISO



F20240728104057





BLK:18,SNR1: 3.2125 ,SNR2: 7.7670




Frequency (Hz)

K20240728104054




BLK:18,SNR1: 1.3999 ,SNR2: 5.3819




Frequency (Hz)


0713-024 2024/07/28 1.71UT FUJI -KISO





T20240728105109




BLK:35,SNR1: 8.7397 ,SNR2: 16.952




F20240728105109




BLK:35,SNR1: 126.23 ,SNR2: 176.72




0723+10 2024/07/28 1.88UT TOYOKAWA-FUJI





T20240728105109




BLK:33,SNR1: 8.9030 ,SNR2: 31.820




K20240728105106





BLK:33,SNR1: 43.706 ,SNR2: 62.921




0723+10 2024/07/28 1.88UT TOYOKAWA-KISO




F20240728105109




BLK:35,SNR1: 127.91 ,SNR2: 195.21




K20240728105106



BLK:35,SNR1: 40.929 ,SNR2: 58.929





0723+10 2024/07/28 1.88UT FUJI -KISO






T20240728110124





BLK:34,SNR1: 6.9557 ,SNR2: 17.071





0732+33 2024/07/28 2.05UT TOYOKAWA-FUJI



F20240728110124




BLK:34,SNR1: 15.786 ,SNR2: 27.828



T20240728110124





BLK:34,SNR1: 10.425 ,SNR2: 24.329





0732+33 2024/07/28 2.05UT TOYOKAWA-KISO



K20240728110121




BLK:34,SNR1: 7.8462 ,SNR2: 19.964





F20240728110124




BLK:35,SNR1: 15.764 ,SNR2: 27.789




K20240728110121





BLK:35,SNR1: 7.8490 ,SNR2: 19.971




0732+33 2024/07/28 2.05UT FUJI -KISO




T20240728110926




BLK: 8,SNR1:-0.70806E-01,SNR2: 1.8008




F20240728110926





BLK: 8,SNR1:-0.79165E-01,SNR2: 2.0063




0741-06 2024/07/28 2.19UT TOYOKAWA-FUJI



T20240728110926




BLK:13,SNR1:-0.24477 ,SNR2: 0.62812




0741-06 2024/07/28 2.19UT TOYOKAWA-KISO


K20240728110923




BLK:13,SNR1: 1.4591 ,SNR2: 4.1523




Frequency (Hz)




F20240728110926




BLK: 9,SNR1:-0.94238E-01,SNR2: 1.4801




K20240728110923




BLK: 9,SNR1:-0.17521 ,SNR2: 1.3327




0741-06 2024/07/28 2.19UT FUJI -KISO




T20240728111910




BLK:19,SNR1: 0.26467 ,SNR2: 2.7399




F20240728111910




BLK:19,SNR1: 1.0974 ,SNR2: 2.9058




0752-200 2024/07/28 2.35UT TOYOKAWA-FUJI




T20240728111910




BLK:23,SNR1: 0.29250 ,SNR2: 2.7619




K20240728111907



BLK:23,SNR1: 1.7332 ,SNR2: 6.6919




0752-200 2024/07/28 2.35UT TOYOKAWA-KISO







F20240728111910




BLK:15,SNR1: 1.0989 ,SNR2: 2.8691




K20240728111907




BLK:15,SNR1: 1.4758 ,SNR2: 6.7098




0752-200 2024/07/28 2.35UT FUJI -KISO




T20240728112645




BLK:19,SNR1: 0.67490 ,SNR2: 1.8088




F20240728112645




BLK:19,SNR1: 10.816 ,SNR2: 15.674




3C190 2024/07/28 2.47UT TOYOKAWA-FUJI



T20240728112645





BLK:22,SNR1: 8.2978 ,SNR2: 22.795





3C190 2024/07/28 2.47UT TOYOKAWA-KISO


K20240728112642




BLK:22,SNR1: 8.5783 ,SNR2: 22.991



F20240728112645





BLK:23,SNR1: 8.9698 ,SNR2: 13.683





3C190 2024/07/28 2.47UT FUJI -KISO



K20240728112642




BLK:23,SNR1: 8.6812 ,SNR2: 23.255




T20240728113909




BLK:15,SNR1: 0.94248 ,SNR2: 2.4777




F20240728113910




BLK:15,SNR1:-0.83379E-01,SNR2: 0.80705




3C196 2024/07/28 2.68UT TOYOKAWA-FUJI





T20240728113909




BLK:35,SNR1: 0.87477 ,SNR2: 1.7156




K20240728113906




BLK:35,SNR1: 0.53035 ,SNR2: 2.2100




3C196 2024/07/28 2.68UT TOYOKAWA-KISO



F20240728113910





BLK: 6,SNR1:-0.10238 ,SNR2: 0.23347





3C196 2024/07/28 2.68UT FUJI -KISO



K20240728113906




BLK: 6,SNR1: 1.2505 ,SNR2: 11.697




T20240728115019




BLK:13,SNR1: 0.81821 ,SNR2: 7.1289




F20240728115019



BLK:13,SNR1: 0.12020E-01,SNR2: 1.6790




0821+394 2024/07/28 2.87UT TOYOKAWA-FUJI







T20240728115019




BLK:28,SNR1: 0.82735 ,SNR2: 5.2464




K20240728115016




BLK:28,SNR1: 0.80736 ,SNR2: 2.4739




0821+394 2024/07/28 2.87UT TOYOKAWA-KISO





F20240728115019




BLK:15,SNR1:-0.87892E-03,SNR2: 1.4703




K20240728115016




BLK:15,SNR1: 1.6466 ,SNR2: 4.9586




0821+394 2024/07/28 2.87UT FUJI -KISO





T20240728120159




BLK:29,SNR1: 5.2125 ,SNR2: 13.548




F20240728120159





BLK:29,SNR1: 65.346 ,SNR2: 80.883




0834-19 2024/07/28 3.06UT TOYOKAWA-FUJI



T20240728120159





BLK:20,SNR1: 6.3019 ,SNR2: 16.226




0834-19 2024/07/28 3.06UT TOYOKAWA-KISO


K20240728120156





BLK:20,SNR1: 0.64160 ,SNR2: 2.7329




Frequency (Hz)



F20240728120159





BLK:10,SNR1: 3.4309 ,SNR2: 21.936





0834-19 2024/07/28 3.06UT FUJI -KISO



K20240728120156




BLK:10,SNR1: 0.13165 ,SNR2: 1.9806




T20240728120705




BLK:13,SNR1: 9.4718 ,SNR2: 15.057




F20240728120706





BLK:13,SNR1: 14.052 ,SNR2: 19.549




0839-071 2024/07/28 3.15UT TOYOKAWA-FUJI



T20240728120705




BLK:21,SNR1: 9.8374 ,SNR2: 18.627





0839-071 2024/07/28 3.15UT TOYOKAWA-KISO


K20240728120702




BLK:21,SNR1: 13.761 ,SNR2: 23.480



F20240728120706




BLK:11,SNR1: 13.483 ,SNR2: 22.634





0839-071 2024/07/28 3.15UT FUJI -KISO

K20240728120702





BLK:11,SNR1: 14.969 ,SNR2: 25.557






T20240728121806




BLK:24,SNR1: 0.32994 ,SNR2: 5.1412





3C208 2024/07/28 3.33UT TOYOKAWA-FUJI



F20240728121806




BLK:24,SNR1: 1.9747 ,SNR2: 4.7842



T20240728121806





BLK:27,SNR1: 0.32862 ,SNR2: 5.1350





3C208 2024/07/28 3.33UT TOYOKAWA-KISO


K20240728121803




BLK:27,SNR1: 8.2615 ,SNR2: 23.482



F20240728121806





BLK:23,SNR1: 1.8898 ,SNR2: 4.5903





3C208 2024/07/28 3.33UT FUJI -KISO


K20240728121803




BLK:23,SNR1: 6.1088 ,SNR2: 10.802



T20240728123447




BLK:11,SNR1: 0.18930 ,SNR2: 2.1349




Frequency (Hz)

F20240728123447




BLK:11,SNR1: 0.52465 ,SNR2: 3.2241





Frequency (Hz)


3C216 2024/07/28 3.61UT TOYOKAWA-FUJI



T20240728123447





BLK:13,SNR1: 0.35991 ,SNR2: 4.2970





3C216 2024/07/28 3.61UT TOYOKAWA-KISO


K20240728123444




BLK:13,SNR1: 0.14824 ,SNR2: 2.2508





F20240728123447




BLK: 6,SNR1: 1.2580 ,SNR2: 3.1618




K20240728123444





BLK: 6,SNR1: 0.29929 ,SNR2: 1.2567




3C216 2024/07/28 3.61UT FUJI -KISO



T20240728124659




BLK: 3,SNR1: 0.48392 ,SNR2: 2.7270





0919-142 2024/07/28 3.81UT TOYOKAWA-FUJI



F20240728124659




BLK: 3,SNR1:-0.12748 ,SNR2: 1.1304



T20240728124659




BLK: 9,SNR1: 0.53506 ,SNR2: 5.2115





0919-142 2024/07/28 3.81UT TOYOKAWA-KISO

K20240728124656




BLK: 9,SNR1: 4.6846 ,SNR2: 13.001






F20240728124659





BLK: 9,SNR1: 0.19137 ,SNR2: 2.2841





0919-142 2024/07/28 3.81UT FUJI -KISO



K20240728124656




BLK: 9,SNR1: 6.6940 ,SNR2: 18.378





T20240728125337




BLK: 4,SNR1: 0.72738E-01,SNR2: 2.8827




F20240728125337





BLK: 4,SNR1: 0.68622E-01,SNR2: 0.66218




0926+117 2024/07/28 3.92UT TOYOKAWA-FUJI





T20240728125337




BLK: 8,SNR1: 0.72535E-01,SNR2: 1.0462




K20240728125334




BLK: 8,SNR1: 0.16975 ,SNR2: 1.4969




0926+117 2024/07/28 3.92UT TOYOKAWA-KISO





F20240728125337




BLK: 5,SNR1: 0.13034 ,SNR2: 1.1892




K20240728125334




BLK: 5,SNR1: 0.40980 ,SNR2: 2.0770




0926+117 2024/07/28 3.92UT FUJI -KISO




T20240728130122




BLK: 8,SNR1: 1.2426 ,SNR2: 8.2102




F20240728130122




BLK: 8,SNR1: 7.7649 ,SNR2: 30.405




3C222 2024/07/28 4.05UT TOYOKAWA-FUJI





T20240728130122




BLK:26,SNR1: 1.4194 ,SNR2: 5.1919




K20240728130120




BLK:26,SNR1: 0.21954 ,SNR2: 1.2828




3C222 2024/07/28 4.05UT TOYOKAWA-KISO





F20240728130122




BLK:11,SNR1: 4.4562 ,SNR2: 10.980




K20240728130120





BLK:11,SNR1: 0.68279 ,SNR2: 3.5942




3C222 2024/07/28 4.05UT FUJI -KISO





T20240728130822




BLK: 7,SNR1: 0.94359E-01,SNR2: 1.4649




F20240728130822



BLK: 7,SNR1: 0.16595 ,SNR2: 1.2988





0941-08 2024/07/28 4.17UT TOYOKAWA-FUJI







T20240728130822




BLK: 7,SNR1: 0.49631 ,SNR2: 2.5507




K20240728130819





BLK: 7,SNR1: 0.45391E-01,SNR2: 0.53531




0941-08 2024/07/28 4.17UT TOYOKAWA-KISO





F20240728130822




BLK: 3,SNR1: 1.1250 ,SNR2: 2.9145




K20240728130819





BLK: 3,SNR1: 0.28082 ,SNR2: 0.85232




0941-08 2024/07/28 4.17UT FUJI -KISO





T20240728131644




BLK:16,SNR1: 0.60543 ,SNR2: 2.7208




F20240728131644





BLK:16,SNR1: 0.12094 ,SNR2: 3.2871




3C230 2024/07/28 4.31UT TOYOKAWA-FUJI





T20240728131644




BLK:21,SNR1: 0.55118 ,SNR2: 2.6159




K20240728131641





BLK:21,SNR1: 6.6887 ,SNR2: 13.080




3C230 2024/07/28 4.31UT TOYOKAWA-KISO



F20240728131644





BLK:16,SNR1: 0.20218 ,SNR2: 3.7305





3C230 2024/07/28 4.31UT FUJI -KISO



K20240728131641




BLK:16,SNR1: 10.113 ,SNR2: 19.697




T20240728133051




BLK: 7,SNR1: 0.40327 ,SNR2: 7.2171




F20240728133052





BLK: 7,SNR1:-0.38022 ,SNR2: 0.23061




3C236 2024/07/28 4.54UT TOYOKAWA-FUJI





T20240728133051




BLK:15,SNR1: 0.36011 ,SNR2: 2.8375




K20240728133049




BLK:15,SNR1: 0.29807 ,SNR2: 2.2589




3C236 2024/07/28 4.54UT TOYOKAWA-KISO



F20240728133052





BLK: 3,SNR1:-0.38824 ,SNR2: 0.47589E-01





3C236 2024/07/28 4.54UT FUJI -KISO

K20240728133049





BLK: 3,SNR1: 0.27010 ,SNR2: 1.1915








T20240728133901




BLK: 5,SNR1: 0.20168 ,SNR2: 3.9614




F20240728133901





BLK: 5,SNR1: 0.29973E-02,SNR2: 0.97182




1011+110 2024/07/28 4.68UT TOYOKAWA-FUJI





T20240728133901




BLK: 1,SNR1: 0.46403E-01,SNR2: 0.53793




K20240728133858





BLK: 1,SNR1: 0.36661 ,SNR2: 0.44724




1011+110 2024/07/28 4.68UT TOYOKAWA-KISO





F20240728133901




BLK: 4,SNR1: 0.20109 ,SNR2: 1.7082




K20240728133858





BLK: 4,SNR1:-0.12333E-01,SNR2: 0.22471




1011+110 2024/07/28 4.68UT FUJI -KISO





T20240728134642




BLK:15,SNR1: 0.58216 ,SNR2: 2.7972




F20240728134643





BLK:15,SNR1: 8.2551 ,SNR2: 20.446




3C241 2024/07/28 4.81UT TOYOKAWA-FUJI





T20240728134642




BLK:17,SNR1: 0.37498 ,SNR2: 1.9310




K20240728134640





BLK:17,SNR1: 12.446 ,SNR2: 23.375




3C241 2024/07/28 4.81UT TOYOKAWA-KISO



F20240728134643





BLK:20,SNR1: 5.1840 ,SNR2: 7.5851





3C241 2024/07/28 4.81UT FUJI -KISO



K20240728134640




BLK:20,SNR1: 40.260 ,SNR2: 50.465




T20240728135811




BLK: 2,SNR1: 0.33742 ,SNR2: 0.88704




F20240728135811





BLK: 2,SNR1: 0.37327 ,SNR2: 1.7615




1031-11 2024/07/28 5.00UT TOYOKAWA-FUJI





T20240728135811




BLK: 5,SNR1: 0.16186 ,SNR2: 1.1676




K20240728135808



BLK: 5,SNR1: 1.3491 ,SNR2: 7.5107




1031-11 2024/07/28 5.00UT TOYOKAWA-KISO






F20240728135811




BLK: 1,SNR1:-0.20090 ,SNR2: 0.0000





1031-11 2024/07/28 5.00UT FUJI -KISO



K20240728135808




BLK: 1,SNR1: 0.72345 ,SNR2: 4.2990




T20240728140245




BLK: 4,SNR1: 482.17 ,SNR2: 4487.1




F20240728140245





BLK: 4,SNR1:-0.28841E-01,SNR2: 2.2556




1035-058 2024/07/28 5.07UT TOYOKAWA-FUJI





T20240728140245




BLK: 2,SNR1: 808.27 ,SNR2: 4157.1




K20240728140242




BLK: 2,SNR1: 0.55026E-01,SNR2: 0.60265




1035-058 2024/07/28 5.07UT TOYOKAWA-KISO





F20240728140245




BLK: 3,SNR1:-0.18672E-01,SNR2: 0.81448




K20240728140242





BLK: 3,SNR1: 0.10898 ,SNR2: 0.80325




1035-058 2024/07/28 5.07UT FUJI -KISO





T20240728141157




BLK: 4,SNR1:-0.33806E-01,SNR2: 0.33955




F20240728141157





BLK: 4,SNR1:-0.18959E-01,SNR2: 3.4140




1044-008 2024/07/28 5.23UT TOYOKAWA-FUJI





T20240728141157




BLK: 6,SNR1: 0.58839E-01,SNR2: 0.29702




K20240728141154





BLK: 6,SNR1: 0.97986 ,SNR2: 3.9500




1044-008 2024/07/28 5.23UT TOYOKAWA-KISO





F20240728141157




BLK: 8,SNR1:-0.19597 ,SNR2: 0.97303




K20240728141154





BLK: 8,SNR1: 0.20095 ,SNR2: 1.5554




1044-008 2024/07/28 5.23UT FUJI -KISO




T20240728142302




BLK: 5,SNR1: 0.25373 ,SNR2: 0.74249




F20240728142302



BLK: 5,SNR1: 0.31831 ,SNR2: 1.6505





1055+01 2024/07/28 5.41UT TOYOKAWA-FUJI








T20240728142302




BLK: 6,SNR1: 0.66869E-01,SNR2: 0.65856




K20240728142259




BLK: 6,SNR1: 0.31466 ,SNR2: 2.6379




1055+01 2024/07/28 5.41UT TOYOKAWA-KISO



F20240728142302





BLK: 5,SNR1: 0.99917 ,SNR2: 2.4184




Frequency (Hz)

K20240728142259




BLK: 5,SNR1: 0.12964 ,SNR2: 0.37591





Frequency (Hz)


1055+01 2024/07/28 5.41UT FUJI -KISO



T20240728143419





BLK: 3,SNR1: 0.51880E-01,SNR2: 1.5609




Frequency (Hz)

F20240728143419




BLK: 3,SNR1: 0.62303 ,SNR2: 2.6602





Frequency (Hz)


1107+109 2024/07/28 5.60UT TOYOKAWA-FUJI



T20240728143419





BLK:10,SNR1: 0.77597 ,SNR2: 11.233




Frequency (Hz)

K20240728143416




BLK:10,SNR1: 0.41052 ,SNR2: 2.5137





Frequency (Hz)


1107+109 2024/07/28 5.60UT TOYOKAWA-KISO



F20240728143419





BLK: 9,SNR1: 1.3859 ,SNR2: 3.6833




Frequency (Hz)

K20240728143416




BLK: 9,SNR1: 0.36996 ,SNR2: 1.7937





Frequency (Hz)


1107+109 2024/07/28 5.60UT FUJI -KISO



T20240728144357




BLK: 4,SNR1: 0.34483 ,SNR2: 2.6066




Frequency (Hz)

F20240728144357




BLK: 4,SNR1: 0.28832 ,SNR2: 3.3290





Frequency (Hz)


3C255 2024/07/28 5.76UT TOYOKAWA-FUJI





T20240728144357




BLK:13,SNR1: 0.32571 ,SNR2: 3.0279




K20240728144354





BLK:13,SNR1: 0.17787 ,SNR2: 0.54273




3C255 2024/07/28 5.76UT TOYOKAWA-KISO



F20240728144357





BLK: 7,SNR1: 0.59436 ,SNR2: 2.2528




Frequency (Hz)

K20240728144354




BLK: 7,SNR1: 0.11392 ,SNR2: 1.1969





Frequency (Hz)

3C255 2024/07/28 5.76UT FUJI -KISO








T20240728145434




BLK: 1,SNR1:-0.63299E-01,SNR2: 0.56132




F20240728145434





BLK: 1,SNR1: 0.53411E-01,SNR2: 2.3037




1127-14 2024/07/28 5.94UT TOYOKAWA-FUJI



T20240728145434





BLK: 8,SNR1: 0.60893E-02,SNR2: 1.7660




Frequency (Hz)

K20240728145431




BLK: 8,SNR1: 0.71890 ,SNR2: 8.3511




Frequency (Hz)


1127-14 2024/07/28 5.94UT TOYOKAWA-KISO





F20240728145434




BLK: 6,SNR1:-0.38298 ,SNR2: 0.0000




K20240728145431





BLK: 6,SNR1: 1.0173 ,SNR2: 6.5453




1127-14 2024/07/28 5.94UT FUJI -KISO



T20240728150755




BLK: 8,SNR1: 0.16789 ,SNR2: 0.47101




Frequency (Hz)

F20240728150755




BLK: 8,SNR1: 0.32140 ,SNR2: 5.0863




Frequency (Hz)


3C263.1 2024/07/28 6.16UT TOYOKAWA-FUJI



T20240728150755





BLK: 9,SNR1: 0.11924E-01,SNR2: 1.5293




Frequency (Hz)

K20240728150752




BLK: 9,SNR1: 0.35194 ,SNR2: 3.5819




Frequency (Hz)


3C263.1 2024/07/28 6.16UT TOYOKAWA-KISO





F20240728150755




BLK: 5,SNR1: 0.50826 ,SNR2: 3.1296




K20240728150752





BLK: 5,SNR1: 0.31868 ,SNR2: 1.5209




3C263.1 2024/07/28 6.16UT FUJI -KISO



T20240728151422





BLK: 4,SNR1: 0.24564 ,SNR2: 1.9775




Frequency (Hz)

F20240728151422




BLK: 4,SNR1: 0.12956 ,SNR2: 2.0357





Frequency (Hz)


3C267 2024/07/28 6.27UT TOYOKAWA-FUJI



T20240728151422





BLK: 6,SNR1: 0.38998 ,SNR2: 2.9250




Frequency (Hz)

K20240728151419




BLK: 6,SNR1: 0.64995 ,SNR2: 3.1239





Frequency (Hz)

3C267 2024/07/28 6.27UT TOYOKAWA-KISO








F20240728151422




BLK: 4,SNR1: 0.99637E-01,SNR2: 0.47252




K20240728151419





BLK: 4,SNR1: 0.40917 ,SNR2: 2.0951




3C267 2024/07/28 6.27UT FUJI -KISO



T20240728154009




BLK: 6,SNR1: 0.98618 ,SNR2: 5.4522




Frequency (Hz)

F20240728154009




BLK: 6,SNR1: 0.21841E-01,SNR2: 2.1162





Frequency (Hz)


1213-17 2024/07/28 6.70UT TOYOKAWA-FUJI



T20240728154009





BLK: 6,SNR1: 1.1496 ,SNR2: 5.8140




Frequency (Hz)

K20240728154006




BLK: 6,SNR1: 0.32673 ,SNR2: 1.3548





Frequency (Hz)


1213-17 2024/07/28 6.70UT TOYOKAWA-KISO



F20240728154009





BLK: 5,SNR1: 0.17100 ,SNR2: 1.3811




Frequency (Hz)

K20240728154006




BLK: 5,SNR1:-0.12812E-02,SNR2: 1.3086





Frequency (Hz)


1213-17 2024/07/28 6.70UT FUJI -KISO



T20240728155327





BLK:14,SNR1: 2.3711 ,SNR2: 13.315




Frequency (Hz)

F20240728155327




BLK:14,SNR1:-0.15150 ,SNR2: 1.4380




Frequency (Hz)


3C273 2024/07/28 6.92UT TOYOKAWA-FUJI



T20240728155327




BLK:24,SNR1: 2.5409 ,SNR2: 11.331




Frequency (Hz)

K20240728155324




BLK:24,SNR1: 0.30894 ,SNR2: 1.0932





Frequency (Hz)


3C273 2024/07/28 6.92UT TOYOKAWA-KISO



F20240728155327




BLK: 7,SNR1: 0.86953E-01,SNR2: 1.7640




Frequency (Hz)

K20240728155324




BLK: 7,SNR1: 0.26868 ,SNR2: 2.6487





Frequency (Hz)


3C273 2024/07/28 6.92UT FUJI -KISO





T20240728160638




BLK: 5,SNR1: 0.29463 ,SNR2: 1.4687




F20240728160639



BLK: 5,SNR1: 0.81930 ,SNR2: 5.0211





3C275 2024/07/28 7.14UT TOYOKAWA-FUJI








T20240728160638




BLK: 8,SNR1: 0.27136 ,SNR2: 1.2971




K20240728160635




BLK: 8,SNR1: 2.9723 ,SNR2: 12.694




3C275 2024/07/28 7.14UT TOYOKAWA-KISO



F20240728160639





BLK: 7,SNR1: 3.4890 ,SNR2: 6.8763




Frequency (Hz)

K20240728160635




BLK: 7,SNR1: 3.4448 ,SNR2: 14.836





Frequency (Hz)


3C275 2024/07/28 7.14UT FUJI -KISO





T20240728161243




BLK: 3,SNR1: 0.63928E-01,SNR2: 0.75309




F20240728161243





BLK: 3,SNR1: 0.73361E-01,SNR2: 0.71058




1245-19 2024/07/28 7.24UT TOYOKAWA-FUJI





T20240728161243




BLK: 4,SNR1: 0.32898 ,SNR2: 1.4059




K20240728161240




BLK: 4,SNR1: 0.15011 ,SNR2: 1.6067




1245-19 2024/07/28 7.24UT TOYOKAWA-KISO



F20240728161243





BLK: 4,SNR1:-0.17613 ,SNR2: 0.26521




Frequency (Hz)

K20240728161240




BLK: 4,SNR1:-0.91886E-02,SNR2: 1.0011




Frequency (Hz)


1245-19 2024/07/28 7.24UT FUJI -KISO



T20240728162026




BLK: 1,SNR1: 0.68604 ,SNR2: 1.8358




Frequency (Hz)

F20240728162026




BLK: 1,SNR1:-0.17907 ,SNR2: 0.91275





Frequency (Hz)


3C279 2024/07/28 7.37UT TOYOKAWA-FUJI



T20240728162026





BLK: 8,SNR1: 0.35621 ,SNR2: 1.3293




Frequency (Hz)

K20240728162023




BLK: 8,SNR1: 0.49268 ,SNR2: 1.8079




Frequency (Hz)


3C279 2024/07/28 7.37UT TOYOKAWA-KISO



F20240728162026





BLK: 3,SNR1:-0.31682 ,SNR2: 0.45598




Frequency (Hz)

K20240728162023




BLK: 3,SNR1: 0.16466 ,SNR2: 3.4396





Frequency (Hz)

3C279 2024/07/28 7.37UT FUJI -KISO







T20240728164014




BLK: 4,SNR1:-0.49394E-01,SNR2: 0.50955




F20240728164015





BLK: 4,SNR1: 0.39628 ,SNR2: 1.8118




1313+453 2024/07/28 7.70UT TOYOKAWA-FUJI



T20240728164014




BLK: 2,SNR1:-0.12812E-01,SNR2: 1.6062




Frequency (Hz)

K20240728164011




BLK: 2,SNR1: 1.3370 ,SNR2: 5.6135





Frequency (Hz)


1313+453 2024/07/28 7.70UT TOYOKAWA-KISO



F20240728164015





BLK: 6,SNR1:-0.13475 ,SNR2: 0.87142




Frequency (Hz)

K20240728164011




BLK: 6,SNR1: 1.0699 ,SNR2: 3.4500





Frequency (Hz)


1313+453 2024/07/28 7.70UT FUJI -KISO



T20240728165020




BLK: 7,SNR1: 0.13486 ,SNR2: 1.5309




Frequency (Hz)

F20240728165021




BLK: 7,SNR1: 0.16633 ,SNR2: 1.4332





Frequency (Hz)


1323+32 2024/07/28 7.87UT TOYOKAWA-FUJI



T20240728165020





BLK:15,SNR1: 0.32721 ,SNR2: 2.1248




Frequency (Hz)

K20240728165017




BLK:15,SNR1: 0.83815 ,SNR2: 3.4958




Frequency (Hz)


1323+32 2024/07/28 7.87UT TOYOKAWA-KISO



F20240728165021





BLK:10,SNR1: 0.60477 ,SNR2: 2.4887




Frequency (Hz)

K20240728165017




BLK:10,SNR1: 0.58120 ,SNR2: 2.7893




Frequency (Hz)


1323+32 2024/07/28 7.87UT FUJI -KISO



T20240728165510




BLK:16,SNR1: 1.3929 ,SNR2: 8.9882




Frequency (Hz)

F20240728165510




BLK:16,SNR1: 0.41919 ,SNR2: 2.6264




Frequency (Hz)


3C286 2024/07/28 7.95UT TOYOKAWA-FUJI



T20240728165510





BLK:17,SNR1: 1.2024 ,SNR2: 6.5856




Frequency (Hz)

K20240728165507




BLK:17,SNR1: 1.6680 ,SNR2: 6.3295




Frequency (Hz)

3C286 2024/07/28 7.95UT TOYOKAWA-KISO






F20240728165510





BLK:25,SNR1: 0.35692 ,SNR2: 1.9107




Frequency (Hz)

K20240728165507




BLK:25,SNR1: 2.2976 ,SNR2: 4.5597





Frequency (Hz)


3C286 2024/07/28 7.95UT FUJI -KISO



T20240728171138





BLK: 8,SNR1: 0.21826 ,SNR2: 1.2241




Frequency (Hz)

F20240728171138






BLK: 8,SNR1: 0.72925E-01,SNR2: 1.6204




Frequency (Hz)

1345+12 2024/07/28 8.22UT TOYOKAWA-FUJI








1345+12 2024/07/28 8.22UT TOYOKAWA-KISO



F20240728171138




BLK: 3,SNR1: 0.92905E-01,SNR2: 1.3423




Frequency (Hz)

K20240728171135



BLK: 3,SNR1: 0.67694 ,SNR2: 4.2552



Frequency (Hz)

1345+12 2024/07/28 8.22UT FUJI -KISO

