



T20240730062000




BLK: 3,SNR1: 0.98619E-01,SNR2: 0.45302




Frequency (Hz)

F20240730062001




BLK: 3,SNR1: 0.12040 ,SNR2: 1.4425





Frequency (Hz)


0258+350 2024/07/29 21.36UT TOYOKAWA-FUJI



T20240730062000




BLK: 6,SNR1: 0.15709E-01,SNR2: 0.66873




Frequency (Hz)

K20240730061957




BLK: 6,SNR1: 0.28130 ,SNR2: 1.9636




Frequency (Hz)

0258+350 2024/07/29 21.36UT TOYOKAWA-KISO






F20240730062001




BLK: 2,SNR1:-0.26530E-01,SNR2: 0.51300




Frequency (Hz)

K20240730061957




BLK: 2,SNR1:-0.14830E-01,SNR2: 1.6335




Frequency (Hz)


0258+350 2024/07/29 21.36UT FUJI -KISO



T20240730062949




BLK: 5,SNR1: 0.12214 ,SNR2: 1.3680




Frequency (Hz)

F20240730062949




BLK: 5,SNR1: 0.77198 ,SNR2: 3.3255





Frequency (Hz)


0308+305 2024/07/29 21.53UT TOYOKAWA-FUJI



T20240730062949




BLK: 3,SNR1: 0.55551E-01,SNR2: 0.59393




Frequency (Hz)

K20240730062946




BLK: 3,SNR1: 0.88219 ,SNR2: 8.8777





Frequency (Hz)


0308+305 2024/07/29 21.53UT TOYOKAWA-KISO



F20240730062949




BLK: 8,SNR1:-0.36529E-01,SNR2: 1.6616




Frequency (Hz)

K20240730062946




BLK: 8,SNR1: 0.29847 ,SNR2: 4.5061





Frequency (Hz)


0308+305 2024/07/29 21.53UT FUJI -KISO



T20240730064121





BLK: 4,SNR1: 0.87767E-01,SNR2: 2.1849




Frequency (Hz)

F20240730064121




BLK: 4,SNR1: 0.32210E-01,SNR2: 0.68433





Frequency (Hz)


0320+05 2024/07/29 21.72UT TOYOKAWA-FUJI



T20240730064121




BLK: 4,SNR1: 0.17958 ,SNR2: 0.58234




Frequency (Hz)

K20240730064118




BLK: 4,SNR1: 0.46543 ,SNR2: 5.1195




Frequency (Hz)


0320+05 2024/07/29 21.72UT TOYOKAWA-KISO



F20240730064121





BLK: 4,SNR1: 0.86285E-02,SNR2: 1.7487




Frequency (Hz)

K20240730064118




BLK: 4,SNR1: 2.3549 ,SNR2: 12.515




Frequency (Hz)


0320+05 2024/07/29 21.72UT FUJI -KISO



T20240730065442




BLK: 1,SNR1:-0.32827E-02,SNR2: 0.38386




Frequency (Hz)

F20240730065443




BLK: 1,SNR1:-0.84611E-01,SNR2: 0.46327




Frequency (Hz)

0333+32 2024/07/29 21.94UT TOYOKAWA-FUJI






T20240730065442




BLK: 3,SNR1:-0.44850E-02,SNR2: 0.62199




Frequency (Hz)

K20240730065439




BLK: 3,SNR1: 1.0841 ,SNR2: 4.6402




Frequency (Hz)


0333+32 2024/07/29 21.94UT TOYOKAWA-KISO



F20240730065443




BLK: 2, SNR1: 0.31021 ,SNR2: 3.9122




Frequency (Hz)

K20240730065439




BLK: 2, SNR1: 6.5944 ,SNR2: 17.856





Frequency (Hz)


0333+32 2024/07/29 21.94UT FUJI -KISO



T20240730070744




BLK: 4,SNR1: 0.37130E-01,SNR2: 0.97593




Frequency (Hz)

F20240730070744




BLK: 4,SNR1: 0.44734E-01,SNR2: 2.1043





Frequency (Hz)


0347+05 2024/07/29 22.16UT TOYOKAWA-FUJI



T20240730070744




BLK: 1,SNR1:-0.62181E-01,SNR2: 0.33980




Frequency (Hz)

K20240730070741




BLK: 1,SNR1: 2.0549 ,SNR2: 9.9206




Frequency (Hz)


0347+05 2024/07/29 22.16UT TOYOKAWA-KISO



F20240730070744




BLK: 3,SNR1: 0.26604 ,SNR2: 5.6488




Frequency (Hz)

K20240730070741




BLK: 3,SNR1: 0.95849 ,SNR2: 5.2136





Frequency (Hz)


0347+05 2024/07/29 22.16UT FUJI -KISO



T20240730072318





BLK: 2,SNR1: 0.24123 ,SNR2: 1.1178




Frequency (Hz)

F20240730072318




BLK: 2,SNR1: 3.0277 ,SNR2: 6.2111





Frequency (Hz)


0403-132 2024/07/29 22.42UT TOYOKAWA-FUJI



T20240730072318





BLK: 8,SNR1: 0.48405E-01,SNR2: 1.2181




Frequency (Hz)

K20240730072315




BLK: 8,SNR1: 0.57181 ,SNR2: 2.2613





Frequency (Hz)


0403-132 2024/07/29 22.42UT TOYOKAWA-KISO



F20240730072318





BLK: 5,SNR1: 1.1190 ,SNR2: 2.6818




Frequency (Hz)

K20240730072315




BLK: 5,SNR1: 0.48248 ,SNR2: 1.8914





Frequency (Hz)

0403-132 2024/07/29 22.42UT FUJI -KISO








T20240730073229




BLK: 4,SNR1: 0.51164E-01,SNR2: 0.77059




F20240730073229





BLK: 4,SNR1:-0.35325E-02,SNR2: 1.3685




0411+05 2024/07/29 22.57UT TOYOKAWA-FUJI



T20240730073229





BLK: 7,SNR1: 0.15395 ,SNR2: 1.0880




Frequency (Hz)

K20240730073226




BLK: 7,SNR1: 0.92972 ,SNR2: 2.9284




Frequency (Hz)


0411+05 2024/07/29 22.57UT TOYOKAWA-KISO



F20240730073229




BLK: 6,SNR1: 0.72956 ,SNR2: 4.0459




Frequency (Hz)

K20240730073226




BLK: 6,SNR1:-0.75596E-01,SNR2: 1.8054





Frequency (Hz)


0411+05 2024/07/29 22.57UT FUJI -KISO



T20240730073923





BLK: 4,SNR1: 0.15562 ,SNR2: 2.3302




Frequency (Hz)

F20240730073923




BLK: 4,SNR1: 0.29624 ,SNR2: 2.8020





Frequency (Hz)


0418+236 2024/07/29 22.68UT TOYOKAWA-FUJI





T20240730073923




BLK: 8,SNR1: 0.74863 ,SNR2: 3.2026




K20240730073920





BLK: 8,SNR1: 1.0706 ,SNR2: 6.0433




0418+236 2024/07/29 22.68UT TOYOKAWA-KISO



F20240730073923





BLK: 2,SNR1:-0.21932 ,SNR2: 1.5734




Frequency (Hz)

K20240730073920




BLK: 2,SNR1: 0.58200 ,SNR2: 2.0106





Frequency (Hz)


0418+236 2024/07/29 22.68UT FUJI -KISO



T20240730075050





BLK: 7,SNR1: 0.59618 ,SNR2: 5.4093




Frequency (Hz)

F20240730075050




BLK: 7,SNR1:-0.81232E-01,SNR2: 1.1296




Frequency (Hz)


3C119 2024/07/29 22.88UT TOYOKAWA-FUJI



T20240730075050




BLK:14,SNR1: 0.90339 ,SNR2: 3.8796




Frequency (Hz)

K20240730075047




BLK:14,SNR1: 0.36190 ,SNR2: 1.3959




Frequency (Hz)

3C119 2024/07/29 22.88UT TOYOKAWA-KISO








F20240730075050




BLK: 1,SNR1:-0.35523E-01,SNR2: 0.38618




K20240730075047




BLK: 1,SNR1: 0.28351E-01,SNR2: 1.8292




3C119 2024/07/29 22.88UT FUJI -KISO



T20240730083858




BLK:19,SNR1: 0.83116 ,SNR2: 4.6904




Frequency (Hz)

3C138 2024/07/29 23.68UT TOYOKAWA-FUJI


F20240730083858





BLK:19,SNR1: 0.49428 ,SNR2: 2.4986




Frequency (Hz)



T20240730083858





BLK:13,SNR1: 0.97530 ,SNR2: 3.8108




Frequency (Hz)

K20240730083855




BLK:13,SNR1: 85.648 ,SNR2: 83.994




Frequency (Hz)


3C138 2024/07/29 23.68UT TOYOKAWA-KISO




F20240730083858




BLK: 8,SNR1: 0.92419E-01,SNR2: 1.7320




K20240730083855




BLK: 8,SNR1: 0.24744 ,SNR2: 1.1136




3C138 2024/07/29 23.68UT FUJI -KISO



T20240730085231





BLK:12,SNR1: 0.82394 ,SNR2: 3.3635




Frequency (Hz)

F20240730085231




BLK:12,SNR1: 1.5681 ,SNR2: 7.2272





Frequency (Hz)


0531+194 2024/07/29 23.90UT TOYOKAWA-FUJI



T20240730085231





BLK:12,SNR1: 0.61920 ,SNR2: 5.2230




Frequency (Hz)

K20240730085228




BLK:12,SNR1: 76.236 ,SNR2: 71.328





Frequency (Hz)


0531+194 2024/07/29 23.90UT TOYOKAWA-KISO



F20240730085231





BLK:13,SNR1: 1.0406 ,SNR2: 5.2106




Frequency (Hz)

K20240730085228




BLK:13,SNR1: 0.52706 ,SNR2: 2.2784





Frequency (Hz)


0531+194 2024/07/29 23.90UT FUJI -KISO



T20240730090051





BLK:16,SNR1: 14.633 ,SNR2: 33.877




Frequency (Hz)

3C147 2024/07/30 0.04UT TOYOKAWA-FUJI


F20240730090051



BLK:16,SNR1: 0.63487 ,SNR2: 5.4894





Frequency (Hz)






T20240730090051





BLK:23,SNR1: 14.602 ,SNR2: 44.310




Frequency (Hz)

3C147 2024/07/30 0.04UT TOYOKAWA-KISO


K20240730090048





BLK:23,SNR1: 1.8273 ,SNR2: 7.4640




Frequency (Hz)



F20240730090051





BLK:21,SNR1: 0.63244 ,SNR2: 6.3069




Frequency (Hz)

3C147 2024/07/30 00.4UT FUJI -KISO


K20240730090048





BLK:21,SNR1: 1.8055 ,SNR2: 7.9756




Frequency (Hz)



T20240730090902




BLK: 6,SNR1: 0.23427 ,SNR2: 1.9271




Frequency (Hz)

F20240730090902




BLK: 6,SNR1: 1.6917 ,SNR2: 3.2235





Frequency (Hz)


0548+16 2024/07/30 0.18UT TOYOKAWA-FUJI



T20240730090902





BLK: 7,SNR1: 0.16125 ,SNR2: 1.1504




Frequency (Hz)

K20240730090859




BLK: 7,SNR1: 81.773 ,SNR2: 78.304




Frequency (Hz)


0548+16 2024/07/30 0.18UT TOYOKAWA-KISO



F20240730090902





BLK: 4,SNR1: 1.0218 ,SNR2: 4.8479




Frequency (Hz)

K20240730090859




BLK: 4,SNR1: 0.10924 ,SNR2: 1.1841




Frequency (Hz)


0548+16 2024/07/30 0.18UT FUJI -KISO



T20240730091313




BLK: 7,SNR1: 8.8850 ,SNR2: 47.734




Frequency (Hz)

0552+12 2024/07/30 0.25UT TOYOKAWA-FUJI


F20240730091313




BLK: 7,SNR1: 1.0999 ,SNR2: 3.0167




Frequency (Hz)



T20240730091313





BLK:13,SNR1: 3.6176 ,SNR2: 15.368




Frequency (Hz)

0552+12 2024/07/30 0.25UT TOYOKAWA-KISO


K20240730091310





BLK:13,SNR1: 80.366 ,SNR2: 72.190




Frequency (Hz)





F20240730091313




BLK:15,SNR1: 2.8479 ,SNR2: 12.668




K20240730091310



BLK:15,SNR1: 2.2224 ,SNR2: 8.1995




0552+12 2024/07/30 0.25UT FUJI -KISO






T20240730091740




BLK:13,SNR1: 1.1841 ,SNR2: 4.3269




Frequency (Hz)

F20240730091740




BLK:13,SNR1: 1.4096 ,SNR2: 6.4272





Frequency (Hz)


0556+191 2024/07/30 0.32UT TOYOKAWA-FUJI



T20240730091740





BLK:14,SNR1: 1.1804 ,SNR2: 4.4725





0556+191 2024/07/30 0.32UT TOYOKAWA-KISO



K20240730091737




BLK:14,SNR1: 80.356 ,SNR2: 78.051





F20240730091740




BLK:14,SNR1: 1.3486 ,SNR2: 5.3942




K20240730091737





BLK:14,SNR1: 79.927 ,SNR2: 77.634




0556+191 2024/07/30 0.32UT FUJI -KISO



T20240730092212




BLK:16,SNR1: 0.58595 ,SNR2: 1.8491




Frequency (Hz)

F20240730092213




BLK:16,SNR1: 0.14171 ,SNR2: 2.8879





Frequency (Hz)


3C152 2024/07/30 0.40UT TOYOKAWA-FUJI



T20240730092212





BLK:13,SNR1: 1.0216 ,SNR2: 2.4913




Frequency (Hz)

3C152 2024/07/30 0.40UT TOYOKAWA-KISO


K20240730092209





BLK:13,SNR1: 79.343 ,SNR2: 78.954




Frequency (Hz)



F20240730092213





BLK: 9,SNR1: 1.7680 ,SNR2: 6.7877




Frequency (Hz)

3C152 2024/07/30 0.40UT FUJI -KISO


K20240730092209




BLK: 9,SNR1: 42.323 ,SNR2: 67.163




Frequency (Hz)




T20240730094434




BLK:15,SNR1: 1.4423 ,SNR2: 9.0620




F20240730094434




BLK:15,SNR1: 0.25159 ,SNR2: 2.6107




3C161 2024/07/30 0.77UT TOYOKAWA-FUJI



T20240730094434




BLK:33,SNR1: 1.1849 ,SNR2: 5.5264





3C161 2024/07/30 0.77UT TOYOKAWA-KISO

K20240730094431





BLK:33,SNR1: 0.50219 ,SNR2: 1.8579






F20240730094434





BLK:15,SNR1: 0.13286 ,SNR2: 2.3832




Frequency (Hz)

K20240730094431




BLK:15,SNR1: 0.21490 ,SNR2: 1.6836





Frequency (Hz)


3C161 2024/07/30 0.77UT FUJI -KISO



T20240730101207





BLK:32,SNR1: 2.8586 ,SNR2: 13.618




Frequency (Hz)

F20240730101207




BLK:32,SNR1: 8.8832 ,SNR2: 22.229





Frequency (Hz)


0652-130 2024/07/30 1.23UT TOYOKAWA-FUJI



T20240730101207





BLK:28,SNR1: 2.8600 ,SNR2: 13.624




Frequency (Hz)

K20240730101205




BLK:28,SNR1: 8.6498 ,SNR2: 21.673





Frequency (Hz)


0652-130 2024/07/30 1.23UT TOYOKAWA-KISO



F20240730101207





BLK:33,SNR1: 9.4624 ,SNR2: 23.650




Frequency (Hz)

0652-130 2024/07/30 1.23UT FUJI -KISO


K20240730101205





BLK:33,SNR1: 8.5684 ,SNR2: 21.484




Frequency (Hz)



T20240730102343





BLK:33,SNR1: 3.0322 ,SNR2: 14.291




Frequency (Hz)

F20240730102343




BLK:33,SNR1: 10.391 ,SNR2: 24.158





Frequency (Hz)


0703+138 2024/07/30 1.42UT TOYOKAWA-FUJI



T20240730102343





BLK:31,SNR1: 17.320 ,SNR2: 30.498




Frequency (Hz)

K20240730102340




BLK:31,SNR1: 14.702 ,SNR2: 25.976





Frequency (Hz)


0703+138 2024/07/30 1.42UT TOYOKAWA-KISO



F20240730102343




BLK:32,SNR1: 10.234 ,SNR2: 24.044









0703+138 2024/07/30 1.42UT FUJI -KISO

K20240730102340




BLK:32,SNR1: 14.747 ,SNR2: 26.055










0713-024 2024/07/30 1.58UT TOYOKAWA-FUJI









0713-024 2024/07/30 1.58UT TOYOKAWA-KISO





F20240730103306




BLK:31,SNR1: 25.014 ,SNR2: 32.596




K20240730103303




BLK:31,SNR1: 9.8026 ,SNR2: 27.340




0713-024 2024/07/30 1.58UT FUJI -KISO




T20240730104317




BLK:14,SNR1: 3.5690 ,SNR2: 5.7776




F20240730104317




BLK:14,SNR1: 5.5045 ,SNR2: 8.9619




0723+10 2024/07/30 1.75UT TOYOKAWA-FUJI



T20240730104317




BLK:17,SNR1: 3.8803 ,SNR2: 7.2061





0723+10 2024/07/30 1.75UT TOYOKAWA-KISO


K20240730104314




BLK:17,SNR1: 8.6578 ,SNR2: 14.596



F20240730104317




BLK:16,SNR1: 4.2692 ,SNR2: 6.8651




Frequency (Hz)

K20240730104314




BLK:16,SNR1: 0.15922 ,SNR2: 2.7898





Frequency (Hz)


0723+10 2024/07/30 1.75UT FUJI -KISO



T20240730105332




BLK:13,SNR1: 0.29702 ,SNR2: 4.3009





0732+33 2024/07/30 1.92UT TOYOKAWA-FUJI



F20240730105332




BLK:13,SNR1: 0.20853 ,SNR2: 3.2608



T20240730105332





BLK:22,SNR1: 4.4565 ,SNR2: 7.6523





0732+33 2024/07/30 1.92UT TOYOKAWA-KISO


K20240730105329




BLK:22,SNR1: 2.4897 ,SNR2: 3.9904





F20240730105332




BLK:14,SNR1: 0.74542E-01,SNR2: 2.2795




K20240730105329



BLK:14,SNR1: 1.7426 ,SNR2: 2.9585




0732+33 2024/07/30 1.92UT FUJI -KISO






T20240730110134





BLK:11,SNR1: 4.2558 ,SNR2: 16.421





0741-06 2024/07/30 2.05UT TOYOKAWA-FUJI


F20240730110134




BLK:11,SNR1: 1.4132 ,SNR2: 5.6121



T20240730110134





BLK:28,SNR1: 6.0348 ,SNR2: 10.949





0741-06 2024/07/30 2.05UT TOYOKAWA-KISO


K20240730110131




BLK:28,SNR1: 8.1397 ,SNR2: 23.140



F20240730110134





BLK:25,SNR1: 2.3494 ,SNR2: 9.5527





0741-06 2024/07/30 2.05UT FUJI -KISO


K20240730110131




BLK:25,SNR1: 8.6873 ,SNR2: 23.897



T20240730111118





BLK: 3,SNR1: 0.19107 ,SNR2: 0.59549





0752-200 2024/07/30 2.22UT TOYOKAWA-FUJI


F20240730111118




BLK: 3,SNR1: 0.31415 ,SNR2: 1.5796



T20240730111118





BLK: 4,SNR1: 0.33209 ,SNR2: 2.9149




0752-200 2024/07/30 2.22UT TOYOKAWA-KISO


K20240730111115





BLK: 4,SNR1: 0.14854 ,SNR2: 1.3744




Frequency (Hz)





F20240730111118




BLK: 5,SNR1: 0.40114 ,SNR2: 1.8652




K20240730111115





BLK: 5,SNR1: 0.17441 ,SNR2: 0.85528




0752-200 2024/07/30 2.22UT FUJI -KISO



T20240730111853





BLK:19,SNR1: 6.2988 ,SNR2: 10.554




Frequency (Hz)

F20240730111853




BLK:19,SNR1: 0.14314 ,SNR2: 4.8478




Frequency (Hz)


3C190 2024/07/30 2.34UT TOYOKAWA-FUJI




T20240730111853




BLK:24,SNR1: 4.3656 ,SNR2: 7.3814




K20240730111850



BLK:24,SNR1: 7.5926 ,SNR2: 12.240




3C190 2024/07/30 2.34UT TOYOKAWA-KISO







F20240730111853




BLK:18,SNR1: 12.236 ,SNR2: 16.346




K20240730111850




BLK:18,SNR1: 8.7194 ,SNR2: 12.663




3C190 2024/07/30 2.34UT FUJI -KISO




T20240730113118




BLK:15,SNR1: 1.1139 ,SNR2: 3.5099




F20240730113118




BLK:15,SNR1: 0.51873 ,SNR2: 2.9958




3C196 2024/07/30 2.55UT TOYOKAWA-FUJI



T20240730113118




BLK:15,SNR1: 0.63599 ,SNR2: 2.5729





3C196 2024/07/30 2.55UT TOYOKAWA-KISO


K20240730113115




BLK:15,SNR1: 63.543 ,SNR2: 96.905





F20240730113118




BLK:15,SNR1: 0.60134 ,SNR2: 2.9570




K20240730113115





BLK:15,SNR1: 2.6953 ,SNR2: 7.3450




3C196 2024/07/30 2.55UT FUJI -KISO



T20240730114227




BLK:12,SNR1: 0.87772 ,SNR2: 3.1752




Frequency (Hz)

F20240730114227




BLK:12,SNR1: 0.30204 ,SNR2: 3.2381





Frequency (Hz)


0821+394 2024/07/30 2.74UT TOYOKAWA-FUJI



T20240730114227





BLK:15,SNR1: 0.99226 ,SNR2: 2.0438




0821+394 2024/07/30 2.74UT TOYOKAWA-KISO


K20240730114224





BLK:15,SNR1: 32.042 ,SNR2: 56.102




Frequency (Hz)



F20240730114227





BLK:14,SNR1: 0.31081 ,SNR2: 3.0437




Frequency (Hz)

K20240730114224




BLK:14,SNR1: 31.061 ,SNR2: 53.921




Frequency (Hz)


0821+394 2024/07/30 2.74UT FUJI -KISO



T20240730115408





BLK:30,SNR1: 15.686 ,SNR2: 27.543




Frequency (Hz)

F20240730115408




BLK:30,SNR1: 16.702 ,SNR2: 27.539




Frequency (Hz)

0834-19 2024/07/30 2.93UT TOYOKAWA-FUJI






T20240730115408




BLK:33,SNR1: 11.785 ,SNR2: 24.936





0834-19 2024/07/30 2.93UT TOYOKAWA-KISO



K20240730115405




BLK:33,SNR1: 26.700 ,SNR2: 45.920




F20240730115408




BLK:30,SNR1: 15.666 ,SNR2: 21.932




K20240730115405





BLK:30,SNR1: 23.196 ,SNR2: 40.585




0834-19 2024/07/30 2.93UT FUJI -KISO




T20240730115913




BLK: 7,SNR1: 1.1450 ,SNR2: 8.1522




F20240730115913





BLK: 7,SNR1:-0.31394 ,SNR2: 0.65876




0839-071 2024/07/30 3.02UT TOYOKAWA-FUJI



T20240730115913





BLK:11,SNR1: 1.5912 ,SNR2: 14.303





0839-071 2024/07/30 3.02UT TOYOKAWA-KISO


K20240730115910




BLK:11,SNR1: 3.7511 ,SNR2: 14.723



F20240730115913





BLK: 5,SNR1:-0.32055 ,SNR2: 0.71793





0839-071 2024/07/30 3.02UT FUJI -KISO


K20240730115910




BLK: 5,SNR1: 1.4746 ,SNR2: 6.9161





T20240730121014




BLK:26,SNR1: 6.1410 ,SNR2: 16.878




F20240730121014




BLK:26,SNR1: 0.54036 ,SNR2: 2.2782




3C208 2024/07/30 3.20UT TOYOKAWA-FUJI



T20240730121014




BLK:18,SNR1: 7.3846 ,SNR2: 25.059





3C208 2024/07/30 3.20UT TOYOKAWA-KISO


K20240730121011




BLK:18,SNR1: 0.93678 ,SNR2: 4.8594





F20240730121014




BLK:13,SNR1: 0.83738 ,SNR2: 5.2122




K20240730121011



BLK:13,SNR1: 1.5775 ,SNR2: 6.6327





3C208 2024/07/30 3.20UT FUJI -KISO






T20240730122655




BLK:15,SNR1: 0.50542 ,SNR2: 4.2666




Frequency (Hz)

F20240730122655




BLK:15,SNR1:-0.52452E-01,SNR2: 2.4427





Frequency (Hz)


3C216 2024/07/30 3.48UT TOYOKAWA-FUJI





T20240730122655




BLK:16,SNR1: 0.42413 ,SNR2: 3.8437




K20240730122652





BLK:16,SNR1: 73.112 ,SNR2: 75.722




3C216 2024/07/30 3.48UT TOYOKAWA-KISO



F20240730122655





BLK: 9,SNR1: 0.43753 ,SNR2: 5.4045




Frequency (Hz)

K20240730122652




BLK: 9,SNR1: 0.59161 ,SNR2: 4.2976





Frequency (Hz)


3C216 2024/07/30 3.48UT FUJI -KISO



T20240730123907




BLK: 3,SNR1: 63.950 ,SNR2: 102.33





0919-142 2024/07/30 3.68UT TOYOKAWA-FUJI



F20240730123907




BLK: 3,SNR1:-0.11595 ,SNR2: 0.56898



T20240730123907





BLK: 6,SNR1: 627.84 ,SNR2: 650.27





0919-142 2024/07/30 3.68UT TOYOKAWA-KISO


K20240730123904




BLK: 6,SNR1: 0.24832 ,SNR2: 0.60997



F20240730123907





BLK: 1,SNR1: 0.20058 ,SNR2: 2.4147





0919-142 2024/07/30 3.68UT FUJI -KISO



K20240730123904




BLK: 1,SNR1: 0.10123 ,SNR2: 0.37505E-01





T20240730124546




BLK: 5,SNR1: 0.83661E-01,SNR2: 0.57782




F20240730124546





BLK: 5,SNR1: 0.10291E-01,SNR2: 2.4981




0926+117 2024/07/30 3.79UT TOYOKAWA-FUJI





T20240730124546




BLK: 4,SNR1: 0.10655 ,SNR2: 1.2006




K20240730124543



BLK: 4,SNR1: 0.64398 ,SNR2: 5.4884




0926+117 2024/07/30 3.79UT TOYOKAWA-KISO






F20240730124546





BLK: 1,SNR1: 1.7644 ,SNR2: 6.5942





0926+117 2024/07/30 3.79UT FUJI -KISO



K20240730124543




BLK: 1,SNR1:-0.64908E-01,SNR2: 2.4360



T20240730125330





BLK:15,SNR1: 1.5016 ,SNR2: 11.455




Frequency (Hz)

F20240730125330




BLK:15,SNR1: 0.25902 ,SNR2: 3.1660




Frequency (Hz)


3C222 2024/07/30 3.92UT TOYOKAWA-FUJI



T20240730125330





BLK:24,SNR1: 1.2501 ,SNR2: 10.026





3C222 2024/07/30 3.92UT TOYOKAWA-KISO



K20240730125327




BLK:24,SNR1: 2.0497 ,SNR2: 8.3728





F20240730125330




BLK:11,SNR1: 0.34035 ,SNR2: 3.6724




K20240730125327




BLK:11,SNR1: 2.3850 ,SNR2: 9.8443




3C222 2024/07/30 3.92UT FUJI -KISO




T20240730130030




BLK: 5,SNR1: 0.17826E-01,SNR2: 1.0574




F20240730130030





BLK: 5,SNR1: 0.17579 ,SNR2: 1.6918




0941-08 2024/07/30 4.04UT TOYOKAWA-FUJI





T20240730130030




BLK:15,SNR1: 0.31149 ,SNR2: 2.2736




K20240730130027





BLK:15,SNR1: 0.98375 ,SNR2: 4.7123




0941-08 2024/07/30 4.04UT TOYOKAWA-KISO





F20240730130030




BLK: 3,SNR1: 0.27536 ,SNR2: 2.3049




K20240730130027




BLK: 3,SNR1: 0.46323 ,SNR2: 3.1345







0941-08 2024/07/30 4.04UT FUJI -KISO



T20240730130852




F20240730130852






T20240730130852





BLK:24,SNR1: 0.84173 ,SNR2: 5.1284





3C230 2024/07/30 4.18UT TOYOKAWA-KISO



K20240730130849




BLK:24,SNR1: 0.40497 ,SNR2: 1.7686



F20240730130852





BLK: 5,SNR1:-0.11836 ,SNR2: 1.7102





3C230 2024/07/30 4.18UT FUJI -KISO



K20240730130849




BLK: 5,SNR1: 0.12200 ,SNR2: 0.77046




T20240730132259




BLK:11,SNR1: 0.55289 ,SNR2: 6.0403




F20240730132259





BLK:11,SNR1: 0.51009E-01,SNR2: 3.1017




3C236 2024/07/30 4.41UT TOYOKAWA-FUJI





T20240730132259




BLK:22,SNR1: 0.59519 ,SNR2: 5.2670




K20240730132256




BLK:22,SNR1: 0.31510 ,SNR2: 1.5230




3C236 2024/07/30 4.41UT TOYOKAWA-KISO





F20240730132259




BLK: 9,SNR1:-0.14022E-01,SNR2: 0.99581




K20240730132256





BLK: 9,SNR1: 0.46526 ,SNR2: 3.0172




3C236 2024/07/30 4.41UT FUJI -KISO





T20240730133109




BLK: 1,SNR1: 0.26941 ,SNR2: 0.70289




F20240730133109





BLK: 1,SNR1: 0.74352E-01,SNR2: 0.65704




1011+110 2024/07/30 4.55UT TOYOKAWA-FUJI





T20240730133109




BLK: 2,SNR1:-0.17025E-01,SNR2: 2.1304




K20240730133107





BLK: 2,SNR1: 0.13670 ,SNR2: 1.3159




1011+110 2024/07/30 4.55UT TOYOKAWA-KISO





F20240730133109




BLK: 1,SNR1: 0.90615 ,SNR2: 3.2847




K20240730133107



BLK: 1,SNR1: 0.17690 ,SNR2: 0.52084





1011+110 2024/07/30 4.55UT FUJI -KISO








T20240730133850




BLK:22,SNR1: 9.0601 ,SNR2: 42.844




F20240730133850





BLK:22,SNR1: 0.25390 ,SNR2: 2.4706




3C241 2024/07/30 4.68UT TOYOKAWA-FUJI





T20240730133850




BLK:32,SNR1: 7.1832 ,SNR2: 15.777




K20240730133848





BLK:32,SNR1: 18.195 ,SNR2: 21.609




3C241 2024/07/30 4.68UT TOYOKAWA-KISO



F20240730133850





BLK:16,SNR1: 0.45022E-01,SNR2: 1.8897




Frequency (Hz)

3C241 2024/07/30 4.68UT FUJI -KISO


K20240730133848





BLK:16,SNR1: 15.284 ,SNR2: 34.228




Frequency (Hz)





T20240730135019




BLK: 2,SNR1: 0.14401 ,SNR2: 1.6189




F20240730135019





BLK: 2,SNR1: 0.15898 ,SNR2: 1.0638




1031-11 2024/07/30 4.87UT TOYOKAWA-FUJI





T20240730135019




BLK: 3,SNR1:-0.16291E-01,SNR2: 1.1610




K20240730135017




BLK: 3,SNR1: 0.45786 ,SNR2: 2.5708




1031-11 2024/07/30 4.87UT TOYOKAWA-KISO



F20240730135019





BLK: 3,SNR1: 0.90990E-01,SNR2: 3.0866





1031-11 2024/07/30 4.87UT FUJI -KISO



K20240730135017




BLK: 3,SNR1: 0.21997 ,SNR2: 0.54271





T20240730135453




BLK: 7,SNR1: 0.19906 ,SNR2: 0.96015




F20240730135453




BLK: 7,SNR1: 0.80782 ,SNR2: 4.6426




1035-058 2024/07/30 4.94UT TOYOKAWA-FUJI





T20240730135453




BLK: 3,SNR1: 0.93515E-01,SNR2: 0.72998




K20240730135450



BLK: 3,SNR1:-0.58318E-01,SNR2: 1.2985




1035-058 2024/07/30 4.94UT TOYOKAWA-KISO








F20240730135453




BLK: 5,SNR1: 1.6255 ,SNR2: 4.6101




K20240730135450





BLK: 5,SNR1: 0.49826E-01,SNR2: 1.5512




1035-058 2024/07/30 4.94UT FUJI -KISO




T20240730140406




BLK: 4,SNR1: 0.11626 ,SNR2: 0.78691




F20240730140406





BLK: 4,SNR1: 3.2598 ,SNR2: 15.782




1044-008 2024/07/30 5.10UT TOYOKAWA-FUJI



T20240730140406





BLK: 3,SNR1:-0.12305 ,SNR2: 0.70361




Frequency (Hz)

K20240730140403




BLK: 3,SNR1: 0.32267 ,SNR2: 0.69929




Frequency (Hz)


1044-008 2024/07/30 5.10UT TOYOKAWA-KISO





F20240730140406




BLK: 7,SNR1: 2.3841 ,SNR2: 6.9741




K20240730140403





BLK: 7,SNR1: 0.35980 ,SNR2: 1.1124




1044-008 2024/07/30 5.10UT FUJI -KISO



T20240730141510





BLK: 4,SNR1: 0.37271 ,SNR2: 1.4059




Frequency (Hz)

F20240730141511




BLK: 4,SNR1: 0.17069 ,SNR2: 3.1407





Frequency (Hz)


1055+01 2024/07/30 5.28UT TOYOKAWA-FUJI





T20240730141510




BLK:10,SNR1: 0.24581 ,SNR2: 1.8055




K20240730141508




BLK:10,SNR1: 0.16543 ,SNR2: 1.0456




1055+01 2024/07/30 5.28UT TOYOKAWA-KISO





F20240730141511




BLK: 7,SNR1: 0.33662 ,SNR2: 4.3329




K20240730141508





BLK: 7,SNR1: 0.28172 ,SNR2: 1.2096




1055+01 2024/07/30 5.28UT FUJI -KISO





T20240730142628




BLK: 8,SNR1: 0.13725 ,SNR2: 1.1730




F20240730142628



BLK: 8,SNR1: 0.76089 ,SNR2: 2.0187





1107+109 2024/07/30 5.47UT TOYOKAWA-FUJI








T20240730142628




BLK: 6,SNR1: 0.21640 ,SNR2: 1.6215




K20240730142626





BLK: 6,SNR1: 0.58120 ,SNR2: 2.6023




1107+109 2024/07/30 5.47UT TOYOKAWA-KISO





F20240730142628




BLK: 4,SNR1: 0.64038 ,SNR2: 6.9639




K20240730142626




BLK: 4,SNR1: 0.79822E-01,SNR2: 0.65938






1107+109 2024/07/30 5.47UT FUJI -KISO




T20240730143605





F20240730143605




3C255 2024/07/30 5.63UT TOYOKAWA-FUJI





T20240730143605




BLK:26,SNR1: 0.48379 ,SNR2: 1.7805




K20240730143603





BLK:26,SNR1: 0.40098 ,SNR2: 1.2730




3C255 2024/07/30 5.63UT TOYOKAWA-KISO





F20240730143605




BLK:12,SNR1: 1.0858 ,SNR2: 4.0486




K20240730143603





BLK:12,SNR1: 0.47714 ,SNR2: 4.0668




3C255 2024/07/30 5.63UT FUJI -KISO



T20240730144643





BLK: 3,SNR1: 0.47688E-01,SNR2: 0.56862




Frequency (Hz)

F20240730144643




BLK: 3,SNR1:-0.22217 ,SNR2: 0.61336E-01





Frequency (Hz)


1127-14 2024/07/30 5.81UT TOYOKAWA-FUJI





T20240730144643




BLK:11,SNR1: 0.39917 ,SNR2: 2.0789




K20240730144641





BLK:11,SNR1: 0.25169 ,SNR2: 1.5834




1127-14 2024/07/30 5.81UT TOYOKAWA-KISO



F20240730144643





BLK: 2,SNR1: 1.2855 ,SNR2: 3.6618




Frequency (Hz)

K20240730144641




BLK: 2,SNR1:-0.68528E-01,SNR2: 0.60614





Frequency (Hz)

1127-14 2024/07/30 5.81UT FUJI -KISO







T20240730150003




BLK: 3,SNR1: 0.26684 ,SNR2: 0.69155




F20240730150003





BLK: 3,SNR1: 1.2096 ,SNR2: 7.0594




3C263.1 2024/07/30 6.03UT TOYOKAWA-FUJI





T20240730150003




BLK:10,SNR1: 0.82444E-01,SNR2: 1.4423




K20240730150001




BLK:10,SNR1: 0.64514 ,SNR2: 4.8162




3C263.1 2024/07/30 6.03UT TOYOKAWA-KISO



F20240730150003





BLK: 4,SNR1: 0.97986 ,SNR2: 3.5776




Frequency (Hz)

K20240730150001




BLK: 4,SNR1: 0.46740E-01,SNR2: 0.26395




Frequency (Hz)


3C263.1 2024/07/30 6.03UT FUJI -KISO





T20240730150630




BLK: 8,SNR1: 2.2495 ,SNR2: 6.3610




F20240730150630





BLK: 8,SNR1: 0.62016 ,SNR2: 3.5200




3C267 2024/07/30 6.14UT TOYOKAWA-FUJI





T20240730150630




BLK:13,SNR1: 1.7786 ,SNR2: 5.0307




K20240730150627





BLK:13,SNR1: 8.4194 ,SNR2: 23.887




3C267 2024/07/30 6.14UT TOYOKAWA-KISO



F20240730150630





BLK:18,SNR1: 0.96631 ,SNR2: 1.0861




Frequency (Hz)

K20240730150627




BLK:18,SNR1: 5.9791 ,SNR2: 16.695





Frequency (Hz)


3C267 2024/07/30 6.14UT FUJI -KISO



T20240730153218





BLK: 7,SNR1: 0.14618 ,SNR2: 0.88790




Frequency (Hz)

F20240730153218




BLK: 7,SNR1: 6.7084 ,SNR2: 7.7840





Frequency (Hz)


1213-17 2024/07/30 6.57UT TOYOKAWA-FUJI



T20240730153218





BLK: 5,SNR1: 0.84770E-01,SNR2: 0.89273




Frequency (Hz)

K20240730153216




BLK: 5,SNR1: 0.61440 ,SNR2: 2.9622




Frequency (Hz)

1213-17 2024/07/30 6.57UT TOYOKAWA-KISO








F20240730153218




BLK: 5,SNR1:-0.12673 ,SNR2: 0.73563




K20240730153216





BLK: 5,SNR1: 2.8192 ,SNR2: 8.1585




1213-17 2024/07/30 6.57UT FUJI -KISO



T20240730154535





BLK: 6,SNR1: 2.7364 ,SNR2: 13.787




Frequency (Hz)

F20240730154535




BLK: 6,SNR1:-0.65316E-01,SNR2: 1.0284




Frequency (Hz)


3C273 2024/07/30 6.79UT TOYOKAWA-FUJI



T20240730154535




BLK:20,SNR1: 2.5758 ,SNR2: 12.025




Frequency (Hz)

K20240730154533




BLK:20,SNR1: 1.7558 ,SNR2: 7.5151




Frequency (Hz)


3C273 2024/07/30 6.79UT TOYOKAWA-KISO





F20240730154535




BLK:14,SNR1: 2.0540 ,SNR2: 8.9516




K20240730154533





BLK:14,SNR1: 3.8917 ,SNR2: 16.689




3C273 2024/07/30 6.79UT FUJI -KISO



T20240730155846





No.Good Data




Frequency (Hz)

F20240730155847




No.Good Data





Frequency (Hz)


3C275 2024/07/30 7.01UT TOYOKAWA-FUJI





T20240730155846




BLK: 3,SNR1: 0.16339 ,SNR2: 1.0985




K20240730155844




BLK: 3,SNR1: 0.57878 ,SNR2: 6.1549




3C275 2024/07/30 7.01UT TOYOKAWA-KISO





F20240730155847




BLK: 4,SNR1:-0.24056 ,SNR2: 1.6210




K20240730155844





BLK: 4,SNR1: 1.9383 ,SNR2: 8.1753




3C275 2024/07/30 7.01UT FUJI -KISO



T20240730160451




BLK: 8,SNR1: 0.12739 ,SNR2: 0.91842




Frequency (Hz)

F20240730160452




BLK: 8,SNR1: 0.48359 ,SNR2: 3.6150





Frequency (Hz)


1245-19 2024/07/30 7.11UT TOYOKAWA-FUJI









1245-19 2024/07/30 7.11UT TOYOKAWA-KISO





F20240730160452




BLK: 4,SNR1: 0.49584 ,SNR2: 5.6629




K20240730160448





BLK: 4,SNR1: 0.53508 ,SNR2: 1.7672




1245-19 2024/07/30 7.11UT FUJI -KISO



T20240730161234




BLK:15,SNR1: 11.164 ,SNR2: 19.063




Frequency (Hz)

F20240730161234




BLK:15,SNR1: 1.5367 ,SNR2: 7.6353





Frequency (Hz)


3C279 2024/07/30 7.24UT TOYOKAWA-FUJI





T20240730161234




No.Good Data




KISO






No.Good Data



3C279 2024/07/30 7.24UT TOYOKAWA-KISO






F20240730161234




No.Good Data

KISO




No.Good Data


3C279 2024/07/30 7.24UT FUJI -KISO



T20240730162804





BLK:10,SNR1: 2.5501 ,SNR2: 11.426




Frequency (Hz)

F20240730162804




BLK:10,SNR1: 2.1650 ,SNR2: 9.2626





Frequency (Hz)


3C283 2024/07/30 7.50UT TOYOKAWA-FUJI





T20240730162804




BLK:19,SNR1: 2.1872 ,SNR2: 9.9101




K20240730162801




BLK:19,SNR1: 7.5208 ,SNR2: 21.082




3C283 2024/07/30 7.50UT TOYOKAWA-KISO



F20240730162804





BLK:19,SNR1: 1.9076 ,SNR2: 5.1908




Frequency (Hz)

K20240730162801




BLK:19,SNR1: 8.0591 ,SNR2: 22.595





Frequency (Hz)

3C283 2024/07/30 7.50UT FUJI -KISO






T20240730164228





BLK: 6,SNR1: 0.31082 ,SNR2: 0.95559




Frequency (Hz)

F20240730164228




BLK: 6,SNR1: 0.51989 ,SNR2: 3.0615





Frequency (Hz)


1323+32 2024/07/30 7.74UT TOYOKAWA-FUJI





T20240730164228




BLK: 5,SNR1: 0.37559E-01,SNR2: 0.69245




K20240730164225




BLK: 5,SNR1: 2.0952 ,SNR2: 9.2988




1323+32 2024/07/30 7.74UT TOYOKAWA-KISO



F20240730164228




BLK:13,SNR1: 0.56169 ,SNR2: 4.4888




Frequency (Hz)

K20240730164225




BLK:13,SNR1: 9.4757 ,SNR2: 18.031




Frequency (Hz)


1323+32 2024/07/30 7.74UT FUJI -KISO



T20240730164719




BLK:18,SNR1: 1.5417 ,SNR2: 5.4200




Frequency (Hz)

F20240730164720




BLK:18,SNR1: 0.89296E-01,SNR2: 0.61432




Frequency (Hz)


3C286 2024/07/30 7.82UT TOYOKAWA-FUJI



T20240730164719




BLK:19,SNR1: 1.3660 ,SNR2: 5.0545




Frequency (Hz)

K20240730164716




BLK:19,SNR1: 0.69709 ,SNR2: 4.0765




Frequency (Hz)


3C286 2024/07/30 7.82UT TOYOKAWA-KISO



F20240730164720




BLK:16,SNR1: 0.93436E-01,SNR2: 1.3518




Frequency (Hz)

K20240730164716




BLK:16,SNR1: 3.9261 ,SNR2: 7.9980





Frequency (Hz)


3C286 2024/07/30 7.82UT FUJI -KISO



T20240730170346





BLK:14,SNR1: 8.8212 ,SNR2: 23.797




Frequency (Hz)

F20240730170346




BLK:14,SNR1: 1.0240 ,SNR2: 2.3538





Frequency (Hz)


1345+12 2024/07/30 8.09UT TOYOKAWA-FUJI



T20240730170346





BLK:23,SNR1: 8.5490 ,SNR2: 23.066




Frequency (Hz)

K20240730170343




BLK:23,SNR1: 3.3505 ,SNR2: 14.096





Frequency (Hz)

1345+12 2024/07/30 8.09UT TOYOKAWA-KISO






F20240730170346





BLK:22,SNR1: 1.0104 ,SNR2: 3.7315




Frequency (Hz)

K20240730170343




BLK:22,SNR1: 3.1746 ,SNR2: 8.2980





Frequency (Hz)


1345+12 2024/07/30 8.09UT FUJI -KISO



T20240730180946





BLK:24,SNR1: 7.7062 ,SNR2: 14.414




Frequency (Hz)

F20240730180947




BLK:24,SNR1: 8.1033 ,SNR2: 24.284





Frequency (Hz)


1452+502 2024/07/30 9.19UT TOYOKAWA-FUJI





T20240730180946




BLK:30,SNR1: 7.7039 ,SNR2: 14.410




K20240730180944





BLK:30,SNR1: 7.1710 ,SNR2: 21.041




1452+502 2024/07/30 9.19UT TOYOKAWA-KISO



F20240730180947





BLK:27,SNR1: 8.1021 ,SNR2: 24.281




Frequency (Hz)

K20240730180944



BLK:27,SNR1: 7.1554 ,SNR2: 20.992



Frequency (Hz)

1452+502 2024/07/30 9.19UT FUJI -KISO

