




TOYOKAWA 0255+460 2024/08/12(225)05:25:48-05:29:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0307+444 2024/08/12(225)05:37:46-05:41:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0311+363 2024/08/12(225)05:41:48-05:45:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C84


2024/08/12(225)05:47:01-05:50:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0322+245 2024/08/12(225)05:52:05-05:55:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0326+455 2024/08/12(225)05:57:36-06:01:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0333+32 2024/08/12(225)06:03:34-06:07:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0337+319 2024/08/12(225)06:07:12-06:10:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0347+05 2024/08/12(225)06:16:35-06:20:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0349+382 2024/08/12(225)06:20:17-06:23:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0355+50 2024/08/12(225)06:26:48-06:30:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0403-132 2024/08/12(225)06:32:10-06:35:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0406+386 2024/08/12(225)06:36:27-06:39:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0411+05 2024/08/12(225)06:41:20-06:44:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0418+236 2024/08/12(225)06:48:14-06:51:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0422+178 2024/08/12(225)06:52:13-06:55:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C119

2024/08/12(225)06:59:42-07:03:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C138


2024/08/12(225)07:47:49-07:51:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0531+194 2024/08/12(225)08:01:23-08:04:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C147


2024/08/12(225)08:09:42-08:13:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0548+16 2024/08/12(225)08:17:54-08:21:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0552+12 2024/08/12(225)08:22:04-08:25:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0556+191 2024/08/12(225)08:26:31-08:29:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C152 2024/08/12(225)08:31:04-08:34:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C158

2024/08/12(225)08:48:10-08:51:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C161


2024/08/12(225)08:53:25-08:56:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2024/08/12(225)09:20:58-09:24:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0703+138 2024/08/12(225)09:32:34-09:36:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0713-024 2024/08/12(225)09:41:57-09:45:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2024/08/12(225)09:45:37-09:49:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0723+10 2024/08/12(225)09:52:09-09:55:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0732+33 2024/08/12(225)10:02:23-10:05:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0741-06 2024/08/12(225)10:10:25-10:13:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0752-200 2024/08/12(225)10:20:10-10:23:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C190

2024/08/12(225)10:27:44-10:31:10JST


5811+/- 120




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0806-103 2024/08/12(225)10:34:50-10:38:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196

2024/08/12(225)10:40:09-10:43:35JST


6273+/- 35




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2024/08/12(225)10:46:53-10:50:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0821+394 2024/08/12(225)10:51:19-10:54:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0834-19 2024/08/12(225)11:02:59-11:06:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 0839-071 2024/08/12(225)11:08:04-11:11:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208

2024/08/12(225)11:19:05-11:22:31JST


6532+/- 352




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0857-191 2024/08/12(225)11:25:25-11:28:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C216

2024/08/12(225)11:35:46-11:39:12JST


6788+/- 382




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2024/08/12(225)11:40:31-11:43:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2024/08/12(225)11:47:58-11:51:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0926+117 2024/08/12(225)11:54:37-11:58:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C222 2024/08/12(225)12:02:22-12:05:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0941-08 2024/08/12(225)12:09:22-12:12:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C230 2024/08/12(225)12:17:43-12:21:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C236

2024/08/12(225)12:31:51-12:35:17JST


6192+/- 922




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1011+110 2024/08/12(225)12:40:00-12:43:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241 2024/08/12(225)12:47:41-12:51:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1031-11 2024/08/12(225)12:59:11-13:02:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1035-058 2024/08/12(225)13:03:44-13:07:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1044-008 2024/08/12(225)13:12:57-13:16:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1055+20 2024/08/12(225)13:23:55-13:27:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1059-010 2024/08/12(225)13:27:37-13:31:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2024/08/12(225)13:35:19-13:38:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C255 2024/08/12(225)13:44:56-13:48:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2024/08/12(225)13:55:34-13:59:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1136-13 2024/08/12(225)14:04:38-14:08:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2024/08/12(225)14:08:54-14:12:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C267 2024/08/12(225)14:15:21-14:18:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1154+552 2024/08/12(225)14:22:46-14:26:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2024/08/12(225)14:34:35-14:38:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1213-17 2024/08/12(225)14:41:09-14:44:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2024/08/12(225)14:54:26-14:57:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C275 2024/08/12(225)15:07:37-15:11:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1245-19 2024/08/12(225)15:13:42-15:17:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C279


2024/08/12(225)15:21:26-15:24:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C283 2024/08/12(225)15:36:55-15:40:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1313+453 2024/08/12(225)15:41:14-15:44:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1323+32 2024/08/12(225)15:51:20-15:54:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286 2024/08/12(225)15:56:10-15:59:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1334-17 2024/08/12(225)16:02:47-16:06:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1345+12 2024/08/12(225)16:12:37-16:16:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1355+01 2024/08/12(225)16:22:57-16:26:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2024/08/12(225)16:44:08-16:47:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1428-03 2024/08/12(225)16:55:52-16:59:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1436-16 2024/08/12(225)17:04:33-17:07:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1452+16 2024/08/12(225)17:19:10-17:22:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1456+092 2024/08/12(225)17:24:15-17:27:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318 2024/08/12(225)17:44:49-17:48:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1536+574 2024/08/12(225)18:01:33-18:04:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1545+497 2024/08/12(225)18:11:36-18:15:02JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1554+430 2024/08/12(225)18:20:56-18:24:22JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

