




TOYOKAWA 0431+615 2024/09/03(247)05:36:37-05:40:03JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0446+422 2024/09/03(247)05:50:07-05:53:33JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0450+314 2024/09/03(247)05:53:48-05:57:14JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0456+332 2024/09/03(247)05:59:51-06:03:17JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0500+339 2024/09/03(247)06:04:21-06:07:47JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0505+173 2024/09/03(247)06:08:12-06:11:38JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0510-040 2024/09/03(247)06:12:48-06:16:14JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0514+109 2024/09/03(247)06:16:54-06:20:20JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C138 2024/09/03(247)06:21:19-06:24:45JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0523+116 2024/09/03(247)06:26:22-06:29:48JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0528-212 2024/09/03(247)06:30:30-06:33:56JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0531+194 2024/09/03(247)06:34:53-06:38:19JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C147 2024/09/03(247)06:43:12-06:46:38JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0545-071 2024/09/03(247)06:47:19-06:50:45JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0548+16 2024/09/03(247)06:51:24-06:54:50JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0552+12 2024/09/03(247)06:55:34-06:59:00JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0556+191 2024/09/03(247)07:00:01-07:03:27JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C152 2024/09/03(247)07:04:34-07:08:00JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C158 2024/09/03(247)07:21:40-07:25:06JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C161 2024/09/03(247)07:26:55-07:30:21JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2024/09/03(247)07:54:28-07:57:54JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0703+138 2024/09/03(247)08:06:04-08:09:30JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0713-024 2024/09/03(247)08:15:27-08:18:53JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0716+022 2024/09/03(247)08:19:07-08:22:33JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0723+10 2024/09/03(247)08:25:39-08:29:05JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0732+33 2024/09/03(247)08:35:53-08:39:19JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2024/09/03(247)08:43:55-08:47:21JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0752-200 2024/09/03(247)08:53:40-08:57:06JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C190 2024/09/03(247)09:01:15-09:04:41JST 143Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0806-103 2024/09/03(247)09:08:20-09:11:46JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C196 2024/09/03(247)09:13:39-09:17:05JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0817+183 2024/09/03(247)09:20:24-09:23:50JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0821+394 2024/09/03(247)09:24:49-09:28:15JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0834-19 2024/09/03(247)09:36:29-09:39:55JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0839-071 2024/09/03(247)09:41:34-09:45:00JST 123Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C208 2024/09/03(247)09:52:35-09:56:01JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0857-191 2024/09/03(247)09:58:55-10:02:21JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C216 2024/09/03(247)10:09:17-10:12:43JST 143Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0912-132 2024/09/03(247)10:14:01-10:17:27JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0919-142 2024/09/03(247)10:21:28-10:24:54JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0926+117 2024/09/03(247)10:28:07-10:31:33JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C222 2024/09/03(247)10:35:52-10:39:18JST 67Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0941-08 2024/09/03(247)10:42:52-10:46:18JST 83Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C230 2024/09/03(247)10:51:14-10:54:40JST 60Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C236 2024/09/03(247)11:05:21-11:08:47JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1011+110 2024/09/03(247)11:13:31-11:16:57JST 34Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241 2024/09/03(247)11:21:12-11:24:38JST 59Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1031-11 2024/09/03(247)11:32:41-11:36:07JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1035-058 2024/09/03(247)11:37:14-11:40:40JST 51Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1044-008 2024/09/03(247)11:46:27-11:49:53JST 32Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2024/09/03(247)11:57:32-12:00:58JST 24Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2024/09/03(247)12:08:49-12:12:15JST 22Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1117+14 2024/09/03(247)12:19:32-12:22:58JST 38Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1127-14 2024/09/03(247)12:29:04-12:32:30JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2024/09/03(247)12:38:08-12:41:34JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C263.1 2024/09/03(247)12:42:24-12:45:50JST 72Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C267 2024/09/03(247)12:48:51-12:52:17JST 59Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1154+552 2024/09/03(247)12:56:16-12:59:42JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1206+439 2024/09/03(247)13:08:06-13:11:32JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2024/09/03(247)13:14:39-13:18:05JST 117Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C273 2024/09/03(247)13:27:56-13:31:22JST 93Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C275 2024/09/03(247)13:41:07-13:44:33JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2024/09/03(247)13:47:12-13:50:38JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C279 2024/09/03(247)13:54:56-13:58:22JST 122Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C283 2024/09/03(247)14:10:25-14:13:51JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2024/09/03(247)14:14:44-14:18:10JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1323+32 2024/09/03(247)14:24:50-14:28:16JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1355+01 2024/09/03(247)14:56:28-14:59:54JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C298 2024/09/03(247)15:17:38-15:21:04JST 170Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2024/09/03(247)15:29:22-15:32:48JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1436-16 2024/09/03(247)15:38:03-15:41:29JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1453-10 2024/09/03(247)15:54:26-15:57:52JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1508-05 2024/09/03(247)16:09:19-16:12:45JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318 2024/09/03(247)16:18:19-16:21:45JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1523+03 2024/09/03(247)16:24:06-16:27:32JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2024/09/03(247)16:35:45-16:39:11JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1545-12 2024/09/03(247)16:46:09-16:49:35JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1607+26 2024/09/03(247)17:07:12-17:10:38JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1634+269 2024/09/03(247)17:34:31-17:37:57JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1641+399 2024/09/03(247)17:40:42-17:44:08JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )





TOYOKAWA 1647+429 2024/09/03(247)17:46:33-17:49:59JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

