




TOYOKAWA 0500+339 2024/09/05(249)05:56:29-05:59:55JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0505+173 2024/09/05(249)06:00:20-06:03:46JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0511+123 2024/09/05(249)06:06:08-06:09:34JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C138


2024/09/05(249)06:13:28-06:16:54JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0523+116 2024/09/05(249)06:18:30-06:21:56JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0528-212 2024/09/05(249)06:22:38-06:26:04JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0531+194 2024/09/05(249)06:27:01-06:30:27JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C147 2024/09/05(249)06:35:20-06:38:46JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0545-071 2024/09/05(249)06:39:27-06:42:53JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0548+16 2024/09/05(249)06:43:32-06:46:58JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0552+12 2024/09/05(249)06:47:43-06:51:09JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0556+191 2024/09/05(249)06:52:09-06:55:35JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C152 2024/09/05(249)06:56:42-07:00:08JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C158 2024/09/05(249)07:13:48-07:17:14JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C161

2024/09/05(249)07:19:03-07:22:29JST 201Rs


5088+/- 52




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0652-130 2024/09/05(249)07:46:36-07:50:02JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0703+138 2024/09/05(249)07:58:12-08:01:38JST 181Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0713-024 2024/09/05(249)08:07:35-08:11:01JST 178Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2024/09/05(249)08:11:15-08:14:41JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0723+10 2024/09/05(249)08:17:47-08:21:13JST 170Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0732+33 2024/09/05(249)08:28:02-08:31:28JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0741-06 2024/09/05(249)08:36:04-08:39:30JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0752-200 2024/09/05(249)08:45:48-08:49:14JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190

2024/09/05(249)08:53:23-08:56:49JST 148Rs

3597+/- 64




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 0806-103 2024/09/05(249)09:00:28-09:03:54JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C196

2024/09/05(249)09:05:47-09:09:13JST 174Rs


3743+/- 24




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2024/09/05(249)09:12:32-09:15:58JST 137Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0821+394 2024/09/05(249)09:16:57-09:20:23JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0834-19 2024/09/05(249)09:28:37-09:32:03JST 148Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0839-071 2024/09/05(249)09:33:43-09:37:09JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208

2024/09/05(249)09:44:44-09:48:10JST 111Rs


3496+/- 22




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0857-191 2024/09/05(249)09:51:04-09:54:30JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C216 2024/09/05(249)10:01:25-10:04:51JST 147Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0912-132 2024/09/05(249)10:06:09-10:09:35JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0919-142 2024/09/05(249)10:13:36-10:17:02JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0926+117 2024/09/05(249)10:20:15-10:23:41JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C222 2024/09/05(249)10:28:00-10:31:26JST 73Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0941-08 2024/09/05(249)10:35:00-10:38:26JST 86Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C230 2024/09/05(249)10:43:22-10:46:48JST 64Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C236

2024/09/05(249)10:57:29-11:00:55JST 109Rs

3591+/- 192




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1011+110 2024/09/05(249)11:05:39-11:09:05JST 41Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C241 2024/09/05(249)11:13:20-11:16:46JST 64Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1031-11 2024/09/05(249)11:24:49-11:28:15JST 73Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1035-058 2024/09/05(249)11:29:23-11:32:49JST 51Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1044-008 2024/09/05(249)11:38:35-11:42:01JST 30Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1055+01 2024/09/05(249)11:49:40-11:53:06JST 19Rs


5884+/- 1341




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2024/09/05(249)12:00:57-12:04:23JST 19Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C255 2024/09/05(249)12:10:35-12:14:01JST 42Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1127-14 2024/09/05(249)12:21:12-12:24:38JST 85Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2024/09/05(249)12:30:16-12:33:42JST 85Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C263.1 2024/09/05(249)12:34:33-12:37:59JST 70Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2024/09/05(249)12:41:00-12:44:26JST 54Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1154+552 2024/09/05(249)12:48:24-12:51:50JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2024/09/05(249)13:00:14-13:03:40JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2024/09/05(249)13:06:47-13:10:13JST 112Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C273 2024/09/05(249)13:20:05-13:23:31JST 86Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C275 2024/09/05(249)13:33:15-13:36:41JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1245-19 2024/09/05(249)13:39:20-13:42:46JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C279


2024/09/05(249)13:47:04-13:50:30JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C283 2024/09/05(249)14:02:34-14:06:00JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1313+453 2024/09/05(249)14:06:52-14:10:18JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1323+32 2024/09/05(249)14:16:58-14:20:24JST 147Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C286 2024/09/05(249)14:21:48-14:25:14JST 148Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1334-17 2024/09/05(249)14:28:25-14:31:51JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1345+12 2024/09/05(249)14:38:15-14:41:41JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1355+01 2024/09/05(249)14:48:36-14:52:02JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C298 2024/09/05(249)15:09:47-15:13:13JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1428-03 2024/09/05(249)15:21:30-15:24:56JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1436-16 2024/09/05(249)15:30:11-15:33:37JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1453-10 2024/09/05(249)15:46:35-15:50:01JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1508-05 2024/09/05(249)16:01:27-16:04:53JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C318 2024/09/05(249)16:10:27-16:13:53JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1523+03 2024/09/05(249)16:16:14-16:19:40JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1535+139 2024/09/05(249)16:27:53-16:31:19JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1545-12 2024/09/05(249)16:38:17-16:41:43JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1607+26 2024/09/05(249)16:59:21-17:02:47JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1621-11 2024/09/05(249)17:14:24-17:17:50JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1641+173 2024/09/05(249)17:33:56-17:37:22JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1647+352 2024/09/05(249)17:39:30-17:42:56JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )

