




TOYOKAWA 0605-08 2024/09/19(263)06:04:53-06:08:19JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0609+228 2024/09/19(263)06:10:03-06:13:29JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158

2024/09/19(263)06:18:45-06:22:11JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161

2024/09/19(263)06:24:01-06:27:27JST 212Rs


10841+/- 158




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2024/09/19(263)06:51:34-06:55:00JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2024/09/19(263)07:03:10-07:06:36JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2024/09/19(263)07:12:33-07:15:59JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2024/09/19(263)07:16:13-07:19:39JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2024/09/19(263)07:22:44-07:26:10JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2024/09/19(263)07:32:59-07:36:25JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2024/09/19(263)07:41:01-07:44:27JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0752-200 2024/09/19(263)07:50:45-07:54:11JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190


2024/09/19(263)07:58:20-08:01:46JST 180Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0806-103 2024/09/19(263)08:05:26-08:08:52JST 177Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196

2024/09/19(263)08:10:45-08:14:11JST 195Rs


7337+/- 212




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2024/09/19(263)08:17:29-08:20:55JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2024/09/19(263)08:21:55-08:25:21JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2024/09/19(263)08:33:35-08:37:01JST 167Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0839-071 2024/09/19(263)08:38:40-08:42:06JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208

2024/09/19(263)08:49:41-08:53:07JST 151Rs


6827+/- 449




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0854+100 2024/09/19(263)08:53:50-08:57:16JST 146Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216

2024/09/19(263)09:06:22-09:09:48JST 174Rs


6636+/- 19




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2024/09/19(263)09:11:07-09:14:33JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2024/09/19(263)09:18:34-09:22:00JST 136Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2024/09/19(263)09:25:13-09:28:39JST 125Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2024/09/19(263)09:32:57-09:36:23JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0941-08 2024/09/19(263)09:39:57-09:43:23JST 114Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230

2024/09/19(263)09:48:19-09:51:45JST 103Rs


6909+/- 101




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C237 2024/09/19(263)10:04:20-10:07:46JST 91Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2024/09/19(263)10:10:36-10:14:02JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241 2024/09/19(263)10:18:17-10:21:43JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2024/09/19(263)10:29:46-10:33:12JST 83Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2024/09/19(263)10:34:20-10:37:46JST 68Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2024/09/19(263)10:43:33-10:46:59JST 55Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+20 2024/09/19(263)10:54:31-10:57:57JST 80Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1059-010 2024/09/19(263)10:58:13-11:01:39JST 42Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2024/09/19(263)11:05:55-11:09:21JST 48Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2024/09/19(263)11:15:32-11:18:58JST 30Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1127-14 2024/09/19(263)11:26:10-11:29:36JST 62Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2024/09/19(263)11:35:13-11:38:39JST 57Rs


8268+/- 587




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2024/09/19(263)11:39:30-11:42:56JST 76Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2024/09/19(263)11:45:57-11:49:23JST 42Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2024/09/19(263)11:53:22-11:56:48JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2024/09/19(263)12:05:11-12:08:37JST 145Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2024/09/19(263)12:11:45-12:15:11JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2024/09/19(263)12:25:02-12:28:28JST 39Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2024/09/19(263)12:38:13-12:41:39JST 56Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1245-19 2024/09/19(263)12:44:18-12:47:44JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C279 2024/09/19(263)12:52:01-12:55:27JST 69Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283


2024/09/19(263)13:07:31-13:10:57JST 112Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2024/09/19(263)13:11:49-13:15:15JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1323+32 2024/09/19(263)13:21:55-13:25:21JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286

2024/09/19(263)13:26:46-13:30:12JST 133Rs


6145+/- 28




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2024/09/19(263)13:33:23-13:36:49JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2024/09/19(263)13:43:13-13:46:39JST 113Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2024/09/19(263)13:53:33-13:56:59JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2024/09/19(263)14:14:44-14:18:10JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2024/09/19(263)14:26:27-14:29:53JST 142Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1436-16 2024/09/19(263)14:35:09-14:38:35JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2024/09/19(263)14:51:32-14:54:58JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1508-05 2024/09/19(263)15:06:24-15:09:50JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318

2024/09/19(263)15:15:24-15:18:50JST 177Rs


7031+/- 56




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2024/09/19(263)15:21:11-15:24:37JST 176Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2024/09/19(263)15:32:51-15:36:17JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1545-12 2024/09/19(263)15:43:15-15:46:41JST 189Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1607+26 2024/09/19(263)16:04:18-16:07:44JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1623-228 2024/09/19(263)16:21:48-16:25:14JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1631-222 2024/09/19(263)16:30:18-16:33:44JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2024/09/19(263)16:35:56-16:39:22JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2024/09/19(263)16:42:50-16:46:16JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1650+004 2024/09/19(263)16:48:11-16:51:37JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1656+053 2024/09/19(263)16:53:42-16:57:08JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2024/09/19(263)17:10:12-17:13:38JST 213Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1725+107 2024/09/19(263)17:22:54-17:26:20JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

