




T20240909062751





BLK: 4,SNR1: 2.4611 ,SNR2: 42.127




Frequency (Hz)

F20240909062750




BLK: 4,SNR1: 0.63404 ,SNR2: 2.4581





Frequency (Hz)


0548+16 2024/09/08 21.49UT TOYOKAWA-FUJI



T20240909062751





BLK:12,SNR1: 5.4535 ,SNR2: 30.964




Frequency (Hz)

K20240909062749




BLK:12,SNR1: 1.5108 ,SNR2: 4.9229




Frequency (Hz)

0548+16 2024/09/08 21.49UT TOYOKAWA-KISO








F20240909062750




BLK: 2,SNR1:-0.69384E-01,SNR2: 1.0510




K20240909062749





BLK: 2,SNR1: 0.31989 ,SNR2: 1.2065




0548+16 2024/09/08 21.49UT FUJI -KISO



T20240909063202





BLK: 5,SNR1: 2.4593 ,SNR2: 24.202




Frequency (Hz)

F20240909063201




BLK: 5,SNR1: 0.99445 ,SNR2: 3.3274





Frequency (Hz)


0552+12 2024/09/08 21.56UT TOYOKAWA-FUJI



T20240909063202





BLK:10,SNR1: 4.8835 ,SNR2: 36.604




Frequency (Hz)

K20240909063200




BLK:10,SNR1: 2.1704 ,SNR2: 6.4785





Frequency (Hz)


0552+12 2024/09/08 21.56UT TOYOKAWA-KISO



F20240909063201





BLK: 8,SNR1: 0.50949 ,SNR2: 2.2431




Frequency (Hz)

K20240909063200




BLK: 8,SNR1: 0.17773 ,SNR2: 0.66068





Frequency (Hz)


0552+12 2024/09/08 21.56UT FUJI -KISO



T20240909063629





BLK: 5,SNR1: 0.11073 ,SNR2: 0.53351




Frequency (Hz)

F20240909063628




BLK: 5,SNR1: 2.0619 ,SNR2: 9.2865





Frequency (Hz)


0556+191 2024/09/08 21.64UT TOYOKAWA-FUJI



T20240909063629





BLK: 4,SNR1: 0.45253 ,SNR2: 1.0991




Frequency (Hz)

K20240909063627




BLK: 4,SNR1: 1.4773 ,SNR2: 5.5952





Frequency (Hz)


0556+191 2024/09/08 21.64UT TOYOKAWA-KISO





F20240909063628




No.Good Data




K20240909063627





No.Good Data




0556+191 2024/09/08 21.64UT FUJI -KISO





T20240909064101




No.Good Data




F20240909064100



No.Good Data





3C152 2024/09/08 21.71UT TOYOKAWA-FUJI






T20240909064101





BLK: 3,SNR1: 0.11415 ,SNR2: 0.32130




Frequency (Hz)

K20240909064059




BLK: 3,SNR1: 0.93746E-01,SNR2: 1.3652




Frequency (Hz)


3C152 2024/09/08 21.71UT TOYOKAWA-KISO





F20240909064100




BLK:10,SNR1: 1.9931 ,SNR2: 5.9331




K20240909064059





BLK:10,SNR1: 1.6451 ,SNR2: 2.7572




3C152 2024/09/08 21.71UT FUJI -KISO



T20240909070323




BLK: 5,SNR1: 0.26879 ,SNR2: 2.0210




Frequency (Hz)

3C161 2024/09/08 22.08UT TOYOKAWA-FUJI


F20240909070322





BLK: 5,SNR1: 0.21835 ,SNR2: 1.8779




Frequency (Hz)



T20240909070323





BLK:14,SNR1: 0.16532 ,SNR2: 1.8369




Frequency (Hz)

K20240909070321




BLK:14,SNR1: 75.868 ,SNR2: 71.971





Frequency (Hz)


3C161 2024/09/08 22.08UT TOYOKAWA-KISO





F20240909070322




BLK: 5,SNR1:-0.28851 ,SNR2: 0.70124




K20240909070321





BLK: 5,SNR1: 3.7791 ,SNR2: 12.440




3C161 2024/09/08 22.08UT FUJI -KISO



T20240909073056





BLK: 5,SNR1:-0.81322E-01,SNR2: 0.53190




Frequency (Hz)

F20240909073055




BLK: 5,SNR1:-0.25702E-01,SNR2: 0.76891





Frequency (Hz)


0652-130 2024/09/08 22.54UT TOYOKAWA-FUJI



T20240909073056





BLK: 5,SNR1: 0.85109E-01,SNR2: 0.58334




Frequency (Hz)

K20240909073054




BLK: 5,SNR1: 2.0298 ,SNR2: 9.1345




Frequency (Hz)


0652-130 2024/09/08 22.54UT TOYOKAWA-KISO



F20240909073055





BLK: 8,SNR1: 2.9363 ,SNR2: 12.459




Frequency (Hz)

K20240909073054




BLK: 8,SNR1: 1.0178 ,SNR2: 4.3179





Frequency (Hz)

0652-130 2024/09/08 22.54UT FUJI -KISO






T20240909074232





BLK: 8,SNR1: 12.173 ,SNR2: 43.027




Frequency (Hz)

F20240909074231




BLK: 8,SNR1: 1.1595 ,SNR2: 3.9285





Frequency (Hz)


0703+138 2024/09/08 22.74UT TOYOKAWA-FUJI



T20240909074232





BLK: 5,SNR1: 11.267 ,SNR2: 79.723




Frequency (Hz)

K20240909074230




BLK: 5,SNR1: 1.1032 ,SNR2: 9.3203





Frequency (Hz)


0703+138 2024/09/08 22.74UT TOYOKAWA-KISO



F20240909074231





BLK: 7,SNR1: 1.9847 ,SNR2: 6.1407




Frequency (Hz)

K20240909074230




BLK: 7,SNR1: 1.5556 ,SNR2: 3.6065





Frequency (Hz)


0703+138 2024/09/08 22.74UT FUJI -KISO



T20240909075155





BLK: 5,SNR1: 0.40539 ,SNR2: 1.1100




Frequency (Hz)

F20240909075154




BLK: 5,SNR1: 0.89105 ,SNR2: 2.6744





Frequency (Hz)


0713-024 2024/09/08 22.89UT TOYOKAWA-FUJI



T20240909075155




BLK: 8,SNR1: 0.30488E-01,SNR2: 1.4232




Frequency (Hz)

K20240909075153




BLK: 8,SNR1: 0.87409 ,SNR2: 3.1200




Frequency (Hz)


0713-024 2024/09/08 22.89UT TOYOKAWA-KISO



F20240909075154




BLK:10,SNR1: 0.87678 ,SNR2: 2.6057




Frequency (Hz)

K20240909075153




BLK:10,SNR1: 1.4988 ,SNR2: 4.9261





Frequency (Hz)


0713-024 2024/09/08 22.89UT FUJI -KISO



T20240909080206





BLK: 4,SNR1: 0.59235 ,SNR2: 4.6113




Frequency (Hz)

F20240909080205




BLK: 4,SNR1: 0.95832 ,SNR2: 3.5576





Frequency (Hz)


0723+10 2024/09/08 23.06UT TOYOKAWA-FUJI



T20240909080206





BLK: 8,SNR1: 0.55801 ,SNR2: 2.1361




Frequency (Hz)

0723+10 2024/09/08 23.06UT TOYOKAWA-KISO


K20240909080204



BLK: 8,SNR1: 2.4185 ,SNR2: 7.1325




Frequency (Hz)






F20240909080205





BLK: 8,SNR1: 4.1358 ,SNR2: 12.002




Frequency (Hz)

0723+10 2024/09/08 23.06UT FUJI -KISO


K20240909080204





BLK: 8,SNR1: 1.7657 ,SNR2: 3.9486




Frequency (Hz)



T20240909081221





BLK:12,SNR1: 0.10542 ,SNR2: 1.1018




Frequency (Hz)

F20240909081220




BLK:12,SNR1: 1.3076 ,SNR2: 3.9271





Frequency (Hz)


0732+33 2024/09/08 23.23UT TOYOKAWA-FUJI



T20240909081221





BLK: 9,SNR1: 0.44152E-01,SNR2: 0.71256




Frequency (Hz)

K20240909081219




BLK: 9,SNR1: 40.906 ,SNR2: 60.235





Frequency (Hz)


0732+33 2024/09/08 23.23UT TOYOKAWA-KISO



F20240909081220





BLK:13,SNR1: 5.0774 ,SNR2: 13.839




Frequency (Hz)

K20240909081219




BLK:13,SNR1: 52.848 ,SNR2: 87.924





Frequency (Hz)


0732+33 2024/09/08 23.23UT FUJI -KISO



T20240909082023





BLK:13,SNR1: 0.26831 ,SNR2: 2.0365




Frequency (Hz)

F20240909082022




BLK:13,SNR1:-0.15982 ,SNR2: 1.5734





Frequency (Hz)


0741-06 2024/09/08 23.37UT TOYOKAWA-FUJI



T20240909082023





BLK:17,SNR1: 0.26743 ,SNR2: 2.5047




Frequency (Hz)

K20240909082021




BLK:17,SNR1: 1.5298 ,SNR2: 5.3693





Frequency (Hz)


0741-06 2024/09/08 23.37UT TOYOKAWA-KISO



F20240909082022





BLK: 9,SNR1:-0.20766 ,SNR2: 0.57859




Frequency (Hz)

K20240909082021




BLK: 9,SNR1: 1.3546 ,SNR2: 3.7638





Frequency (Hz)


0741-06 2024/09/08 23.37UT FWJ -KISO



T20240909083007





BLK: 5,SNR1: 11.747 ,SNR2: 24.695





0752-200 2024/09/08 23.53UT TOYOKAWA-FUJI

F20240909083006





BLK: 5,SNR1: 0.19365 ,SNR2: 1.3222






T20240909083007




BLK: 9,SNR1: 3.5176 ,SNR2: 10.000




Frequency (Hz)

K20240909083005




BLK: 9,SNR1: 0.54009 ,SNR2: 5.3176




Frequency (Hz)


0752-200 2024/09/08 23.53UT TOYOKAWA-KISO



F20240909083006




BLK: 2,SNR1: 1.4799 ,SNR2: 5.1678




Frequency (Hz)

K20240909083005




BLK: 2,SNR1: 0.47128 ,SNR2: 1.4871





Frequency (Hz)


0752-200 2024/09/08 23.53UT FUJI -KISO



T20240909083742




BLK: 7,SNR1: 1.7000 ,SNR2: 9.2377




Frequency (Hz)

3C190 2024/09/08 23.66UT TOYOKAWA-FUJI


F20240909083741





BLK: 7,SNR1: 0.68297 ,SNR2: 1.9204




Frequency (Hz)



T20240909083742





BLK:14,SNR1: 2.7699 ,SNR2: 9.9034




Frequency (Hz)

K20240909083740




BLK:14,SNR1: 1.7569 ,SNR2: 5.1461





Frequency (Hz)


3C190 2024/09/08 23.66UT TOYOKAWA-KISO



F20240909083741





BLK: 2,SNR1:-0.17968 ,SNR2: 1.0873




Frequency (Hz)

3C190 2024/09/08 23.66UT FUJI -KISO


K20240909083740





BLK: 2,SNR1: 0.23595 ,SNR2: 1.8115




Frequency (Hz)



T20240909085007




BLK:12,SNR1: 8.8926 ,SNR2: 13.078




Frequency (Hz)

3C196 2024/09/08 23.86UT TOYOKAWA-FUJI


F20240909085006





BLK:12,SNR1: 1.6130 ,SNR2: 3.8898




Frequency (Hz)



T20240909085007





BLK:14,SNR1: 6.5462 ,SNR2: 15.266




Frequency (Hz)

K20240909085005




BLK:14,SNR1: 11.878 ,SNR2: 23.868




Frequency (Hz)


3C196 2024/09/08 23.86UT TOYOKAWA-KISO



F20240909085006




BLK:17,SNR1: 0.85717 ,SNR2: 3.9522




Frequency (Hz)

3C196 2024/09/08 23.86UT FUJI -KISO


K20240909085005



BLK:17,SNR1: 11.610 ,SNR2: 23.075





Frequency (Hz)








T202409090117




BLK: 3,SNR1: 0.62245E-01,SNR2: 0.74583




F202409090116





BLK: 3,SNR1: 4.4486 ,SNR2: 11.879




0821+394 2024/09/09 0.05UT TOYOKAWA-FUJI



T202409090117




BLK: 5,SNR1: 1.8902 ,SNR2: 4.9454





0821+394 2024/09/09 0.05UT TOYOKAWA-KISO



K202409090115




BLK: 5,SNR1: 1.5402 ,SNR2: 4.1086





F202409090116




BLK: 2,SNR1: 0.80624E-01,SNR2: 1.0683




K202409090115





BLK: 2,SNR1: 5.4109 ,SNR2: 19.606




0821+394 2024/09/09 0.05UT FUJI -KISO





T20240909091257




BLK:10,SNR1: 0.23751 ,SNR2: 0.94346




F20240909091256





BLK:10,SNR1: 0.94333 ,SNR2: 2.3560




0834-19 2024/09/09 0.24UT TOYOKAWA-FUJI





T20240909091257




BLK:16,SNR1: 0.16229 ,SNR2: 1.1839




K20240909091255





BLK:16,SNR1: 1.1905 ,SNR2: 3.8400




0834-19 2024/09/09 0.24UT TOYOKAWA-KISO





F20240909091256




BLK: 8,SNR1: 0.74908 ,SNR2: 1.9656




K20240909091255




BLK: 8,SNR1: 1.9564 ,SNR2: 6.0841




0834-19 2024/09/09 0.24UT FUJI -KISO



T20240909091802





BLK:16,SNR1: 24.857 ,SNR2: 32.183





0839-071 2024/09/09 0.33UT TOYOKAWA-FUJI



F20240909091801




BLK:16,SNR1: 1.8651 ,SNR2: 6.4679



T20240909091802




BLK: 9, SNR1: 4.1913 , SNR2: 11.596




Frequency (Hz)

K20240909091800




BLK: 9, SNR1: 30.482 , SNR2: 36.826




Frequency (Hz)

0839-071 2024/09/09 0.33UT TOYOKAWA-KISO






F20240909091801




BLK: 9,SNR1: 2.0329 ,SNR2: 6.8499





0839-071 2024/09/09 0.33UT FUJI -KISO



K20240909091800




BLK: 9,SNR1: 7.7666 ,SNR2: 19.622





T20240909092903




BLK: 8,SNR1: 0.24406 ,SNR2: 0.93930




F20240909092902





BLK: 8,SNR1: 5.7354 ,SNR2: 16.379




3C208 2024/09/09 0.51UT TOYOKAWA-FUJI



T20240909092903





BLK: 6,SNR1: 5.8618 ,SNR2: 16.724





3C208 2024/09/09 0.51UT TOYOKAWA-KISO


K20240909092901




BLK: 6,SNR1: 11.244 ,SNR2: 29.470



F20240909092902





BLK: 5,SNR1: 8.4211 ,SNR2: 24.265





3C208 2024/09/09 0.51UT FUJI -KISO


K20240909092901




BLK: 5,SNR1: 8.9363 ,SNR2: 23.733



T20240909094543




BLK: 3,SNR1: 0.20247 ,SNR2: 1.4606




Frequency (Hz)

3C216 2024/09/09 0.79UT TOYOKAWA-FUJI


F20240909094543





BLK: 3,SNR1: 1.2206 ,SNR2: 6.0592




Frequency (Hz)



T20240909094543




BLK:11,SNR1: 0.61964 ,SNR2: 1.0835





3C216 2024/09/09 0.79UT TOYOKAWA-KISO



K20240909094540




BLK:11,SNR1: 1.9174 ,SNR2: 3.0673



F20240909094543




BLK: 3,SNR1: 0.13477 ,SNR2: 3.8415





3C216 2024/09/09 0.79UT FUJI -KISO


K20240909094540




BLK: 3,SNR1: 0.42786 ,SNR2: 2.2255



T20240909095755




BLK: 8,SNR1: 0.48713 ,SNR2: 2.1417





0919-142 2024/09/09 0.99UT TOYOKAWA-FUJI

F20240909095755




BLK: 8,SNR1: 0.73310 ,SNR2: 3.2701






T20240909095755





BLK:13,SNR1: 3.4737 ,SNR2: 14.949





0919-142 2024/09/09 0.99UT TOYOKAWA-KISO


K20240909095752




BLK:13,SNR1: 2.8454 ,SNR2: 11.899




F20240909095755




BLK:10,SNR1: 1.0296 ,SNR2: 4.7664




K20240909095752





BLK:10,SNR1: 1.8870 ,SNR2: 8.1545




0919-142 2024/09/09 0.99UT FUJI -KISO



T20240909100434





BLK: 6,SNR1: 9.8304 ,SNR2: 27.987




Frequency (Hz)

F20240909100434




BLK: 6,SNR1: 9.9423 ,SNR2: 25.299





Frequency (Hz)


0926+117 2024/09/09 1.10UT TOYOKAWA-FUJI



T20240909100434





BLK:10,SNR1: 6.8530 ,SNR2: 20.060




Frequency (Hz)

0926+117 2024/09/09 1.10UT TOYOKAWA-KISO


K20240909100431





BLK:10,SNR1: 8.0609 ,SNR2: 23.317




Frequency (Hz)



F20240909100434





BLK: 6, SNR1: 6.3008 , SNR2: 18.298




Frequency (Hz)

0926+117 2024/09/09 1.10UT FUJI -KISO


K20240909100431





BLK: 6, SNR1: 10.686 , SNR2: 33.746




Frequency (Hz)





T20240909101218




BLK:14,SNR1: 1.3446 ,SNR2: 3.4797




F20240909101218





BLK:14,SNR1: 3.0844 ,SNR2: 14.456




3C222 2024/09/09 1.23UT TOYOKAWA-FUJI



T20240909101218





BLK:18,SNR1: 1.0734 ,SNR2: 2.8098




Frequency (Hz)

K20240909101215




BLK:18,SNR1: 3.4190 ,SNR2: 6.7597





Frequency (Hz)


3C222 2024/09/09 1.23UT TOYOKAWA-KISO



F20240909101218




BLK:13,SNR1: 7.1186 ,SNR2: 21.031





3C222 2024/09/09 1.23UT FUJI -KISO

K20240909101215





BLK:13,SNR1: 3.7521 ,SNR2: 10.766






T20240909101918




BLK:10,SNR1: 0.97722 ,SNR2: 3.8295





0941-08 2024/09/09 1.35UT TOYOKAWA-FUJI



F20240909101918




BLK:10,SNR1: 1.2470 ,SNR2: 3.5052



T20240909101918




BLK:12,SNR1: 0.68060 ,SNR2: 1.6899





0941-08 2024/09/09 1.35UT TOYOKAWA-KISO


K20240909101915




BLK:12,SNR1: 4.2792 ,SNR2: 12.388



F20240909101918




BLK: 3,SNR1: 0.54356 ,SNR2: 2.8297





0941-08 2024/09/09 1.35UT FUJI -KISO


K20240909101915




BLK: 3,SNR1: 1.3213 ,SNR2: 5.1492



T20240909102740




BLK: 9, SNR1: 10.203 , SNR2: 26.369





3C230 2024/09/09 1.49UT TOYOKAWA-FUJI



F20240909102740




BLK: 9, SNR1: 8.0024 , SNR2: 20.629



T20240909102740




BLK: 6, SNR1: 9.3540 , SNR2: 27.484





3C230 2024/09/09 1.49UT TOYOKAWA-KISO


K20240909102737




BLK: 6, SNR1: 10.962 , SNR2: 27.950



F20240909102740




BLK: 5,SNR1: 13.915 ,SNR2: 34.237




Frequency (Hz)

3C230 2024/09/09 1.49UT FUJI -KISO


K20240909102737





BLK: 5,SNR1: 8.9672 ,SNR2: 27.562




Frequency (Hz)



T20240909104147




BLK: 7,SNR1: 2.5723 ,SNR2: 4.5376





3C236 2024/09/09 1.72UT TOYOKAWA-FUJI



F20240909104147




BLK: 7,SNR1: 2.1448 ,SNR2: 6.5150



T20240909104147




BLK:13,SNR1: 6.9243 ,SNR2: 18.372





3C236 2024/09/09 1.72UT TOYOKAWA-KISO

K20240909104144




BLK:13,SNR1: 2.9284 ,SNR2: 7.7200






F20240909104147




BLK:10,SNR1: 2.2446 ,SNR2: 6.7720





3C236 2024/09/09 1.72UT FUJI -KISO


K20240909104144




BLK:10,SNR1: 2.9866 ,SNR2: 7.8304




T20240909104957




BLK: 7,SNR1: 6.1594 ,SNR2: 15.437




F20240909104957




BLK: 7,SNR1: 8.8159 ,SNR2: 21.895




1011+110 2024/09/09 1.86UT TOYOKAWA-FUJI



T20240909104957




BLK: 6,SNR1: 7.3677 ,SNR2: 19.036





1011+110 2024/09/09 1.86UT TOYOKAWA-KISO


K20240909104954




BLK: 6,SNR1: 9.8449 ,SNR2: 24.762



F20240909104957




BLK: 6,SNR1: 5.8379 ,SNR2: 15.057




Frequency (Hz)

K20240909104954




BLK: 6,SNR1: 6.6753 ,SNR2: 17.652





Frequency (Hz)


1011+110 2024/09/09 1.86UT FUJI -KISO




T20240909105738




BLK:12,SNR1: 0.69012 ,SNR2: 4.2941




F20240909105738





BLK:12,SNR1: 0.83601E-01,SNR2: 1.5202




3C241 2024/09/09 1.99UT TOYOKAWA-FUJI




T20240909105738




BLK:18,SNR1: 1.1424 ,SNR2: 3.9898




K20240909105735




BLK:18,SNR1: 30.052 ,SNR2: 76.517




3C241 2024/09/09 1.99UT TOYOKAWA-KISO




F20240909105738




BLK:12,SNR1: 0.55464 ,SNR2: 1.9855




K20240909105735




BLK:12,SNR1: 8.1557 ,SNR2: 20.950




3C241 2024/09/09 1.99UT FUJI -KISO




T20240909110907




BLK: 6,SNR1: 0.65171E-01,SNR2: 1.5014




F20240909110907



BLK: 6,SNR1:-0.97568E-01,SNR2: 1.3791




1031-11 2024/09/09 2.18UT TOYOKAWA-FUJI






T20240909110907




BLK:11,SNR1: 0.23868 ,SNR2: 0.72141




1031-11 2024/09/09 2.18UT TOYOKAWA-KISO


K20240909110904





BLK:11,SNR1: 3.9919 ,SNR2: 12.444




Frequency (Hz)



F20240909110907





BLK: 3,SNR1: 0.14043 ,SNR2: 2.8769




Frequency (Hz)

K20240909110904




BLK: 3,SNR1: 0.52946 ,SNR2: 1.9365




Frequency (Hz)


1031-11 2024/09/09 2.18UT FUJI -KISO



T20240909111341




BLK: 9,SNR1: 9.7919 ,SNR2: 25.258





1035-058 2024/09/09 2.26UT TOYOKAWA-FUJI



F20240909111341




BLK: 9,SNR1: 9.3319 ,SNR2: 23.790



T20240909111341




BLK:10,SNR1: 8.8461 ,SNR2: 22.299





1035-058 2024/09/09 2.26UT TOYOKAWA-KISO


K20240909111338




BLK:10,SNR1: 19.008 ,SNR2: 45.263



F20240909111341




BLK: 7,SNR1: 7.1380 ,SNR2: 20.573





1035-058 2024/09/09 2.26UT FUJI -KISO


K20240909111338




BLK: 7,SNR1: 56.480 ,SNR2: 110.31




T20240909112254




BLK: 5,SNR1: 1.1013 ,SNR2: 3.7855




F20240909112254




BLK: 5,SNR1: 0.26252 ,SNR2: 1.6132




1044-008 2024/09/09 2.41UT TOYOKAWA-FUJI



T20240909112254




BLK: 6,SNR1: 3.5904 ,SNR2: 16.213




1044-008 2024/09/09 2.41UT TOYOKAWA-KISO


K20240909112251




BLK: 6,SNR1: 7.0051 ,SNR2: 18.184




Frequency (Hz)




F20240909112254




BLK: 4,SNR1: 0.33830E-01,SNR2: 1.6448




K20240909112251



BLK: 4,SNR1: 7.2072 ,SNR2: 14.912





1044-008 2024/09/09 2.41UT FUJI -KISO






T20240909113358





BLK:13,SNR1: 12.253 ,SNR2: 29.717





1055+01 2024/09/09 2.59UT TOYOKAWA-FUJI



F20240909113358




BLK:13,SNR1: 9.6267 ,SNR2: 25.074



T20240909113358





BLK: 7,SNR1: 7.6039 ,SNR2: 20.722




1055+01 2024/09/09 2.59UT TOYOKAWA-KISO


K20240909113355





BLK: 7,SNR1: 19.975 ,SNR2: 61.063




Frequency (Hz)



F20240909113358





BLK: 7,SNR1: 12.144 ,SNR2: 38.960





1055+01 2024/09/09 2.59UT FUJI -KISO


K20240909113355




BLK: 7,SNR1: 13.665 ,SNR2: 39.369



T20240909114516




BLK: 8,SNR1:-0.33500 ,SNR2: 1.4640





1107+109 2024/09/09 2.78UT TOYOKAWA-FUJI


F20240909114516




BLK: 8,SNR1: 36.274 ,SNR2: 47.226



T20240909114516





BLK: 9,SNR1: 19.262 ,SNR2: 23.783





1107+109 2024/09/09 2.78UT TOYOKAWA-KISO


K20240909114513




BLK: 9,SNR1:-0.41510 ,SNR2: 0.80071



F20240909114516





BLK:11,SNR1:-0.36577 ,SNR2: 1.1834





1107+109 2024/09/09 2.78UT FUJI -KISO


K20240909114513




BLK:11,SNR1: 21.426 ,SNR2: 27.394



T20240909115453





BLK:10,SNR1: 7.9138 ,SNR2: 19.151





3C255 2024/09/09 2.94UT TOYOKAWA-FUJI


F20240909115453




BLK:10,SNR1: 2.1428 ,SNR2: 6.4706



T20240909115453





BLK:17,SNR1: 6.0244 ,SNR2: 14.432





3C255 2024/09/09 2.94UT TOYOKAWA-KISO

K20240909115450





BLK:17,SNR1: 87.322 ,SNR2: 91.849






F20240909115453





BLK:11,SNR1: 8.8998 ,SNR2: 21.147





3C255 2024/09/09 2.94UT FUJI -KISO



K20240909115450




BLK:11,SNR1: 25.831 ,SNR2: 58.988



T20240909120531





BLK: 8,SNR1: 0.29874 ,SNR2: 2.7580




Frequency (Hz)

F20240909120531




BLK: 8,SNR1: 0.41286 ,SNR2: 3.9572





Frequency (Hz)


1127-14 2024/09/09 3.12UT TOYOKAWA-FUJI



T20240909120531





BLK: 8,SNR1: 1.0289 ,SNR2: 4.1582




Frequency (Hz)

K20240909120528




BLK: 8,SNR1: 27.032 ,SNR2: 41.251




Frequency (Hz)


1127-14 2024/09/09 3.12UT TOYOKAWA-KISO



F20240909120531




BLK: 3,SNR1: 1.1525 ,SNR2: 9.2062





1127-14 2024/09/09 3.12UT FUJI -KISO


K20240909120528




BLK: 3,SNR1: 0.84973 ,SNR2: 2.6979





T20240909121851




BLK:13,SNR1: 2.0228 ,SNR2: 6.0525




F20240909121851




BLK:13,SNR1: 2.2547 ,SNR2: 6.2803




3C263.1 2024/09/09 3.34UT TOYOKAWA-FUJI




T20240909121851




BLK:11,SNR1: 2.4419 ,SNR2: 7.0336




K20240909121848





BLK:11,SNR1: 6.1130 ,SNR2: 16.958




3C263.1 2024/09/09 3.34UT TOYOKAWA-KISO



F20240909121851




BLK: 8,SNR1: 10.375 ,SNR2: 26.005





3C263.1 2024/09/09 3.34UT FUJI -KISO



K20240909121848




BLK: 8,SNR1: 11.415 ,SNR2: 28.036




T20240909122518




BLK:14,SNR1: 0.53456 ,SNR2: 1.8909




F20240909122518



BLK:14,SNR1: 3.3432 ,SNR2: 9.8611





3C267 2024/09/09 3.45UT TOYOKAWA-FUJI







T20240909122518




BLK:19,SNR1: 0.61228 ,SNR2: 2.0793




K20240909122515




BLK:19,SNR1: 0.98269 ,SNR2: 3.4822




3C267 2024/09/09 3.45UT TOYOKAWA-KISO




F20240909122518




BLK: 4,SNR1: 1.0345 ,SNR2: 2.4955




K20240909122515





BLK: 4,SNR1: 1.2528 ,SNR2: 3.8165




3C267 2024/09/09 3.45UT FUJI -KISO



T20240909125106




BLK: 1,SNR1: 0.18245 ,SNR2: 3.8219




Frequency (Hz)

F20240909125106




BLK: 1,SNR1:-0.27251 ,SNR2: 0.76399





Frequency (Hz)


1213-17 2024/09/09 3.88UT TOYOKAWA-FUJI





T20240909125106




BLK: 5,SNR1: 0.12077 ,SNR2: 1.6410




K20240909125103





BLK: 5,SNR1: 1.0509 ,SNR2: 5.3015




1213-17 2024/09/09 3.88UT TOYOKAWA-KISO





F20240909125106




BLK: 9,SNR1: 0.86248E-01,SNR2: 1.1731




K20240909125103





BLK: 9,SNR1: 1.3141 ,SNR2: 4.0209




1213-17 2024/09/09 3.88UT FUJI -KISO





T20240909130423




BLK:17,SNR1: 15.518 ,SNR2: 66.982




F20240909130423





BLK:17,SNR1: 0.33888 ,SNR2: 3.6835




3C273 2024/09/09 4.10UT TOYOKAWA-FUJI




T20240909130423




BLK:24,SNR1: 15.355 ,SNR2: 62.230




K20240909130420




BLK:24,SNR1: 2.8379 ,SNR2: 9.1738




3C273 2024/09/09 4.10UT TOYOKAWA-KISO



F20240909130423




BLK:30,SNR1: 0.44411 ,SNR2: 4.0685





3C273 2024/09/09 4.10UT FUJI -KISO

K20240909130420





BLK:30,SNR1: 2.6531 ,SNR2: 9.1275








T20240909131734




BLK: 8,SNR1: 0.21396 ,SNR2: 1.7800




F20240909131734





BLK: 8,SNR1: 1.6740 ,SNR2: 5.2533




3C275 2024/09/09 4.32UT TOYOKAWA-FUJI




T20240909131734




BLK: 6,SNR1: 0.97018 ,SNR2: 1.6169




K20240909131731





BLK: 6,SNR1: 6.1205 ,SNR2: 15.823




3C275 2024/09/09 4.32UT TOYOKAWA-KISO



F20240909131734




BLK:11,SNR1: 2.6416 ,SNR2: 7.8211





3C275 2024/09/09 4.32UT FUJI -KISO



K20240909131731




BLK:11,SNR1: 6.2479 ,SNR2: 17.043





T20240909132339




BLK: 7,SNR1: 0.54096E-01,SNR2: 0.93756




F20240909132339





BLK: 7,SNR1: 0.55280,SNR2: 2.0914




1245-19 2024/09/09 4.42UT TOYOKAWA-FUJI





T20240909132339




BLK:14,SNR1: 0.12048E-02,SNR2: 1.1190




K20240909132336




BLK:14,SNR1: 0.59636 ,SNR2: 2.0082




1245-19 2024/09/09 4.42UT TOYOKAWA-KISO





F20240909132339




BLK: 3,SNR1:-0.34228E-01,SNR2: 0.68678




K20240909132336




BLK: 3,SNR1: 0.28215 ,SNR2: 1.7374




1245-19 2024/09/09 4.42UT FUJI -KISO




T20240909133122




BLK:10,SNR1: 0.29688 ,SNR2: 1.7073




F20240909133122




BLK:10,SNR1:-0.63697E-01,SNR2: 1.5441




3C279 2024/09/09 4.55UT TOYOKAWA-FUJI





T20240909133122




BLK:20,SNR1: 0.35636 ,SNR2: 4.2354




K20240909133119



BLK:20,SNR1: 0.19620 ,SNR2: 1.0214




3C279 2024/09/09 4.55UT TOYOKAWA-KISO








F20240909133122




BLK: 6,SNR1: 0.35219E-01,SNR2: 1.0485




K20240909133119




BLK: 6,SNR1: 0.38607,SNR2: 1.2588




3C279 2024/09/09 4.55UT FUJI -KISO




T20240909134652




BLK:12,SNR1: 0.31756 ,SNR2: 2.4875




F20240909134652





BLK:12,SNR1: 0.23455 ,SNR2: 2.7743




3C283 2024/09/09 4.81UT TOYOKAWA-FUJI





T20240909134652




BLK:23,SNR1: 0.34866 ,SNR2: 2.2491




K20240909134649




BLK:23,SNR1: 0.64546 ,SNR2: 2.1302




3C283 2024/09/09 4.81UT TOYOKAWA-KISO




F20240909134652




BLK:12,SNR1: 1.0166 ,SNR2: 2.2401




K20240909134649





BLK:12,SNR1: 0.34252 ,SNR2: 1.1235




3C283 2024/09/09 4.81UT FUJI -KISO



T20240909140116





BLK:14,SNR1: 0.28129 ,SNR2: 1.5327




Frequency (Hz)

F20240909140116




BLK:14,SNR1: 0.84954 ,SNR2: 3.5601





Frequency (Hz)


1323+32 2024/09/09 5.05UT TOYOKAWA-FUJI




T20240909140116




BLK:12,SNR1: 0.31299 ,SNR2: 1.5038




K20240909140113




BLK:12,SNR1: 1.8954 ,SNR2: 3.7386




1323+32 2024/09/09 5.05UT TOYOKAWA-KISO




F20240909140116




BLK:15,SNR1: 1.0741 ,SNR2: 4.4371




K20240909140113




BLK:15,SNR1: 5.0026 ,SNR2: 9.8032




1323+32 2024/09/09 5.05UT FUJI -KISO




T20240909140607




BLK:22,SNR1: 1.5386 ,SNR2: 7.5871




F20240909140607



BLK:22,SNR1: 2.3039 ,SNR2: 6.7192




3C286 2024/09/09 5.13UT TOYOKAWA-FUJI







T20240909140607




BLK:27,SNR1: 1.6991 ,SNR2: 8.3118




K20240909140604




BLK:27,SNR1: 0.66156 ,SNR2: 2.4016




3C286 2024/09/09 5.13UT TOYOKAWA-KISO





F20240909140607




BLK: 9,SNR1: 3.4532 ,SNR2: 9.9519




K20240909140604





BLK: 9,SNR1: 0.20775 ,SNR2: 2.2644




3C286 2024/09/09 5.13UT FUJI -KISO





T20240909142234




BLK:13,SNR1: 0.77571 ,SNR2: 2.7441




F20240909142234





BLK:13,SNR1: 0.27133 ,SNR2: 2.5294




1345+12 2024/09/09 5.40UT TOYOKAWA-FUJI





T20240909142234




BLK:17,SNR1: 74.962 ,SNR2: 142.28




K20240909142231





BLK:17,SNR1: 0.79894 ,SNR2: 2.3601




1345+12 2024/09/09 5.40UT TOYOKAWA-KISO



F20240909142234





BLK:10,SNR1: 0.37425 ,SNR2: 3.2127




Frequency (Hz)

K20240909142231




BLK:10,SNR1: 1.3515 ,SNR2: 3.9410





Frequency (Hz)


1345+12 2024/09/09 5.40UT FUJI -KISO



T20240909143254




BLK: 8,SNR1: 0.19481 ,SNR2: 0.87287




Frequency (Hz)

F20240909143254




BLK: 8,SNR1: 0.14149 ,SNR2: 3.8579





Frequency (Hz)


1355+01 2024/09/09 5.58UT TOYOKAWA-FUJI



T20240909143254





BLK: 8,SNR1: 0.12696 ,SNR2: 1.3397




Frequency (Hz)

K20240909143251




BLK: 8,SNR1: 0.63581 ,SNR2: 3.2914





Frequency (Hz)


1355+01 2024/09/09 5.58UT TOYOKAWA-KISO



F20240909143254





BLK: 8,SNR1: 0.95274E-01,SNR2: 3.6143




Frequency (Hz)

K20240909143251




BLK: 8,SNR1: 0.23857 ,SNR2: 1.3478





Frequency (Hz)

1355+01 2024/09/09 5.58UT FUJI -KISO








T20240909145405




BLK:12,SNR1: 0.52741 ,SNR2: 1.8199




F20240909145405




BLK:12,SNR1: 72.157 ,SNR2: 240.34




3C298 2024/09/09 5.93UT TOYOKAWA-FUJI





T20240909145405




BLK:21,SNR1: 0.46025 ,SNR2: 1.8066




K20240909145402





BLK:21,SNR1: 0.65041 ,SNR2: 2.3994




3C298 2024/09/09 5.93UT TOYOKAWA-KISO





F20240909145405




BLK:12,SNR1: 35.616 ,SNR2: 83.248




K20240909145402





BLK:12,SNR1: 0.95509 ,SNR2: 3.6803




3C298 2024/09/09 5.93UT FUJI -KISO




T20240909150548




BLK: 6,SNR1: 91.857 ,SNR2: 116.54




F20240909150548





BLK: 6,SNR1: 0.48379 ,SNR2: 4.5072




1428-03 2024/09/09 6.12UT TOYOKAWA-FUJI





T20240909150548




BLK: 7,SNR1: 71.513 ,SNR2: 104.42




K20240909150545




BLK: 7,SNR1: 1.0767 ,SNR2: 3.6284




1428-03 2024/09/09 6.12UT TOYOKAWA-KISO



F20240909150548





BLK: 1,SNR1: 0.86054E-01,SNR2: 0.10170




Frequency (Hz)

K20240909150545




BLK: 1,SNR1: 0.10213 ,SNR2: 0.64894





Frequency (Hz)


1428-03 2024/09/09 6.12UT FUJI -KISO




T20240909151430




BLK: 3,SNR1: 0.20171 ,SNR2: 1.5173




F20240909151430





BLK: 3,SNR1: 0.47957 ,SNR2: 3.7310




1436-16 2024/09/09 6.27UT TOYOKAWA-FUJI





T20240909151430




BLK: 2,SNR1: 0.14697 ,SNR2: 1.3839




K20240909151427



BLK: 2,SNR1: 1.8142 ,SNR2: 5.2331





1436-16 2024/09/09 6.27UT TOYOKAWA-KISO






F20240909151430





BLK: 3,SNR1: 0.38775 ,SNR2: 4.0898




Frequency (Hz)

K20240909151427




BLK: 3,SNR1:-0.34335E-01,SNR2: 0.43269




Frequency (Hz)


1436-16 2024/09/09 6.27UT FUJI -KISO




T20240909153053




BLK: 3,SNR1:-0.11798E-01,SNR2: 0.64065




F20240909153053





BLK: 3,SNR1: 0.10189 ,SNR2: 0.79845




1453-10 2024/09/09 6.54UT TOYOKAWA-FUJI





T20240909153053




BLK: 7,SNR1: 0.94907E-01,SNR2: 0.75437




K20240909153050




BLK: 7,SNR1: 34.854 ,SNR2: 68.220




1453-10 2024/09/09 6.54UT TOYOKAWA-KISO





F20240909153053




BLK: 4,SNR1:-0.31382 ,SNR2: 0.0000




K20240909153050





BLK: 4,SNR1: 10.188 ,SNR2: 38.458




1453-10 2024/09/09 6.54UT FUJI -KISO



T20240909154545




BLK: 7,SNR1: 0.34914 ,SNR2: 2.9736




Frequency (Hz)

F20240909154545




BLK: 7,SNR1: 0.61101 ,SNR2: 2.6038





Frequency (Hz)


1508-05 2024/09/09 6.79UT TOYOKAWA-FUJI



T20240909154545




BLK: 8,SNR1: 0.24373 ,SNR2: 1.4255




Frequency (Hz)

K20240909154542




BLK: 8,SNR1: 0.68012 ,SNR2: 2.3237




Frequency (Hz)


1508-05 2024/09/09 6.79UT TOYOKAWA-KISO



F20240909154545




BLK: 3,SNR1: 0.45189 ,SNR2: 4.2407




Frequency (Hz)

K20240909154542




BLK: 3,SNR1: 0.84971 ,SNR2: 3.0358





Frequency (Hz)


1508-05 2024/09/09 6.79UT FUJI -KISO



T20240909155445




BLK: 6,SNR1: 0.21117 ,SNR2: 0.60665




Frequency (Hz)

F20240909155445




BLK: 6,SNR1: 0.85231 ,SNR2: 2.8923





Frequency (Hz)

3C318 2024/09/09 6.94UT TOYOKAWA-FUJI








T20240909155445




BLK: 6,SNR1:-0.70493E-01,SNR2: 0.57067




K20240909155442




BLK: 6,SNR1: 0.90649 ,SNR2: 2.4271




3C318 2024/09/09 6.94UT TOYOKAWA-KISO



F20240909155445




BLK: 4,SNR1: 0.13489 ,SNR2: 1.3720




Frequency (Hz)

K20240909155442




BLK: 4,SNR1: 0.54769 ,SNR2: 2.6566





Frequency (Hz)


3C318 2024/09/09 6.94UT FUJI -KISO



T20240909160032




BLK: 5,SNR1: 1.1565 ,SNR2: 3.8906




Frequency (Hz)

F20240909160032




BLK: 5,SNR1:-0.97359E-01,SNR2: 2.3563





Frequency (Hz)


1523+03 2024/09/09 7.04UT TOYOKAWA-FUJI





T20240909160032




BLK: 4,SNR1: 0.84192 ,SNR2: 4.7139




K20240909160029




BLK: 4,SNR1: 0.90918E-01,SNR2: 0.72640




1523+03 2024/09/09 7.04UT TOYOKAWA-KISO




F20240909160032




BLK: 4,SNR1: 0.34041 ,SNR2: 2.2940




K20240909160029





BLK: 4,SNR1: 0.29466 ,SNR2: 0.80130




1523+03 2024/09/09 7.04UT FUJI -KISO



T20240909161212




BLK: 2,SNR1:-0.13801 ,SNR2: 0.15360




Frequency (Hz)

F20240909161212




BLK: 2,SNR1:-0.55288E-01,SNR2: 0.66395





Frequency (Hz)


1535+139 2024/09/09 7.23UT TOYOKAWA-FUJI



T20240909161212





BLK: 4,SNR1: 0.23753 ,SNR2: 0.38158




Frequency (Hz)

K20240909161209




BLK: 4,SNR1: 0.84155 ,SNR2: 8.1561




Frequency (Hz)


1535+139 2024/09/09 7.23UT TOYOKAWA-KISO



F20240909161212





BLK: 4,SNR1:-0.84071E-01,SNR2: 0.69542




Frequency (Hz)

K20240909161209




BLK: 4,SNR1: 0.38317 ,SNR2: 1.5308





Frequency (Hz)

1535+139 2024/09/09 7.23UT FUJI -KISO







T20240909162236




BLK: 3,SNR1: 0.23180 ,SNR2: 1.4386




F20240909162236





BLK: 3,SNR1:-0.19412 ,SNR2: 1.4301




1545-12 2024/09/09 7.40UT TOYOKAWA-FUJI




T20240909162236




BLK: 5,SNR1: 0.29853E-01,SNR2: 0.38177




K20240909162233





BLK: 5,SNR1: 2.8633 ,SNR2: 8.8865




1545-12 2024/09/09 7.40UT TOYOKAWA-KISO



F20240909162236





BLK: 3,SNR1: 0.38388 ,SNR2: 2.1173




Frequency (Hz)

K20240909162233




BLK: 3,SNR1: 0.57997 ,SNR2: 3.6668





Frequency (Hz)


1545-12 2024/09/09 7.40UT FUJI -KISO



T20240909164339




BLK: 3,SNR1: 0.35332 ,SNR2: 2.8159




Frequency (Hz)

F20240909164339




BLK: 3,SNR1: 0.62496 ,SNR2: 2.1905





Frequency (Hz)


1607+26 2024/09/09 7.76UT TOYOKAWA-FUJI



T20240909164339





BLK: 2,SNR1: 0.33054 ,SNR2: 1.5928




Frequency (Hz)

K20240909164337




BLK: 2,SNR1: 1.4935 ,SNR2: 4.4075




Frequency (Hz)


1607+26 2024/09/09 7.76UT TOYOKAWA-KISO



F20240909164339





BLK: 6,SNR1: 6.1377 ,SNR2: 17.560




Frequency (Hz)

K20240909164337



BLK: 6,SNR1: 4.7711 ,SNR2: 11.798



Frequency (Hz)

1607+26 2024/09/09 7.76UT FUJI -KISO

