






T20240927062008




No.Good Data




FUJI





No.Good Data




0652-130 2024/09/26 21.36UT TOYOKAWA-FUJI



T20240927062008





BLK: 3,SNR1: 0.22602E-01,SNR2: 0.87993




Frequency (Hz)

K20240927062006




BLK: 3,SNR1: 0.72075E-01,SNR2: 0.90834





Frequency (Hz)


0652-130 2024/09/26 21.36UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927062006




No.Good Data





Frequency (Hz)


0652-130 2024/09/26 21.36UT FUJI -KISO




T20240927064107




No.Good Data




FUJI



No.Good Data




0713-024 2024/09/26 21.71UT TOYOKAWA-FUJI






T20240927064107





BLK: 4,SNR1: 0.12119 ,SNR2: 0.63961




Frequency (Hz)

K20240927064105




BLK: 4,SNR1: 0.55848 ,SNR2: 3.9723





Frequency (Hz)


0713-024 2024/09/26 21.71UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927064105




No.Good Data





Frequency (Hz)


0713-024 2024/09/26 21.71UT FUJI -KISO



T20240927065119





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0723+10 2024/09/26 21.88UT TOYOKAWA-FUJI



T20240927065119





BLK: 9,SNR1:-0.41478E-02,SNR2: 1.1818




Frequency (Hz)

K20240927065117




BLK: 9,SNR1: 0.65462 ,SNR2: 1.5869




Frequency (Hz)


0723+10 2024/09/26 21.88UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927065117




No.Good Data




Frequency (Hz)


0723+10 2024/09/26 21.88UT FUJI -KISO



T20240927070134





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0732+33 2024/09/26 22.05UT TOYOKAWA-FUJI



T20240927070134





BLK: 1,SNR1:-0.73511E-01,SNR2: 0.24676E-01




Frequency (Hz)

K20240927070132




BLK: 1,SNR1: 0.52173E-01,SNR2: 0.51986E-01





Frequency (Hz)


0732+33 2024/09/26 22.05UT TOYOKAWA-KISO




FUJI




No.Good Data




K20240927070132



No.Good Data





0732+33 2024/09/26 22.05UT FUJI -KISO






T20240927070936




No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0741-06 2024/09/26 22.19UT TOYOKAWA-FUJI



T20240927070936




BLK: 7,SNR1: 0.51107 ,SNR2: 2.2081




Frequency (Hz)

K20240927070933




BLK: 7,SNR1: 5.7096 ,SNR2: 14.528





Frequency (Hz)


0741-06 2024/09/26 22.19UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240927070933





No.Good Data




0741-06 2024/09/26 22.19UT FUJI -KISO





T20240927071920




No.Good Data




FUJI





No.Good Data




0752-200 2024/09/26 22.35UT TOYOKAWA-FUJI



T20240927071920





BLK: 4,SNR1:-0.88475E-01,SNR2: 0.80522




Frequency (Hz)

K20240927071917




BLK: 4,SNR1: 1.0098 ,SNR2: 6.4498





Frequency (Hz)


0752-200 2024/09/26 22.35UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240927071917





No.Good Data




0752-200 2024/09/26 22.35UT FUJI -KISO




T20240927072655




No.Good Data




FUJI





No.Good Data




3C190 2024/09/26 22.48UT TOYOKAWA-FUJI



T20240927072655





BLK: 5,SNR1: 0.29785 ,SNR2: 1.1417




Frequency (Hz)

3C190 2024/09/26 22.48UT TOYOKAWA-KISO


K20240927072652



BLK: 5,SNR1: 0.23380 ,SNR2: 1.3205





Frequency (Hz)






FUJI





No.Good Data




Frequency (Hz)

K20240927072652




No.Good Data





Frequency (Hz)


3C190 2024/09/26 22.48UT FUJI -KISO





T20240927073920




No.Good Data




FUJI





No.Good Data




3C196 2024/09/26 22.68UT TOYOKAWA-FUJI



T20240927073920





BLK:12,SNR1: 47.716 ,SNR2: 103.21




Frequency (Hz)

3C196 2024/09/26 22.68UT TOYOKAWA-KISO


K20240927073918





BLK:12,SNR1: 1.5422 ,SNR2: 6.1329




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240927073918




No.Good Data




Frequency (Hz)


3C196 2024/09/26 22.68UT FUJI -KISO





T20240927075029




No.Good Data




FUJI





No.Good Data




0821+394 2024/09/26 22.87UT TOYOKAWA-FUJI



T20240927075029





BLK: 2,SNR1:-0.15096E-01,SNR2: 0.42994





0821+394 2024/09/26 22.87UT TOYOKAWA-KISO



K20240927075027




BLK: 2,SNR1: 0.15595 ,SNR2: 3.7625



FUJI





No.Good Data




Frequency (Hz)

K20240927075027




No.Good Data





Frequency (Hz)


0821+394 2024/09/26 22.87UT FUJI -KISO





T20240927080209




No.Good Data




FUJI



No.Good Data





0834-19 2024/09/26 23.06UT TOYOKAWA-FUJI






T20240927080209





BLK: 5,SNR1: 0.16910E-01,SNR2: 2.3316




Frequency (Hz)

K20240927080206




BLK: 5,SNR1: 1.2297 ,SNR2: 5.0233





Frequency (Hz)


0834-19 2024/09/26 23.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927080206




No.Good Data





Frequency (Hz)


0834-19 2024/09/26 23.06UT FUJI -KISO



T20240927080715





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0839-071 2024/09/26 23.15UT TOYOKAWA-FUJI




T20240927080715




BLK: 7,SNR1: 1.2061 ,SNR2: 9.4722




K20240927080712





BLK: 7,SNR1: 0.76249 ,SNR2: 2.5147




0839-071 2024/09/26 23.15UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927080712




No.Good Data





Frequency (Hz)


0839-071 2024/09/26 23.15UT FUJI -KISO





T20240927081816




No.Good Data




FUJI





No.Good Data




3C208 2024/09/26 23.33UT TOYOKAWA-FUJI



T20240927081816





BLK:12,SNR1: 2.4135 ,SNR2: 7.1637




Frequency (Hz)

3C208 2024/09/26 23.33UT TOYOKAWA-KISO


K20240927081813





BLK:12,SNR1: 4.2109 ,SNR2: 11.514




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240927081813




No.Good Data





Frequency (Hz)

3C208 2024/09/26 23.33UT FUJI -KISO








T20240927083457




No.Good Data




FUJI





No.Good Data




3C216 2024/09/26 23.61UT TOYOKAWA-FUJI



T20240927083457





BLK: 1,SNR1:-0.76530E-01,SNR2: 0.0000




Frequency (Hz)

3C216 2024/09/26 23.61UT TOYOKAWA-KISO


K20240927083454





BLK: 1,SNR1:-0.58764E-01,SNR2: 0.35723




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240927083454




No.Good Data





Frequency (Hz)


3C216 2024/09/26 23.61UT FUJI -KISO





T20240927084709




No.Good Data




FUJI





No.Good Data




0919-142 2024/09/26 23.81UT TOYOKAWA-FUJI



T20240927084709





BLK: 3,SNR1: 0.11594 ,SNR2: 1.9860




Frequency (Hz)

K20240927084706




BLK: 3,SNR1: 1.4378 ,SNR2: 7.6907





Frequency (Hz)


0919-142 2024/09/26 23.81UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927084706




No.Good Data





Frequency (Hz)


0919-142 2024/09/26 23.81UT FUJI -KISO





T20240927085347




No.Good Data




FUJI





No.Good Data




0926+117 2024/09/26 23.92UT TOYOKAWA-FUJI



T20240927085347




BLK: 8,SNR1: 0.21695 ,SNR2: 1.5946




Frequency (Hz)

K20240927085344




BLK: 8,SNR1: 0.48308 ,SNR2: 1.2766





Frequency (Hz)

0926+117 2024/09/26 23.92UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240927085344




No.Good Data





Frequency (Hz)


0926+117 2024/09/26 23.92UT FUJI -KISO





T20240927090132




No.Good Data




FUJI





No.Good Data




3C222 2024/09/27 0.05UT TOYOKAWA-FUJI



T20240927090132





BLK:11,SNR1: 0.38308 ,SNR2: 3.8359




Frequency (Hz)

K20240927090129




BLK:11,SNR1: 0.38767 ,SNR2: 4.2193





Frequency (Hz)


3C222 2024/09/27 0.05UT TOYOKAWA-KISO





FUJI




No.Good Data




K20240927090129





No.Good Data




3C222 2024/09/27 0.05UT FUJI -KISO





T20240927090832




No.Good Data




FUJI




No.Good Data




0941-08 2024/09/27 0.17UT TOYOKAWA-FUJI



T20240927090832





BLK: 4,SNR1: 0.14338 ,SNR2: 1.7965




Frequency (Hz)

0941-08 2024/09/27 0.17UT TOYOKAWA-KISO


K20240927090829




BLK: 4,SNR1: 0.55346 ,SNR2: 3.1866




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20240927090829




No.Good Data





Frequency (Hz)


0941-08 2024/09/27 0.17UT FUJI -KISO



T20240927091654





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C230 2024/09/27 0.31UT TOYOKAWA-FUJI







T20240927091654




BLK:12,SNR1: 0.24406 ,SNR2: 1.6636




K20240927091651





BLK:12,SNR1: 1.0436 ,SNR2: 3.0167




3C230 2024/09/27 0.31UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927091651




No.Good Data





Frequency (Hz)


3C230 2024/09/27 0.31UT FUJI -KISO



T20240927093255





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


3C237 2024/09/27 0.58UT TOYOKAWA-FUJI



T20240927093255





BLK:24,SNR1: 0.89814 ,SNR2: 8.5412





3C237 2024/09/27 0.58UT TOYOKAWA-KISO



K20240927093252




BLK:24,SNR1: 0.96799 ,SNR2: 2.6853



FUJI





No.Good Data




Frequency (Hz)

K20240927093252




No.Good Data





Frequency (Hz)


3C237 2024/09/27 0.58UT FUJI -KISO





T20240927093911




No.Good Data




FUJI





No.Good Data




1011+110 2024/09/27 0.68UT TOYOKAWA-FUJI



T20240927093911





BLK: 5, SNR1: 0.70331E-01, SNR2: 1.5228




Frequency (Hz)

K20240927093908




BLK: 5, SNR1: 1.6380, SNR2: 6.3167





Frequency (Hz)


1011+110 2024/09/27 0.68UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240927093908




No. Good Data




Frequency (Hz)

1011+110 2024/09/27 0.68UT FUJI -KISO








T20240927094652




No. Good Data




FUJI




No. Good Data




3C241 2024/09/27 0.81UT TOYOKAWA-FUJI





T20240927094652




BLK:12,SNR1: 47.257 ,SNR2: 118.64




K20240927094649





BLK:12,SNR1: 2.1517 ,SNR2: 5.9183




3C241 2024/09/27 0.81UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240927094649




No. Good Data





Frequency (Hz)


3C241 2024/09/27 0.81UT FUJI -KISO





T20240927095821




No. Good Data




FUJI





No. Good Data




1031-11 2024/09/27 1.00UT TOYOKAWA-FUJI



T20240927095821





BLK:11,SNR1: 0.82717 ,SNR2: 2.0644





1031-11 2024/09/27 1.00UT TOYOKAWA-KISO



K20240927095818




BLK:11,SNR1: 8.7565 ,SNR2: 21.242



FUJI





No. Good Data




Frequency (Hz)

K20240927095818




No. Good Data





Frequency (Hz)


1031-11 2024/09/27 1.00UT FUJI -KISO



T20240927100255





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1035-058 2024/09/27 1.08UT TOYOKAWA-FUJI



T20240927100255





BLK: 5,SNR1: 2.2002 ,SNR2: 13.049





1035-058 2024/09/27 1.08UT TOYOKAWA-KISO

K20240927100252





BLK: 5,SNR1: 0.41688 ,SNR2: 2.4990






FUJI





No. Good Data




Frequency (Hz)

K20240927100252




No. Good Data





Frequency (Hz)


1035-058 2024/09/27 1.08UT FUJI -KISO



T20240927101207





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1044-008 2024/09/27 1.23UT TOYOKAWA-FUJI



T20240927101207




BLK: 5,SNR1: 0.29719 ,SNR2: 2.1894





1044-008 2024/09/27 1.23UT TOYOKAWA-KISO



K20240927101204




BLK: 5,SNR1: 9.7731 ,SNR2: 22.097



FUJI





No.Good Data




Frequency (Hz)

K20240927101204




No.Good Data





Frequency (Hz)


1044-008 2024/09/27 1.23UT FUJI -KISO





T20240927102312




No. Good Data




FUJI




No. Good Data




1055+01 2024/09/27 1.41UT TOYOKAWA-FUJI



T20240927102312




BLK:21,SNR1: 1.6315 ,SNR2: 8.5500





1055+01 2024/09/27 1.41UT TOYOKAWA-KISO



K20240927102310




BLK:21,SNR1: 1.2052 ,SNR2: 5.6729



FUJI





No.Good Data




Frequency (Hz)

K20240927102310




No.Good Data





Frequency (Hz)


1055+01 2024/09/27 1.41UT FUJI -KISO



T20240927103429





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

1107+109 2024/09/27 1.60UT TOYOKAWA-FUJI







T20240927103429




BLK: 7,SNR1: 2.1456 ,SNR2: 5.5463




K20240927103427





BLK: 7,SNR1: 4.5351 ,SNR2: 13.517




1107+109 2024/09/27 1.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927103427




No.Good Data





Frequency (Hz)


1107+109 2024/09/27 1.60UT FUJI -KISO





T20240927104407




No.Good Data




FUJI




No.Good Data




3C255 2024/09/27 1.76UT TOYOKAWA-FUJI




T20240927104407




BLK:10,SNR1: 4.0452 ,SNR2: 13.274




K20240927104404





BLK:10,SNR1: 1.3852 ,SNR2: 9.8296




3C255 2024/09/27 1.76UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240927104404




No. Good Data





Frequency (Hz)


3C255 2024/09/27 1.76UT FUJI -KISO





T20240927105444




No.Good Data




FUJI





No.Good Data




1127-14 2024/09/27 1.94UT TOYOKAWA-FUJI




T20240927105444




BLK: 1,SNR1: 55.439 ,SNR2: 105.25




K20240927105442





BLK: 1,SNR1: 15.578 ,SNR2: 33.209




1127-14 2024/09/27 1.94UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927105442




No.Good Data





Frequency (Hz)

1127-14 2024/09/27 1.94UT FUJI -KISO






T20240927110805





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C263.1 2024/09/27 2.16UT TOYOKAWA-FUJI




T20240927110805




BLK: 4,SNR1: 0.43687 ,SNR2: 4.2671




K20240927110802





BLK: 4,SNR1:-0.15718 ,SNR2: 2.5659




3C263.1 2024/09/27 2.16UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927110802




No.Good Data





Frequency (Hz)


3C263.1 2024/09/27 2.16UT FUJI -KISO



T20240927111432





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C267 2024/09/27 2.27UT TOYOKAWA-FUJI



T20240927111432




BLK: 1,SNR1: 17.186 ,SNR2: 36.525





3C267 2024/09/27 2.27UT TOYOKAWA-KISO



K20240927111429




BLK: 1,SNR1: 21.642 ,SNR2: 45.522



FUJI





No. Good Data




Frequency (Hz)

K20240927111429




No. Good Data





Frequency (Hz)


3C267 2024/09/27 2.27UT FUJI -KISO



T20240927114020





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1213-17 2024/09/27 2.70UT TOYOKAWA-FUJI




T20240927114020




BLK: 7,SNR1: 4.0783 ,SNR2: 7.9962




K20240927114017



BLK: 7,SNR1: 12.140 ,SNR2: 30.356





1213-17 2024/09/27 2.70UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20240927114017




No. Good Data





Frequency (Hz)


1213-17 2024/09/27 2.70UT FUJI -KISO





T20240927115337




No.Good Data




FUJI





No.Good Data




3C273 2024/09/27 2.92UT TOYOKAWA-FUJI




T20240927115337




BLK: 8,SNR1: 13.957 ,SNR2: 33.101




K20240927115335





BLK: 8,SNR1: 11.972 ,SNR2: 29.247




3C273 2024/09/27 2.92UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927115335




No.Good Data





Frequency (Hz)


3C273 2024/09/27 2.92UT FUJI -KISO





T20240927120648




No.Good Data




FUJI





No.Good Data




3C275 2024/09/27 3.14UT TOYOKAWA-FUJI





T20240927120648




BLK:16,SNR1: 0.25357 ,SNR2: 1.7510




K20240927120645





BLK:16,SNR1: 0.22825 ,SNR2: 3.2388




3C275 2024/09/27 3.14UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927120645




No.Good Data





Frequency (Hz)


3C275 2024/09/27 3.14UT FUJI -KISO



T20240927121253





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1245-19 2024/09/27 3.24UT TOYOKAWA-FUJI







T20240927121253




BLK:13,SNR1: 8.7891 ,SNR2: 22.214




K20240927121250





BLK:13,SNR1: 10.377 ,SNR2: 26.235




1245-19 2024/09/27 3.24UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20240927121250




No. Good Data





Frequency (Hz)


1245-19 2024/09/27 3.24UT FUJI -KISO



T20240927122036





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C279 2024/09/27 3.37UT TOYOKAWA-FUJI




T20240927122036




BLK: 9,SNR1: 6.9362 ,SNR2: 22.141




K20240927122033





BLK: 9,SNR1: 1.7948 ,SNR2: 5.9301




3C279 2024/09/27 3.37UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927122033




No.Good Data





Frequency (Hz)


3C279 2024/09/27 3.37UT FUJI -KISO



T20240927123606





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C283 2024/09/27 3.63UT TOYOKAWA-FUJI



T20240927123606




BLK: 1,SNR1: 15.459 ,SNR2: 37.538





3C283 2024/09/27 3.63UT TOYOKAWA-KISO



K20240927123604




BLK: 1,SNR1: 7.5637 ,SNR2: 20.432



FUJI





No.Good Data




Frequency (Hz)

K20240927123604




No.Good Data





Frequency (Hz)

3C283 2024/09/27 3.63UT FUJI -KISO






T20240927125030





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1323+32 2024/09/27 3.87UT TOYOKAWA-FUJI




T20240927125030




BLK:17,SNR1: 46.621 ,SNR2: 88.700




K20240927125027





BLK:17,SNR1: 0.68168E-01,SNR2: 1.5453




1323+32 2024/09/27 3.87UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927125027




No.Good Data





Frequency (Hz)


1323+32 2024/09/27 3.87UT FUJI -KISO





T20240927125520




No. Good Data




FUJI





No. Good Data




3C286 2024/09/27 3.95UT TOYOKAWA-FUJI





T20240927125520




BLK:17,SNR1: 14.333 ,SNR2: 33.383




K20240927125517





BLK:17,SNR1: 2.6939 ,SNR2: 3.7980




3C286 2024/09/27 3.95UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927125517




No.Good Data





Frequency (Hz)


3C286 2024/09/27 3.95UT FUJI -KISO



T20240927131148





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/09/27 4.22UT TOYOKAWA-FUJI




T20240927131148




BLK:22,SNR1: 10.049 ,SNR2: 25.938




K20240927131145



BLK:22,SNR1: 8.0655 ,SNR2: 17.670





1345+12 2024/09/27 4.22UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240927131145




No.Good Data






Frequency (Hz)




1345+12 2024/09/27 4.22UT FUJI -KISO




T20240927132208




FUJI




1355+01 2024/09/27 4.40UT TOYOKAWA-FUJI




T20240927132208




BLK:17,SNR1: 3.0125 ,SNR2: 7.0000




K20240927132205




BLK:17,SNR1: 4.3876 ,SNR2: 11.882




1355+01 2024/09/27 4.40UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927132205




No.Good Data






Frequency (Hz)




1355+01 2024/09/27 4.40UT FUJI -KISO




T20240927134319




FUJI




3C298 2024/09/27 4.75UT TOYOKAWA-FUJI





T20240927134319




BLK:28,SNR1: 1.2546 ,SNR2: 4.1254




K20240927134316




BLK:28,SNR1: 0.57763 ,SNR2: 2.5265




3C298 2024/09/27 4.75UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927134316




No.Good Data






Frequency (Hz)




3C298 2024/09/27 4.75UT FUJI -KISO




T20240927135502



FUJI





1428-03 2024/09/27 4.95UT TOYOKAWA-FUJI







T20240927135502




BLK: 7,SNR1: 1.1518 ,SNR2: 3.6686




K20240927135459





BLK: 7,SNR1: 36.724 ,SNR2: 52.490




1428-03 2024/09/27 4.95UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927135459




No.Good Data





Frequency (Hz)


1428-03 2024/09/27 4.95UT FUJI -KISO





T20240927140105




No.Good Data




FUJI




No.Good Data




1434+03 2024/09/27 5.05UT TOYOKAWA-FUJI




T20240927140105




BLK:11,SNR1: 1.0732 ,SNR2: 5.2152




K20240927140102





BLK:11,SNR1: 6.6890 ,SNR2: 15.350




1434+03 2024/09/27 5.05UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927140102




No.Good Data





Frequency (Hz)


1434+03 2024/09/27 5.05UT FUJI -KISO



T20240927142007





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/09/27 5.36UT TOYOKAWA-FUJI





T20240927142007




BLK: 8,SNR1: 32.900 ,SNR2: 48.423




K20240927142004





BLK: 8,SNR1: 1.3798 ,SNR2: 6.5450




1453-10 2024/09/27 5.36UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927142004




No.Good Data






Frequency (Hz)

1453-10 2024/09/27 5.36UT FUJI -KISO









T20240927143459





FUJI




1508-05 2024/09/27 5.61UT TOYOKAWA-FUJI





T20240927143459




BLK: 7,SNR1: 61.148 ,SNR2: 87.504




K20240927143456





BLK: 7,SNR1: 0.28739 ,SNR2: 1.3820




1508-05 2024/09/27 5.61UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927143456




No.Good Data






Frequency (Hz)




1508-05 2024/09/27 5.61UT FUJI -KISO




T20240927144359





FUJI




3C318 2024/09/27 5.76UT TOYOKAWA-FUJI





T20240927144359




BLK:13,SNR1: 0.11852 ,SNR2: 2.6465




K20240927144356





BLK:13,SNR1: 0.66468 ,SNR2: 3.0900




3C318 2024/09/27 5.76UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927144356




No.Good Data






Frequency (Hz)




3C318 2024/09/27 5.76UT FUJI -KISO




T20240927144946




FUJI




1523+03 2024/09/27 5.86UT TOYOKAWA-FUJI



T20240927144946





BLK:10,SNR1: 0.30106 ,SNR2: 4.2637




Frequency (Hz)

K20240927144943




BLK:10,SNR1: 2.5022 ,SNR2: 12.190





Frequency (Hz)

1523+03 2024/09/27 5.86UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240927144943




No.Good Data




Frequency (Hz)


1523+03 2024/09/27 5.86UT FUJI -KISO



T20240927150126





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1535+139 2024/09/27 6.05UT TOYOKAWA-FUJI



T20240927150126





BLK: 5,SNR1: 0.95025E-01,SNR2: 0.94529




Frequency (Hz)

K20240927150123




BLK: 5,SNR1: 1.0558 ,SNR2: 3.4803





Frequency (Hz)


1535+139 2024/09/27 6.05UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927150123




No.Good Data






Frequency (Hz)




1535+139 2024/09/27 6.05UT FUJI -KISO




T20240927151150




FUJI





1545-12 2024/09/27 6.23UT TOYOKAWA-FUJI







BLK: 7,SNR1: 2.8444 ,SNR2: 10.158






BLK: 7,SNR1: 0.39303 ,SNR2: 1.6568






1545-12 2024/09/27 6.23UT TOYOKAWA-KISO




FUJI






K20240927151147






1545-12 2024/09/27 6.23UT FUJI -KISO




T20240927153253



FUJI





1607+26 2024/09/27 6.58UT TOYOKAWA-FUJI








T20240927153253




BLK: 6,SNR1: 0.33157E-01,SNR2: 0.89804




K20240927153250





BLK: 6,SNR1: 0.81969 ,SNR2: 2.9087




1607+26 2024/09/27 6.58UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927153250




No.Good Data






Frequency (Hz)




1607+26 2024/09/27 6.58UT FUJI -KISO




T20240927155023





FUJI




1623-228 2024/09/27 6.87UT TOYOKAWA-FUJI



T20240927155023





BLK: 8,SNR1: 1.3299 ,SNR2: 9.7246




Frequency (Hz)

K20240927155021




BLK: 8,SNR1: 2.6128 ,SNR2: 8.6357





Frequency (Hz)


1623-228 2024/09/27 6.87UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927155021




No.Good Data






Frequency (Hz)




1623-228 2024/09/27 6.87UT FUJI -KISO




T20240927155853





FUJI




1631-222 2024/09/27 7.01UT TOYOKAWA-FUJI



T20240927155853




BLK: 4,SNR1: 0.19580 ,SNR2: 3.3904




Frequency (Hz)

K20240927155850




BLK: 4,SNR1: 3.6128 ,SNR2: 10.529





Frequency (Hz)


1631-222 2024/09/27 7.01UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927155850




No.Good Data






Frequency (Hz)

1631-222 2024/09/27 7.01UT FUJI -KISO









T20240927160430




FUJI




1638-025 2024/09/27 7.10UT TOYOKAWA-FUJI



T20240927160430





BLK: 5,SNR1: 1.9450 ,SNR2: 16.983




Frequency (Hz)

K20240927160427




BLK: 5,SNR1: 0.26169 ,SNR2: 2.3195





Frequency (Hz)


1638-025 2024/09/27 7.10UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927160427




No.Good Data





Frequency (Hz)


1638-025 2024/09/27 7.10UT FUJI -KISO



T20240927161125





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1644-106 2024/09/27 7.22UT TOYOKAWA-FUJI



T20240927161125




BLK: 8,SNR1: 0.53236 ,SNR2: 3.9369




Frequency (Hz)

K20240927161122




BLK: 8,SNR1: 4.3251 ,SNR2: 9.4830





Frequency (Hz)


1644-106 2024/09/27 7.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927161122




No.Good Data





Frequency (Hz)


1644-106 2024/09/27 7.22UT FUJI -KISO



T20240927161645





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1650+004 2024/09/27 7.31UT TOYOKAWA-FUJI



T20240927161645





BLK: 8,SNR1: 0.91914E-01,SNR2: 0.51245




Frequency (Hz)

K20240927161642




BLK: 8,SNR1: 2.3265 ,SNR2: 6.8373





Frequency (Hz)

1650+004 2024/09/27 7.31UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20240927161642




No.Good Data




Frequency (Hz)


1650+004 2024/09/27 7.31UT FUJI -KISO



T20240927162217





No.Good Data




Frequency (Hz)

FUJI






No.Good Data




Frequency (Hz)

1656+053 2024/09/27 7.40UT TOYOKAWA-FUJI








1656+053 2024/09/27 7.40UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927162215




No.Good Data





Frequency (Hz)


1656+053 2024/09/27 7.40UT FUJI -KISO



T20240927163847





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1712-033 2024/09/27 7.67UT TOYOKAWA-FUJI



T20240927163847





BLK: 2,SNR1: 0.14101 ,SNR2: 0.33241




Frequency (Hz)

K20240927163844




BLK: 2,SNR1: 0.77173 ,SNR2: 5.2799





Frequency (Hz)


1712-033 2024/09/27 7.67UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927163844




No.Good Data





Frequency (Hz)


1712-033 2024/09/27 7.67UT FUJI -KISO



T20240927165649





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1730-13 2024/09/27 7.98UT TOYOKAWA-FUJI






T20240927165649





No.Good Data




Frequency (Hz)

K20240927165646




No.Good Data





Frequency (Hz)


1730-13 2024/09/27 7.98UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20240927165646



No.Good Data



Frequency (Hz)

1730-13 2024/09/27 7.98UT FUJI -KISO

