




TOYOKAWA 0645-056 2024/10/01(275)05:57:56-06:01:22JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0652-130 2024/10/01(275)06:04:23-06:07:49JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0656-242 2024/10/01(275)06:08:22-06:11:48JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0703+138 2024/10/01(275)06:15:59-06:19:25JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0707+063 2024/10/01(275)06:19:45-06:23:11JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0713-024 2024/10/01(275)06:25:22-06:28:48JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0716+022 2024/10/01(275)06:29:02-06:32:28JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0723+10 2024/10/01(275)06:35:34-06:39:00JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0732+33 2024/10/01(275)06:45:48-06:49:14JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0741-06 2024/10/01(275)06:53:50-06:57:16JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0752-200 2024/10/01(275)07:03:35-07:07:01JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C190 2024/10/01(275)07:11:09-07:14:35JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0806-103 2024/10/01(275)07:18:15-07:21:41JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C196

2024/10/01(275)07:23:34-07:27:00JST 208Rs


9571+/- 207




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0817+183 2024/10/01(275)07:30:18-07:33:44JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0821+394 2024/10/01(275)07:34:44-07:38:10JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 0834-19 2024/10/01(275)07:46:24-07:49:50JST 184Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0839-071 2024/10/01(275)07:51:29-07:54:55JST 179Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C208 2024/10/01(275)08:02:30-08:05:56JST 178Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0857-191 2024/10/01(275)08:08:50-08:12:16JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C216

2024/10/01(275)08:19:11-08:22:37JST 193Rs


8387+/- 42




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0912-132 2024/10/01(275)08:23:56-08:27:22JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0919-142 2024/10/01(275)08:31:23-08:34:49JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0926+117 2024/10/01(275)08:38:02-08:41:28JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C222 2024/10/01(275)08:45:47-08:49:13JST 148Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0941-08 2024/10/01(275)08:52:47-08:56:13JST 142Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C230

2024/10/01(275)09:01:08-09:04:34JST 136Rs


8254+/- 258




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C237 2024/10/01(275)09:17:09-09:20:35JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1011+110 2024/10/01(275)09:23:25-09:26:51JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C241 2024/10/01(275)09:31:06-09:34:32JST 138Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1031-11 2024/10/01(275)09:42:36-09:46:02JST 107Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1035-058 2024/10/01(275)09:47:09-09:50:35JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1044-008 2024/10/01(275)09:56:22-09:59:48JST 92Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1055+01 2024/10/01(275)10:07:26-10:10:52JST 84Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1059-010 2024/10/01(275)10:11:02-10:14:28JST 80Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1107+109 2024/10/01(275)10:18:44-10:22:10JST 88Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C255 2024/10/01(275)10:28:21-10:31:47JST 64Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1127-14 2024/10/01(275)10:38:59-10:42:25JST 69Rs

8058+/- 86




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1136-13 2024/10/01(275)10:48:03-10:51:29JST 60Rs


8381+/- 3419




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C263.1 2024/10/01(275)10:52:19-10:55:45JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )






TOYOKAWA 3C267 2024/10/01(275)10:58:46-11:02:12JST 69Rs


6822+/- 5330




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1154+552 2024/10/01(275)11:06:11-11:09:37JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1206+439 2024/10/01(275)11:18:00-11:21:26JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1213-17 2024/10/01(275)11:24:34-11:28:00JST 54Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C273 2024/10/01(275)11:37:51-11:41:17JST 19Rs


12470+/- 354




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C275 2024/10/01(275)11:51:02-11:54:28JST 13Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1245-19 2024/10/01(275)11:57:07-12:00:33JST 64Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 3C279 2024/10/01(275)12:04:51-12:08:17JST 26Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 3C283 2024/10/01(275)12:20:20-12:23:46JST 79Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2024/10/01(275)12:24:38-12:28:04JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1323+32 2024/10/01(275)12:34:45-12:38:11JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C286 2024/10/01(275)12:39:35-12:43:01JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2024/10/01(275)12:46:12-12:49:38JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1345+12 2024/10/01(275)12:56:02-12:59:28JST 90Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1355+01 2024/10/01(275)13:06:22-13:09:48JST 81Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C298 2024/10/01(275)13:27:33-13:30:59JST 104Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1428-03 2024/10/01(275)13:39:16-13:42:42JST 108Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1434+03 2024/10/01(275)13:45:19-13:48:45JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2024/10/01(275)14:04:21-14:07:47JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1508-05 2024/10/01(275)14:19:13-14:22:39JST 138Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C318 2024/10/01(275)14:28:13-14:31:39JST 159Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2024/10/01(275)14:34:00-14:37:26JST 150Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1535+139 2024/10/01(275)14:45:40-14:49:06JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1545-12 2024/10/01(275)14:56:04-14:59:30JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1607+26 2024/10/01(275)15:17:07-15:20:33JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1623-228 2024/10/01(275)15:34:37-15:38:03JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1631-222 2024/10/01(275)15:43:08-15:46:34JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1638-025 2024/10/01(275)15:48:45-15:52:11JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2024/10/01(275)15:55:39-15:59:05JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1650+004 2024/10/01(275)16:01:00-16:04:26JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1656+053 2024/10/01(275)16:06:32-16:09:58JST 198Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1712-033 2024/10/01(275)16:23:02-16:26:28JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1730-13 2024/10/01(275)16:41:04-16:44:30JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1748+031 2024/10/01(275)16:58:28-17:01:54JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1759+13 2024/10/01(275)17:09:22-17:12:48JST 213Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1808-209 2024/10/01(275)17:19:08-17:22:34JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )

