




T20241002061552




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0707+063 2024/10/01 21.29UT TOYOKAWA-FUJI



T20241002061552





BLK: 3,SNR1:-0.37436E-01,SNR2: 0.82796




Frequency (Hz)

K20241002061549




BLK: 3,SNR1: 2.5331 ,SNR2: 8.3385



Frequency (Hz)

0707+063 2024/10/01 21.29UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241002061549



No.Good Data




Frequency (Hz)


0707+063 2024/10/01 21.29UT FUJI -KISO



T20241002062128




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

0713-024 2024/10/01 21.39UT TOYOKAWA-FUJI






T20241002062128





No. Good Data




Frequency (Hz)

K20241002062125




No. Good Data





Frequency (Hz)


0713-024 2024/10/01 21.39UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241002062125




No.Good Data



Frequency (Hz)

0713-024 2024/10/01 21.39UT FUJI -KISO



T20241002063140





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0723+10 2024/10/01 21.56UT TOYOKAWA-FUJI



T20241002063140




BLK: 4,SNR1: 0.15516E-01,SNR2: 1.6959




Frequency (Hz)

K20241002063137




BLK: 4,SNR1: 7.4275 ,SNR2: 11.116





Frequency (Hz)


0723+10 2024/10/01 21.56UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241002063137




No.Good Data





Frequency (Hz)


0723+10 2024/10/01 21.56UT FUJI -KISO





T20241002064154




No.Good Data




FUJI





No.Good Data




0732+33 2024/10/01 21.73UT TOYOKAWA-FUJI




T20241002064154




BLK: 7,SNR1: 0.25080 ,SNR2: 0.43778




K20241002064151




BLK: 7,SNR1: 26.750 ,SNR2: 35.255



0732+33 2024/10/01 21.73UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241002064151




No.Good Data




Frequency (Hz)

0732+33 2024/10/01 21.73UT FUJI -KISO






T20241002064956





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0741-06 2024/10/01 21.86UT TOYOKAWA-FUJI




T20241002064956




BLK: 7,SNR1:-0.16726E-01,SNR2: 0.43467




K20241002064953




BLK: 7,SNR1: 4.4828 ,SNR2: 13.603




0741-06 2024/10/01 21.86UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002064953




No.Good Data




Frequency (Hz)


0741-06 2024/10/01 21.86UT FUJI -KISO





T20241002065941




No.Good Data




FUJI





No.Good Data




0752-200 2024/10/01 22.02UT TOYOKAWA-FUJI



T20241002065941





BLK: 4,SNR1: 0.89880E-01,SNR2: 0.60235




Frequency (Hz)

K20241002065938




BLK: 4,SNR1: 0.29889 ,SNR2: 1.2245




Frequency (Hz)


0752-200 2024/10/01 22.02UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241002065938




No.Good Data





Frequency (Hz)


0752-200 2024/10/01 22.02UT FUJI -KISO




T20241002070716




No.Good Data




FUJI




No.Good Data




3C190 2024/10/01 22.15UT TOYOKAWA-FUJI




T20241002070716




BLK:13,SNR1: 0.26278 ,SNR2: 1.4152




K20241002070713



BLK:13,SNR1: 3.5948 ,SNR2: 10.150




3C190 2024/10/01 22.15UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241002070713




No.Good Data





Frequency (Hz)


3C190 2024/10/01 22.15UT FUJI -KISO





T20241002071940




No.Good Data




FUJI





No.Good Data




3C196 2024/10/01 22.36UT TOYOKAWA-FUJI



T20241002071940





BLK:13,SNR1: 0.13092 ,SNR2: 0.38300




Frequency (Hz)

K20241002071937




BLK:13,SNR1: 13.828 ,SNR2: 35.235






Frequency (Hz)




3C196 2024/10/01 22.36UT TOYOKAWA-KISO




FUJI





K20241002071937




3C196 2024/10/01 22.36UT FUJI -KISO




T20241002073050




No.Good Data




FUJI





No.Good Data




0821+394 2024/10/01 22.54UT TOYOKAWA-FUJI



T20241002073050




BLK:18,SNR1: 0.66235 ,SNR2: 3.5045




Frequency (Hz)

0821+394 2024/10/01 22.54UT TOYOKAWA-KISO


K20241002073047





BLK:18,SNR1: 9.5435 ,SNR2: 16.336




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241002073047




No.Good Data





Frequency (Hz)


0821+394 2024/10/01 22.54UT FUJI -KISO



T20241002074230





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

0834-19 2024/10/01 22.74UT TOYOKAWA-FUJI






T20241002074230




BLK: 4,SNR1: 4.1569 ,SNR2: 11.665





0834-19 2024/10/01 22.74UT TOYOKAWA-KISO



K20241002074227




BLK: 4,SNR1: 1.6933 ,SNR2: 5.5965



FUJI





No.Good Data




Frequency (Hz)

K20241002074227




No.Good Data





Frequency (Hz)


0834-19 2024/10/01 22.74UT FUJI -KISO



T20241002074735





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0839-071 2024/10/01 22.82UT TOYOKAWA-FUJI



T20241002074735




BLK: 7,SNR1: 13.475 ,SNR2: 50.759




Frequency (Hz)

K20241002074732




BLK: 7,SNR1: 1.5812 ,SNR2: 5.6821




Frequency (Hz)


0839-071 2024/10/01 22.82UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002074732




No.Good Data





Frequency (Hz)


0839-071 2024/10/01 22.82UT FUJI -KISO





T20241002075836




No.Good Data




FUJI





No.Good Data




3C208 2024/10/01 23.00UT TOYOKAWA-FUJI




T20241002075836




BLK: 4,SNR1:-0.53836E-01,SNR2: 0.40177




K20241002075833





BLK: 4,SNR1: 0.30990 ,SNR2: 1.3328




3C208 2024/10/01 23.00UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002075833




No.Good Data





Frequency (Hz)

3C208 2024/10/01 23.00UT FUJI -KISO







T20241002081518




No.Good Data




FUJI





No.Good Data




3C216 2024/10/01 23.28UT TOYOKAWA-FUJI





T20241002081518




BLK: 3,SNR1: 0.19664 ,SNR2: 0.65426




K20241002081515



BLK: 3,SNR1: 4.4727 ,SNR2: 10.756




3C216 2024/10/01 23.28UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241002081515




No. Good Data





Frequency (Hz)


3C216 2024/10/01 23.28UT FUJI -KISO




T20241002082729




No.Good Data




FUJI




No.Good Data




0919-142 2024/10/01 23.49UT TOYOKAWA-FUJI




T20241002082729




BLK: 8,SNR1: 0.36562E-01,SNR2: 1.2452




K20241002082727




BLK: 8,SNR1:-0.31376 ,SNR2: 1.4201



0919-142 2024/10/01 23.49UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002082727




No.Good Data



Frequency (Hz)

0919-142 2024/10/01 23.49UT FUJI -KISO



T20241002083408



No.Good Data




FUJI





No.Good Data




0926+117 2024/10/01 23.60UT TOYOKAWA-FUJI



T20241002083408





BLK: 4,SNR1: 15.855 ,SNR2: 26.333




Frequency (Hz)

0926+117 2024/10/01 23.60UT TOYOKAWA-KISO


K20241002083406



BLK: 4,SNR1: 22.212 ,SNR2: 36.574





Frequency (Hz)








FUJI




No.Good Data




K20241002083406




No.Good Data



0926+117 2024/10/01 23.60UT FUJI -KISO




T20241002084153




No.Good Data



FUJI





No.Good Data




3C222 2024/10/01 23.73UT TOYOKAWA-FUJI





T20241002084153




BLK:14,SNR1: 0.60692 ,SNR2: 1.9392




K20241002084151



BLK:14,SNR1: 2.2445 ,SNR2: 6.4587



3C222 2024/10/01 23.73UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241002084151



No.Good Data




Frequency (Hz)


3C222 2024/10/01 23.73UT FUJI -KISO




T20241002084853




No.Good Data



FUJI





No.Good Data




0941-08 2024/10/01 23.84UT TOYOKAWA-FUJI



T20241002084853





BLK: 3,SNR1: 5.8602 ,SNR2: 15.121





0941-08 2024/10/01 23.84UT TOYOKAWA-KISO

K20241002084850




BLK: 3,SNR1: 6.7893 ,SNR2: 15.446



FUJI



No. Good Data




Frequency (Hz)

K20241002084850



No. Good Data



Frequency (Hz)

0941-08 2024/10/01 23.84UT FUJI -KISO




T20241002091315



No.Good Data




FUJI



No.Good Data





3C237 2024/10/02 0.25UT TOYOKAWA-FUJI






T20241002091315





BLK:16,SNR1: 2.4488 ,SNR2: 6.2170




Frequency (Hz)

3C237 2024/10/02 0.25UT TOYOKAWA-KISO


K20241002091313



BLK:16,SNR1: 8.1078 ,SNR2: 20.484




Frequency (Hz)



FUJI



No.Good Data




Frequency (Hz)

K20241002091313




No.Good Data



Frequency (Hz)

3C237 2024/10/02 0.25UT FUJI -KISO



T20241002091931




No.Good Data




FUJI





No.Good Data




1011+110 2024/10/02 0.35UT TOYOKAWA-FUJI



T20241002091931





BLK: 3,SNR1: 0.24197 ,SNR2: 0.62332





1011+110 2024/10/02 0.35UT TOYOKAWA-KISO



K20241002091929




BLK: 3,SNR1: 2.1994 ,SNR2: 9.3732



FUJI



No. Good Data




Frequency (Hz)

K20241002091929




No. Good Data



Frequency (Hz)

1011+110 2024/10/02 0.35UT FUJI -KISO




T20241002092712



No.Good Data



FUJI





No.Good Data




3C241 2024/10/02 0.48UT TOYOKAWA-FUJI



T20241002092712




BLK: 1,SNR1: 2.5776 ,SNR2: 11.755





3C241 2024/10/02 0.48UT TOYOKAWA-KISO



K20241002092710




BLK: 1,SNR1: 3.3634 ,SNR2: 14.489



FUJI



No. Good Data



Frequency (Hz)

K20241002092710




No. Good Data



Frequency (Hz)

3C241 2024/10/02 0.48UT FUJI -KISO





T20241002093842





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


1031-11 2024/10/02 0.67UT TOYOKAWA-FUJI



T20241002093842




BLK:11,SNR1: 5.0780 ,SNR2: 12.439




Frequency (Hz)

1031-11 2024/10/02 0.67UT TOYOKAWA-KISO


K20241002093840




BLK:11,SNR1: 4.5418 ,SNR2: 11.588




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241002093840




No.Good Data



Frequency (Hz)

1031-11 2024/10/02 0.67UT FUJI -KISO




T20241002094315



No. Good Data



FUJI





No. Good Data




1035-058 2024/10/02 0.75UT TOYOKAWA-FUJI



T20241002094315





BLK: 3,SNR1: 1.8427 ,SNR2: 29.324





1035-058 2024/10/02 0.75UT TOYOKAWA-KISO

K20241002094313



BLK: 3,SNR1: 2.1522 ,SNR2: 8.2227



FUJI



No. Good Data



Frequency (Hz)

K20241002094313



No. Good Data



Frequency (Hz)

1035-058 2024/10/02 0.75UT FUJI -KISO





T20241002095228




No. Good Data




FUJI





No. Good Data




1044-008 2024/10/02 0.90UT TOYOKAWA-FUJI



T20241002095228





BLK: 3, SNR1: 4.8874 , SNR2: 23.245





1044-008 2024/10/02 0.90UT TOYOKAWA-KISO

K20241002095226



BLK: 3, SNR1: 11.993 , SNR2: 26.539





FUJI



No. Good Data



Frequency (Hz)

K20241002095226




No. Good Data





Frequency (Hz)


1044-008 2024/10/02 0.90UT FUJI -KISO



T20241002100332





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1055+01 2024/10/02 1.09UT TOYOKAWA-FUJI



T20241002100332





No. Good Data




Frequency (Hz)

K20241002100330




No. Good Data





Frequency (Hz)

1055+01 2024/10/02 1.09UT TOYOKAWA-KISO



FUJI





No.Good Data



Frequency (Hz)

K20241002100330




No.Good Data



Frequency (Hz)

1055+01 2024/10/02 1.09UT FUJI -KISO



T20241002101450





No.Good Data




Frequency (Hz)

FUJI




No.Good Data



Frequency (Hz)

1107+109 2024/10/02 1.28UT TOYOKAWA-FUJI





FUJI



No. Good Data



Frequency (Hz)

K20241002101448




No. Good Data





Frequency (Hz)


1107+109 2024/10/02 1.28UT FUJI -KISO



T20241002102427





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C255 2024/10/02 1.44UT TOYOKAWA-FUJI






T20241002102427





BLK:11,SNR1: 7.7078 ,SNR2: 22.629




Frequency (Hz)

3C255 2024/10/02 1.44UT TOYOKAWA-KISO


K20241002102425





BLK:11,SNR1: 6.5234 ,SNR2: 15.867




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241002102425




No. Good Data



Frequency (Hz)

3C255 2024/10/02 1.44UT FUJI -KISO



T20241002103505





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1127-14 2024/10/02 1.61UT TOYOKAWA-FUJI





T20241002103505




BLK: 7, SNR1: 4.0327 ,SNR2: 10.983




K20241002103503





BLK: 7, SNR1: 8.4654 ,SNR2: 21.329




1127-14 2024/10/02 1.61UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002103503




No.Good Data



Frequency (Hz)

1127-14 2024/10/02 1.61UT FUJI -KISO



T20241002104825



No.Good Data



Frequency (Hz)

FUJI



No.Good Data




Frequency (Hz)


3C263.1 2024/10/02 1.84UT TOYOKAWA-FUJI




T20241002104825




BLK: 7,SNR1: 0.57322 ,SNR2: 2.4344




K20241002104822



BLK: 7,SNR1: 3.4896 ,SNR2: 7.7126




3C263.1 2024/10/02 1.84UT TOYOKAWA-KISO



FUJI



No. Good Data




Frequency (Hz)

K20241002104822



No. Good Data



Frequency (Hz)

3C263.1 2024/10/02 1.84UT FUJI -KISO





T20241002105452



No.Good Data



Frequency (Hz)

FUJI



No.Good Data





Frequency (Hz)


3C267 2024/10/02 1.94UT TOYOKAWA-FUJI



T20241002105452





BLK: 9,SNR1: 8.0090 ,SNR2: 20.558




Frequency (Hz)

3C267 2024/10/02 1.94UT TOYOKAWA-KISO


K20241002105449




BLK: 9,SNR1: 10.063 ,SNR2: 25.270




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241002105449




No.Good Data





Frequency (Hz)

3C267 2024/10/02 1.94UT FUJI -KISO



T20241002112040





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1213-17 2024/10/02 2.37UT TOYOKAWA-FUJI



T20241002112040





BLK:12,SNR1: 1.3960 ,SNR2: 2.8349





1213-17 2024/10/02 2.37UT TOYOKAWA-KISO

K20241002112038



BLK:12,SNR1: 1.7481 ,SNR2: 4.1875



FUJI



No. Good Data



Frequency (Hz)

K20241002112038



No. Good Data





Frequency (Hz)


1213-17 2024/10/02 2.37UT FUJI -KISO





T20241002113357




No.Good Data




FUJI





No.Good Data




3C273 2024/10/02 2.59UT TOYOKAWA-FUJI



T20241002113357





BLK:12,SNR1: 2.2713 ,SNR2: 6.1027





3C273 2024/10/02 2.59UT TOYOKAWA-KISO

K20241002113355





BLK:12,SNR1: 2.2312 ,SNR2: 5.2414






FUJI





No. Good Data




Frequency (Hz)

K20241002113355




No. Good Data




Frequency (Hz)

3C273 2024/10/02 2.59UT FUJI -KISO



T20241002115313




No.Good Data



Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1245-19 2024/10/02 2.92UT TOYOKAWA-FUJI



T20241002115313




BLK:24,SNR1: 6.1487 ,SNR2: 19.102





1245-19 2024/10/02 2.92UT TOYOKAWA-KISO


K20241002115310



BLK:24,SNR1: 7.9596 ,SNR2: 13.199



FUJI





No.Good Data




Frequency (Hz)

K20241002115310




No.Good Data



Frequency (Hz)

1245-19 2024/10/02 2.92UT FUJI -KISO



T20241002120057





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C279 2024/10/02 3.04UT TOYOKAWA-FUJI




T20241002120057




BLK: 7,SNR1: 1.3273 ,SNR2: 2.3997




K20241002120054




BLK: 7,SNR1: 1.0542 ,SNR2: 4.2223



3C279 2024/10/02 3.04UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002120054




No.Good Data



Frequency (Hz)


3C279 2024/10/02 3.04UT FUJI -KISO



T20241002121626



No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C283 2024/10/02 3.30UT TOYOKAWA-FUJI






T20241002121626




BLK:31,SNR1: 1.1025 ,SNR2: 7.9623





3C283 2024/10/02 3.30UT TOYOKAWA-KISO


K20241002121624



BLK:31,SNR1: 4.4503 ,SNR2: 9.9098



FUJI





No.Good Data




Frequency (Hz)

K20241002121624




No.Good Data



Frequency (Hz)


3C283 2024/10/02 3.30UT FUJI -KISO



T20241002123051



No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1323+32 2024/10/02 3.54UT TOYOKAWA-FUJI





T20241002123051




BLK:16,SNR1: 0.14747 ,SNR2: 1.1563




K20241002123048





BLK:16,SNR1: 7.1909 ,SNR2: 16.270



1323+32 2024/10/02 3.54UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002123048



No.Good Data




Frequency (Hz)


1323+32 2024/10/02 3.54UT FUJI -KISO



T20241002123541





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C286 2024/10/02 3.62UT TOYOKAWA-FUJI





T20241002123541




BLK:28,SNR1: 1.8576 ,SNR2: 16.029




K20241002123538





BLK:28,SNR1: 0.66029 ,SNR2: 3.2241




3C286 2024/10/02 3.62UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002123538




No.Good Data





Frequency (Hz)

3C286 2024/10/02 3.62UT FUJI -KISO






T20241002125208





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1345+12 2024/10/02 3.90UT TOYOKAWA-FUJI





T20241002125208




BLK:29,SNR1: 2.2821 ,SNR2: 8.5528




K20241002125205





BLK:29,SNR1: 0.65714 ,SNR2: 2.7242




1345+12 2024/10/02 3.90UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002125205




No.Good Data





Frequency (Hz)


1345+12 2024/10/02 3.90UT FUJI -KISO



T20241002130229





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


1355+01 2024/10/02 4.07UT TOYOKAWA-FUJI





T20241002130229




BLK:23,SNR1: 1.8238 ,SNR2: 6.6925




K20241002130226






BLK:23,SNR1: 0.58455 ,SNR2: 3.2879






1355+01 2024/10/02 4.07UT TOYOKAWA-KISO




FUJI





K20241002130226




1355+01 2024/10/02 4.07UT FUJI -KISO



T20241002132339





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C298 2024/10/02 4.42UT TOYOKAWA-FUJI





T20241002132339




BLK:34,SNR1: 4.1351 ,SNR2: 18.255




K20241002132336



BLK:34,SNR1: 0.57449 ,SNR2: 3.0018




3C298 2024/10/02 4.42UT TOYOKAWA-KISO






FUJI




No.Good Data




Frequency (Hz)

K20241002132336




No.Good Data






Frequency (Hz)




3C298 2024/10/02 4.42UT FUJI -KISO




T20241002133523





FUJI




1428-03 2024/10/02 4.62UT TOYOKAWA-FUJI





T20241002133523




BLK:10,SNR1: 0.21469 ,SNR2: 1.4281




K20241002133520





BLK:10,SNR1: 22.458 ,SNR2: 27.314




1428-03 2024/10/02 4.62UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002133520




No.Good Data






Frequency (Hz)




1428-03 2024/10/02 4.62UT FUJI -KISO




T20241002134125




FUJI




1434+03 2024/10/02 4.72UT TOYOKAWA-FUJI




T20241002134125




BLK:13,SNR1: 5.3344 ,SNR2: 9.1799




K20241002134122





BLK:13,SNR1: 1.9297 ,SNR2: 4.4325




1434+03 2024/10/02 4.72UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002134122




No.Good Data






Frequency (Hz)




1434+03 2024/10/02 4.72UT FUJI -KISO




T20241002140027



FUJI





1453-10 2024/10/02 5.04UT TOYOKAWA-FUJI








T20241002140027




BLK:12,SNR1: 0.46064 ,SNR2: 2.6064




K20241002140024





BLK:12,SNR1: 0.88201E-03,SNR2: 0.22390E-01




1453-10 2024/10/02 5.04UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002140024




No.Good Data




Frequency (Hz)

1453-10 2024/10/02 5.04UT FUJI -KISO





T20241002141520




No.Good Data




FUJI





No.Good Data




1508-05 2024/10/02 5.28UT TOYOKAWA-FUJI





T20241002141520




BLK:14,SNR1:-0.72073E-02,SNR2: 0.33359E-01




K20241002141517





BLK:14,SNR1: 0.89954E-04,SNR2: 0.38288E-01




1508-05 2024/10/02 5.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002141517




No.Good Data





Frequency (Hz)


1508-05 2024/10/02 5.28UT FUJI -KISO



T20241002142420




No.Good Data




Frequency (Hz)

FUJI





No.Good Data





Frequency (Hz)

3C318 2024/10/02 5.43UT TOYOKAWA-FUJI







BLK: 7,SNR1:-0.60506E-02,SNR2: 0.22989E-01





BLK: 7,SNR1: 0.66235 ,SNR2: 4.5190




3C318 2024/10/02 5.43UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002142417




No.Good Data





Frequency (Hz)

3C318 2024/10/02 5.43UT FUJI -KISO






T20241002143007





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1523+03 2024/10/02 5.53UT TOYOKAWA-FUJI




T20241002143007




BLK:15,SNR1: 3.8506 ,SNR2: 23.206




K20241002143004





BLK:15,SNR1: 8.3339 ,SNR2: 28.892




1523+03 2024/10/02 5.53UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002143004




No.Good Data






Frequency (Hz)




1523+03 2024/10/02 5.53UT FUJI -KISO




T20241002144146





FUJI




1535+139 2024/10/02 5.72UT TOYOKAWA-FUJI





T20241002144146




BLK: 2,SNR1: 0.74768E-01,SNR2: 0.56014




K20241002144143






BLK: 2,SNR1: 0.82510 ,SNR2: 8.2284






1535+139 2024/10/02 5.72UT TOYOKAWA-KISO




FUJI






K20241002144143






1535+139 2024/10/02 5.72UT FUJI -KISO




T20241002145210





FUJI




1545-12 2024/10/02 5.90UT TOYOKAWA-FUJI



T20241002145210





BLK: 3,SNR1: 0.34799 ,SNR2: 3.1501




Frequency (Hz)

K20241002145207




BLK: 3,SNR1: 0.41194E-02,SNR2: 0.76770






Frequency (Hz)

1545-12 2024/10/02 5.90UT TOYOKAWA-KISO








FUJI




K20241002145207




1545-12 2024/10/02 5.90UT FUJI -KISO



T20241002151313





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1607+26 2024/10/02 6.25UT TOYOKAWA-FUJI





T20241002151313




BLK: 2,SNR1:-0.57239E-01,SNR2: 0.30393




K20241002151310






BLK: 2,SNR1:-0.47707E-01,SNR2: 1.3931






1607+26 2024/10/02 6.25UT TOYOKAWA-KISO




FUJI





K20241002151310




1607+26 2024/10/02 6.25UT FUJI -KISO



T20241002153044





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1623-228 2024/10/02 6.54UT TOYOKAWA-FUJI





T20241002153044




BLK: 7,SNR1: 0.90617 ,SNR2: 6.0449




K20241002153041






BLK: 7,SNR1: 14.788 ,SNR2: 47.257



1623-228 2024/10/02 6.54UT TOYOKAWA-KISO






FUJI




No.Good Data

K20241002153041






No.Good Data




1623-228 2024/10/02 6.54UT FUJI -KISO




T20241002153914



FUJI





1631-222 2024/10/02 6.68UT TOYOKAWA-FUJI






T20241002153914





BLK: 4,SNR1: 0.89557 ,SNR2: 6.8262




Frequency (Hz)

K20241002153911




BLK: 4,SNR1: 96.647 ,SNR2: 200.32




Frequency (Hz)


1631-222 2024/10/02 6.68UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002153911




No.Good Data






Frequency (Hz)




1631-222 2024/10/02 6.68UT FUJI -KISO




T20241002154451




FUJI




1638-025 2024/10/02 6.78UT TOYOKAWA-FUJI



T20241002154451




BLK: 1,SNR1: 20.096 ,SNR2: 40.593




Frequency (Hz)

K20241002154448




BLK: 1,SNR1: 3.6726 ,SNR2: 16.615






Frequency (Hz)




1638-025 2024/10/02 6.78UT TOYOKAWA-KISO




FUJI






K20241002154448






1638-025 2024/10/02 6.78UT FUJI -KISO




T20241002155145





FUJI




1644-106 2024/10/02 6.89UT TOYOKAWA-FUJI



T20241002155145





BLK: 1,SNR1: 0.17988 ,SNR2: 1.4515




Frequency (Hz)

K20241002155142




BLK: 1,SNR1: 0.45886 ,SNR2: 1.6540





Frequency (Hz)


1644-106 2024/10/02 6.89UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241002155142




No.Good Data






Frequency (Hz)

1644-106 2024/10/02 6.89UT FUJI -KISO









T20241002155706




FUJI




1650+004 2024/10/02 6.98UT TOYOKAWA-FUJI



T20241002155706




BLK: 3,SNR1: 4.5881 ,SNR2: 16.144




Frequency (Hz)

K20241002155703




BLK: 3,SNR1: 18.384 ,SNR2: 39.429





Frequency (Hz)


1650+004 2024/10/02 6.98UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241002155703




No.Good Data





Frequency (Hz)


1650+004 2024/10/02 6.98UT FUJI -KISO



T20241002160238





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1656+053 2024/10/02 7.07UT TOYOKAWA-FUJI



T20241002160238




BLK: 7,SNR1: 0.12686 ,SNR2: 0.58068




Frequency (Hz)

K20241002160235




BLK: 7,SNR1: 0.24557 ,SNR2: 1.2553






Frequency (Hz)




1656+053 2024/10/02 7.07UT TOYOKAWA-KISO




FUJI






K20241002160235






1656+053 2024/10/02 7.07UT FUJI -KISO




T20241002161908





FUJI




1712-033 2024/10/02 7.35UT TOYOKAWA-FUJI




T20241002161908




BLK: 3,SNR1: 0.22423 ,SNR2: 1.0205




K20241002161906



BLK: 3,SNR1: 0.64122E-01,SNR2: 0.98260




1712-033 2024/10/02 7.35UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241002161906




No.Good Data





Frequency (Hz)


1712-033 2024/10/02 7.35UT FUJI -KISO



T20241002163710





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1730-13 2024/10/02 7.65UT TOYOKAWA-FUJI



T20241002163710





BLK: 6,SNR1: 12.903 ,SNR2: 29.599




Frequency (Hz)

K20241002163707




BLK: 6,SNR1: 5.1510 ,SNR2: 10.147





Frequency (Hz)


1730-13 2024/10/02 7.65UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241002163707




No.Good Data




Frequency (Hz)


1730-13 2024/10/02 7.65UT FUJI -KISO



T20241002165435





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1748+031 2024/10/02 7.94UT TOYOKAWA-FUJI



T20241002165435





BLK: 1,SNR1:-0.11831 ,SNR2: 0.38878




Frequency (Hz)

1748+031 2024/10/02 7.94UT TOYOKAWA-KISO


K20241002165433





BLK: 1,SNR1: 1.5880 ,SNR2: 3.3725




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241002165433



No.Good Data



Frequency (Hz)

1748+031 2024/10/02 7.94UT FUJI -KISO

