




T20241003061732




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0713-024 2024/10/02 21.32UT TOYOKAWA-FUJI




T20241003061732




BLK: 8,SNR1: 0.54632 ,SNR2: 1.1549




K20241003061729



BLK: 8,SNR1: 1.8427 ,SNR2: 4.3544



0713-024 2024/10/02 21.32UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241003061729



No.Good Data





Frequency (Hz)


0713-024 2024/10/02 21.32UT FUJI -KISO



T20241003062744





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

0723+10 2024/10/02 21.49UT TOYOKAWA-FUJI






T20241003062744





BLK: 3,SNR1: 0.95817 ,SNR2: 4.9134




Frequency (Hz)

K20241003062742




BLK: 3,SNR1: 0.23641E-01,SNR2: 1.0716



Frequency (Hz)

0723+10 2024/10/02 21.49UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241003062742



No.Good Data




Frequency (Hz)


0723+10 2024/10/02 21.49UT FUJI -KISO



T20241003063758





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0732+33 2024/10/02 21.66UT TOYOKAWA-FUJI



T20241003063758





BLK: 4,SNR1: 0.73610E-01,SNR2: 0.45568




Frequency (Hz)

K20241003063756




BLK: 4,SNR1: 2.3574 ,SNR2: 8.5250





Frequency (Hz)


0732+33 2024/10/02 21.66UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241003063756




No.Good Data




Frequency (Hz)


0732+33 2024/10/02 21.66UT FUJI -KISO



T20241003064600





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0741-06 2024/10/02 21.79UT TOYOKAWA-FUJI



T20241003064600




BLK: 8,SNR1: 0.14333 ,SNR2: 0.77978




Frequency (Hz)

K20241003064558




BLK: 8,SNR1: 16.821 ,SNR2: 22.188




Frequency (Hz)


0741-06 2024/10/02 21.79UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241003064558



No.Good Data




0741-06 2024/10/02 21.79UT FUJI -KISO







T20241003065545




No.Good Data




FUJI





No.Good Data




0752-200 2024/10/02 21.96UT TOYOKAWA-FUJI



T20241003065545





BLK: 9,SNR1: 0.10649 ,SNR2: 1.7967




Frequency (Hz)

K20241003065543




BLK: 9,SNR1:-0.30830 ,SNR2: 1.3198




Frequency (Hz)


0752-200 2024/10/02 21.96UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241003065543




No.Good Data





Frequency (Hz)


0752-200 2024/10/02 21.96UT FUJI -KISO





T20241003070320




No.Good Data




FUJI




No.Good Data




3C190 2024/10/02 22.08UT TOYOKAWA-FUJI





T20241003070320




BLK: 3,SNR1: 0.26629 ,SNR2: 1.2117




K20241003070318




BLK: 3,SNR1: 0.21533 ,SNR2: 2.9819




3C190 2024/10/02 22.08UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003070318




No.Good Data





Frequency (Hz)


3C190 2024/10/02 22.08UT FUJI -KISO




T20241003071544




No.Good Data




FUJI





No.Good Data




3C196 2024/10/02 22.29UT TOYOKAWA-FUJI




T20241003071544




BLK: 9,SNR1: 1.3708 ,SNR2: 4.0502




K20241003071542



BLK: 9,SNR1: 1.3965 ,SNR2: 7.9270




3C196 2024/10/02 22.29UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241003071542




No.Good Data





Frequency (Hz)


3C196 2024/10/02 22.29UT FUJI -KISO





T20241003072654




No.Good Data



FUJI





No.Good Data




0821+394 2024/10/02 22.48UT TOYOKAWA-FUJI



T20241003072654





BLK: 5,SNR1: 0.20824 ,SNR2: 0.60805




Frequency (Hz)

0821+394 2024/10/02 22.48UT TOYOKAWA-KISO


K20241003072652





BLK: 5,SNR1: 2.2676 ,SNR2: 9.0256




Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20241003072652




No.Good Data





Frequency (Hz)


0821+394 2024/10/02 22.48UT FUJI -KISO



T20241003073834





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0834-19 2024/10/02 22.67UT TOYOKAWA-FUJI



T20241003073834




BLK: 5,SNR1: 0.82971E-01,SNR2: 1.1683





0834-19 2024/10/02 22.67UT TOYOKAWA-KISO



K20241003073832




BLK: 5,SNR1: 1.1411 ,SNR2: 6.1366





FUJI




No.Good Data




K20241003073832





No.Good Data




0834-19 2024/10/02 22.67UT FUJI -KISO





T20241003074339




No.Good Data




FUJI



No.Good Data





0839-071 2024/10/02 22.76UT TOYOKAWA-FUJI







T20241003074339




BLK: 5,SNR1: 2.9786 ,SNR2: 14.433




K20241003074337





BLK: 5,SNR1: 2.2494 ,SNR2: 6.5673




0839-071 2024/10/02 22.76UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003074337




No.Good Data





Frequency (Hz)


0839-071 2024/10/02 22.76UT FUJI -KISO





T20241003075440




No.Good Data




FUJI




No.Good Data




3C208 2024/10/02 22.94UT TOYOKAWA-FUJI



T20241003075440




BLK: 6,SNR1: 4.9095 ,SNR2: 28.792





3C208 2024/10/02 22.94UT TOYOKAWA-KISO


K20241003075438




BLK: 6,SNR1: 3.4165 ,SNR2: 9.9107



FUJI





No.Good Data




Frequency (Hz)

K20241003075438




No.Good Data





Frequency (Hz)


3C208 2024/10/02 22.94UT FUJI -KISO





T20241003081122




No.Good Data




FUJI





No.Good Data




3C216 2024/10/02 23.22UT TOYOKAWA-FUJI



T20241003081122





BLK: 3,SNR1: 0.23278 ,SNR2: 0.68460





3C216 2024/10/02 23.22UT TOYOKAWA-KISO



K20241003081120




BLK: 3,SNR1: 3.5755 ,SNR2: 13.114



FUJI





No.Good Data




Frequency (Hz)

K20241003081120




No.Good Data





Frequency (Hz)

3C216 2024/10/02 23.22UT FUJI -KISO







T20241003082333




No.Good Data




FUJI





No.Good Data




0919-142 2024/10/02 23.42UT TOYOKAWA-FUJI



T20241003082333





BLK: 2,SNR1: 2.6872 ,SNR2: 8.5063




Frequency (Hz)

K20241003082331




BLK: 2,SNR1: 10.270 ,SNR2: 26.199





Frequency (Hz)


0919-142 2024/10/02 23.42UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241003082331




No. Good Data





Frequency (Hz)


0919-142 2024/10/02 23.42UT FUJI -KISO




T20241003083012




No.Good Data




FUJI





No.Good Data




0926+117 2024/10/02 23.53UT TOYOKAWA-FUJI



T20241003083012





BLK: 2,SNR1: 11.007 ,SNR2: 24.264




Frequency (Hz)

0926+117 2024/10/02 23.53UT TOYOKAWA-KISO


K20241003083010




BLK: 2,SNR1: 5.4610 ,SNR2: 25.723



Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20241003083010




No.Good Data




Frequency (Hz)


0926+117 2024/10/02 23.53UT FUJI -KISO




T20241003083757




No.Good Data




FUJI




No.Good Data




3C222 2024/10/02 23.66UT TOYOKAWA-FUJI




T20241003083757




BLK: 8,SNR1: 68.018 ,SNR2: 95.890




K20241003083755



BLK: 8,SNR1:-0.33730 ,SNR2: 1.3801





3C222 2024/10/02 23.66UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241003083755




No.Good Data




Frequency (Hz)


3C222 2024/10/02 23.66UT FUJI -KISO




T20241003084457




No.Good Data



FUJI





No.Good Data




0941-08 2024/10/02 23.78UT TOYOKAWA-FUJI





T20241003084457




No. Good Data




K20241003084455



No. Good Data



0941-08 2024/10/02 23.78UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241003084455



No.Good Data




Frequency (Hz)


0941-08 2024/10/02 23.78UT FUJI -KISO




T20241003085319




No.Good Data



FUJI




No.Good Data




3C230 2024/10/02 23.92UT TOYOKAWA-FUJI





T20241003085319




BLK: 3,SNR1: 3.5429 ,SNR2: 12.389




K20241003085317





BLK: 3,SNR1: 7.3657 ,SNR2: 16.695




3C230 2024/10/02 23.92UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241003085317




No.Good Data



Frequency (Hz)


3C230 2024/10/02 23.92UT FUJI -KISO





T20241003090919




No.Good Data




FUJI



No.Good Data





3C237 2024/10/03 0.18UT TOYOKAWA-FUJI






T20241003090919





BLK: 3, SNR1: 8.4731 , SNR2: 25.637





3C237 2024/10/03 0.18UT TOYOKAWA-KISO



K20241003090917




BLK: 3, SNR1: 12.423 , SNR2: 30.159



FUJI



No. Good Data




Frequency (Hz)

K20241003090917




No. Good Data



Frequency (Hz)


3C237 2024/10/03 0.18UT FUJI -KISO



T20241003091536




No.Good Data




FUJI




No.Good Data




1011+110 2024/10/03 0.29UT TOYOKAWA-FUJI



T20241003091536




BLK: 2, SNR1: 5.0633 ,SNR2: 17.180





1011+110 2024/10/03 0.29UT TOYOKAWA-KISO


K20241003091534




BLK: 2, SNR1: 10.813 ,SNR2: 18.360



FUJI



No.Good Data



Frequency (Hz)

K20241003091534




No.Good Data




Frequency (Hz)

1011+110 2024/10/03 0.29UT FUJI -KISO




T20241003092317



No.Good Data



FUJI




No.Good Data




3C241 2024/10/03 0.42UT TOYOKAWA-FUJI



T20241003092317




BLK:10,SNR1: 7.2285 ,SNR2: 18.642





3C241 2024/10/03 0.42UT TOYOKAWA-KISO

K20241003092315



BLK:10,SNR1: 9.0800 ,SNR2: 26.696



FUJI



No. Good Data



Frequency (Hz)

K20241003092315




No. Good Data



Frequency (Hz)

3C241 2024/10/03 0.42UT FUJI -KISO





T20241003093446




No. Good Data




FUJI




No. Good Data




1031-11 2024/10/03 0.61UT TOYOKAWA-FUJI



T20241003093446




BLK: 7, SNR1: 12.036 , SNR2: 29.853





1031-11 2024/10/03 0.61UT TOYOKAWA-KISO


K20241003093444




BLK: 7, SNR1: 13.956 , SNR2: 33.861



FUJI





No.Good Data




Frequency (Hz)

K20241003093444




No.Good Data



Frequency (Hz)

1031-11 2024/10/03 0.61UT FUJI -KISO




T20241003093919



No. Good Data




FUJI







No. Good Data




1035-058 2024/10/03 0.68UT TOYOKAWA-FUJI





1035-058 2024/10/03 0.68UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241003093916




No. Good Data





Frequency (Hz)


1035-058 2024/10/03 0.68UT FUJI -KISO



T20241003094832





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1044-008 2024/10/03 0.84UT TOYOKAWA-FUJI





T20241003094832




BLK: 5, SNR1: 2.1639 , SNR2: 4.2324




K20241003094829



BLK: 5, SNR1: 0.67207 , SNR2: 2.6178



1044-008 2024/10/03 0.84UT TOYOKAWA-KISO





FUJI



No.Good Data



Frequency (Hz)

K20241003094829




No.Good Data





Frequency (Hz)


1044-008 2024/10/03 0.84UT FUJI -KISO



T20241003095936





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1055+01 2024/10/03 1.02UT TOYOKAWA-FUJI



T20241003095936




BLK: 5, SNR1: 0.83722 , SNR2: 3.2058




Frequency (Hz)

1055+01 2024/10/03 1.02UT TOYOKAWA-KISO


K20241003095933



BLK: 5, SNR1: 3.3032 , SNR2: 7.6295



Frequency (Hz)



FUJI



No. Good Data



Frequency (Hz)

K20241003095933



No. Good Data



Frequency (Hz)

1055+01 2024/10/03 1.02UT FUJI -KISO



T20241003101054





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1107+109 2024/10/03 1.21UT TOYOKAWA-FUJI



T20241003101054




BLK: 4, SNR1: 2.7415 , SNR2: 9.1133





1107+109 2024/10/03 1.21UT TOYOKAWA-KISO

K20241003101052



BLK: 4, SNR1: 9.0359 , SNR2: 18.765



FUJI



No. Good Data



Frequency (Hz)

K20241003101052




No. Good Data



Frequency (Hz)

1107+109 2024/10/03 1.21UT FUJI -KISO



T20241003102031



No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C255 2024/10/03 1.37UT TOYOKAWA-FUJI






T20241003102031




BLK:11,SNR1: 0.30656 ,SNR2: 6.1768





3C255 2024/10/03 1.37UT TOYOKAWA-KISO



K20241003102029




BLK:11,SNR1: 0.15847 ,SNR2: 3.9086



FUJI





No.Good Data




Frequency (Hz)

K20241003102029




No.Good Data



Frequency (Hz)

3C255 2024/10/03 1.37UT FUJI -KISO



T20241003103109





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1127-14 2024/10/03 1.55UT TOYOKAWA-FUJI



T20241003103109




BLK:10,SNR1: 12.924 ,SNR2: 33.617




1127-14 2024/10/03 1.55UT TOYOKAWA-KISO


K20241003103107





BLK:10,SNR1: 10.637 ,SNR2: 25.707




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241003103107




No.Good Data



Frequency (Hz)


1127-14 2024/10/03 1.55UT FUJI -KISO



T20241003104429



No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C263.1 2024/10/03 1.77UT TOYOKAWA-FUJI





T20241003104429




BLK: 5, SNR1: 5.3192 , SNR2: 24.141




K20241003104427



BLK: 5, SNR1: 1.3912 , SNR2: 2.9345




3C263.1 2024/10/03 1.77UT TOYOKAWA-KISO



FUJI



No.Good Data




Frequency (Hz)

K20241003104427



No.Good Data



Frequency (Hz)

3C263.1 2024/10/03 1.77UT FUJI -KISO





T20241003105056



No.Good Data



Frequency (Hz)

FUJI



No.Good Data





Frequency (Hz)


3C267 2024/10/03 1.88UT TOYOKAWA-FUJI



T20241003105056




BLK:10,SNR1: 31.680 ,SNR2: 44.051





3C267 2024/10/03 1.88UT TOYOKAWA-KISO


K20241003105054




BLK:10,SNR1: 7.2645 ,SNR2: 18.816



FUJI





No.Good Data




Frequency (Hz)

K20241003105054




No.Good Data





Frequency (Hz)

3C267 2024/10/03 1.88UT FUJI -KISO



T20241003111644





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1213-17 2024/10/03 2.31UT TOYOKAWA-FUJI




T20241003111644




BLK:10,SNR1: 0.73493 ,SNR2: 3.1294




K20241003111642



BLK:10,SNR1: 2.0692 ,SNR2: 5.6059



1213-17 2024/10/03 2.31UT TOYOKAWA-KISO



FUJI



No. Good Data



Frequency (Hz)

K20241003111642



No. Good Data




Frequency (Hz)

1213-17 2024/10/03 2.31UT FUJI -KISO





T20241003113001




No.Good Data




FUJI




No.Good Data




3C273 2024/10/03 2.53UT TOYOKAWA-FUJI





T20241003113001




BLK:12,SNR1: 4.2273 ,SNR2: 10.724




K20241003112959



BLK:12,SNR1: 1.4835 ,SNR2: 4.7239



3C273 2024/10/03 2.53UT TOYOKAWA-KISO






FUJI




No. Good Data




Frequency (Hz)

K20241003112959




No. Good Data




Frequency (Hz)

3C273 2024/10/03 2.53UT FUJI -KISO



T20241003114917




No.Good Data



Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1245-19 2024/10/03 2.85UT TOYOKAWA-FUJI





T20241003114917




BLK:22,SNR1: 2.1633 ,SNR2: 5.6401




K20241003114915





BLK:22,SNR1: 2.6673 ,SNR2: 7.0124



1245-19 2024/10/03 2.85UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003114915




No.Good Data



Frequency (Hz)

1245-19 2024/10/03 2.85UT FUJI -KISO



T20241003115701





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C279 2024/10/03 2.98UT TOYOKAWA-FUJI



T20241003115701





BLK:12,SNR1: 2.4970 ,SNR2: 6.6938





3C279 2024/10/03 2.98UT TOYOKAWA-KISO

K20241003115659



BLK:12,SNR1: 0.55057 ,SNR2: 3.3563



FUJI





No.Good Data




Frequency (Hz)

K20241003115659




No.Good Data



Frequency (Hz)

3C279 2024/10/03 2.98UT FUJI -KISO





T20241003121230




No.Good Data




FUJI



No.Good Data




3C283 2024/10/03 3.24UT TOYOKAWA-FUJI






T20241003121230




BLK:30,SNR1: 1.0882 ,SNR2: 7.8805





3C283 2024/10/03 3.24UT TOYOKAWA-KISO

K20241003121228



BLK:30,SNR1: 0.77176 ,SNR2: 8.2260



FUJI





No. Good Data




Frequency (Hz)

K20241003121228




No. Good Data



Frequency (Hz)


3C283 2024/10/03 3.24UT FUJI -KISO



T20241003122655



No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1323+32 2024/10/03 3.48UT TOYOKAWA-FUJI




T20241003122655




BLK:13,SNR1: 29.953 ,SNR2: 37.550




K20241003122653





BLK:13,SNR1: 22.265 ,SNR2: 35.627




1323+32 2024/10/03 3.48UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003122653




No.Good Data





Frequency (Hz)


1323+32 2024/10/03 3.48UT FUJI -KISO



T20241003123145





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C286 2024/10/03 3.56UT TOYOKAWA-FUJI




T20241003123145




BLK:22,SNR1: 68.308 ,SNR2: 106.65




K20241003123143





BLK:22,SNR1: 0.68601 ,SNR2: 2.3275




3C286 2024/10/03 3.56UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003123143




No.Good Data





Frequency (Hz)

3C286 2024/10/03 3.56UT FUJI -KISO






T20241003124812





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1345+12 2024/10/03 3.83UT TOYOKAWA-FUJI





T20241003124812




BLK:21,SNR1: 51.719 ,SNR2: 86.129




K20241003124810





BLK:21,SNR1: 6.3781 ,SNR2: 10.720




1345+12 2024/10/03 3.83UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241003124810




No.Good Data





Frequency (Hz)


1345+12 2024/10/03 3.83UT FUJI -KISO



T20241003125833





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1355+01 2024/10/03 4.00UT TOYOKAWA-FUJI





T20241003125833




BLK:23,SNR1: 1.6465 ,SNR2: 11.274




K20241003125831





BLK:23,SNR1: 0.33233 ,SNR2: 1.3798




1355+01 2024/10/03 4.00UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003125831




No.Good Data





Frequency (Hz)


1355+01 2024/10/03 4.00UT FUJI -KISO



T20241003131943





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C298 2024/10/03 4.36UT TOYOKAWA-FUJI



T20241003131943




BLK:30,SNR1: 3.4225 ,SNR2: 27.627




Frequency (Hz)

K20241003131941




BLK:30,SNR1: 0.58344 ,SNR2: 2.8170




Frequency (Hz)

3C298 2024/10/03 4.36UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241003131941




No.Good Data






Frequency (Hz)




3C298 2024/10/03 4.36UT FUJI -KISO




T20241003133127







FUJI




1428-03 2024/10/03 4.55UT TOYOKAWA-FUJI








1428-03 2024/10/03 4.55UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003133125




No.Good Data





Frequency (Hz)


1428-03 2024/10/03 4.55UT FUJI -KISO



T20241003133729





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1434+03 2024/10/03 4.65UT TOYOKAWA-FUJI




T20241003133729




BLK: 2,SNR1: 0.24122 ,SNR2: 0.83463




K20241003133727





BLK: 2,SNR1: 7.5498 ,SNR2: 16.135




1434+03 2024/10/03 4.65UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003133727




No.Good Data





Frequency (Hz)


1434+03 2024/10/03 4.65UT FUJI -KISO



T20241003135631





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1453-10 2024/10/03 4.97UT TOYOKAWA-FUJI







T20241003135631




BLK: 4,SNR1: 0.42564 ,SNR2: 2.9719




K20241003135629





BLK: 4,SNR1: 0.10705 ,SNR2: 0.34524




1453-10 2024/10/03 4.97UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003135629




No.Good Data





Frequency (Hz)




1453-10 2024/10/03 4.97UT FUJI -KISO




T20241003141124





FUJI




1508-05 2024/10/03 5.22UT TOYOKAWA-FUJI





T20241003141124




BLK: 7,SNR1: 1.3516 ,SNR2: 6.3186




K20241003141122





BLK: 7,SNR1: 17.654 ,SNR2: 25.481




1508-05 2024/10/03 5.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003141122




No.Good Data






Frequency (Hz)




1508-05 2024/10/03 5.22UT FUJI -KISO




T20241003142024





FUJI




3C318 2024/10/03 5.37UT TOYOKAWA-FUJI



T20241003142024





BLK:11,SNR1: 0.87463 ,SNR2: 2.3215




Frequency (Hz)

3C318 2024/10/03 5.37UT TOYOKAWA-KISO


K20241003142021





BLK:11,SNR1: 2.1521 ,SNR2: 7.5305




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241003142021




No.Good Data






Frequency (Hz)

3C318 2024/10/03 5.37UT FUJI -KISO









T20241003142611





FUJI




1523+03 2024/10/03 5.46UT TOYOKAWA-FUJI





T20241003142611




BLK:17,SNR1: 1.1102 ,SNR2: 7.1882




K20241003142609





BLK:17,SNR1: 0.20871 ,SNR2: 3.6895




1523+03 2024/10/03 5.46UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003142609




No.Good Data






Frequency (Hz)




1523+03 2024/10/03 5.46UT FUJI -KISO




T20241003143750




FUJI





1535+139 2024/10/03 5.66UT TOYOKAWA-FUJI







BLK: 5, SNR1: 0.86739 , SNR2: 4.0323






BLK: 5, SNR1: 2.6560 , SNR2: 11.753






1535+139 2024/10/03 5.66UT TOYOKAWA-KISO




FUJI






K20241003143747






1535+139 2024/10/03 5.66UT FUJI -KISO




T20241003144814





FUJI




1545-12 2024/10/03 5.83UT TOYOKAWA-FUJI







1545-12 2024/10/03 5.83UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241003144812




No.Good Data




Frequency (Hz)


1545-12 2024/10/03 5.83UT FUJI -KISO



T20241003150917





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1607+26 2024/10/03 6.18UT TOYOKAWA-FUJI



T20241003150917




BLK: 2,SNR1: 7.3235 ,SNR2: 15.970




Frequency (Hz)

K20241003150914




BLK: 2,SNR1: 15.379 ,SNR2: 25.956





Frequency (Hz)


1607+26 2024/10/03 6.18UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003150914




No.Good Data






Frequency (Hz)




1607+26 2024/10/03 6.18UT FUJI -KISO




T20241003152648





FUJI




1623-228 2024/10/03 6.47UT TOYOKAWA-FUJI



T20241003152648





No. Good Data




Frequency (Hz)

K20241003152645




No. Good Data





Frequency (Hz)


1623-228 2024/10/03 6.47UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003152645




No.Good Data






Frequency (Hz)




1623-228 2024/10/03 6.47UT FUJI -KISO




T20241003153518



FUJI





1631-222 2024/10/03 6.62UT TOYOKAWA-FUJI








T20241003153518




BLK:17,SNR1: 0.17383 ,SNR2: 2.0840




K20241003153516






BLK:17,SNR1: 2.7742 ,SNR2: 5.6112






1631-222 2024/10/03 6.62UT TOYOKAWA-KISO




FUJI






K20241003153516






1631-222 2024/10/03 6.62UT FUJI -KISO




T20241003154055





FUJI




1638-025 2024/10/03 6.71UT TOYOKAWA-FUJI





T20241003154055




BLK: 2,SNR1: 8.2926 ,SNR2: 29.727




K20241003154053






BLK: 2,SNR1: 2.6938 ,SNR2: 13.219






1638-025 2024/10/03 6.71UT TOYOKAWA-KISO




FUJI






K20241003154053






1638-025 2024/10/03 6.71UT FUJI -KISO




T20241003154749




FUJI




1644-106 2024/10/03 6.83UT TOYOKAWA-FUJI



T20241003154749




BLK:12,SNR1: 0.55715 ,SNR2: 2.1282




Frequency (Hz)

K20241003154747




BLK:12,SNR1: 12.540 ,SNR2: 40.182






Frequency (Hz)




1644-106 2024/10/03 6.83UT TOYOKAWA-KISO




FUJI



K20241003154747






1644-106 2024/10/03 6.83UT FUJI -KISO









T20241003155310




FUJI




1650+004 2024/10/03 6.91UT TOYOKAWA-FUJI



T20241003155310




BLK: 2,SNR1: 19.030 ,SNR2: 31.404




Frequency (Hz)

K20241003155308




BLK: 2,SNR1: 16.173 ,SNR2: 34.106





Frequency (Hz)


1650+004 2024/10/03 6.91UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003155308




No.Good Data





Frequency (Hz)


1650+004 2024/10/03 6.91UT FUJI -KISO





T20241003155842




No.Good Data




FUJI





No.Good Data




1656+053 2024/10/03 7.01UT TOYOKAWA-FUJI



T20241003155842





BLK: 8,SNR1: 0.57535 ,SNR2: 2.4018




Frequency (Hz)

K20241003155840




BLK: 8,SNR1: 11.440 ,SNR2: 24.054






Frequency (Hz)




1656+053 2024/10/03 7.01UT TOYOKAWA-KISO




FUJI





K20241003155840




1656+053 2024/10/03 7.01UT FUJI -KISO



T20241003161512





No.Good Data




Frequency (Hz)

FUJI






No.Good Data




Frequency (Hz)

1712-033 2024/10/03 7.28UT TOYOKAWA-FUJI






1712-033 2024/10/03 7.28UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241003161510




No.Good Data




Frequency (Hz)


1712-033 2024/10/03 7.28UT FUJI -KISO



T20241003163314





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1730-13 2024/10/03 7.58UT TOYOKAWA-FUJI



T20241003163314




BLK: 9, SNR1: 1.1790 , SNR2: 3.7569




Frequency (Hz)

K20241003163312




BLK: 9, SNR1: 3.1953 , SNR2: 9.3807





Frequency (Hz)


1730-13 2024/10/03 7.58UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241003163312




No.Good Data





Frequency (Hz)


1730-13 2024/10/03 7.58UT FUJI -KISO



T20241003165039




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1748+031 2024/10/03 7.87UT TOYOKAWA-FUJI



T20241003165039





BLK: 2, SNR1: 0.76387 , SNR2: 2.5669




Frequency (Hz)

K20241003165036




BLK: 2, SNR1: 2.0415 , SNR2: 7.2248






Frequency (Hz)




1748+031 2024/10/03 7.87UT TOYOKAWA-KISO



FUJI



K20241003165036



1748+031 2024/10/03 7.87UT FUJI -KISO

