




T20241017060042





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0752-200 2024/10/16 21.04UT TOYOKAWA-FUJI



T20241017060042





BLK: 2,SNR1: 0.42854E-01,SNR2: 1.8581




Frequency (Hz)

K20241017060040




BLK: 2,SNR1: 1.8746 ,SNR2: 5.4409





Frequency (Hz)


0752-200 2024/10/16 21.04UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017060040




No.Good Data





Frequency (Hz)


0752-200 2024/10/16 21.04UT FUJI -KISO




T20241017061522




No.Good Data




FUJI



No.Good Data




0806-103 2024/10/16 21.28UT TOYOKAWA-FUJI






T20241017061522





BLK:22,SNR1: 10.858 ,SNR2: 18.439




Frequency (Hz)

0806-103 2024/10/16 21.28UT TOYOKAWA-KISO


K20241017061520





BLK:22,SNR1: 6.7232 ,SNR2: 21.071




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241017061520




No.Good Data





Frequency (Hz)


0806-103 2024/10/16 21.28UT FUJI -KISO





T20241017062726




No.Good Data




FUJI





No.Good Data




0817+183 2024/10/16 21.49UT TOYOKAWA-FUJI



T20241017062726





BLK: 5, SNR1: 0.68304 , SNR2: 2.8058




Frequency (Hz)

K20241017062724




BLK: 5, SNR1: 0.75885 , SNR2: 2.6363




Frequency (Hz)


0817+183 2024/10/16 21.49UT TOYOKAWA-KISO




FUJI




No.Good Data




K20241017062724




No.Good Data




0817+183 2024/10/16 21.49UT FUJI -KISO





T20241017063611




No.Good Data




FUJI





No.Good Data




0826+095 2024/10/16 21.63UT TOYOKAWA-FUJI



T20241017063611





BLK: 8,SNR1: 26.440 ,SNR2: 149.46




Frequency (Hz)

K20241017063609




BLK: 8,SNR1: 0.77978 ,SNR2: 1.9403




Frequency (Hz)


0826+095 2024/10/16 21.63UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017063609




No.Good Data




Frequency (Hz)

0826+095 2024/10/16 21.63UT FUJI -KISO







T20241017064331




No.Good Data




FUJI





No.Good Data




0834-19 2024/10/16 21.75UT TOYOKAWA-FUJI



T20241017064331





BLK:18,SNR1: 7.8736 ,SNR2: 13.423




Frequency (Hz)

K20241017064329




BLK:18,SNR1: 11.000 ,SNR2: 18.601




Frequency (Hz)


0834-19 2024/10/16 21.75UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241017064329





No.Good Data




0834-19 2024/10/16 21.75UT FUJI -KISO





T20241017064837




No.Good Data




FUJI





No.Good Data




0839-071 2024/10/16 21.84UT TOYOKAWA-FUJI



T20241017064837




BLK: 3,SNR1: 0.63014 ,SNR2: 2.4311




Frequency (Hz)

0839-071 2024/10/16 21.84UT TOYOKAWA-KISO


K20241017064835





BLK: 3,SNR1: 0.36747 ,SNR2: 5.8535




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241017064835




No.Good Data




Frequency (Hz)


0839-071 2024/10/16 21.84UT FUJI -KISO




T20241017065938




No.Good Data




FUJI





No.Good Data




3C208 2024/10/16 22.02UT TOYOKAWA-FUJI



T20241017065938





BLK: 3,SNR1: 0.10248 ,SNR2: 0.45440




Frequency (Hz)

K20241017065936




BLK: 3,SNR1: 1.1244 ,SNR2: 6.7822





Frequency (Hz)

3C208 2024/10/16 22.02UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241017065936




No.Good Data





Frequency (Hz)


3C208 2024/10/16 22.02UT FUJI -KISO





T20241017071619




No.Good Data




FUJI





No.Good Data




3C216 2024/10/16 22.30UT TOYOKAWA-FUJI



T20241017071619





BLK: 5,SNR1: 0.56829 ,SNR2: 2.3240




Frequency (Hz)

3C216 2024/10/16 22.30UT TOYOKAWA-KISO


K20241017071617





BLK: 5,SNR1: 2.3279 ,SNR2: 7.7121




Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20241017071617




No.Good Data





Frequency (Hz)


3C216 2024/10/16 22.30UT FUJI -KISO



T20241017072830





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0919-142 2024/10/16 22.50UT TOYOKAWA-FUJI



T20241017072830




BLK: 2,SNR1:-0.47834E-01,SNR2: 0.41415




Frequency (Hz)

K20241017072827




BLK: 2,SNR1: 0.57106 ,SNR2: 3.6321





Frequency (Hz)


0919-142 2024/10/16 22.50UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017072827




No.Good Data





Frequency (Hz)


0919-142 2024/10/16 22.50UT FUJI -KISO





T20241017074254




No.Good Data




FUJI



No.Good Data





3C222 2024/10/16 22.74UT TOYOKAWA-FUJI






T20241017074254





BLK: 2,SNR1: 0.16976 ,SNR2: 0.50750




Frequency (Hz)

K20241017074251




BLK: 2,SNR1:-0.79110E-01,SNR2: 1.1104





Frequency (Hz)


3C222 2024/10/16 22.74UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017074251




No.Good Data





Frequency (Hz)


3C222 2024/10/16 22.74UT FUJI -KISO



T20241017074954





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0941-08 2024/10/16 22.86UT TOYOKAWA-FUJI



T20241017074954




BLK:12,SNR1: 2.3457 ,SNR2: 9.5180




Frequency (Hz)

0941-08 2024/10/16 22.86UT TOYOKAWA-KISO


K20241017074951





BLK:12,SNR1: 0.13439E-01,SNR2: 0.73486




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241017074951




No.Good Data





Frequency (Hz)


0941-08 2024/10/16 22.86UT FUJI -KISO





T20241017075816




No.Good Data




FUJI





No.Good Data




3C230 2024/10/16 23.00UT TOYOKAWA-FUJI



T20241017075816




BLK: 9,SNR1: 6.1437 ,SNR2: 44.492




Frequency (Hz)

3C230 2024/10/16 23.00UT TOYOKAWA-KISO


K20241017075813





BLK: 9,SNR1: 0.28928 ,SNR2: 2.8751




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241017075813




No.Good Data





Frequency (Hz)

3C230 2024/10/16 23.00UT FUJI -KISO








T20241017081417




No.Good Data




FUJI





No.Good Data




3C237 2024/10/16 23.27UT TOYOKAWA-FUJI





T20241017081417




BLK:19,SNR1: 0.63430 ,SNR2: 1.7799




K20241017081414





BLK:19,SNR1: 0.35410 ,SNR2: 1.7420




3C237 2024/10/16 23.27UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241017081414




No. Good Data





Frequency (Hz)


3C237 2024/10/16 23.27UT FUJI -KISO





T20241017082033




No.Good Data




FUJI




No.Good Data




1011+110 2024/10/16 23.37UT TOYOKAWA-FUJI




T20241017082033




BLK:10,SNR1: 0.79499 ,SNR2: 2.6153




K20241017082030





BLK:10,SNR1: 6.1106 ,SNR2: 14.263




1011+110 2024/10/16 23.37UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017082030




No.Good Data





Frequency (Hz)


1011+110 2024/10/16 23.37UT FUJI -KISO





T20241017082814




No.Good Data




FUJI





No.Good Data




3C241 2024/10/16 23.50UT TOYOKAWA-FUJI



T20241017082814





BLK: 7,SNR1: 0.18342 ,SNR2: 2.9124





3C241 2024/10/16 23.50UT TOYOKAWA-KISO

K20241017082811





BLK: 7,SNR1: 0.70992 ,SNR2: 6.5706






FUJI





No.Good Data




Frequency (Hz)

K20241017082811




No.Good Data





Frequency (Hz)


3C241 2024/10/16 23.50UT FUJI -KISO





T20241017083943




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/16 23.69UT TOYOKAWA-FUJI



T20241017083943





BLK:15,SNR1: 0.57153E-01,SNR2: 0.76604





1031-11 2024/10/16 23.69UT TOYOKAWA-KISO



K20241017083940




BLK:15,SNR1: 16.443 ,SNR2: 35.134



FUJI





No.Good Data




Frequency (Hz)

K20241017083940




No.Good Data





Frequency (Hz)


1031-11 2024/10/16 23.69UT FUJI -KISO





T20241017084417




No.Good Data




FUJI





No.Good Data




1035-058 2024/10/16 23.77UT TOYOKAWA-FUJI



T20241017084417





BLK: 7,SNR1: 0.12355 ,SNR2: 1.3423




Frequency (Hz)

K20241017084414




BLK: 7,SNR1: 0.40501 ,SNR2: 2.0001





Frequency (Hz)


1035-058 2024/10/16 23.77UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241017084414




No. Good Data





Frequency (Hz)


1035-058 2024/10/16 23.77UT FUJI -KISO





T20241017085329




No.Good Data




FUJI



No.Good Data





1044-008 2024/10/16 23.92UT TOYOKAWA-FUJI






T20241017085329





BLK: 1,SNR1: 0.50322 ,SNR2: 0.82729




Frequency (Hz)

K20241017085326




BLK: 1,SNR1: 0.37186 ,SNR2: 7.3861





Frequency (Hz)


1044-008 2024/10/16 23.92UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017085326




No.Good Data





Frequency (Hz)


1044-008 2024/10/16 23.92UT FUJI -KISO





T20241017090434




No.Good Data




FUJI




No.Good Data




1055+01 2024/10/17 0.10UT TOYOKAWA-FUJI



T20241017090434




BLK:11,SNR1: 0.20101 ,SNR2: 1.3475





1055+01 2024/10/17 0.10UT TOYOKAWA-KISO



K20241017090431




BLK:11,SNR1: 0.48321 ,SNR2: 2.1226



FUJI





No.Good Data




Frequency (Hz)

K20241017090431




No.Good Data





Frequency (Hz)


1055+01 2024/10/17 0.10UT FUJI -KISO





T20241017091551




No.Good Data




FUJI





No.Good Data




1107+109 2024/10/17 0.29UT TOYOKAWA-FUJI





T20241017091551




BLK: 7,SNR1: 0.34903E-01,SNR2: 0.47731




K20241017091548





BLK: 7,SNR1: 0.12744 ,SNR2: 2.5449




1107+109 2024/10/17 0.29UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017091548




No.Good Data




Frequency (Hz)

1107+109 2024/10/17 0.29UT FUJI -KISO








T20241017092529




No. Good Data




FUJI





No. Good Data




3C255 2024/10/17 0.45UT TOYOKAWA-FUJI



T20241017092529





BLK:17,SNR1: 3.2799 ,SNR2: 6.4242





3C255 2024/10/17 0.45UT TOYOKAWA-KISO



K20241017092526




BLK:17,SNR1: 0.29349 ,SNR2: 2.1338



FUJI





No. Good Data




Frequency (Hz)

K20241017092526




No. Good Data





Frequency (Hz)


3C255 2024/10/17 0.45UT FUJI -KISO





T20241017093606




No. Good Data




FUJI





No. Good Data




1127-14 2024/10/17 0.63UT TOYOKAWA-FUJI



T20241017093606





BLK:16,SNR1: 0.29732 ,SNR2: 2.4913




Frequency (Hz)

1127-14 2024/10/17 0.63UT TOYOKAWA-KISO


K20241017093603





BLK:16,SNR1: 0.55290E-01,SNR2: 1.2714




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241017093603




No. Good Data





Frequency (Hz)


1127-14 2024/10/17 0.63UT FUJI -KISO



T20241017094927





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


3C263.1 2024/10/17 0.85UT TOYOKAWA-FUJI



T20241017094927




BLK:22,SNR1: 1.5330 ,SNR2: 14.029





3C263.1 2024/10/17 0.85UT TOYOKAWA-KISO

K20241017094924





BLK:22,SNR1: 0.22588 ,SNR2: 2.7551






FUJI





No.Good Data




Frequency (Hz)

K20241017094924




No.Good Data





Frequency (Hz)


3C263.1 2024/10/17 0.85UT FUJI -KISO



T20241017095554





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C267 2024/10/17 0.96UT TOYOKAWA-FUJI






FUJI





No. Good Data




Frequency (Hz)

K20241017095551




No. Good Data





Frequency (Hz)


3C267 2024/10/17 0.96UT FUJI -KISO



T20241017102142





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1213-17 2024/10/17 1.39UT TOYOKAWA-FUJI



T20241017102142





BLK:14,SNR1: 0.29424 ,SNR2: 2.5526





1213-17 2024/10/17 1.39UT TOYOKAWA-KISO



K20241017102139




BLK:14,SNR1: 2.3805 ,SNR2: 7.9685



FUJI





No. Good Data




Frequency (Hz)

K20241017102139




No. Good Data





Frequency (Hz)


1213-17 2024/10/17 1.39UT FUJI -KISO



T20241017103459





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C273 2024/10/17 1.61UT TOYOKAWA-FUJI






T20241017103459




BLK:27,SNR1: 18.786 ,SNR2: 70.704





3C273 2024/10/17 1.61UT TOYOKAWA-KISO



K20241017103456




BLK:27,SNR1: 2.9525 ,SNR2: 18.767



FUJI





No.Good Data




Frequency (Hz)

K20241017103456




No.Good Data





Frequency (Hz)


3C273 2024/10/17 1.61UT FUJI -KISO





T20241017104810




No.Good Data




FUJI




No.Good Data




3C275 2024/10/17 1.83UT TOYOKAWA-FUJI



T20241017104810





BLK:18,SNR1: 1.7682 ,SNR2: 8.3230





3C275 2024/10/17 1.83UT TOYOKAWA-KISO



K20241017104807




BLK:18,SNR1: 4.0001 ,SNR2: 16.870



FUJI





No. Good Data




Frequency (Hz)

K20241017104807




No. Good Data





Frequency (Hz)


3C275 2024/10/17 1.83UT FUJI -KISO



T20241017105415





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1245-19 2024/10/17 1.93UT TOYOKAWA-FUJI



T20241017105415





BLK:34,SNR1: 1.8626 ,SNR2: 3.3480




Frequency (Hz)

1245-19 2024/10/17 1.93UT TOYOKAWA-KISO


K20241017105412





BLK:34,SNR1: 0.79986 ,SNR2: 1.5653




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241017105412




No.Good Data





Frequency (Hz)

1245-19 2024/10/17 1.93UT FUJI -KISO






T20241017110158





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C279 2024/10/17 2.06UT TOYOKAWA-FUJI




T20241017110158




BLK:14,SNR1: 3.6737 ,SNR2: 13.091




K20241017110155





BLK:14,SNR1: 1.2201 ,SNR2: 3.4887




3C279 2024/10/17 2.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017110155




No.Good Data





Frequency (Hz)


3C279 2024/10/17 2.06UT FUJI -KISO



T20241017111728





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C283 2024/10/17 2.32UT TOYOKAWA-FUJI





T20241017111728




BLK:30,SNR1: 4.2956 ,SNR2: 7.8838




K20241017111725





BLK:30,SNR1: 4.4835 ,SNR2: 7.6143




3C283 2024/10/17 2.32UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241017111725




No. Good Data





Frequency (Hz)


3C283 2024/10/17 2.32UT FUJI -KISO



T20241017113152





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1323+32 2024/10/17 2.56UT TOYOKAWA-FUJI




T20241017113152




BLK:25,SNR1: 1.9184 ,SNR2: 5.0537




K20241017113150



BLK:25,SNR1: 3.3099 ,SNR2: 6.1287





1323+32 2024/10/17 2.56UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241017113150




No. Good Data





Frequency (Hz)


1323+32 2024/10/17 2.56UT FUJI -KISO



T20241017113642





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C286 2024/10/17 2.64UT TOYOKAWA-FUJI



T20241017113642




BLK:16,SNR1: 9.4295 ,SNR2: 23.447





3C286 2024/10/17 2.64UT TOYOKAWA-KISO



K20241017113640




BLK:16,SNR1: 6.6422 ,SNR2: 18.865



FUJI





No.Good Data




Frequency (Hz)

K20241017113640




No.Good Data





Frequency (Hz)


3C286 2024/10/17 2.64UT FUJI -KISO



T20241017115310





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


1345+12 2024/10/17 2.91UT TOYOKAWA-FUJI



T20241017115310





BLK:33,SNR1: 17.684 ,SNR2: 67.018





1345+12 2024/10/17 2.91UT TOYOKAWA-KISO



K20241017115308




BLK:33,SNR1: 0.80112 ,SNR2: 2.5845



FUJI





No.Good Data




Frequency (Hz)

K20241017115308




No.Good Data





Frequency (Hz)


1345+12 2024/10/17 2.91UT FUJI -KISO



T20241017120330





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

1355+01 2024/10/17 3.09UT TOYOKAWA-FUJI







T20241017120330




BLK:28,SNR1: 3.1294 ,SNR2: 13.813




K20241017120328





BLK:28,SNR1: 0.49237 ,SNR2: 1.7491




1355+01 2024/10/17 3.09UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017120328




No.Good Data





Frequency (Hz)


1355+01 2024/10/17 3.09UT FUJI -KISO



T20241017122441





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C298 2024/10/17 3.44UT TOYOKAWA-FUJI



T20241017122441





BLK:24,SNR1: 7.5030 ,SNR2: 23.113





3C298 2024/10/17 3.44UT TOYOKAWA-KISO



K20241017122439




BLK:24,SNR1: 2.4226 ,SNR2: 6.3855



FUJI





No.Good Data




Frequency (Hz)

K20241017122439




No.Good Data





Frequency (Hz)


3C298 2024/10/17 3.44UT FUJI -KISO



T20241017123624





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1428-03 2024/10/17 3.63UT TOYOKAWA-FUJI





T20241017123624




BLK:14,SNR1: 1.2335 ,SNR2: 3.4270




K20241017123622





BLK:14,SNR1: 3.6071 ,SNR2: 6.1200




1428-03 2024/10/17 3.63UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017123622




No.Good Data





Frequency (Hz)

1428-03 2024/10/17 3.63UT FUJI -KISO






T20241017124227





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1434+03 2024/10/17 3.74UT TOYOKAWA-FUJI




T20241017124227




BLK:10,SNR1: 10.196 ,SNR2: 24.600




K20241017124225





BLK:10,SNR1: 9.2994 ,SNR2: 23.754




1434+03 2024/10/17 3.74UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017124225




No.Good Data






Frequency (Hz)




1434+03 2024/10/17 3.74UT FUJI -KISO




T20241017130129




FUJI




1453-10 2024/10/17 4.05UT TOYOKAWA-FUJI



T20241017130129





BLK:10,SNR1: 7.2207 ,SNR2: 18.489





1453-10 2024/10/17 4.05UT TOYOKAWA-KISO



K20241017130126




BLK:10,SNR1: 0.74772 ,SNR2: 2.5574



FUJI





No.Good Data




Frequency (Hz)

K20241017130126




No.Good Data





Frequency (Hz)


1453-10 2024/10/17 4.05UT FUJI -KISO



T20241017131621





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1508-05 2024/10/17 4.30UT TOYOKAWA-FUJI




T20241017131621




BLK: 9,SNR1: 1.4551 ,SNR2: 3.8051




K20241017131618



BLK: 9,SNR1: 3.9731 ,SNR2: 16.745





1508-05 2024/10/17 4.30UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241017131618




No.Good Data





Frequency (Hz)


1508-05 2024/10/17 4.30UT FUJI -KISO



T20241017132521





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/10/17 4.45UT TOYOKAWA-FUJI





T20241017132521




BLK: 7,SNR1: 0.13125 ,SNR2: 0.66896




K20241017132518





BLK: 7,SNR1: 0.64341 ,SNR2: 2.5182




3C318 2024/10/17 4.45UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017132518




No.Good Data






Frequency (Hz)




3C318 2024/10/17 4.45UT FUJI -KISO




T20241017133108




FUJI




1523+03 2024/10/17 4.55UT TOYOKAWA-FUJI




T20241017133108




BLK:14,SNR1: 2.6032 ,SNR2: 7.9493




K20241017133105





BLK:14,SNR1: 7.0547 ,SNR2: 18.147




1523+03 2024/10/17 4.55UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017133105




No.Good Data






Frequency (Hz)




1523+03 2024/10/17 4.55UT FUJI -KISO




T20241017134247



FUJI





1535+139 2024/10/17 4.74UT TOYOKAWA-FUJI








T20241017134247




BLK:16,SNR1: 14.064 ,SNR2: 16.426




K20241017134245





BLK:16,SNR1: 10.097 ,SNR2: 16.762




1535+139 2024/10/17 4.74UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017134245




No.Good Data





Frequency (Hz)


1535+139 2024/10/17 4.74UT FUJI -KISO



T20241017135553





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1548+05 2024/10/17 4.96UT TOYOKAWA-FUJI





T20241017135553




BLK: 8,SNR1: 1.5676 ,SNR2: 11.340




K20241017135550





BLK: 8,SNR1: 1.5781 ,SNR2: 4.7335




1548+05 2024/10/17 4.96UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017135550




No.Good Data






Frequency (Hz)




1548+05 2024/10/17 4.96UT FUJI -KISO




T20241017141415




FUJI




1607+26 2024/10/17 5.27UT TOYOKAWA-FUJI





T20241017141415




BLK: 6,SNR1: 2.7021 ,SNR2: 7.9258




K20241017141412





BLK: 6,SNR1: 10.303 ,SNR2: 25.306




1607+26 2024/10/17 5.27UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017141412




No.Good Data






Frequency (Hz)

1607+26 2024/10/17 5.27UT FUJI -KISO









T20241017143145





FUJI




1623-228 2024/10/17 5.56UT TOYOKAWA-FUJI





T20241017143145




BLK:11,SNR1: 0.96592 ,SNR2: 7.0342




K20241017143142





BLK:11,SNR1: 1.1720 ,SNR2: 3.8180




1623-228 2024/10/17 5.56UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017143142




No.Good Data






Frequency (Hz)




1623-228 2024/10/17 5.56UT FUJI -KISO




T20241017144015





FUJI




1631-222 2024/10/17 5.70UT TOYOKAWA-FUJI





T20241017144015




BLK: 9,SNR1: 0.21295 ,SNR2: 3.0518




K20241017144013





BLK: 9,SNR1: 0.38108 ,SNR2: 1.8484




1631-222 2024/10/17 5.70UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017144013




No.Good Data




Frequency (Hz)


1631-222 2024/10/17 5.70UT FUJI -KISO



T20241017144552





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1638-025 2024/10/17 5.79UT TOYOKAWA-FUJI



T20241017144552





BLK: 9,SNR1: 0.19034 ,SNR2: 1.1258




Frequency (Hz)

K20241017144550




BLK: 9,SNR1: 0.50066 ,SNR2: 1.2854






Frequency (Hz)

1638-025 2024/10/17 5.79UT TOYOKAWA-KISO









FUJI




K20241017144550




1638-025 2024/10/17 5.79UT FUJI -KISO



T20241017145247





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1644-106 2024/10/17 5.91UT TOYOKAWA-FUJI





T20241017145247




BLK: 3,SNR1: 0.21050 ,SNR2: 0.77128




K20241017145245






BLK: 3,SNR1: 1.0436 ,SNR2: 2.7151






1644-106 2024/10/17 5.91UT TOYOKAWA-KISO




FUJI





K20241017145245




1644-106 2024/10/17 5.91UT FUJI -KISO



T20241017145807





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1650+004 2024/10/17 6.00UT TOYOKAWA-FUJI





T20241017145807




BLK: 5,SNR1:-0.54680E-01,SNR2: 0.52032




K20241017145805






BLK: 5,SNR1: 1.2351 ,SNR2: 3.9940






1650+004 2024/10/17 6.00UT TOYOKAWA-KISO




FUJI






K20241017145805






1650+004 2024/10/17 6.00UT FUJI -KISO




T20241017150339







FUJI




1656+053 2024/10/17 6.09UT TOYOKAWA-FUJI













1656+053 2024/10/17 6.09UT TOYOKAWA-KISO




FUJI






K20241017150337






1656+053 2024/10/17 6.09UT FUJI -KISO




T20241017152009





FUJI




1712-033 2024/10/17 6.36UT TOYOKAWA-FUJI





T20241017152009




BLK: 6,SNR1: 0.33229 ,SNR2: 1.8399




K20241017152006






BLK: 6,SNR1: 0.32004E-01,SNR2: 1.0405






1712-033 2024/10/17 6.36UT TOYOKAWA-KISO




FUJI






K20241017152006






1712-033 2024/10/17 6.36UT FUJI -KISO




T20241017153811





FUJI




1730-13 2024/10/17 6.66UT TOYOKAWA-FUJI





T20241017153811




BLK: 6,SNR1: 0.10420 ,SNR2: 1.3915




K20241017153808






BLK: 6,SNR1: 1.1107 ,SNR2: 7.2670






1730-13 2024/10/17 6.66UT TOYOKAWA-KISO




FUJI



K20241017153808






1730-13 2024/10/17 6.66UT FUJI -KISO









T20241017155536




FUJI




1748+031 2024/10/17 6.95UT TOYOKAWA-FUJI





T20241017155536




BLK: 3,SNR1: 0.99638E-01,SNR2: 0.45631




K20241017155534






BLK: 3,SNR1: 0.84628 ,SNR2: 4.8054






1748+031 2024/10/17 6.95UT TOYOKAWA-KISO




FUJI






K20241017155534






1748+031 2024/10/17 6.95UT FUJI -KISO




T20241017160629





FUJI




1759+13 2024/10/17 7.14UT TOYOKAWA-FUJI



T20241017160629





BLK: 3,SNR1: 0.85769E-01,SNR2: 1.0816




Frequency (Hz)

K20241017160626




BLK: 3,SNR1: 0.65230 ,SNR2: 4.7275





Frequency (Hz)


1759+13 2024/10/17 7.14UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241017160626






No.Good Data






1759+13 2024/10/17 7.14UT FUJI -KISO




T20241017162729





FUJI




1819-096 2024/10/17 7.49UT TOYOKAWA-FUJI





T20241017162729




BLK: 4, SNR1: 1.5987 , SNR2: 7.4524




K20241017162727



BLK: 4, SNR1: 0.12098 , SNR2: 0.69775





1819-096 2024/10/17 7.49UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241017162727




No.Good Data




Frequency (Hz)


1819-096 2024/10/17 7.49UT FUJI -KISO



T20241017163845





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1830-210 2024/10/17 7.67UT TOYOKAWA-FUJI





T20241017163845




BLK: 1, SNR1: 0.25868 , SNR2: 0.76744




K20241017163843





BLK: 1, SNR1: 0.32793 , SNR2: 0.56588




1830-210 2024/10/17 7.67UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241017163843



No.Good Data



Frequency (Hz)

1830-210 2024/10/17 7.67UT FUJI -KISO

