



T20241024055402





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0812-184 2024/10/23 20.93UT TOYOKAWA-FUJI



T20241024055402





BLK: 6,SNR1: 0.15959 ,SNR2: 1.2010




Frequency (Hz)

K20241024055359




BLK: 6,SNR1: 0.83609 ,SNR2: 5.0304





Frequency (Hz)


0812-184 2024/10/23 20.93UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024055359




No.Good Data




Frequency (Hz)


0812-184 2024/10/23 20.93UT FUJI -KISO




T20241024060324




No.Good Data




FUJI



No.Good Data




0822-096 2024/10/23 21.08UT TOYOKAWA-FUJI






T20241024060324





BLK: 3,SNR1: 3.6732 ,SNR2: 48.166




Frequency (Hz)

0822-096 2024/10/23 21.08UT TOYOKAWA-KISO


K20241024060321





BLK: 3,SNR1: 4.9357 ,SNR2: 12.458




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024060321




No.Good Data





Frequency (Hz)


0822-096 2024/10/23 21.08UT FUJI -KISO





T20241024061122




No.Good Data




FUJI






No.Good Data






0830-118 2024/10/23 21.22UT TOYOKAWA-FUJI




T20241024061122




K20241024061119




0830-118 2024/10/23 21.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024061119




No.Good Data




Frequency (Hz)


0830-118 2024/10/23 21.22UT FUJI -KISO



T20241024061600





No.Good Data




Frequency (Hz)

FUJI





No.Good Data





Frequency (Hz)

0834-19 2024/10/23 21.29UT TOYOKAWA-FUJI







BLK: 3,SNR1: 0.16668E-01,SNR2: 1.4721





BLK: 3,SNR1: 1.1546 ,SNR2: 2.9380




0834-19 2024/10/23 21.29UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241024061558




No.Good Data




Frequency (Hz)

0834-19 2024/10/23 21.29UT FUJI -KISO






T20241024062105




No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0839-071 2024/10/23 21.38UT TOYOKAWA-FUJI



T20241024062105





BLK: 7,SNR1: 11.147 ,SNR2: 98.127




Frequency (Hz)

0839-071 2024/10/23 21.38UT TOYOKAWA-KISO


K20241024062103




BLK: 7,SNR1: 0.56522 ,SNR2: 5.4283




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024062103




No.Good Data





Frequency (Hz)


0839-071 2024/10/23 21.38UT FUJI -KISO




T20241024063206




No.Good Data




FUJI





No.Good Data




3C208 2024/10/23 21.56UT TOYOKAWA-FUJI



T20241024063206





BLK: 2,SNR1:-0.11983 ,SNR2: 0.20629




Frequency (Hz)

K20241024063204




BLK: 2,SNR1: 0.49370 ,SNR2: 8.2475




Frequency (Hz)


3C208 2024/10/23 21.56UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241024063204




No.Good Data





Frequency (Hz)


3C208 2024/10/23 21.56UT FUJI -KISO





T20241024065332




No.Good Data




FUJI




No.Good Data




0912-132 2024/10/23 21.92UT TOYOKAWA-FUJI



T20241024065332





BLK:10,SNR1: 3.1857 ,SNR2: 9.7339




Frequency (Hz)

K20241024065330




BLK:10,SNR1: 6.5820 ,SNR2: 20.651





Frequency (Hz)

0912-132 2024/10/23 21.92UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241024065330




No.Good Data





Frequency (Hz)


0912-132 2024/10/23 21.92UT FUJI -KISO



T20241024070059





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0919-142 2024/10/23 22.04UT TOYOKAWA-FUJI



T20241024070059





BLK: 1,SNR1: 1.1793 ,SNR2: 5.0422




Frequency (Hz)

0919-142 2024/10/23 22.04UT TOYOKAWA-KISO


K20241024070057




BLK: 1,SNR1: 0.27913 ,SNR2: 0.99112




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024070057




No.Good Data




Frequency (Hz)


0919-142 2024/10/23 22.04UT FUJI -KISO





T20241024071523




No.Good Data




FUJI




No.Good Data




3C222 2024/10/23 22.28UT TOYOKAWA-FUJI



T20241024071523




BLK: 3,SNR1: 0.15467 ,SNR2: 2.1678




Frequency (Hz)

3C222 2024/10/23 22.28UT TOYOKAWA-KISO


K20241024071521





BLK: 3,SNR1: 0.28297 ,SNR2: 0.97637




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024071521




No.Good Data





Frequency (Hz)


3C222 2024/10/23 22.28UT FUJI -KISO





T20241024072223




No.Good Data




FUJI



No.Good Data




0941-08 2024/10/23 22.40UT TOYOKAWA-FUJI






T20241024072223




BLK: 8,SNR1: 6.2573 ,SNR2: 11.469





0941-08 2024/10/23 22.40UT TOYOKAWA-KISO



K20241024072221




BLK: 8,SNR1: 19.096 ,SNR2: 24.907



FUJI





No.Good Data




Frequency (Hz)

K20241024072221




No.Good Data





Frequency (Hz)


0941-08 2024/10/23 22.40UT FUJI -KISO





T20241024073045




No.Good Data




FUJI





No.Good Data




3C230 2024/10/23 22.54UT TOYOKAWA-FUJI



T20241024073045





BLK: 8,SNR1: 0.77673E-01,SNR2: 1.2710




Frequency (Hz)

3C230 2024/10/23 22.54UT TOYOKAWA-KISO


K20241024073043





BLK: 8,SNR1: 0.38224 ,SNR2: 2.4686




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024073043




No.Good Data





Frequency (Hz)


3C230 2024/10/23 22.54UT FUJI -KISO





T20241024074645




No.Good Data




FUJI







No.Good Data




3C237 2024/10/23 22.81UT TOYOKAWA-FUJI








3C237 2024/10/23 22.81UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024074643




No.Good Data





Frequency (Hz)

3C237 2024/10/23 22.81UT FUJI -KISO








T20241024075302




No.Good Data




FUJI





No.Good Data




1011+110 2024/10/23 22.91UT TOYOKAWA-FUJI



T20241024075302




BLK: 1,SNR1: 1.2182 ,SNR2: 11.333





1011+110 2024/10/23 22.91UT TOYOKAWA-KISO



K20241024075259




BLK: 1,SNR1: 1.1568 ,SNR2: 10.836



FUJI





No.Good Data




Frequency (Hz)

K20241024075259




No.Good Data




Frequency (Hz)


1011+110 2024/10/23 22.91UT FUJI -KISO





T20241024080043




No.Good Data




FUJI





No.Good Data




3C241 2024/10/23 23.04UT TOYOKAWA-FUJI



T20241024080043





BLK: 7,SNR1: 0.85943E-01,SNR2: 1.1663




Frequency (Hz)

3C241 2024/10/23 23.04UT TOYOKAWA-KISO


K20241024080040





BLK: 7,SNR1: 0.22137 ,SNR2: 4.4986




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024080040




No.Good Data





Frequency (Hz)


3C241 2024/10/23 23.04UT FUJI -KISO





T20241024081212




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/23 23.23UT TOYOKAWA-FUJI




T20241024081212




BLK:14,SNR1: 0.14032 ,SNR2: 1.2414




K20241024081209



BLK:14,SNR1: 2.8259 ,SNR2: 8.2857





1031-11 2024/10/23 23.23UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241024081209




No.Good Data





Frequency (Hz)


1031-11 2024/10/23 23.23UT FUJI -KISO





T20241024081645




No.Good Data




FUJI





No.Good Data




1035-058 2024/10/23 23.31UT TOYOKAWA-FUJI



T20241024081645





BLK: 3,SNR1: 12.598 ,SNR2: 27.463




Frequency (Hz)

K20241024081642




BLK: 3,SNR1: 12.201 ,SNR2: 27.273





Frequency (Hz)


1035-058 2024/10/23 23.31UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024081642




No.Good Data





Frequency (Hz)


1035-058 2024/10/23 23.31UT FUJI -KISO





T20241024082558




No.Good Data




FUJI





No.Good Data




1044-008 2024/10/23 23.46UT TOYOKAWA-FUJI




T20241024082558




BLK: 2,SNR1: 0.72793E-01,SNR2: 0.53905




K20241024082555




BLK: 2,SNR1: 2.4357 ,SNR2: 9.6541




1044-008 2024/10/23 23.46UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024082555




No.Good Data





Frequency (Hz)


1044-008 2024/10/23 23.46UT FUJI -KISO





T20241024083703




No.Good Data




FUJI



No.Good Data





1055+01 2024/10/23 23.65UT TOYOKAWA-FUJI






T20241024083703





BLK: 1,SNR1:-0.22861E-01,SNR2: 2.5753





1055+01 2024/10/23 23.65UT TOYOKAWA-KISO



K20241024083700




BLK: 1,SNR1: 0.70222 ,SNR2: 2.9594



FUJI





No.Good Data




Frequency (Hz)

K20241024083700




No.Good Data





Frequency (Hz)


1055+01 2024/10/23 23.65UT FUJI -KISO





T20241024084820




No. Good Data




FUJI





No. Good Data




1107+109 2024/10/23 23.83UT TOYOKAWA-FUJI



T20241024084820





BLK: 8,SNR1: 12.071 ,SNR2: 28.116





1107+109 2024/10/23 23.83UT TOYOKAWA-KISO



K20241024084817




BLK: 8,SNR1: 8.8200 ,SNR2: 21.456



FUJI





No.Good Data




Frequency (Hz)

K20241024084817




No.Good Data





Frequency (Hz)


1107+109 2024/10/23 23.83UT FUJI -KISO





T20241024085410




No.Good Data




FUJI





No.Good Data




1112+218 2024/10/23 23.93UT TOYOKAWA-FUJI





T20241024085410




BLK: 5,SNR1: 0.16321 ,SNR2: 0.89737




K20241024085407





BLK: 5,SNR1: 0.51802 ,SNR2: 1.5798




1112+218 2024/10/23 23.93UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241024085407




No. Good Data




Frequency (Hz)

1112+218 2024/10/23 23.93UT FUJI -KISO








T20241024090835




No. Good Data




FUJI






No. Good Data







1127-14 2024/10/24 0.17UT TOYOKAWA-FUJI





T20241024090835




K20241024090832



FUJI





No.Good Data




Frequency (Hz)

K20241024090832




No.Good Data





Frequency (Hz)


1127-14 2024/10/24 0.17UT FUJI -KISO



T20241024092155





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C263.1 2024/10/24 0.39UT TOYOKAWA-FUJI



T20241024092155





BLK: 8, SNR1: 7.6718 ,SNR2: 20.826





3C263.1 2024/10/24 0.39UT TOYOKAWA-KISO



K20241024092152




BLK: 8, SNR1: 10.110 ,SNR2: 26.923



FUJI





No. Good Data




Frequency (Hz)

K20241024092152




No. Good Data





Frequency (Hz)


3C263.1 2024/10/24 0.39UT FUJI -KISO



T20241024092822





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


3C267 2024/10/24 0.50UT TOYOKAWA-FUJI



T20241024092822




BLK: 5,SNR1: 0.11976 ,SNR2: 2.6194





3C267 2024/10/24 0.50UT TOYOKAWA-KISO

K20241024092819





BLK: 5,SNR1: 1.5178 ,SNR2: 2.9080






FUJI





No. Good Data




Frequency (Hz)

K20241024092819




No. Good Data





Frequency (Hz)


3C267 2024/10/24 0.50UT FUJI -KISO



T20241024095410





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1213-17 2024/10/24 0.93UT TOYOKAWA-FUJI



T20241024095410




BLK: 6,SNR1: 5.4688 ,SNR2: 15.868





1213-17 2024/10/24 0.93UT TOYOKAWA-KISO



K20241024095407




BLK: 6,SNR1: 9.3695 ,SNR2: 23.703



FUJI





No. Good Data




Frequency (Hz)

K20241024095407




No. Good Data





Frequency (Hz)


1213-17 2024/10/24 0.93UT FUJI -KISO





T20241024100727




No.Good Data




FUJI





No.Good Data




3C273 2024/10/24 1.15UT TOYOKAWA-FUJI



T20241024100727




BLK:12,SNR1: 10.137 ,SNR2: 26.082





3C273 2024/10/24 1.15UT TOYOKAWA-KISO



K20241024100724




BLK:12,SNR1: 10.567 ,SNR2: 26.710



FUJI





No. Good Data




Frequency (Hz)

K20241024100724




No. Good Data





Frequency (Hz)


3C273 2024/10/24 1.15UT FUJI -KISO



T20241024102038





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C275 2024/10/24 1.37UT TOYOKAWA-FUJI






T20241024102038





BLK:11,SNR1: 6.8421 ,SNR2: 20.164





3C275 2024/10/24 1.37UT TOYOKAWA-KISO



K20241024102035




BLK:11,SNR1: 6.5231 ,SNR2: 19.110



FUJI





No.Good Data




Frequency (Hz)

K20241024102035




No.Good Data





Frequency (Hz)


3C275 2024/10/24 1.37UT FUJI -KISO



T20241024102643





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1245-19 2024/10/24 1.47UT TOYOKAWA-FUJI



T20241024102643





BLK:27,SNR1: 3.8524 ,SNR2: 10.703




1245-19 2024/10/24 1.47UT TOYOKAWA-KISO


K20241024102640





BLK:27,SNR1: 3.9764 ,SNR2: 11.025




Frequency (Hz)



FUJI




No. Good Data




Frequency (Hz)

K20241024102640




No. Good Data





Frequency (Hz)


1245-19 2024/10/24 1.47UT FUJI -KISO





T20241024103427




No.Good Data




FUJI





No.Good Data




3C279 2024/10/24 1.60UT TOYOKAWA-FUJI





T20241024103427




BLK:25,SNR1: 5.0411 ,SNR2: 13.089




K20241024103424





BLK:25,SNR1: 6.4627 ,SNR2: 20.240




3C279 2024/10/24 1.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024103424




No.Good Data





Frequency (Hz)

3C279 2024/10/24 1.60UT FUJI -KISO






T20241024104956





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

3C283 2024/10/24 1.86UT TOYOKAWA-FUJI








3C283 2024/10/24 1.86UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241024104953




No. Good Data





Frequency (Hz)


3C283 2024/10/24 1.86UT FUJI -KISO



T20241024110421





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1323+32 2024/10/24 2.10UT TOYOKAWA-FUJI



T20241024110421




BLK:10,SNR1: 0.63905 ,SNR2: 2.4728





1323+32 2024/10/24 2.10UT TOYOKAWA-KISO



K20241024110418




BLK:10,SNR1: 6.2433 ,SNR2: 17.020



FUJI





No.Good Data




Frequency (Hz)

K20241024110418




No.Good Data





Frequency (Hz)


1323+32 2024/10/24 2.10UT FUJI -KISO



T20241024110911





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C286 2024/10/24 2.18UT TOYOKAWA-FUJI





T20241024110911




BLK:31,SNR1: 1.4418 ,SNR2: 4.9214




K20241024110908



BLK:31,SNR1: 0.37984 ,SNR2: 1.6366





3C286 2024/10/24 2.18UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241024110908




No. Good Data





Frequency (Hz)


3C286 2024/10/24 2.18UT FUJI -KISO



T20241024112538





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


1345+12 2024/10/24 2.46UT TOYOKAWA-FUJI



T20241024112538




BLK:24,SNR1: 134.76 ,SNR2: 147.08




1345+12 2024/10/24 2.46UT TOYOKAWA-KISO


K20241024112536





BLK:24,SNR1: 10.196 ,SNR2: 17.282




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241024112536




No.Good Data





Frequency (Hz)


1345+12 2024/10/24 2.46UT FUJI -KISO



T20241024113559





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1355+01 2024/10/24 2.63UT TOYOKAWA-FUJI



T20241024113559




BLK:27,SNR1: 40.822 ,SNR2: 69.628





1355+01 2024/10/24 2.63UT TOYOKAWA-KISO



K20241024113557




BLK:27,SNR1: 6.0239 ,SNR2: 17.269



FUJI





No.Good Data




Frequency (Hz)

K20241024113557




No.Good Data





Frequency (Hz)


1355+01 2024/10/24 2.63UT FUJI -KISO



T20241024115709





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C298 2024/10/24 2.98UT TOYOKAWA-FUJI






T20241024115709





BLK:31,SNR1: 7.9898 ,SNR2: 58.003





3C298 2024/10/24 2.98UT TOYOKAWA-KISO



K20241024115707




BLK:31,SNR1: 1.2392 ,SNR2: 3.8079



FUJI





No.Good Data




Frequency (Hz)

K20241024115707




No.Good Data





Frequency (Hz)


3C298 2024/10/24 2.98UT FUJI -KISO



T20241024120853





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1428-03 2024/10/24 3.18UT TOYOKAWA-FUJI




T20241024120853




BLK:10,SNR1: 0.66821 ,SNR2: 2.1813




K20241024120851





BLK:10,SNR1: 1.1039 ,SNR2: 2.9185




1428-03 2024/10/24 3.18UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024120851




No.Good Data





Frequency (Hz)


1428-03 2024/10/24 3.18UT FUJI -KISO





T20241024121455




No.Good Data




FUJI





No.Good Data




1434+03 2024/10/24 3.28UT TOYOKAWA-FUJI



T20241024121455




BLK:13,SNR1: 0.13503 ,SNR2: 0.68157




Frequency (Hz)

K20241024121453




BLK:13,SNR1: 0.36749 ,SNR2: 1.5041





Frequency (Hz)


1434+03 2024/10/24 3.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024121453




No.Good Data





Frequency (Hz)

1434+03 2024/10/24 3.28UT FUJI -KISO






T20241024123357





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/10/24 3.59UT TOYOKAWA-FUJI





T20241024123357




BLK:14,SNR1: 70.590 ,SNR2: 80.953




K20241024123355





BLK:14,SNR1: 96.071 ,SNR2: 114.03




1453-10 2024/10/24 3.59UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024123355




No.Good Data





Frequency (Hz)


1453-10 2024/10/24 3.59UT FUJI -KISO



T20241024124850





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1508-05 2024/10/24 3.84UT TOYOKAWA-FUJI





T20241024124850




BLK:16,SNR1: 0.43543 ,SNR2: 2.6699




K20241024124847





BLK:16,SNR1: 0.42254 ,SNR2: 0.96994




1508-05 2024/10/24 3.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024124847




No.Good Data





Frequency (Hz)


1508-05 2024/10/24 3.84UT FUJI -KISO



T20241024125750





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/10/24 3.99UT TOYOKAWA-FUJI





T20241024125750




BLK:14,SNR1: 0.34422 ,SNR2: 5.5102




K20241024125748



BLK:14,SNR1: 1.3731 ,SNR2: 2.5190





3C318 2024/10/24 3.99UT TOYOKAWA-KISO






FUJI




No.Good Data




Frequency (Hz)

K20241024125748




No.Good Data






Frequency (Hz)




3C318 2024/10/24 3.99UT FUJI -KISO




T20241024130337





FUJI




1523+03 2024/10/24 4.09UT TOYOKAWA-FUJI





T20241024130337




BLK:13,SNR1: 103.83 ,SNR2: 117.08




K20241024130335




BLK:13,SNR1: 0.55379E-01,SNR2: 0.79780




1523+03 2024/10/24 4.09UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024130335




No.Good Data






Frequency (Hz)




1523+03 2024/10/24 4.09UT FUJI -KISO




T20241024131516





FUJI




1535+139 2024/10/24 4.28UT TOYOKAWA-FUJI





T20241024131516




BLK: 6,SNR1: 0.12730 ,SNR2: 1.9224




K20241024131514





BLK: 6,SNR1: 1.1604 ,SNR2: 5.1194




1535+139 2024/10/24 4.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024131514




No.Good Data






Frequency (Hz)




1535+139 2024/10/24 4.28UT FUJI -KISO




T20241024132822



FUJI





1548+05 2024/10/24 4.50UT TOYOKAWA-FUJI








T20241024132822




BLK: 6,SNR1: 0.68400E-01,SNR2: 1.2238




K20241024132819





BLK: 6,SNR1: 0.68284E-01,SNR2: 0.46229




1548+05 2024/10/24 4.50UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024132819




No.Good Data






Frequency (Hz)




1548+05 2024/10/24 4.50UT FUJI -KISO




T20241024134643





FUJI




1607+26 2024/10/24 4.81UT TOYOKAWA-FUJI





T20241024134643




BLK: 5,SNR1: 0.37219E-01,SNR2: 0.30515




K20241024134640





BLK: 5,SNR1: 0.68521 ,SNR2: 3.4091




1607+26 2024/10/24 4.81UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024134640




No.Good Data






Frequency (Hz)




1607+26 2024/10/24 4.81UT FUJI -KISO




T20241024140414







FUJI




1623-228 2024/10/24 5.10UT TOYOKAWA-FUJI








1623-228 2024/10/24 5.10UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024140412




No.Good Data






Frequency (Hz)

1623-228 2024/10/24 5.10UT FUJI -KISO









T20241024141244





FUJI




1631-222 2024/10/24 5.24UT TOYOKAWA-FUJI





T20241024141244




BLK: 8,SNR1: 0.97222 ,SNR2: 6.4863




K20241024141242





BLK: 8,SNR1: 0.28119 ,SNR2: 1.3543




1631-222 2024/10/24 5.24UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024141242




No.Good Data




Frequency (Hz)


1631-222 2024/10/24 5.24UT FUJI -KISO



T20241024141821





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1638-025 2024/10/24 5.33UT TOYOKAWA-FUJI





T20241024141821




BLK:10,SNR1: 0.14907 ,SNR2: 0.66201




K20241024141819





BLK:10,SNR1: 1.3561 ,SNR2: 3.7938




1638-025 2024/10/24 5.33UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024141819




No.Good Data






Frequency (Hz)




1638-025 2024/10/24 5.33UT FUJI -KISO




T20241024142516





FUJI




1644-106 2024/10/24 5.45UT TOYOKAWA-FUJI





T20241024142516




BLK: 9,SNR1: 0.22396 ,SNR2: 1.3696




K20241024142514



BLK: 9,SNR1: 0.78115 ,SNR2: 4.2093






1644-106 2024/10/24 5.45UT TOYOKAWA-KISO









FUJI




K20241024142514




1644-106 2024/10/24 5.45UT FUJI -KISO



T20241024143036





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1650+004 2024/10/24 5.54UT TOYOKAWA-FUJI




T20241024143036




BLK:10,SNR1: 0.70348 ,SNR2: 1.9747




K20241024143034





BLK:10,SNR1: 1.6631 ,SNR2: 5.1088




1650+004 2024/10/24 5.54UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024143034




No.Good Data





Frequency (Hz)


1650+004 2024/10/24 5.54UT FUJI -KISO



T20241024143608





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1656+053 2024/10/24 5.63UT TOYOKAWA-FUJI





T20241024143608




BLK: 6,SNR1: 100.28 ,SNR2: 128.85




K20241024143606





BLK: 6,SNR1: 82.494 ,SNR2: 85.882




1656+053 2024/10/24 5.63UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024143606




No.Good Data






Frequency (Hz)

1656+053 2024/10/24 5.63UT FUJI -KISO






T20241024145238




No.Good Data

FUJI





No.Good Data

1712-033 2024/10/24 5.91UT TOYOKAWA-FUJI






T20241024145238




BLK: 9,SNR1: 0.16721 ,SNR2: 1.3169




Frequency (Hz)

K20241024145236




BLK: 9,SNR1: 0.97184 ,SNR2: 1.9568






Frequency (Hz)




1712-033 2024/10/24 5.91UT TOYOKAWA-KISO




FUJI





K20241024145236




1712-033 2024/10/24 5.91UT FUJI -KISO



T20241024151040





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1730-13 2024/10/24 6.21UT TOYOKAWA-FUJI




T20241024151040




BLK: 2, SNR1: 0.58153E-01, SNR2: 1.7951




K20241024151038






BLK: 2, SNR1: 1.5146, SNR2: 4.7980






1730-13 2024/10/24 6.21UT TOYOKAWA-KISO




FUJI





K20241024151038




1730-13 2024/10/24 6.21UT FUJI -KISO



T20241024152805





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1748+031 2024/10/24 6.50UT TOYOKAWA-FUJI




T20241024152805




BLK: 3,SNR1: 0.12103 ,SNR2: 0.50113




K20241024152802






BLK: 3,SNR1: 0.49270 ,SNR2: 3.0395






1748+031 2024/10/24 6.50UT TOYOKAWA-KISO




FUJI



K20241024152802





1748+031 2024/10/24 6.50UT FUJI -KISO






T20241024153858





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1759+13 2024/10/24 6.68UT TOYOKAWA-FUJI





T20241024153858




BLK: 9,SNR1: 0.77129E-01,SNR2: 0.80326




K20241024153855





BLK: 9,SNR1: 52.827 ,SNR2: 77.794




1759+13 2024/10/24 6.68UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024153855




No.Good Data






Frequency (Hz)

1759+13 2024/10/24 6.68UT FUJI -KISO






T20241024155958




No.Good Data


FUJI





No.Good Data

1819-096 2024/10/24 7.03UT TOYOKAWA-FUJI







BLK: 8,SNR1: 0.84134 ,SNR2: 2.0857




BLK: 8,SNR1: 7.7646 ,SNR2: 22.730




1819-096 2024/10/24 7.03UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024155956




No.Good Data





Frequency (Hz)


1819-096 2024/10/24 7.03UT FUJI -KISO





T20241024161113




No.Good Data




FUJI





No.Good Data




1830-210 2024/10/24 7.22UT TOYOKAWA-FUJI



T20241024161113





BLK: 8,SNR1: 2.6545 ,SNR2: 6.3017




Frequency (Hz)

K20241024161111




BLK: 8,SNR1: 10.038 ,SNR2: 24.216





Frequency (Hz)

1830-210 2024/10/24 7.22UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241024161111




No.Good Data




Frequency (Hz)


1830-210 2024/10/24 7.22UT FUJI -KISO



T20241024163738





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1858+171 2024/10/24 7.66UT TOYOKAWA-FUJI



T20241024163738





BLK: 3,SNR1: 0.95057 ,SNR2: 3.1691




Frequency (Hz)

K20241024163736




BLK: 3,SNR1: 1.0474 ,SNR2: 4.1484





Frequency (Hz)


1858+171 2024/10/24 7.66UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024163736




No.Good Data





Frequency (Hz)


1858+171 2024/10/24 7.66UT FUJI -KISO



T20241024164823





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1908-20 2024/10/24 7.83UT TOYOKAWA-FUJI



T20241024164823





BLK: 6,SNR1: 0.15289 ,SNR2: 2.4967




Frequency (Hz)

K20241024164820




BLK: 6,SNR1: 0.69384 ,SNR2: 2.7785





Frequency (Hz)


1908-20 2024/10/24 7.83UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024164820




No.Good Data





Frequency (Hz)


1908-20 2024/10/24 7.83UT FUJI -KISO



T20241024165513





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1915-121 2024/10/24 7.95UT TOYOKAWA-FUJI






T20241024165513





BLK:10,SNR1: 9.4082 ,SNR2: 23.467




Frequency (Hz)

K20241024165510




BLK:10,SNR1: 10.876 ,SNR2: 27.186





Frequency (Hz)


1915-121 2024/10/24 7.95UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024165510




No.Good Data





Frequency (Hz)


1915-121 2024/10/24 7.95UT FUJI -KISO



T20241024170855





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1928-142 2024/10/24 8.18UT TOYOKAWA-FUJI



T20241024170855





BLK: 9, SNR1: 3.5134 , SNR2: 6.7495




Frequency (Hz)

K20241024170852




BLK: 9, SNR1: 4.0983 , SNR2: 17.200





Frequency (Hz)


1928-142 2024/10/24 8.18UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241024170852



No.Good Data



Frequency (Hz)

1928-142 2024/10/24 8.18UT FUJI -KISO

