






T20241025055006




No.Good Data




FUJI




No.Good Data




0812-184 2024/10/24 20.86UT TOYOKAWA-FUJI





T20241025055006




BLK: 2,SNR1:-0.13523 ,SNR2: 1.4901




K20241025055003





BLK: 2,SNR1: 0.38494 ,SNR2: 3.7527




0812-184 2024/10/24 20.86UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025055003




No.Good Data





Frequency (Hz)


0812-184 2024/10/24 20.86UT FUJI -KISO




T20241025055928




No.Good Data




FUJI



No.Good Data





0822-096 2024/10/24 21.02UT TOYOKAWA-FUJI






T20241025055928





BLK: 5, SNR1: 2.6792 ,SNR2: 6.9371




Frequency (Hz)

K20241025055926




BLK: 5, SNR1: 9.7123 ,SNR2: 22.872





Frequency (Hz)


0822-096 2024/10/24 21.02UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025055926




No.Good Data




Frequency (Hz)


0822-096 2024/10/24 21.02UT FUJI -KISO





T20241025060726




No.Good Data




FUJI





No.Good Data




0830-118 2024/10/24 21.15UT TOYOKAWA-FUJI



T20241025060726





BLK: 8,SNR1: 10.151 ,SNR2: 109.05




Frequency (Hz)

K20241025060724




BLK: 8,SNR1: 4.4893 ,SNR2: 7.8745





Frequency (Hz)


0830-118 2024/10/24 21.15UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025060724




No.Good Data




Frequency (Hz)


0830-118 2024/10/24 21.15UT FUJI -KISO



T20241025061204





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0834-19 2024/10/24 21.23UT TOYOKAWA-FUJI



T20241025061204





No.Good Data




Frequency (Hz)

K20241025061202




No.Good Data




Frequency (Hz)


0834-19 2024/10/24 21.23UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025061202




No.Good Data




Frequency (Hz)

0834-19 2024/10/24 21.23UT FUJI -KISO






T20241025061709




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0839-071 2024/10/24 21.31UT TOYOKAWA-FUJI



T20241025061709





BLK: 4, SNR1: 0.66263 ,SNR2: 8.4524




Frequency (Hz)

K20241025061706




BLK: 4, SNR1: 0.11548 ,SNR2: 1.5814




Frequency (Hz)


0839-071 2024/10/24 21.31UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025061706




No.Good Data





Frequency (Hz)


0839-071 2024/10/24 21.31UT FUJI -KISO




T20241025062810




No.Good Data




FUJI





No.Good Data




3C208 2024/10/24 21.50UT TOYOKAWA-FUJI





T20241025062810




BLK: 2,SNR1: 0.13100 ,SNR2: 0.48819




K20241025062808




BLK: 2,SNR1: 9.6935 ,SNR2: 20.437




3C208 2024/10/24 21.50UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025062808




No.Good Data





Frequency (Hz)


3C208 2024/10/24 21.50UT FUJI -KISO





T20241025064936




No.Good Data




FUJI




No.Good Data




0912-132 2024/10/24 21.85UT TOYOKAWA-FUJI



T20241025064936





BLK: 1,SNR1:-0.78976E-01,SNR2: 0.53993





0912-132 2024/10/24 21.85UT TOYOKAWA-KISO

K20241025064934





BLK: 1,SNR1: 0.31555 ,SNR2: 6.4708






FUJI





No.Good Data




Frequency (Hz)

K20241025064934




No.Good Data





Frequency (Hz)


0912-132 2024/10/24 21.85UT FUJI -KISO



T20241025065703





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0919-142 2024/10/24 21.98UT TOYOKAWA-FUJI



T20241025065703





BLK: 5,SNR1: 1.2822 ,SNR2: 19.766




Frequency (Hz)

0919-142 2024/10/24 21.98UT TOYOKAWA-KISO


K20241025065700





BLK: 5,SNR1: 1.5188 ,SNR2: 12.829




Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20241025065700




No.Good Data





Frequency (Hz)


0919-142 2024/10/24 21.98UT FUJI -KISO





T20241025071127




No.Good Data




FUJI





No.Good Data




3C222 2024/10/24 22.22UT TOYOKAWA-FUJI





T20241025071127




BLK: 2,SNR1: 0.19525 ,SNR2: 1.3074




K20241025071125





BLK: 2,SNR1: 1.0442 ,SNR2: 7.7433




3C222 2024/10/24 22.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025071125




No.Good Data





Frequency (Hz)


3C222 2024/10/24 22.22UT FUJI -KISO





T20241025071827




No.Good Data




FUJI



No.Good Data





0941-08 2024/10/24 22.34UT TOYOKAWA-FUJI






T20241025071827





BLK: 4,SNR1: 0.35217 ,SNR2: 7.1407




Frequency (Hz)

0941-08 2024/10/24 22.34UT TOYOKAWA-KISO


K20241025071825





BLK: 4,SNR1: 11.504 ,SNR2: 20.262




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241025071825




No.Good Data





Frequency (Hz)


0941-08 2024/10/24 22.34UT FUJI -KISO





T20241025072649




No.Good Data




FUJI





No.Good Data




3C230 2024/10/24 22.48UT TOYOKAWA-FUJI



T20241025072649




BLK: 3,SNR1: 7.1753 ,SNR2: 16.902




Frequency (Hz)

3C230 2024/10/24 22.48UT TOYOKAWA-KISO


K20241025072646





BLK: 3,SNR1: 8.6515 ,SNR2: 18.615




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241025072646




No.Good Data





Frequency (Hz)


3C230 2024/10/24 22.48UT FUJI -KISO



T20241025074249





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C237 2024/10/24 22.74UT TOYOKAWA-FUJI





T20241025074249




BLK: 8,SNR1: 13.697 ,SNR2: 30.615




K20241025074247





BLK: 8,SNR1: 13.891 ,SNR2: 31.059




3C237 2024/10/24 22.74UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025074247




No.Good Data





Frequency (Hz)

3C237 2024/10/24 22.74UT FUJI -KISO








T20241025074906




No.Good Data




FUJI





No.Good Data




1011+110 2024/10/24 22.85UT TOYOKAWA-FUJI



T20241025074906





No. Good Data




Frequency (Hz)

K20241025074904




No. Good Data





Frequency (Hz)


1011+110 2024/10/24 22.85UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025074904




No.Good Data





Frequency (Hz)


1011+110 2024/10/24 22.85UT FUJI -KISO





T20241025075647




No.Good Data




FUJI





No.Good Data




3C241 2024/10/24 22.97UT TOYOKAWA-FUJI



T20241025075647





BLK: 3,SNR1: 0.22026 ,SNR2: 1.1781




Frequency (Hz)

3C241 2024/10/24 22.97UT TOYOKAWA-KISO


K20241025075644





BLK: 3,SNR1: 2.2260 ,SNR2: 7.1345




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241025075644




No.Good Data





Frequency (Hz)


3C241 2024/10/24 22.97UT FUJI -KISO





T20241025080816




No.Good Data




FUJI





No.Good Data




1031-11 2024/10/24 23.17UT TOYOKAWA-FUJI



T20241025080816





BLK: 2,SNR1: 112.14 ,SNR2: 128.67




Frequency (Hz)

1031-11 2024/10/24 23.17UT TOYOKAWA-KISO


K20241025080813



BLK: 2,SNR1: 0.24737 ,SNR2: 0.79594





Frequency (Hz)






FUJI





No.Good Data




Frequency (Hz)

K20241025080813




No.Good Data





Frequency (Hz)


1031-11 2024/10/24 23.17UT FUJI -KISO





T20241025081250




No.Good Data




FUJI





No.Good Data




1035-058 2024/10/24 23.24UT TOYOKAWA-FUJI



T20241025081250





BLK: 8,SNR1: 25.576 ,SNR2: 39.256




Frequency (Hz)

K20241025081247




BLK: 8,SNR1: 5.6611 ,SNR2: 12.898





Frequency (Hz)


1035-058 2024/10/24 23.24UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241025081247





No.Good Data




1035-058 2024/10/24 23.24UT FUJI -KISO





T20241025082202




No.Good Data




FUJI




No.Good Data




1044-008 2024/10/24 23.40UT TOYOKAWA-FUJI



T20241025082202





BLK: 3, SNR1: 2.3680 , SNR2: 8.2619





1044-008 2024/10/24 23.40UT TOYOKAWA-KISO


K20241025082159




BLK: 3, SNR1: 6.1234 , SNR2: 15.807



FUJI





No.Good Data




Frequency (Hz)

K20241025082159




No.Good Data





Frequency (Hz)


1044-008 2024/10/24 23.40UT FUJI -KISO





T20241025083307




No.Good Data




FUJI



No.Good Data




1055+01 2024/10/24 23.58UT TOYOKAWA-FUJI







T20241025083307




BLK: 5, SNR1: 0.59963 , SNR2: 1.7502




K20241025083304





BLK: 5, SNR1: 2.5927 , SNR2: 4.3380




1055+01 2024/10/24 23.58UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025083304




No.Good Data





Frequency (Hz)


1055+01 2024/10/24 23.58UT FUJI -KISO





T20241025084424




No.Good Data




FUJI




No.Good Data




1107+109 2024/10/24 23.77UT TOYOKAWA-FUJI



T20241025084424





BLK: 8, SNR1: 4.0017 , SNR2: 8.9682





1107+109 2024/10/24 23.77UT TOYOKAWA-KISO



K20241025084421




BLK: 8, SNR1: 6.4183 , SNR2: 17.641





FUJI




No. Good Data




K20241025084421





No. Good Data




1107+109 2024/10/24 23.77UT FUJI -KISO



T20241025085402





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C255 2024/10/24 23.93UT TOYOKAWA-FUJI



T20241025085402




BLK:13,SNR1: 1.0127 ,SNR2: 1.9621





3C255 2024/10/24 23.93UT TOYOKAWA-KISO



K20241025085359




BLK:13,SNR1: 3.0844 ,SNR2: 7.8731



FUJI





No. Good Data




Frequency (Hz)

K20241025085359




No. Good Data




Frequency (Hz)

3C255 2024/10/24 23.93UT FUJI -KISO








T20241025090439




No. Good Data




FUJI




No. Good Data




1127-14 2024/10/25 0.11UT TOYOKAWA-FUJI



T20241025090439




BLK:11,SNR1: 0.29385 ,SNR2: 3.3395





1127-14 2024/10/25 0.11UT TOYOKAWA-KISO



K20241025090436




BLK:11,SNR1: 8.8705 ,SNR2: 23.869



FUJI





No. Good Data




Frequency (Hz)

K20241025090436




No. Good Data





Frequency (Hz)


1127-14 2024/10/25 0.11UT FUJI -KISO



T20241025091800





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


3C263.1 2024/10/25 0.33UT TOYOKAWA-FUJI



T20241025091800





BLK: 9,SNR1: 8.0602 ,SNR2: 23.358





3C263.1 2024/10/25 0.33UT TOYOKAWA-KISO



K20241025091757




BLK: 9,SNR1: 6.5652 ,SNR2: 18.781



FUJI





No. Good Data




Frequency (Hz)

K20241025091757




No. Good Data





Frequency (Hz)


3C263.1 2024/10/25 0.33UT FUJI -KISO



T20241025092427





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C267 2024/10/25 0.44UT TOYOKAWA-FUJI





T20241025092427




BLK: 6,SNR1: 0.10124 ,SNR2: 0.64512




K20241025092424



BLK: 6,SNR1: 0.53891 ,SNR2: 2.4484





3C267 2024/10/25 0.44UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241025092424




No. Good Data





Frequency (Hz)


3C267 2024/10/25 0.44UT FUJI -KISO



T20241025095014





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1213-17 2024/10/25 0.87UT TOYOKAWA-FUJI



T20241025095014





BLK:13,SNR1: 0.19250 ,SNR2: 1.8227




1213-17 2024/10/25 0.87UT TOYOKAWA-KISO


K20241025095011





BLK:13,SNR1: 2.8171 ,SNR2: 7.8094




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241025095011




No.Good Data





Frequency (Hz)


1213-17 2024/10/25 0.87UT FUJI -KISO





T20241025100332




No. Good Data




FUJI




No. Good Data




3C273 2024/10/25 1.09UT TOYOKAWA-FUJI



T20241025100332





BLK:23,SNR1: 16.218 ,SNR2: 27.787





3C273 2024/10/25 1.09UT TOYOKAWA-KISO



K20241025100329




BLK:23,SNR1: 10.943 ,SNR2: 18.583



FUJI





No.Good Data




Frequency (Hz)

K20241025100329




No.Good Data





Frequency (Hz)


3C273 2024/10/25 1.09UT FUJI -KISO



T20241025101642





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C275 2024/10/25 1.31UT TOYOKAWA-FUJI






T20241025101642





BLK:18,SNR1: 5.7613 ,SNR2: 13.221





3C275 2024/10/25 1.31UT TOYOKAWA-KISO



K20241025101639




BLK:18,SNR1: 9.9614 ,SNR2: 25.371



FUJI





No.Good Data




Frequency (Hz)

K20241025101639




No.Good Data





Frequency (Hz)


3C275 2024/10/25 1.31UT FUJI -KISO



T20241025102247





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1245-19 2024/10/25 1.41UT TOYOKAWA-FUJI








1245-19 2024/10/25 1.41UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025102244




No.Good Data





Frequency (Hz)


1245-19 2024/10/25 1.41UT FUJI -KISO





T20241025103031




No.Good Data




FUJI




No.Good Data




3C279 2024/10/25 1.54UT TOYOKAWA-FUJI





T20241025103031




BLK:18,SNR1: 3.4578 ,SNR2: 8.9669




K20241025103028





BLK:18,SNR1: 3.3767 ,SNR2: 9.8564




3C279 2024/10/25 1.54UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025103028




No.Good Data





Frequency (Hz)

3C279 2024/10/25 1.54UT FUJI -KISO






T20241025104600





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C283 2024/10/25 1.79UT TOYOKAWA-FUJI



T20241025104600





BLK:38,SNR1: 3.8568 ,SNR2: 25.710





3C283 2024/10/25 1.79UT TOYOKAWA-KISO



K20241025104557




BLK:38,SNR1: 2.7675 ,SNR2: 9.3608



FUJI





No.Good Data




Frequency (Hz)

K20241025104557




No.Good Data





Frequency (Hz)


3C283 2024/10/25 1.79UT FUJI -KISO



T20241025110025





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1323+32 2024/10/25 2.04UT TOYOKAWA-FUJI



T20241025110025





BLK:18,SNR1: 1.1725 ,SNR2: 3.5998




Frequency (Hz)

1323+32 2024/10/25 2.04UT TOYOKAWA-KISO


K20241025110022





BLK:18,SNR1: 10.912 ,SNR2: 12.776




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241025110022




No. Good Data





Frequency (Hz)


1323+32 2024/10/25 2.04UT FUJI -KISO





T20241025110515




No.Good Data




FUJI




No.Good Data




3C286 2024/10/25 2.12UT TOYOKAWA-FUJI



T20241025110515





BLK:31,SNR1: 2.1703 ,SNR2: 16.382





3C286 2024/10/25 2.12UT TOYOKAWA-KISO

K20241025110512





BLK:31,SNR1: 0.82311 ,SNR2: 2.2398






FUJI





No. Good Data




Frequency (Hz)

K20241025110512




No. Good Data





Frequency (Hz)


3C286 2024/10/25 2.12UT FUJI -KISO



T20241025112142





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1345+12 2024/10/25 2.39UT TOYOKAWA-FUJI



T20241025112142




BLK:24,SNR1: 2.0339 ,SNR2: 10.889





1345+12 2024/10/25 2.39UT TOYOKAWA-KISO



K20241025112140




BLK:24,SNR1: 0.82863 ,SNR2: 1.6713



FUJI





No.Good Data




Frequency (Hz)

K20241025112140




No.Good Data





Frequency (Hz)


1345+12 2024/10/25 2.39UT FUJI -KISO



T20241025113203





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1355+01 2024/10/25 2.56UT TOYOKAWA-FUJI




T20241025113203




BLK:23,SNR1: 228.07 ,SNR2: 323.75




K20241025113201





BLK:23,SNR1: 9.7422 ,SNR2: 19.126




1355+01 2024/10/25 2.56UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025113201




No.Good Data





Frequency (Hz)


1355+01 2024/10/25 2.56UT FUJI -KISO



T20241025115314





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C298 2024/10/25 2.92UT TOYOKAWA-FUJI






T20241025115314





BLK:35,SNR1: 8.9244 ,SNR2: 27.981





3C298 2024/10/25 2.92UT TOYOKAWA-KISO



K20241025115311




BLK:35,SNR1: 1.1225 ,SNR2: 5.1921



FUJI





No.Good Data




Frequency (Hz)

K20241025115311




No.Good Data





Frequency (Hz)


3C298 2024/10/25 2.92UT FUJI -KISO



T20241025120457





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1428-03 2024/10/25 3.11UT TOYOKAWA-FUJI




T20241025120457




BLK:12,SNR1: 0.78879 ,SNR2: 2.7792




K20241025120455





BLK:12,SNR1: 0.39658 ,SNR2: 2.9705




1428-03 2024/10/25 3.11UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025120455




No.Good Data





Frequency (Hz)


1428-03 2024/10/25 3.11UT FUJI -KISO



T20241025121059





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1434+03 2024/10/25 3.21UT TOYOKAWA-FUJI





T20241025121059




BLK: 8,SNR1: 0.26151 ,SNR2: 1.7740




K20241025121057




BLK: 8,SNR1: 0.72667 ,SNR2: 1.9933




1434+03 2024/10/25 3.21UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241025121057




No.Good Data





Frequency (Hz)

1434+03 2024/10/25 3.21UT FUJI -KISO






T20241025123002





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1453-10 2024/10/25 3.53UT TOYOKAWA-FUJI




T20241025123002




BLK:18,SNR1: 1.7714 ,SNR2: 4.0674




K20241025123000





BLK:18,SNR1: 23.705 ,SNR2: 27.342




1453-10 2024/10/25 3.53UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025123000




No.Good Data





Frequency (Hz)


1453-10 2024/10/25 3.53UT FUJI -KISO



T20241025124454





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1508-05 2024/10/25 3.78UT TOYOKAWA-FUJI





T20241025124454




BLK:14,SNR1: 45.888 ,SNR2: 65.073




K20241025124451




BLK:14,SNR1: 0.39207 ,SNR2: 1.2804




1508-05 2024/10/25 3.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025124451




No.Good Data





Frequency (Hz)


1508-05 2024/10/25 3.78UT FUJI -KISO



T20241025125354





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/10/25 3.93UT TOYOKAWA-FUJI





T20241025125354




BLK:22,SNR1: 0.28654 ,SNR2: 1.0949




K20241025125352



BLK:22,SNR1: 0.11510 ,SNR2: 0.80796





3C318 2024/10/25 3.93UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241025125352




No.Good Data






Frequency (Hz)




3C318 2024/10/25 3.93UT FUJI -KISO




T20241025125941







FUJI




1523+03 2024/10/25 4.02UT TOYOKAWA-FUJI







1523+03 2024/10/25 4.02UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025125939




No.Good Data






Frequency (Hz)




1523+03 2024/10/25 4.02UT FUJI -KISO




T20241025131120





FUJI




1535+139 2024/10/25 4.22UT TOYOKAWA-FUJI





T20241025131120




BLK: 4,SNR1: 0.15491 ,SNR2: 1.1101




K20241025131117





BLK: 4,SNR1: 2.6277 ,SNR2: 5.4069




1535+139 2024/10/25 4.22UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025131117




No.Good Data




Frequency (Hz)


1535+139 2024/10/25 4.22UT FUJI -KISO



T20241025132426





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1548+05 2024/10/25 4.44UT TOYOKAWA-FUJI






T20241025132426





BLK: 3,SNR1: 0.24288 ,SNR2: 0.68789




Frequency (Hz)

K20241025132423




BLK: 3,SNR1: 0.78897 ,SNR2: 5.3999





Frequency (Hz)


1548+05 2024/10/25 4.44UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025132423




No.Good Data





Frequency (Hz)


1548+05 2024/10/25 4.44UT FUJI -KISO



T20241025134248




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1607+26 2024/10/25 4.74UT TOYOKAWA-FUJI





T20241025134248




BLK: 2,SNR1:-0.17079E-01,SNR2: 0.22901




K20241025134245





BLK: 2,SNR1: 0.74672 ,SNR2: 2.6510




1607+26 2024/10/25 4.74UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025134245




No.Good Data





Frequency (Hz)


1607+26 2024/10/25 4.74UT FUJI -KISO



T20241025140018





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1623-228 2024/10/25 5.03UT TOYOKAWA-FUJI





T20241025140018




BLK:12,SNR1: 0.65185 ,SNR2: 5.5659




K20241025140016





BLK:12,SNR1: 0.22853 ,SNR2: 2.2111




1623-228 2024/10/25 5.03UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025140016




No.Good Data






Frequency (Hz)

1623-228 2024/10/25 5.03UT FUJI -KISO









T20241025140848




FUJI




1631-222 2024/10/25 5.17UT TOYOKAWA-FUJI





T20241025140848




BLK:15,SNR1: 1.0878 ,SNR2: 7.7818




K20241025140845





BLK:15,SNR1: 1.0374 ,SNR2: 4.3489




1631-222 2024/10/25 5.17UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025140845




No.Good Data






Frequency (Hz)




1631-222 2024/10/25 5.17UT FUJI -KISO




T20241025141425





FUJI




1638-025 2024/10/25 5.27UT TOYOKAWA-FUJI




T20241025141425




BLK:19,SNR1: 0.24164 ,SNR2: 2.3737




K20241025141422





BLK:19,SNR1: 3.8992 ,SNR2: 10.966




1638-025 2024/10/25 5.27UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025141422




No.Good Data




Frequency (Hz)


1638-025 2024/10/25 5.27UT FUJI -KISO



T20241025142120




No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1644-106 2024/10/25 5.38UT TOYOKAWA-FUJI





T20241025142120




BLK: 5,SNR1: 0.54094 ,SNR2: 5.7762




K20241025142117



BLK: 5,SNR1: 0.41707 ,SNR2: 3.6073





1644-106 2024/10/25 5.38UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241025142117




No.Good Data






Frequency (Hz)

1644-106 2024/10/25 5.38UT FUJI -KISO






T20241025142640




No.Good Data

FUJI






No.Good Data



1650+004 2024/10/25 5.47UT TOYOKAWA-FUJI




T20241025142640





K20241025142637




1650+004 2024/10/25 5.47UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025142637




No.Good Data






Frequency (Hz)




1650+004 2024/10/25 5.47UT FUJI -KISO




T20241025143212





FUJI




1656+053 2024/10/25 5.56UT TOYOKAWA-FUJI





T20241025143212




BLK: 6,SNR1: 0.10199 ,SNR2: 0.56623




K20241025143209






BLK: 6,SNR1: 0.23567 ,SNR2: 0.74308






1656+053 2024/10/25 5.56UT TOYOKAWA-KISO




FUJI






K20241025143209






1656+053 2024/10/25 5.56UT FUJI -KISO




T20241025144842



FUJI





1712-033 2024/10/25 5.84UT TOYOKAWA-FUJI







T20241025144842




BLK: 4,SNR1: 0.34428 ,SNR2: 3.0440




K20241025144840





BLK: 4,SNR1: 6.4720 ,SNR2: 15.571




1712-033 2024/10/25 5.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025144840




No.Good Data






Frequency (Hz)




1712-033 2024/10/25 5.84UT FUJI -KISO




T20241025150644





FUJI




1730-13 2024/10/25 6.14UT TOYOKAWA-FUJI





T20241025150644




BLK: 7,SNR1: 0.63874 ,SNR2: 2.5685




K20241025150641






BLK: 7,SNR1: 1.2125 ,SNR2: 2.8842






1730-13 2024/10/25 6.14UT TOYOKAWA-KISO




FUJI






K20241025150641






1730-13 2024/10/25 6.14UT FUJI -KISO




T20241025152409




FUJI




1748+031 2024/10/25 6.43UT TOYOKAWA-FUJI



T20241025152409





BLK:14,SNR1: 4.2690 ,SNR2: 18.712




Frequency (Hz)

K20241025152407




BLK:14,SNR1: 4.2186 ,SNR2: 12.193






Frequency (Hz)




1748+031 2024/10/25 6.43UT TOYOKAWA-KISO




FUJI



K20241025152407





1748+031 2024/10/25 6.43UT FUJI -KISO






T20241025153502





No.Good Data




Frequency (Hz)

FUJI





No.Good Data





Frequency (Hz)

1759+13 2024/10/25 6.61UT TOYOKAWA-FUJI







BLK:13,SNR1: 1.2876 ,SNR2: 4.0935






BLK:13,SNR1: 3.5554 ,SNR2: 10.186






1759+13 2024/10/25 6.61UT TOYOKAWA-KISO




FUJI





K20241025153459




1759+13 2024/10/25 6.61UT FUJI -KISO





T20241025155602




No.Good Data




FUJI




No.Good Data




1819-096 2024/10/25 6.96UT TOYOKAWA-FUJI



T20241025155602




BLK: 3,SNR1: 0.96483 ,SNR2: 2.3954




Frequency (Hz)

K20241025155600




BLK: 3,SNR1: 13.647 ,SNR2: 33.475






Frequency (Hz)




1819-096 2024/10/25 6.96UT TOYOKAWA-KISO




FUJI






K20241025155600






1819-096 2024/10/25 6.96UT FUJI -KISO




T20241025160717




FUJI




1830-210 2024/10/25 7.15UT TOYOKAWA-FUJI



T20241025160717




BLK: 7,SNR1: 7.9656 ,SNR2: 24.468




Frequency (Hz)

K20241025160714




BLK: 7,SNR1: 8.8011 ,SNR2: 22.880





Frequency (Hz)

1830-210 2024/10/25 7.15UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241025160714




No.Good Data




Frequency (Hz)


1830-210 2024/10/25 7.15UT FUJI -KISO



T20241025163342





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1858+171 2024/10/25 7.59UT TOYOKAWA-FUJI





T20241025163342




BLK: 4,SNR1:-0.53609E-02,SNR2: 0.39118




K20241025163340





BLK: 4,SNR1: 0.39453 ,SNR2: 2.4669




1858+171 2024/10/25 7.59UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241025163340




No.Good Data





Frequency (Hz)


1858+171 2024/10/25 7.59UT FUJI -KISO



T20241025164427





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1908-20 2024/10/25 7.77UT TOYOKAWA-FUJI





T20241025164427




BLK:13,SNR1: 3.1435 ,SNR2: 6.0957




K20241025164424





BLK:13,SNR1: 8.8777 ,SNR2: 27.270




1908-20 2024/10/25 7.77UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025164424




No.Good Data





Frequency (Hz)


1908-20 2024/10/25 7.77UT FUJI -KISO



T20241025165117





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1915-121 2024/10/25 7.88UT TOYOKAWA-FUJI






T20241025165117




BLK: 5, SNR1: 10.383 , SNR2: 26.474




Frequency (Hz)

K20241025165115




BLK: 5, SNR1: 9.3598 , SNR2: 23.621





Frequency (Hz)


1915-121 2024/10/25 7.88UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025165115




No.Good Data





Frequency (Hz)


1915-121 2024/10/25 7.88UT FUJI -KISO



T20241025170459





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1928-142 2024/10/25 8.11UT TOYOKAWA-FUJI



T20241025170459





BLK: 7, SNR1: 7.6553 , SNR2: 22.749




Frequency (Hz)

K20241025170457




BLK: 7, SNR1: 10.141 , SNR2: 30.685





Frequency (Hz)


1928-142 2024/10/25 8.11UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241025170457



No.Good Data



Frequency (Hz)

1928-142 2024/10/25 8.11UT FUJI -KISO

