




T20241028055538





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0830-118 2024/10/27 20.96UT TOYOKAWA-FUJI



T20241028055538





BLK: 6,SNR1: 10.821 ,SNR2: 27.443




Frequency (Hz)

K20241028055536




BLK: 6,SNR1: 18.179 ,SNR2: 30.086





Frequency (Hz)


0830-118 2024/10/27 20.96UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028055536




No.Good Data





Frequency (Hz)


0830-118 2024/10/27 20.96UT FUJI -KISO



T20241028060016





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)



0834-19 2024/10/27 21.03UT TOYOKAWA-FUJI









BLK: 8, SNR1: 20.403 , SNR2: 30.485





BLK: 8, SNR1: 21.039 , SNR2: 32.024




0834-19 2024/10/27 21.03UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028060014




No.Good Data




Frequency (Hz)


0834-19 2024/10/27 21.03UT FUJI -KISO



T20241028060522





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0839-071 2024/10/27 21.12UT TOYOKAWA-FUJI



T20241028060522




BLK: 6,SNR1: 5.0454 ,SNR2: 26.136





0839-071 2024/10/27 21.12UT TOYOKAWA-KISO


K20241028060520




BLK: 6,SNR1: 6.3707 ,SNR2: 12.781



FUJI





No.Good Data




Frequency (Hz)

K20241028060520




No.Good Data




Frequency (Hz)


0839-071 2024/10/27 21.12UT FUJI -KISO



T20241028062243





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


0857-191 2024/10/27 21.41UT TOYOKAWA-FUJI



T20241028062243




BLK: 6,SNR1: 0.25691 ,SNR2: 2.3962




Frequency (Hz)

K20241028062241




BLK: 6,SNR1: 0.56306 ,SNR2: 5.8093





Frequency (Hz)


0857-191 2024/10/27 21.41UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241028062241




No.Good Data




Frequency (Hz)

0857-191 2024/10/27 21.41UT FUJI -KISO







T20241028063748




No.Good Data




FUJI





No.Good Data




0912-132 2024/10/27 21.66UT TOYOKAWA-FUJI



T20241028063748





BLK: 2,SNR1: 0.25876 ,SNR2: 0.51663




Frequency (Hz)

K20241028063745




BLK: 2,SNR1: 1.6755 ,SNR2: 6.0552




Frequency (Hz)


0912-132 2024/10/27 21.66UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028063745




No.Good Data





Frequency (Hz)


0912-132 2024/10/27 21.66UT FUJI -KISO





T20241028064516




No.Good Data




FUJI





No.Good Data




0919-142 2024/10/27 21.78UT TOYOKAWA-FUJI



T20241028064516





BLK: 5, SNR1: 0.52303 , SNR2: 12.268




Frequency (Hz)

0919-142 2024/10/27 21.78UT TOYOKAWA-KISO


K20241028064513





BLK: 5, SNR1: 12.262 , SNR2: 21.242




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241028064513




No.Good Data





Frequency (Hz)


0919-142 2024/10/27 21.78UT FUJI -KISO




T20241028065939




No.Good Data




FUJI



No.Good Data





3C222 2024/10/27 22.02UT TOYOKAWA-FUJI








FUJI





No.Good Data




Frequency (Hz)

K20241028065936




No.Good Data





Frequency (Hz)


3C222 2024/10/27 22.02UT FUJI -KISO





T20241028070639




No.Good Data




FUJI





No.Good Data




0941-08 2024/10/27 22.14UT TOYOKAWA-FUJI



T20241028070639





BLK: 4,SNR1: 24.537 ,SNR2: 37.829




Frequency (Hz)

0941-08 2024/10/27 22.14UT TOYOKAWA-KISO


K20241028070637





BLK: 4,SNR1: 1.5300 ,SNR2: 13.144




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241028070637




No.Good Data





Frequency (Hz)


0941-08 2024/10/27 22.14UT FUJI -KISO





T20241028071501




No.Good Data




FUJI





No.Good Data




3C230 2024/10/27 22.28UT TOYOKAWA-FUJI



T20241028071501





BLK: 5, SNR1: 9.1659 ,SNR2: 15.659




Frequency (Hz)

K20241028071459




BLK: 5, SNR1: 2.2339 ,SNR2: 5.5936





Frequency (Hz)


3C230 2024/10/27 22.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028071459




No.Good Data





Frequency (Hz)


3C230 2024/10/27 22.28UT FUJI -KISO



T20241028073102





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)

3C237 2024/10/27 22.55UT TOYOKAWA-FUJI






T20241028073102




BLK: 4,SNR1: 24.330 ,SNR2: 50.092




Frequency (Hz)

3C237 2024/10/27 22.55UT TOYOKAWA-KISO


K20241028073100





BLK: 4,SNR1: 5.7451 ,SNR2: 10.256




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241028073100




No.Good Data





Frequency (Hz)


3C237 2024/10/27 22.55UT FUJI -KISO



T20241028073718





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1011+110 2024/10/27 22.65UT TOYOKAWA-FUJI





T20241028073718




No.Good Data




K20241028073716





No.Good Data




1011+110 2024/10/27 22.65UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028073716




No.Good Data





Frequency (Hz)


1011+110 2024/10/27 22.65UT FUJI -KISO





T20241028074459




No.Good Data




FUJI




No.Good Data





3C241 2024/10/27 22.78UT TOYOKAWA-FUJI







BLK: 2,SNR1: 0.33933 ,SNR2: 1.0666





BLK: 2,SNR1: 0.63094E-01,SNR2: 0.78285




3C241 2024/10/27 22.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028074457




No.Good Data





Frequency (Hz)

3C241 2024/10/27 22.78UT FUJI -KISO








T20241028075628




No.Good Data




FUJI




No.Good Data




1031-11 2024/10/27 22.97UT TOYOKAWA-FUJI



T20241028075628




BLK:10,SNR1: 3.5873 ,SNR2: 15.445





1031-11 2024/10/27 22.97UT TOYOKAWA-KISO



K20241028075625




BLK:10,SNR1: 1.3738 ,SNR2: 3.5780



FUJI





No. Good Data




Frequency (Hz)

K20241028075625




No. Good Data





Frequency (Hz)


1031-11 2024/10/27 22.97UT FUJI -KISO





T20241028080102




No.Good Data




FUJI





No.Good Data




1035-058 2024/10/27 23.05UT TOYOKAWA-FUJI



T20241028080102





BLK: 4,SNR1: 6.5422 ,SNR2: 19.224




Frequency (Hz)

K20241028080100




BLK: 4,SNR1: 17.542 ,SNR2: 41.985





Frequency (Hz)


1035-058 2024/10/27 23.05UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241028080100




No. Good Data





Frequency (Hz)


1035-058 2024/10/27 23.05UT FUJI -KISO





T20241028081014




No.Good Data




FUJI





No.Good Data




1044-008 2024/10/27 23.20UT TOYOKAWA-FUJI





T20241028081014




BLK: 4,SNR1: 1.5307 ,SNR2: 3.8739




K20241028081012



BLK: 4,SNR1: 1.8601 ,SNR2: 4.9611





1044-008 2024/10/27 23.20UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241028081012




No.Good Data





Frequency (Hz)


1044-008 2024/10/27 23.20UT FUJI -KISO





T20241028082119




No.Good Data




FUJI





No.Good Data




1055+01 2024/10/27 23.38UT TOYOKAWA-FUJI



T20241028082119





BLK:12,SNR1: 8.0665 ,SNR2: 22.383





1055+01 2024/10/27 23.38UT TOYOKAWA-KISO



K20241028082117




BLK:12,SNR1: 10.921 ,SNR2: 21.773



FUJI





No.Good Data




Frequency (Hz)

K20241028082117




No.Good Data





Frequency (Hz)


1055+01 2024/10/27 23.38UT FUJI -KISO





T20241028083237




No.Good Data




FUJI




No.Good Data




1107+109 2024/10/27 23.57UT TOYOKAWA-FUJI



T20241028083237




BLK: 3, SNR1: 0.43198 , SNR2: 1.5220





1107+109 2024/10/27 23.57UT TOYOKAWA-KISO


K20241028083235




BLK: 3, SNR1: 2.1660 , SNR2: 5.7461




FUJI




No.Good Data




K20241028083235





No.Good Data




1107+109 2024/10/27 23.57UT FUJI -KISO





T20241028084214




No.Good Data




FUJI



No.Good Data




3C255 2024/10/27 23.73UT TOYOKAWA-FUJI







T20241028084214




BLK:13,SNR1: 1.0821 ,SNR2: 6.1235




K20241028084212




BLK:13,SNR1: 0.55431 ,SNR2: 1.1233




3C255 2024/10/27 23.73UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028084212




No.Good Data





Frequency (Hz)


3C255 2024/10/27 23.73UT FUJI -KISO





T20241028085252




No.Good Data




FUJI




No.Good Data




1127-14 2024/10/27 23.91UT TOYOKAWA-FUJI



T20241028085252





BLK:14,SNR1: 3.8535 ,SNR2: 16.231





1127-14 2024/10/27 23.91UT TOYOKAWA-KISO



K20241028085250




BLK:14,SNR1: 3.7017 ,SNR2: 10.315





FUJI




No. Good Data




K20241028085250





No. Good Data




1127-14 2024/10/27 23.91UT FUJI -KISO





T20241028090612




No.Good Data




FUJI





No.Good Data




3C263.1 2024/10/28 0.13UT TOYOKAWA-FUJI



T20241028090612





BLK: 9,SNR1: 4.5629 ,SNR2: 15.318




Frequency (Hz)

3C263.1 2024/10/28 0.13UT TOYOKAWA-KISO


K20241028090610





BLK: 9,SNR1: 1.2070 ,SNR2: 3.6794




Frequency (Hz)



FUJI





No. Good Data




Frequency (Hz)

K20241028090610




No. Good Data




Frequency (Hz)

3C263.1 2024/10/28 0.13UT FUJI -KISO






T20241028091239





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C267 2024/10/28 0.24UT TOYOKAWA-FUJI



T20241028091239





BLK:17,SNR1: 12.454 ,SNR2: 20.926





3C267 2024/10/28 0.24UT TOYOKAWA-KISO



K20241028091237




BLK:17,SNR1: 6.8980 ,SNR2: 21.626



FUJI





No. Good Data




Frequency (Hz)

K20241028091237




No. Good Data





Frequency (Hz)


3C267 2024/10/28 0.24UT FUJI -KISO





T20241028093827




No. Good Data




FUJI




No. Good Data




1213-17 2024/10/28 0.67UT TOYOKAWA-FUJI



T20241028093827





BLK: 7, SNR1: 0.53836 , SNR2: 3.1558





1213-17 2024/10/28 0.67UT TOYOKAWA-KISO



K20241028093825




BLK: 7, SNR1: 3.1168 , SNR2: 7.8793



FUJI





No. Good Data




Frequency (Hz)

K20241028093825




No. Good Data





Frequency (Hz)


1213-17 2024/10/28 0.67UT FUJI -KISO



T20241028095144





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C273 2024/10/28 0.89UT TOYOKAWA-FUJI



T20241028095144




BLK:24,SNR1: 6.9571 ,SNR2: 33.084




Frequency (Hz)

3C273 2024/10/28 0.89UT TOYOKAWA-KISO


K20241028095142



BLK:24,SNR1: 2.2028 ,SNR2: 5.3950





Frequency (Hz)






FUJI





No. Good Data




Frequency (Hz)

K20241028095142




No. Good Data





Frequency (Hz)


3C273 2024/10/28 0.89UT FUJI -KISO



T20241028100455





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C275 2024/10/28 1.11UT TOYOKAWA-FUJI




T20241028100455




BLK:23,SNR1: 0.71612 ,SNR2: 4.9443




K20241028100453





BLK:23,SNR1: 1.3509 ,SNR2: 4.1303




3C275 2024/10/28 1.11UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241028100453




No. Good Data





Frequency (Hz)


3C275 2024/10/28 1.11UT FUJI -KISO



T20241028101100





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1245-19 2024/10/28 1.21UT TOYOKAWA-FUJI



T20241028101100





BLK:26,SNR1: 1.5308 ,SNR2: 3.9172





1245-19 2024/10/28 1.21UT TOYOKAWA-KISO



K20241028101058




BLK:26,SNR1: 9.2294 ,SNR2: 26.266



FUJI





No. Good Data




Frequency (Hz)

K20241028101058




No. Good Data





Frequency (Hz)


1245-19 2024/10/28 1.21UT FUJI -KISO



T20241028101843





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

3C279 2024/10/28 1.34UT TOYOKAWA-FUJI






T20241028101843





BLK:29,SNR1: 3.5225 ,SNR2: 18.679





3C279 2024/10/28 1.34UT TOYOKAWA-KISO



K20241028101841




BLK:29,SNR1: 7.3405 ,SNR2: 21.909



FUJI





No.Good Data




Frequency (Hz)

K20241028101841




No.Good Data





Frequency (Hz)


3C279 2024/10/28 1.34UT FUJI -KISO



T20241028103413





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C283 2024/10/28 1.60UT TOYOKAWA-FUJI





T20241028103413




BLK:33,SNR1: 3.5911 ,SNR2: 7.0049




K20241028103411





BLK:33,SNR1: 3.0372 ,SNR2: 9.3256




3C283 2024/10/28 1.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028103411




No.Good Data





Frequency (Hz)


3C283 2024/10/28 1.60UT FUJI -KISO



T20241028104837





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1323+32 2024/10/28 1.84UT TOYOKAWA-FUJI





T20241028104837




BLK:12,SNR1: 0.17430 ,SNR2: 1.0390




K20241028104835





BLK:12,SNR1: 0.97158 ,SNR2: 3.0517




1323+32 2024/10/28 1.84UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028104835




No.Good Data





Frequency (Hz)

1323+32 2024/10/28 1.84UT FUJI -KISO






T20241028105327





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C286 2024/10/28 1.92UT TOYOKAWA-FUJI



T20241028105327





BLK:26,SNR1: 3.9360 ,SNR2: 9.4767





3C286 2024/10/28 1.92UT TOYOKAWA-KISO



K20241028105325




BLK:26,SNR1: 6.5609 ,SNR2: 16.902



FUJI





No.Good Data




Frequency (Hz)

K20241028105325




No.Good Data





Frequency (Hz)


3C286 2024/10/28 1.92UT FUJI -KISO



T20241028110955





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1345+12 2024/10/28 2.19UT TOYOKAWA-FUJI




T20241028110955




BLK:31,SNR1: 1.7795 ,SNR2: 4.8232




K20241028110953





BLK:31,SNR1: 0.54642 ,SNR2: 1.7877




1345+12 2024/10/28 2.19UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241028110953




No. Good Data





Frequency (Hz)


1345+12 2024/10/28 2.19UT FUJI -KISO



T20241028112015





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1355+01 2024/10/28 2.37UT TOYOKAWA-FUJI







1355+01 2024/10/28 2.37UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241028112012




No. Good Data





Frequency (Hz)


1355+01 2024/10/28 2.37UT FUJI -KISO





T20241028114126




No.Good Data




FUJI







No.Good Data




3C298 2024/10/28 2.72UT TOYOKAWA-FUJI








3C298 2024/10/28 2.72UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028114124




No.Good Data





Frequency (Hz)


3C298 2024/10/28 2.72UT FUJI -KISO



T20241028115309





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1428-03 2024/10/28 2.91UT TOYOKAWA-FUJI





T20241028115309




BLK:14,SNR1: 0.32127 ,SNR2: 2.1206




K20241028115307




BLK:14,SNR1: 0.29775 ,SNR2: 1.2755




1428-03 2024/10/28 2.91UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028115307




No.Good Data





Frequency (Hz)


1428-03 2024/10/28 2.91UT FUJI -KISO



T20241028115912





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1434+03 2024/10/28 3.01UT TOYOKAWA-FUJI






T20241028115912





BLK:11,SNR1: 0.98612E-01,SNR2: 2.3188





1434+03 2024/10/28 3.01UT TOYOKAWA-KISO



K20241028115910




BLK:11,SNR1: 0.33296 ,SNR2: 1.8917



FUJI





No.Good Data




Frequency (Hz)

K20241028115910




No.Good Data





Frequency (Hz)


1434+03 2024/10/28 3.01UT FUJI -KISO



T20241028121814





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/10/28 3.33UT TOYOKAWA-FUJI



T20241028121814





BLK:20,SNR1: 0.86413 ,SNR2: 2.1441





1453-10 2024/10/28 3.33UT TOYOKAWA-KISO



K20241028121811




BLK:20,SNR1: 1.0151 ,SNR2: 2.9329



FUJI





No.Good Data




Frequency (Hz)

K20241028121811




No.Good Data





Frequency (Hz)


1453-10 2024/10/28 3.33UT FUJI -KISO



T20241028123306





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1508-05 2024/10/28 3.58UT TOYOKAWA-FUJI





T20241028123306




BLK:13,SNR1: 0.29465 ,SNR2: 1.0013




K20241028123304





BLK:13,SNR1: 0.93462 ,SNR2: 2.2724




1508-05 2024/10/28 3.58UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028123304




No.Good Data





Frequency (Hz)

1508-05 2024/10/28 3.58UT FUJI -KISO






T20241028124206





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/10/28 3.73UT TOYOKAWA-FUJI





T20241028124206




BLK:22,SNR1: 0.22056 ,SNR2: 3.8862




K20241028124204





BLK:22,SNR1: 0.18919 ,SNR2: 0.75198




3C318 2024/10/28 3.73UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028124204




No.Good Data




Frequency (Hz)


3C318 2024/10/28 3.73UT FUJI -KISO



T20241028124753





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1523+03 2024/10/28 3.83UT TOYOKAWA-FUJI




T20241028124753




BLK:13,SNR1: 0.55572 ,SNR2: 2.2510




K20241028124750





BLK:13,SNR1: 0.43500 ,SNR2: 1.7525




1523+03 2024/10/28 3.83UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028124750




No.Good Data





Frequency (Hz)


1523+03 2024/10/28 3.83UT FUJI -KISO



T20241028125933





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


1535+139 2024/10/28 4.02UT TOYOKAWA-FUJI





T20241028125933




BLK: 3,SNR1: 0.99730E-01,SNR2: 0.93807




K20241028125931



BLK: 3,SNR1: 0.67624 ,SNR2: 5.8237





1535+139 2024/10/28 4.02UT TOYOKAWA-KISO






FUJI




No.Good Data




Frequency (Hz)

K20241028125931




No.Good Data





Frequency (Hz)


1535+139 2024/10/28 4.02UT FUJI -KISO



T20241028131238





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1548+05 2024/10/28 4.24UT TOYOKAWA-FUJI





T20241028131238




BLK: 2,SNR1:-0.44835E-01,SNR2: 0.90738




K20241028131236





BLK: 2,SNR1: 0.39474E-01,SNR2: 0.72123




1548+05 2024/10/28 4.24UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028131236




No.Good Data






Frequency (Hz)




1548+05 2024/10/28 4.24UT FUJI -KISO




T20241028133100





FUJI




1607+26 2024/10/28 4.54UT TOYOKAWA-FUJI





T20241028133100




BLK: 5,SNR1: 0.10560 ,SNR2: 0.82753




K20241028133058





BLK: 5,SNR1: 8.1703 ,SNR2: 24.361




1607+26 2024/10/28 4.54UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028133058




No.Good Data




Frequency (Hz)


1607+26 2024/10/28 4.54UT FUJI -KISO



T20241028134830





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1623-228 2024/10/28 4.84UT TOYOKAWA-FUJI






T20241028134830





BLK: 8,SNR1: 0.77971E-01,SNR2: 1.3710





1623-228 2024/10/28 4.84UT TOYOKAWA-KISO



K20241028134828




BLK: 8,SNR1: 0.80428 ,SNR2: 2.9520



FUJI





No.Good Data




Frequency (Hz)

K20241028134828




No.Good Data





Frequency (Hz)


1623-228 2024/10/28 4.84UT FUJI -KISO



T20241028135700





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1631-222 2024/10/28 4.98UT TOYOKAWA-FUJI








1631-222 2024/10/28 4.98UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028135658




No.Good Data






Frequency (Hz)




1631-222 2024/10/28 4.98UT FUJI -KISO




T20241028140237





FUJI





1638-025 2024/10/28 5.07UT TOYOKAWA-FUJI







BLK: 9,SNR1: 2.1570 ,SNR2: 4.8126





BLK: 9,SNR1: 4.5651 ,SNR2: 13.423




1638-025 2024/10/28 5.07UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028140235




No.Good Data





Frequency (Hz)

1638-025 2024/10/28 5.07UT FUJI -KISO






T20241028140932





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1644-106 2024/10/28 5.19UT TOYOKAWA-FUJI



T20241028140932





BLK: 2,SNR1: 0.13093 ,SNR2: 0.41004




Frequency (Hz)

K20241028140929




BLK: 2,SNR1: 1.8593 ,SNR2: 13.485





Frequency (Hz)


1644-106 2024/10/28 5.19UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028140929




No.Good Data






Frequency (Hz)




1644-106 2024/10/28 5.19UT FUJI -KISO




T20241028141453





FUJI




1650+004 2024/10/28 5.28UT TOYOKAWA-FUJI



T20241028141453





BLK:10,SNR1: 0.25727E-02,SNR2: 1.9317




Frequency (Hz)

K20241028141451




BLK:10,SNR1: 8.7846 ,SNR2: 22.638





Frequency (Hz)


1650+004 2024/10/28 5.28UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241028141451




No.Good Data




Frequency (Hz)


1650+004 2024/10/28 5.28UT FUJI -KISO



T20241028142024




No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1656+053 2024/10/28 5.37UT TOYOKAWA-FUJI



T20241028142024





BLK: 4,SNR1:-0.35140E-01,SNR2: 0.68300




Frequency (Hz)

K20241028142022




BLK: 4,SNR1: 0.47568 ,SNR2: 3.4367





Frequency (Hz)

1656+053 2024/10/28 5.37UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241028142022




No.Good Data




Frequency (Hz)


1656+053 2024/10/28 5.37UT FUJI -KISO



T20241028143654





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1712-033 2024/10/28 5.64UT TOYOKAWA-FUJI





T20241028143654




BLK: 7,SNR1: 8.4707 ,SNR2: 20.975




K20241028143652





BLK: 7,SNR1: 10.157 ,SNR2: 29.418




1712-033 2024/10/28 5.64UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241028143652







No.Good Data





1712-033 2024/10/28 5.64UT FUJI -KISO







1730-13 2024/10/28 5.94UT TOYOKAWA-FUJI







BLK: 4,SNR1:-0.41560E-01,SNR2: 0.34835







BLK: 4,SNR1: 0.41764 ,SNR2: 5.3693




1730-13 2024/10/28 5.94UT TOYOKAWA-KISO







1730-13 2024/10/28 5.94UT FUJI -KISO




T20241028151221




BLK: 4,SNR1: 9.2740 ,SNR2: 23.270




F20241028151223



BLK: 4,SNR1: 8.9316 ,SNR2: 22.825




1748+031 2024/10/28 6.23UT TOYOKAWA-FUJI







T20241028151221




BLK: 5,SNR1: 9.9220 ,SNR2: 25.345




K20241028151218




BLK: 5,SNR1: 14.567 ,SNR2: 36.144




1748+031 2024/10/28 6.23UT TOYOKAWA-KISO



F20241028151223




BLK: 6,SNR1: 8.7090 ,SNR2: 22.016




Frequency (Hz)

K20241028151218




BLK: 6,SNR1: 6.8883 ,SNR2: 18.533





Frequency (Hz)


1748+031 2024/10/28 6.23UT FUJI -KISO





T20241028152314




BLK: 5,SNR1: 6.8934 ,SNR2: 19.629




F20241028152316





BLK: 5,SNR1: 8.8794 ,SNR2: 22.352




1759+13 2024/10/28 6.42UT TOYOKAWA-FUJI



T20241028152314




BLK: 7,SNR1: 8.6129 ,SNR2: 23.396




Frequency (Hz)

K20241028152312




BLK: 7,SNR1: 7.6668 ,SNR2: 23.221





Frequency (Hz)


1759+13 2024/10/28 6.42UT TOYOKAWA-KISO



F20241028152316




BLK: 5,SNR1: 7.9579 ,SNR2: 23.761




Frequency (Hz)

K20241028152312




BLK: 5,SNR1: 7.6594 ,SNR2: 23.200





Frequency (Hz)


1759+13 2024/10/28 6.42UT FUJI -KISO



T20241028154414




BLK: 7,SNR1: 7.2748 ,SNR2: 18.641




Frequency (Hz)

F20241028154416




BLK: 7,SNR1: 8.2734 ,SNR2: 20.299





Frequency (Hz)


1819-096 2024/10/28 6.77UT TOYOKAWA-FUJI



T20241028154414




BLK: 4,SNR1: 7.9972 ,SNR2: 17.397




Frequency (Hz)

K20241028154412




BLK: 4,SNR1: 19.813 ,SNR2: 45.426




Frequency (Hz)


1819-096 2024/10/28 6.77UT TOYOKAWA-KISO




F20241028154416




BLK: 6,SNR1: 7.1280 ,SNR2: 17.569




K20241028154412



BLK: 6,SNR1: 18.338 ,SNR2: 42.555




1819-096 2024/10/28 6.77UT FUJI -KISO








T20241028155530




BLK: 6,SNR1: 4.5561 ,SNR2: 11.063




F20241028155532




BLK: 6,SNR1:-0.14490 ,SNR2: 2.3498




1830-210 2024/10/28 6.95UT TOYOKAWA-FUJI



T20241028155530




BLK: 6,SNR1: 3.9618 ,SNR2: 9.0893




Frequency (Hz)

K20241028155528




BLK: 6,SNR1: 5.7930 ,SNR2: 13.940




Frequency (Hz)


1830-210 2024/10/28 6.95UT TOYOKAWA-KISO



F20241028155532




BLK: 6,SNR1: 4.8252 ,SNR2: 12.025




Frequency (Hz)

K20241028155528




BLK: 6,SNR1: 4.4644 ,SNR2: 12.006




Frequency (Hz)


1830-210 2024/10/28 6.95UT FUJI -KISO



T20241028162154




BLK: 1,SNR1: 0.11687 ,SNR2: 0.51691




Frequency (Hz)

F20241028162156




BLK: 1,SNR1: 0.72127E-01,SNR2: 1.5100




Frequency (Hz)


1858+171 2024/10/28 7.39UT TOYOKAWA-FUJI



T20241028162154




BLK: 3,SNR1: 0.14372 ,SNR2: 0.61516




Frequency (Hz)

K20241028162152




BLK: 3,SNR1: 3.4742 ,SNR2: 7.5745





Frequency (Hz)


1858+171 2024/10/28 7.39UT TOYOKAWA-KISO



F20241028162156




BLK: 2,SNR1: 0.25471 ,SNR2: 2.6544




Frequency (Hz)

K20241028162152




BLK: 2,SNR1: 0.80194 ,SNR2: 4.9362





Frequency (Hz)


1858+171 2024/10/28 7.39UT FUJI -KISO



T20241028163239




BLK: 4, SNR1: 9.6381, SNR2: 23.733




Frequency (Hz)

F20241028163241




BLK: 4, SNR1: 9.4532, SNR2: 23.853





Frequency (Hz)


1908-20 2024/10/28 7.57UT TOYOKAWA-FUJI



T20241028163239





BLK: 3,SNR1: 3.5754 ,SNR2: 4.7769




Frequency (Hz)

K20241028163237




BLK: 3,SNR1: 8.1883 ,SNR2: 24.879




Frequency (Hz)

1908-20 2024/10/28 7.57UT TOYOKAWA-KISO






F20241028163241





BLK: 4,SNR1: 4.1023 ,SNR2: 9.9246




Frequency (Hz)

K20241028163237




BLK: 4,SNR1: 3.5296 ,SNR2: 10.832





Frequency (Hz)


1908-20 2024/10/28 7.57UT FUJI -KISO



T20241028163930





BLK: 6,SNR1: 2.7790 ,SNR2: 6.6692




Frequency (Hz)

F20241028163932




BLK: 6,SNR1: 8.2431 ,SNR2: 15.385





Frequency (Hz)


1915-121 2024/10/28 7.69UT TOYOKAWA-FUJI





T20241028163930




BLK: 6,SNR1: 0.49296 ,SNR2: 1.9221




K20241028163928





BLK: 6,SNR1: 5.1656 ,SNR2: 12.678




1915-121 2024/10/28 7.69UT TOYOKAWA-KISO



F20241028163932





BLK: 5,SNR1: 4.1370 ,SNR2: 11.317




Frequency (Hz)

K20241028163928




BLK: 5,SNR1: 9.9779 ,SNR2: 25.062





Frequency (Hz)


1915-121 2024/10/28 7.69UT FUJI -KISO



T20241028165311





BLK:28,SNR1: 7.5453 ,SNR2: 19.226




Frequency (Hz)

F20241028165313




BLK:28,SNR1: 10.995 ,SNR2: 24.112





Frequency (Hz)


1928-142 2024/10/28 7.91UT TOYOKAWA-FUJI



T20241028165311





BLK:28,SNR1: 7.5448 ,SNR2: 19.225




Frequency (Hz)

K20241028165309




BLK:28,SNR1: 8.4392 ,SNR2: 20.963





Frequency (Hz)


1928-142 2024/10/28 7.91UT TOYOKAWA-KISO



F20241028165313





BLK:33,SNR1: 10.595 ,SNR2: 22.556




Frequency (Hz)

K20241028165309




BLK:33,SNR1: 8.2881 ,SNR2: 20.604





Frequency (Hz)


1928-142 2024/10/28 7.91UT FUJI -KISO



T20241028170251




BLK: 6,SNR1: 9.5196 ,SNR2: 24.311




Frequency (Hz)

F20241028170253




BLK: 6,SNR1: 9.0434 ,SNR2: 23.229





Frequency (Hz)

1938-15 2024/10/28 8.08UT TOYOKAWA-FUJI






T20241028170251




BLK:11,SNR1: 6.8549 ,SNR2: 18.019




Frequency (Hz)

K20241028170248




BLK:11,SNR1: 8.6207 ,SNR2: 24.602




Frequency (Hz)


1938-15 2024/10/28 8.08UT TOYOKAWA-KISO



F20241028170253





BLK: 5, SNR1: 10.159 , SNR2: 25.031




Frequency (Hz)

K20241028170248



BLK: 5, SNR1: 8.6639 , SNR2: 24.692



Frequency (Hz)

1938-15 2024/10/28 8.08UT FUJI -KISO

