




TOYOKAWA 0942-196 2024/11/22(327)05:29:56-05:33:22JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0952-224 2024/11/22(327)05:39:15-05:42:41JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1002-216 2024/11/22(327)05:49:44-05:53:10JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1006-119 2024/11/22(327)05:53:52-05:57:18JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1012+022 2024/11/22(327)05:59:56-06:03:22JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1017+040 2024/11/22(327)06:05:14-06:08:40JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1022+066 2024/11/22(327)06:09:40-06:13:06JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1026-056 2024/11/22(327)06:14:03-06:17:29JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1031-11 2024/11/22(327)06:18:09-06:21:35JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1035-058 2024/11/22(327)06:22:42-06:26:08JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1043+158 2024/11/22(327)06:30:45-06:34:11JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1055+01 2024/11/22(327)06:42:59-06:46:25JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1059-010 2024/11/22(327)06:46:36-06:50:02JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1107+109 2024/11/22(327)06:54:17-06:57:43JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C255 2024/11/22(327)07:03:54-07:07:20JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1127-14 2024/11/22(327)07:14:32-07:17:58JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1136-13 2024/11/22(327)07:23:36-07:27:02JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C263.1 2024/11/22(327)07:27:52-07:31:18JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C267 2024/11/22(327)07:34:19-07:37:45JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1206+439 2024/11/22(327)07:53:33-07:56:59JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1213-17 2024/11/22(327)08:00:07-08:03:33JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C273 2024/11/22(327)08:13:24-08:16:50JST 171Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 3C275 2024/11/22(327)08:26:35-08:30:01JST 158Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1245-19 2024/11/22(327)08:32:40-08:36:06JST 143Rs

17623+/- 569



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C279

2024/11/22(327)08:40:24-08:43:50JST 149Rs


15587+/- 277




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1307+000 2024/11/22(327)08:54:01-08:57:27JST 147Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1313+453 2024/11/22(327)09:00:12-09:03:38JST 204Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1323+32 2024/11/22(327)09:10:18-09:13:44JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C286

2024/11/22(327)09:15:08-09:18:34JST 185Rs


16467+/- 76




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1334-17 2024/11/22(327)09:21:45-09:25:11JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1345+12 2024/11/22(327)09:31:35-09:35:01JST 148Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1355+01 2024/11/22(327)09:41:56-09:45:22JST 120Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C298 2024/11/22(327)10:03:06-10:06:32JST 121Rs


17020+/- 228




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1428-03 2024/11/22(327)10:14:50-10:18:16JST 91Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1436-16 2024/11/22(327)10:23:31-10:26:57JST 62Rs


21969+/- 251




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1453-10 2024/11/22(327)10:39:54-10:43:20JST 58Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1508-05 2024/11/22(327)10:54:47-10:58:13JST 63Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C318

2024/11/22(327)11:03:47-11:07:13JST 139Rs

16202+/- 48




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1523+03 2024/11/22(327)11:09:34-11:13:00JST 86Rs


16071+/- 127




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1535+139 2024/11/22(327)11:21:13-11:24:39JST 118Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 1545-12 2024/11/22(327)11:31:37-11:35:03JST 29Rs


18980+/- 511




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1607+26 2024/11/22(327)11:52:40-11:56:06JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1621-11 2024/11/22(327)12:07:44-12:11:10JST 42Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2024/11/22(327)12:18:41-12:22:07JST 38Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2024/11/22(327)12:24:18-12:27:44JST 76Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1644-106 2024/11/22(327)12:31:12-12:34:38JST 60Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1650+004 2024/11/22(327)12:36:33-12:39:59JST 91Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 1656+053 2024/11/22(327)12:42:05-12:45:31JST 107Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 1712-033 2024/11/22(327)12:58:35-13:02:01JST 94Rs


15659+/- 200




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1732-092 2024/11/22(327)13:18:42-13:22:08JST 97Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1748+031 2024/11/22(327)13:34:02-13:37:28JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2024/11/22(327)13:44:55-13:48:21JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2024/11/22(327)14:05:55-14:09:21JST 130Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1835+134 2024/11/22(327)14:20:39-14:24:05JST 169Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2024/11/22(327)14:43:35-14:47:01JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1908-20 2024/11/22(327)14:54:20-14:57:46JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







TOYOKAWA 1915-121 2024/11/22(327)15:01:10-15:04:36JST 162Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1928-142 2024/11/22(327)15:14:52-15:18:18JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1938-15 2024/11/22(327)15:24:31-15:27:57JST 173Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2014+358 2024/11/22(327)15:59:27-16:02:53JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C422 2024/11/22(327)16:30:04-16:33:30JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2024/11/22(327)16:50:41-16:54:07JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2121-014 2024/11/22(327)17:06:30-17:09:56JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2128-123 2024/11/22(327)17:14:29-17:17:55JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 2135-209 2024/11/22(327)17:20:45-17:24:11JST 208Rs


17703+/- 159



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2156-245 2024/11/22(327)17:42:17-17:45:43JST 210Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

