




T20241031054829





BLK: 5,SNR1: 2.1597 ,SNR2: 7.5641




Frequency (Hz)

0834-19 2024/10/30 20.84UT TOYOKAWA-FUJI


F20241031054831





BLK: 5,SNR1: 19.353 ,SNR2: 29.525




Frequency (Hz)



T20241031054829





BLK: 5, SNR1: 0.54061 , SNR2: 11.913




Frequency (Hz)

K20241031054827




BLK: 5, SNR1: 22.196 , SNR2: 29.283





Frequency (Hz)


0834-19 2024/10/30 20.84UT TOYOKAWA-KISO



F20241031054831





BLK: 2,SNR1: 21.402 ,SNR2: 32.280




Frequency (Hz)

K20241031054827




BLK: 2,SNR1: 15.337 ,SNR2: 23.067





Frequency (Hz)


0834-19 2024/10/30 20.84UT FUJI -KISO



T20241031055902





BLK: 6,SNR1: 1.4428 ,SNR2: 12.542




Frequency (Hz)

F20241031055904




BLK: 6,SNR1: 25.141 ,SNR2: 32.750





Frequency (Hz)


0845-177 2024/10/30 21.01UT TOYOKAWA-FUJI



T20241031055902





BLK: 3, SNR1: 5.1468 , SNR2: 21.466




Frequency (Hz)

K20241031055900




BLK: 3, SNR1: 9.0443 , SNR2: 16.328





Frequency (Hz)


0845-177 2024/10/30 21.01UT TOYOKAWA-KISO



F20241031055904





BLK: 4,SNR1: 17.639 ,SNR2: 26.292




Frequency (Hz)

0845-177 2024/10/30 21.01UT FUJI -KISO


K20241031055900





BLK: 4,SNR1: 0.41938 ,SNR2: 4.9105




Frequency (Hz)



T20241031060416





BLK: 1,SNR1: 0.34080 ,SNR2: 3.2476




Frequency (Hz)

F20241031060418




BLK: 1,SNR1: 0.36767 ,SNR2: 0.50317





Frequency (Hz)


0850-206 2024/10/30 21.10UT TOYOKAWA-FUJI



T20241031060416





BLK: 4,SNR1: 0.35593E-01,SNR2: 0.61207




Frequency (Hz)

K20241031060414




BLK: 4,SNR1: 5.3029 ,SNR2: 18.231





Frequency (Hz)

0850-206 2024/10/30 21.10UT TOYOKAWA-KISO






F20241031060418





BLK: 3,SNR1: 3.5048 ,SNR2: 20.824




Frequency (Hz)

K20241031060414




BLK: 3,SNR1: 11.034 ,SNR2: 19.895





Frequency (Hz)


0850-206 2024/10/30 21.10UT FUJI -KISO



T20241031061055





BLK: 1,SNR1: 0.37398E-01,SNR2: 1.7584




Frequency (Hz)

F20241031061057




BLK: 1,SNR1:-0.86175E-01,SNR2: 0.51174




Frequency (Hz)

0857-191 2024/10/30 21.21UT TOYOKAWA-FUJI




T20241031061055



Time (sec)




BLK: 4,SNR1: 1.5087 ,SNR2: 13.157



Frequency (Hz)

0857-191 2024/10/30 21.21UT TOYOKAWA-KISO


K20241031061053




Time (sec)





BLK: 4,SNR1: 13.494 ,SNR2: 24.247




Frequency (Hz)



F20241031061057





BLK: 1, SNR1: 1.6485 ,SNR2: 5.2335




Frequency (Hz)

K20241031061053




BLK: 1, SNR1: 8.1430 ,SNR2: 23.560





Frequency (Hz)


0857-191 2024/10/30 21.21UT FUJI -KISO



T20241031061700




BLK: 3,SNR1: 0.36724 ,SNR2: 6.6746




Frequency (Hz)

0903-041 2024/10/30 21.31UT TOYOKAWA-FUJI


F20241031061702





BLK: 3,SNR1:-0.60291E-01,SNR2: 1.7103




Frequency (Hz)



T20241031061700





BLK: 3,SNR1: 9.8047 ,SNR2: 46.056









0903-041 2024/10/30 21.31UT TOYOKAWA-KISO

K20241031061658




BLK: 3,SNR1: 2.8321 ,SNR2: 6.0420







0903-041 2024/10/30 21.31UT FUJI -KISO



T20241031062601





BLK: 9,SNR1: 0.27276 ,SNR2: 3.1948




Frequency (Hz)

F20241031062603




BLK: 9,SNR1: 0.43621 ,SNR2: 2.3408




Frequency (Hz)

0912-132 2024/10/30 21.46UT TOYOKAWA-FUJI






T20241031062601





BLK: 7,SNR1: 0.66392 ,SNR2: 2.0974




Frequency (Hz)

K20241031062559




BLK: 7,SNR1: 3.2933 ,SNR2: 9.8451





Frequency (Hz)


0912-132 2024/10/30 21.46UT TOYOKAWA-KISO



F20241031062603





BLK: 3,SNR1: 0.19338 ,SNR2: 1.7775




Frequency (Hz)

K20241031062559




BLK: 3,SNR1: 18.923 ,SNR2: 33.939





Frequency (Hz)


0912-132 2024/10/30 21.46UT FUJI -KISO



T20241031063328





BLK: 4,SNR1: 14.061 ,SNR2: 34.568




Frequency (Hz)

F20241031063330




BLK: 4,SNR1: 11.222 ,SNR2: 32.425





Frequency (Hz)


0919-142 2024/10/30 21.59UT TOYOKAWA-FUJI



T20241031063328





BLK: 2,SNR1: 8.8938 ,SNR2: 25.443




Frequency (Hz)

K20241031063326




BLK: 2,SNR1: 7.2712 ,SNR2: 20.963





Frequency (Hz)


0919-142 2024/10/30 21.59UT TOYOKAWA-KISO



F20241031063330





BLK: 4,SNR1: 10.146 ,SNR2: 28.974




Frequency (Hz)

K20241031063326




BLK: 4,SNR1: 8.1126 ,SNR2: 20.386





Frequency (Hz)


0919-142 2024/10/30 21.59UT FUJI -KISO



T20241031064007





BLK: 4,SNR1:-0.86535E-01,SNR2: 0.15161




Frequency (Hz)

F20241031064009




BLK: 4,SNR1: 0.52070 ,SNR2: 1.9037





Frequency (Hz)


0926+117 2024/10/30 21.70UT TOYOKAWA-FUJI



T20241031064007





BLK: 1,SNR1:-0.18427 ,SNR2: 0.21991




Frequency (Hz)

K20241031064005




BLK: 1,SNR1: 34.376 ,SNR2: 53.481





Frequency (Hz)


0926+117 2024/10/30 21.70UT TOYOKAWA-KISO



F20241031064009





BLK: 2,SNR1: 1.0427 ,SNR2: 3.9691




Frequency (Hz)

K20241031064005




BLK: 2,SNR1: 25.889 ,SNR2: 39.336




Frequency (Hz)

0926+117 2024/10/30 21.70UT FUJI -KISO






T20241031064752




BLK: 6,SNR1: 34.317 ,SNR2: 101.30




Frequency (Hz)

F20241031064754




BLK: 6,SNR1: 1.2729 ,SNR2: 3.7464





Frequency (Hz)


3C222 2024/10/30 21.83UT TOYOKAWA-FUJI



T20241031064752





BLK:11,SNR1: 47.183 ,SNR2: 131.39




Frequency (Hz)

3C222 2024/10/30 21.83UT TOYOKAWA-KISO


K20241031064750





BLK:11,SNR1: 6.9937 ,SNR2: 19.871




Frequency (Hz)





F20241031064754




BLK: 5, SNR1: 6.9486 ,SNR2: 18.022




K20241031064750





BLK: 5, SNR1: 10.150 ,SNR2: 25.720




3C222 2024/10/30 21.83UT FUJI -KISO



T20241031065452





BLK: 5,SNR1: 7.8197 ,SNR2: 22.585




Frequency (Hz)

0941-08 2024/10/30 21.94UT TOYOKAWA-FUJI


F20241031065454




BLK: 5,SNR1: 9.7103 ,SNR2: 28.537




Frequency (Hz)



T20241031065452





BLK: 6,SNR1: 8.4435 ,SNR2: 24.790




Frequency (Hz)

0941-08 2024/10/30 21.94UT TOYOKAWA-KISO


K20241031065450





BLK: 6,SNR1: 13.108 ,SNR2: 32.209




Frequency (Hz)



F20241031065454





BLK: 3,SNR1: 8.0234 ,SNR2: 20.699




Frequency (Hz)

K20241031065450




BLK: 3,SNR1: 9.0759 ,SNR2: 22.726




Frequency (Hz)


0941-08 2024/10/30 21.94UT FUJI -KISO



T20241031070313




BLK: 4,SNR1: 0.91946E-01,SNR2: 1.4927





3C230 2024/10/30 22.08UT TOYOKAWA-FUJI


F20241031070315




BLK: 4,SNR1: 0.71402 ,SNR2: 2.4820




T20241031070313




BLK: 4,SNR1:-0.13970 ,SNR2: 0.42005




K20241031070311



BLK: 4,SNR1: 1.6288 ,SNR2: 3.6569




3C230 2024/10/30 22.08UT TOYOKAWA-KISO







F20241031070315




No.Good Data




K20241031070311





No.Good Data




3C230 2024/10/30 22.08UT FUJI -KISO



T20241031071914





BLK: 4,SNR1: 7.2586 ,SNR2: 19.365




Frequency (Hz)

3C237 2024/10/30 22.35UT TOYOKAWA-FUJI


F20241031071916





BLK: 4,SNR1: 7.7460 ,SNR2: 22.336




Frequency (Hz)



T20241031071914




BLK: 5,SNR1: 14.138 ,SNR2: 34.365





3C237 2024/10/30 22.35UT TOYOKAWA-KISO



K20241031071911




BLK: 5,SNR1: 7.6681 ,SNR2: 22.873



F20241031071916





BLK: 3,SNR1: 5.3811 ,SNR2: 14.000




Frequency (Hz)

3C237 2024/10/30 22.35UT FUJI -KISO


K20241031071911







BLK: 3,SNR1: 11.598 ,SNR2: 28.645




Frequency (Hz)








1011+110 2024/10/30 22.45UT TOYOKAWA-FUJI



T20241031072530





BLK: 2, SNR1: 0.22629 , SNR2: 0.89391




Frequency (Hz)

K20241031072528








BLK: 2, SNR1: 0.54012 , SNR2: 3.4525




Frequency (Hz)

1011+110 2024/10/30 22.45UT TOYOKAWA-KISO








1011+110 2024/10/30 22.45UT FUJI -KISO





T20241031073311




No.Good Data




F20241031073313



No.Good Data




3C241 2024/10/30 22.58UT TOYOKAWA-FUJI






T20241031073311




BLK: 2,SNR1:-0.21118 ,SNR2: 0.78897




Frequency (Hz)

3C241 2024/10/30 22.58UT TOYOKAWA-KISO


K20241031073308





BLK: 2,SNR1: 2.7425 ,SNR2: 7.7894




Frequency (Hz)



F20241031073313





BLK:11,SNR1: 4.0298 ,SNR2: 11.108





3C241 2024/10/30 22.58UT FUJI -KISO


K20241031073308




BLK:11,SNR1: 7.9950 ,SNR2: 20.079



T20241031074441




BLK: 4,SNR1: 0.50762 ,SNR2: 1.5566





1031-11 2024/10/30 22.77UT TOYOKAWA-FUJI



F20241031074443




BLK: 4,SNR1: 0.27730 ,SNR2: 1.7431



T20241031074441





BLK: 7,SNR1: 0.30926 ,SNR2: 1.0607




Frequency (Hz)

1031-11 2024/10/30 22.77UT TOYOKAWA-KISO


K20241031074438




BLK: 7,SNR1: 7.1191 ,SNR2: 18.467




Frequency (Hz)



F20241031074443





BLK: 6,SNR1: 4.0292 ,SNR2: 10.845





1031-11 2024/10/30 22.77UT FUJI -KISO


K20241031074438




BLK: 6,SNR1: 5.4178 ,SNR2: 16.427



T20241031074914





BLK: 6,SNR1: 2.4303 ,SNR2: 4.6234





1035-058 2024/10/30 22.85UT TOYOKAWA-FUJI


F20241031074916




BLK: 6,SNR1:-0.84030E-01,SNR2: 1.1494



T20241031074914





BLK: 5,SNR1: 9.3330 ,SNR2: 85.832





1035-058 2024/10/30 22.85UT TOYOKAWA-KISO


K20241031074911




BLK: 5,SNR1: 1.0508 ,SNR2: 3.0201




F20241031074916




BLK: 7,SNR1:-0.22903E-02,SNR2: 2.1290




K20241031074911



BLK: 7,SNR1: 7.0753 ,SNR2: 11.946




1035-058 2024/10/30 22.85UT FUJI -KISO







T20241031075827




BLK: 3, SNR1: -0.62022E-01, SNR2: 0.74323




F20241031075829




BLK: 3, SNR1: -0.99112E-01, SNR2: 1.2968




1044-008 2024/10/30 23.00UT TOYOKAWA-FUJI





T20241031075827




BLK: 2, SNR1: 0.10584 , SNR2: 1.3094




K20241031075825




BLK: 2, SNR1: 1.2522 , SNR2: 6.5427




1044-008 2024/10/30 23.00UT TOYOKAWA-KISO





F20241031075829




BLK: 2,SNR1:-0.32911 ,SNR2: 0.31105




K20241031075825





BLK: 2,SNR1: 1.2124 ,SNR2: 2.7246




1044-008 2024/10/30 23.00UT FUJI -KISO



T20241031080931





BLK:14,SNR1: 7.6272 ,SNR2: 19.736




Frequency (Hz)

1055+01 2024/10/30 23.19UT TOYOKAWA-FUJI


F20241031080933





BLK:14,SNR1:-0.65343E-01,SNR2: 1.9053




Frequency (Hz)



T20241031080931





BLK:16,SNR1: 5.8084 ,SNR2: 19.508




Frequency (Hz)

1055+01 2024/10/30 23.19UT TOYOKAWA-KISO


K20241031080929




BLK:16,SNR1: 0.88556 ,SNR2: 2.6861




Frequency (Hz)




F20241031080933




BLK: 5,SNR1: 1.0340 ,SNR2: 3.7635




K20241031080929




BLK: 5,SNR1: 1.1650 ,SNR2: 4.1965




1055+01 2024/10/30 23.19UT FUJI -KISO




T20241031082049




BLK: 5,SNR1: 0.96766E-02,SNR2: 1.4201




F20241031082051





BLK: 5,SNR1:-0.48437E-02,SNR2: 1.1523




1107+109 2024/10/30 23.38UT TOYOKAWA-FUJI





T20241031082049




BLK: 9,SNR1: 0.77216E-01,SNR2: 1.2241




K20241031082047



BLK: 9,SNR1: 0.85207E-01,SNR2: 1.1871




1107+109 2024/10/30 23.38UT TOYOKAWA-KISO








F20241031082051




BLK: 5, SNR1: -0.20593 , SNR2: 0.57002




K20241031082047




BLK: 5, SNR1: 0.36368 , SNR2: 2.1795




1107+109 2024/10/30 23.38UT FUJI -KISO




T20241031083026




BLK:13,SNR1: 0.56254 ,SNR2: 6.2801




F20241031083028




BLK:13,SNR1: 0.10195E-01,SNR2: 1.4547




3C255 2024/10/30 23.54UT TOYOKAWA-FUJI




T20241031083026




BLK:21,SNR1: 0.55198 ,SNR2: 6.3203




K20241031083023





BLK:21,SNR1: 0.59135 ,SNR2: 1.9461




3C255 2024/10/30 23.54UT TOYOKAWA-KISO



F20241031083028




BLK: 7,SNR1: 0.17802E-01,SNR2: 2.1253





3C255 2024/10/30 23.54UT FUJI -KISO


K20241031083023




BLK: 7,SNR1: 4.6803 ,SNR2: 13.291



T20241031084104




BLK: 5,SNR1: 0.37659 ,SNR2: 1.6990





1127-14 2024/10/30 23.71UT TOYOKAWA-FUJI


F20241031084106




BLK: 5,SNR1: 0.42589 ,SNR2: 2.0719



T20241031084104




BLK:13,SNR1: 0.17566 ,SNR2: 1.9655




1127-14 2024/10/30 23.71UT TOYOKAWA-KISO


K20241031084102




BLK:13,SNR1: 0.72561 ,SNR2: 2.6034




Frequency (Hz)




F20241031084106




BLK: 2, SNR1: 0.84641 , SNR2: 3.1714




K20241031084102




BLK: 2, SNR1: 4.9536 , SNR2: 12.904




1127-14 2024/10/30 23.71UT FUJI -KISO



T20241031085008




BLK: 3, SNR1: 0.25290 , SNR2: 1.0652





1136-13 2024/10/30 23.86UT TOYOKAWA-FUJI

F20241031085010




BLK: 3, SNR1: 0.66277 , SNR2: 2.2382






T20241031085008





BLK: 8, SNR1: 0.34886 , SNR2: 2.4979




1136-13 2024/10/30 23.86UT TOYOKAWA-KISO


K20241031085006





BLK: 8, SNR1: 6.7603 , SNR2: 18.453




Frequency (Hz)



F20241031085010





BLK: 7, SNR1: 9.3903 ,SNR2: 22.766




Frequency (Hz)

1136-13 2024/10/30 23.86UT FUJI -KISO


K20241031085006







BLK: 7, SNR1: 3.9906 ,SNR2: 10.321




Frequency (Hz)








3C267 2024/10/31 0.04UT TOYOKAWA-FUJI




T20241031090051




BLK: 6,SNR1:-0.10368 ,SNR2: 0.93222




K20241031090049




BLK: 6,SNR1: 8.2237 ,SNR2: 20.670




3C267 2024/10/31 0.04UT TOYOKAWA-KISO



F20241031090053




BLK: 5, SNR1: 0.72726 , SNR2: 2.5653





3C267 2024/10/31 0.04UT FUJI -KISO



K20241031090049




BLK: 5, SNR1: 3.4922 , SNR2: 9.2387



T20241031092639





BLK: 1,SNR1: 0.17684 ,SNR2: 4.5109




Frequency (Hz)

1213-17 2024/10/31 0.47UT TOYOKAWA-FUJI


F20241031092641




BLK: 1,SNR1: 0.21164E-01,SNR2: 2.4916




Frequency (Hz)



T20241031092639





BLK: 8,SNR1: 0.49961 ,SNR2: 3.1370





1213-17 2024/10/31 0.47UT TOYOKAWA-KISO



K20241031092637




BLK: 8,SNR1: 0.71716 ,SNR2: 2.6628





F20241031092641




No.Good Data




K20241031092637



No.Good Data





1213-17 2024/10/31 0.47UT FUJI -KISO






T20241031093956





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C273 2024/10/31 0.69UT TOYOKAWA-FUJI



T20241031093956




BLK:26,SNR1: 15.312 ,SNR2: 50.853





3C273 2024/10/31 0.69UT TOYOKAWA-KISO



K20241031093954




BLK:26,SNR1: 2.7185 ,SNR2: 6.6463



FUJI





No.Good Data




Frequency (Hz)

K20241031093954




No.Good Data





Frequency (Hz)


3C273 2024/10/31 0.69UT FUJI -KISO





T20241031095307




No.Good Data




FUJI




No.Good Data




3C275 2024/10/31 0.91UT TOYOKAWA-FUJI





T20241031095307




BLK:16,SNR1: 0.33189 ,SNR2: 2.9407




K20241031095305





BLK:16,SNR1: 0.20818 ,SNR2: 1.3305




3C275 2024/10/31 0.91UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031095305




No.Good Data





Frequency (Hz)


3C275 2024/10/31 0.91UT FUJI -KISO



T20241031095912





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1245-19 2024/10/31 1.01UT TOYOKAWA-FUJI



T20241031095912




BLK:21,SNR1: 3.6762 ,SNR2: 15.460





1245-19 2024/10/31 1.01UT TOYOKAWA-KISO

K20241031095910





BLK:21,SNR1: 3.4453 ,SNR2: 14.866






FUJI





No.Good Data




Frequency (Hz)

K20241031095910




No.Good Data





Frequency (Hz)


1245-19 2024/10/31 1.01UT FUJI -KISO





T20241031100656




No.Good Data




FUJI





No.Good Data




3C279 2024/10/31 1.14UT TOYOKAWA-FUJI




T20241031100656




BLK:27,SNR1: 0.79149 ,SNR2: 5.1859




K20241031100654





BLK:27,SNR1: 0.74148 ,SNR2: 2.2311




3C279 2024/10/31 1.14UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241031100654




No.Good Data





Frequency (Hz)


3C279 2024/10/31 1.14UT FUJI -KISO





T20241031102225




No.Good Data




FUJI




No.Good Data




3C283 2024/10/31 1.40UT TOYOKAWA-FUJI




T20241031102225




BLK:37,SNR1: 2.3355 ,SNR2: 12.561




K20241031102223





BLK:37,SNR1: 2.0928 ,SNR2: 5.5743




3C283 2024/10/31 1.40UT TOYOKAWA-KISO



FUJI



No.Good Data




Frequency (Hz)

K20241031102223




No.Good Data





Frequency (Hz)


3C283 2024/10/31 1.40UT FUJI -KISO



T20241031103649





No.Good Data




Frequency (Hz)

FUJI




No.Good Data







Frequency (Hz)


1323+32 2024/10/31 1.64UT TOYOKAWA-FUJI










1323+32 2024/10/31 1.64UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031103646




No.Good Data





Frequency (Hz)


1323+32 2024/10/31 1.64UT FUJI -KISO



T20241031104140





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C286 2024/10/31 1.72UT TOYOKAWA-FUJI





T20241031104140




BLK:30,SNR1: 1.0778 ,SNR2: 7.3664




K20241031104137





BLK:30,SNR1: 7.8686 ,SNR2: 22.437




3C286 2024/10/31 1.72UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031104137




No.Good Data





Frequency (Hz)


3C286 2024/10/31 1.72UT FUJI -KISO



T20241031105807





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/10/31 2.00UT TOYOKAWA-FUJI



T20241031105807





BLK:31,SNR1: 38.743 ,SNR2: 78.195




1345+12 2024/10/31 2.00UT TOYOKAWA-KISO


K20241031105804





BLK:31,SNR1: 21.802 ,SNR2: 50.164




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241031105804




No.Good Data





Frequency (Hz)

1345+12 2024/10/31 2.00UT FUJI -KISO






T20241031110827





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1355+01 2024/10/31 2.17UT TOYOKAWA-FUJI



T20241031110827




BLK:29,SNR1: 2.4779 ,SNR2: 12.940





1355+01 2024/10/31 2.17UT TOYOKAWA-KISO


K20241031110824



BLK:29,SNR1: 0.35201 ,SNR2: 1.3660



FUJI





No.Good Data




Frequency (Hz)

K20241031110824




No.Good Data





Frequency (Hz)


1355+01 2024/10/31 2.17UT FUJI -KISO



T20241031112938





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C298 2024/10/31 2.52UT TOYOKAWA-FUJI



T20241031112938





BLK:30,SNR1: 4.1920 ,SNR2: 35.812





3C298 2024/10/31 2.52UT TOYOKAWA-KISO



K20241031112935




BLK:30,SNR1: 2.7341 ,SNR2: 5.5835



FUJI




No.Good Data




Frequency (Hz)

K20241031112935




No.Good Data





Frequency (Hz)


3C298 2024/10/31 2.52UT FUJI -KISO



T20241031114121





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1428-03 2024/10/31 2.72UT TOYOKAWA-FUJI





T20241031114121




BLK:12,SNR1: 10.034 ,SNR2: 27.018




K20241031114118



BLK:12,SNR1: 116.27 ,SNR2: 165.05



1428-03 2024/10/31 2.72UT TOYOKAWA-KISO





FUJI





No.Good Data




Frequency (Hz)

K20241031114118



No.Good Data






Frequency (Hz)




1428-03 2024/10/31 2.72UT FUJI -KISO




T20241031114724





FUJI




1434+03 2024/10/31 2.82UT TOYOKAWA-FUJI



T20241031114724





BLK:20,SNR1: 30.358 ,SNR2: 61.712




Frequency (Hz)

K20241031114721




BLK:20,SNR1: 0.35588E-02,SNR2: 2.1291





Frequency (Hz)


1434+03 2024/10/31 2.82UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031114721




No.Good Data





Frequency (Hz)


1434+03 2024/10/31 2.82UT FUJI -KISO



T20241031120626





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/10/31 3.14UT TOYOKAWA-FUJI





T20241031120626




BLK:19,SNR1: 0.19241 ,SNR2: 2.4871




K20241031120623





BLK:19,SNR1: 0.43400 ,SNR2: 2.4690




1453-10 2024/10/31 3.14UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031120623




No.Good Data





Frequency (Hz)


1453-10 2024/10/31 3.14UT FUJI -KISO



T20241031122118





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)

1508-05 2024/10/31 3.38UT TOYOKAWA-FUJI








T20241031122118




BLK: 9,SNR1: 0.13560 ,SNR2: 1.5544




K20241031122115





BLK: 9,SNR1: 0.17794 ,SNR2: 1.0477




1508-05 2024/10/31 3.38UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241031122115




No.Good Data





Frequency (Hz)


1508-05 2024/10/31 3.38UT FUJI -KISO



T20241031123018





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/10/31 3.53UT TOYOKAWA-FUJI





T20241031123018




BLK: 8,SNR1: 0.76637E-01,SNR2: 0.93772




K20241031123015





BLK: 8,SNR1: 0.49867 ,SNR2: 1.8378




3C318 2024/10/31 3.53UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241031123015




No.Good Data






Frequency (Hz)




3C318 2024/10/31 3.53UT FUJI -KISO




T20241031123605




FUJI




1523+03 2024/10/31 3.63UT TOYOKAWA-FUJI




T20241031123605




BLK:19,SNR1: 0.98823 ,SNR2: 3.3950




K20241031123602




BLK:19,SNR1: 4.5821 ,SNR2: 11.604




1523+03 2024/10/31 3.63UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031123602




No.Good Data






Frequency (Hz)

1523+03 2024/10/31 3.63UT FUJI -KISO









T20241031124745






FUJI





1535+139 2024/10/31 3.82UT TOYOKAWA-FUJI




T20241031124745





K20241031124742




1535+139 2024/10/31 3.82UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031124742




No.Good Data






Frequency (Hz)




1535+139 2024/10/31 3.82UT FUJI -KISO




T20241031130051





FUJI




1548+05 2024/10/31 4.04UT TOYOKAWA-FUJI




T20241031130051




BLK: 9,SNR1: 5.7825 ,SNR2: 12.608




K20241031130048





BLK: 9,SNR1: 1.6603 ,SNR2: 3.1724




1548+05 2024/10/31 4.04UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241031130048




No. Good Data






Frequency (Hz)




1548+05 2024/10/31 4.04UT FUJI -KISO




T20241031131912





FUJI




1607+26 2024/10/31 4.35UT TOYOKAWA-FUJI





T20241031131912




BLK: 7,SNR1: 9.9812 ,SNR2: 25.190




K20241031131909



BLK: 7,SNR1: 12.394 ,SNR2: 30.231





1607+26 2024/10/31 4.35UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241031131909




No.Good Data




Frequency (Hz)


1607+26 2024/10/31 4.35UT FUJI -KISO



T20241031133642




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1623-228 2024/10/31 4.64UT TOYOKAWA-FUJI





T20241031133642




BLK: 7,SNR1:-0.75179E-01,SNR2: 1.1777




K20241031133639





BLK: 7,SNR1: 0.82399 ,SNR2: 4.7050




1623-228 2024/10/31 4.64UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031133639




No.Good Data






Frequency (Hz)




1623-228 2024/10/31 4.64UT FUJI -KISO




T20241031134513





FUJI




1631-222 2024/10/31 4.78UT TOYOKAWA-FUJI




T20241031134513




BLK:10,SNR1: 5.9880 ,SNR2: 16.227




K20241031134510





BLK:10,SNR1: 8.8340 ,SNR2: 25.549




1631-222 2024/10/31 4.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031134510




No.Good Data






Frequency (Hz)




1631-222 2024/10/31 4.78UT FUJI -KISO




T20241031135050



FUJI





1638-025 2024/10/31 4.88UT TOYOKAWA-FUJI








T20241031135050




BLK:11,SNR1: 1.5509 ,SNR2: 23.059




K20241031135047





BLK:11,SNR1: 1.5221 ,SNR2: 4.0401




1638-025 2024/10/31 4.88UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031135047



No.Good Data






Frequency (Hz)




1638-025 2024/10/31 4.88UT FUJI -KISO




T20241031135744





FUJI




1644-106 2024/10/31 4.99UT TOYOKAWA-FUJI





T20241031135744




BLK: 9,SNR1: 1.5420 ,SNR2: 3.7893




K20241031135741






BLK: 9,SNR1: 3.1242 ,SNR2: 9.3921






1644-106 2024/10/31 4.99UT TOYOKAWA-KISO



FUJI





K20241031135741




1644-106 2024/10/31 4.99UT FUJI -KISO



T20241031140305





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1650+004 2024/10/31 5.08UT TOYOKAWA-FUJI








1650+004 2024/10/31 5.08UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031140302




No.Good Data






Frequency (Hz)

1650+004 2024/10/31 5.08UT FUJI -KISO









T20241031140837





FUJI




1656+053 2024/10/31 5.17UT TOYOKAWA-FUJI




T20241031140837




BLK: 5, SNR1: 6.0230 , SNR2: 15.574




K20241031140835






BLK: 5, SNR1: 10.812 , SNR2: 27.589






1656+053 2024/10/31 5.17UT TOYOKAWA-KISO




FUJI






K20241031140835



1656+053 2024/10/31 5.17UT FUJI -KISO






T20241031142507




No.Good Data

FUJI




No.Good Data


1712-033 2024/10/31 5.45UT TOYOKAWA-FUJI





T20241031142507




BLK: 2,SNR1: 0.17779 ,SNR2: 1.7774




K20241031142504





BLK: 2,SNR1: 0.14473 ,SNR2: 2.5897




1712-033 2024/10/31 5.45UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031142504




No.Good Data






Frequency (Hz)




1712-033 2024/10/31 5.45UT FUJI -KISO




T20241031144309





FUJI




1730-13 2024/10/31 5.75UT TOYOKAWA-FUJI





T20241031144309




BLK: 8,SNR1: 0.29274 ,SNR2: 1.2873




K20241031144306



BLK: 8,SNR1: 6.9028 ,SNR2: 17.062






1730-13 2024/10/31 5.75UT TOYOKAWA-KISO









FUJI






K20241031144306






1730-13 2024/10/31 5.75UT FUJI -KISO




T20241031150033





FUJI




1748+031 2024/10/31 6.04UT TOYOKAWA-FUJI



T20241031150033




BLK: 7,SNR1: 2.1208 ,SNR2: 5.9443




Frequency (Hz)

K20241031150030




BLK: 7,SNR1: 6.1036 ,SNR2: 17.603






Frequency (Hz)




1748+031 2024/10/31 6.04UT TOYOKAWA-KISO




FUJI






K20241031150030






1748+031 2024/10/31 6.04UT FUJI -KISO




T20241031151127




FUJI




1759+13 2024/10/31 6.22UT TOYOKAWA-FUJI



T20241031151127




BLK: 5, SNR1: 5.3828 , SNR2: 12.808




Frequency (Hz)

K20241031151124




BLK: 5, SNR1: 2.1219 , SNR2: 5.9387






Frequency (Hz)

1759+13 2024/10/31 6.22UT TOYOKAWA-KISO






FUJI




No.Good Data

K20241031151124






No.Good Data

1759+13 2024/10/31 6.22UT FUJI -KISO






T20241031153227




No.Good Data

FUJI





No.Good Data

1819-096 2024/10/31 6.57UT TOYOKAWA-FUJI






T20241031153227




BLK:25,SNR1: 4.3193 ,SNR2: 10.515




Frequency (Hz)

K20241031153224




BLK:25,SNR1: 5.9257 ,SNR2: 14.736





Frequency (Hz)


1819-096 2024/10/31 6.57UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031153224




No.Good Data





Frequency (Hz)


1819-096 2024/10/31 6.57UT FUJI -KISO



T20241031154342





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1830-210 2024/10/31 6.76UT TOYOKAWA-FUJI



T20241031154342





BLK: 5, SNR1: 29.625 , SNR2: 70.105




Frequency (Hz)

K20241031154339




BLK: 5, SNR1: 3.5726 , SNR2: 10.174




Frequency (Hz)


1830-210 2024/10/31 6.76UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241031154339




No.Good Data




Frequency (Hz)


1830-210 2024/10/31 6.76UT FUJI -KISO



T20241031161007





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1858+171 2024/10/31 7.20UT TOYOKAWA-FUJI



T20241031161007





BLK: 4, SNR1: 8.4334 , SNR2: 23.835




Frequency (Hz)

K20241031161004




BLK: 4, SNR1: 15.692 , SNR2: 39.744





Frequency (Hz)


1858+171 2024/10/31 7.20UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031161004




No.Good Data





Frequency (Hz)

1858+171 2024/10/31 7.20UT FUJI -KISO






T20241031162051




No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1908-20 2024/10/31 7.38UT TOYOKAWA-FUJI



T20241031162051





BLK: 6, SNR1: 17.498 , SNR2: 21.371




Frequency (Hz)

K20241031162048




BLK: 6, SNR1: 0.82498 , SNR2: 5.7450





Frequency (Hz)


1908-20 2024/10/31 7.38UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031162048




No.Good Data





Frequency (Hz)


1908-20 2024/10/31 7.38UT FUJI -KISO



T20241031162742





No.Good Data




Frequency (Hz)

FUJI






No.Good Data




Frequency (Hz)

1915-121 2024/10/31 7.49UT TOYOKAWA-FUJI








1915-121 2024/10/31 7.49UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031162739




No.Good Data





Frequency (Hz)


1915-121 2024/10/31 7.49UT FUJI -KISO



T20241031164124





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1928-142 2024/10/31 7.72UT TOYOKAWA-FUJI



T20241031164124





BLK: 2, SNR1: 0.42295 , SNR2: 3.9636




Frequency (Hz)

K20241031164121




BLK: 2, SNR1: 0.13817 , SNR2: 0.64070





Frequency (Hz)

1928-142 2024/10/31 7.72UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241031164121




No.Good Data





Frequency (Hz)


1928-142 2024/10/31 7.72UT FUJI -KISO



T20241031165103





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1938-15 2024/10/31 7.88UT TOYOKAWA-FUJI



T20241031165103





BLK: 4, SNR1: 0.25078 , SNR2: 1.0688




Frequency (Hz)

K20241031165100




BLK: 4, SNR1: 0.80808 , SNR2: 2.4052





Frequency (Hz)


1938-15 2024/10/31 7.88UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241031165100




No.Good Data





Frequency (Hz)


1938-15 2024/10/31 7.88UT FUJI -KISO



T20241031170551





No.Good Data




Frequency (Hz)

1953-077 2024/10/31 8.13UT TOYOKAWA-FUJI


FUJI




No.Good Data




Frequency (Hz)



T20241031170551




BLK:10,SNR1: 5.1718 ,SNR2: 14.865




Frequency (Hz)

K20241031170548




BLK:10,SNR1: 9.9474 ,SNR2: 25.152





Frequency (Hz)


1953-077 2024/10/31 8.13UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241031170548



No.Good Data



Frequency (Hz)

1953-077 2024/10/31 8.13UT FUJI -KISO

