




T20241106054041





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0850-206 2024/11/05 20.71UT TOYOKAWA-FUJI



T20241106054041





BLK: 6,SNR1: 3.7326 ,SNR2: 7.1101




Frequency (Hz)

K20241106054039




BLK: 6,SNR1: 11.082 ,SNR2: 28.923




Frequency (Hz)

0850-206 2024/11/05 20.71UT TOYOKAWA-KISO



FUJI




No.Good Data



Frequency (Hz)

K20241106054039




No.Good Data





Frequency (Hz)


0850-206 2024/11/05 20.71UT FUJI -KISO



T20241106054720





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0857-191 2024/11/05 20.82UT TOYOKAWA-FUJI



T20241106054720





BLK: 3,SNR1: 1.6062 ,SNR2: 4.3623




Frequency (Hz)

K20241106054717




BLK: 3,SNR1: 1.0942 ,SNR2: 3.7050



Frequency (Hz)

0857-191 2024/11/05 20.82UT TOYOKAWA-KISO



FUJI



No.Good Data



Frequency (Hz)

K20241106054717




No.Good Data





Frequency (Hz)


0857-191 2024/11/05 20.82UT FUJI -KISO



T20241106060225





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0912-132 2024/11/05 21.07UT TOYOKAWA-FUJI



T20241106060225





BLK: 7, SNR1: 2.0471 ,SNR2: 5.0594




Frequency (Hz)

K20241106060222




BLK: 7, SNR1: 9.6262 ,SNR2: 24.418



Frequency (Hz)

0912-132 2024/11/05 21.07UT TOYOKAWA-KISO





FUJI





No.Good Data




Frequency (Hz)

K20241106060222




No.Good Data





Frequency (Hz)


0912-132 2024/11/05 21.07UT FUJI -KISO





T20241106060952




No.Good Data




FUJI





No.Good Data




0919-142 2024/11/05 21.19UT TOYOKAWA-FUJI



T20241106060952





BLK: 3, SNR1: 0.18823 , SNR2: 1.6732





0919-142 2024/11/05 21.19UT TOYOKAWA-KISO


K20241106060950




BLK: 3, SNR1: 5.3853 , SNR2: 14.825



FUJI





No.Good Data




Frequency (Hz)

K20241106060950




No.Good Data





Frequency (Hz)


0919-142 2024/11/05 21.19UT FUJI -KISO



T20241106061631




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0926+117 2024/11/05 21.30UT TOYOKAWA-FUJI



T20241106061631





BLK: 3,SNR1: 0.45616E-01,SNR2: 0.80240




Frequency (Hz)

K20241106061629




BLK: 3,SNR1: 0.40447 ,SNR2: 1.1826




Frequency (Hz)


0926+117 2024/11/05 21.30UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241106061629




No.Good Data




0926+117 2024/11/05 21.30UT FUJI -KISO





T20241106062416




No.Good Data




FUJI



No.Good Data





3C222 2024/11/05 21.43UT TOYOKAWA-FUJI






T20241106062416





BLK: 3,SNR1: 14.239 ,SNR2: 59.445




Frequency (Hz)

3C222 2024/11/05 21.43UT TOYOKAWA-KISO


K20241106062414




BLK: 3,SNR1: 3.5214 ,SNR2: 9.9657




Frequency (Hz)



FUJI




No.Good Data




Frequency (Hz)

K20241106062414




No.Good Data





Frequency (Hz)


3C222 2024/11/05 21.43UT FUJI -KISO



T20241106063116





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


0941-08 2024/11/05 21.55UT TOYOKAWA-FUJI



T20241106063116





BLK: 2,SNR1: 2.9667 ,SNR2: 37.511




Frequency (Hz)

0941-08 2024/11/05 21.55UT TOYOKAWA-KISO


K20241106063114





BLK: 2,SNR1: 0.84490E-01,SNR2: 0.40897




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241106063114




No.Good Data





Frequency (Hz)


0941-08 2024/11/05 21.55UT FUJI -KISO





T20241106063938




No.Good Data




FUJI





No.Good Data




3C230 2024/11/05 21.69UT TOYOKAWA-FUJI



T20241106063938




BLK: 2,SNR1: 0.14400 ,SNR2: 1.2483




Frequency (Hz)

K20241106063935




BLK: 2,SNR1: 2.2447 ,SNR2: 7.4583





Frequency (Hz)


3C230 2024/11/05 21.69UT TOYOKAWA-KISO





FUJI




No.Good Data




K20241106063935



No.Good Data





3C230 2024/11/05 21.69UT FUJI -KISO








T20241106065539




No.Good Data




FUJI




No.Good Data




3C237 2024/11/05 21.96UT TOYOKAWA-FUJI



T20241106065539





BLK:11,SNR1: 0.16268 ,SNR2: 0.65320




Frequency (Hz)

K20241106065537




BLK:11,SNR1: 0.42200 ,SNR2: 1.7594



Frequency (Hz)

3C237 2024/11/05 21.96UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106065537




No.Good Data





Frequency (Hz)


3C237 2024/11/05 21.96UT FUJI -KISO





T20241106070155




No.Good Data




FUJI





No.Good Data




1011+110 2024/11/05 22.06UT TOYOKAWA-FUJI





T20241106070155




BLK: 4,SNR1: 0.11619E-01,SNR2: 0.42503




K20241106070153





BLK: 4,SNR1:-0.99735E-01,SNR2: 1.7023




1011+110 2024/11/05 22.06UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106070153




No.Good Data





Frequency (Hz)


1011+110 2024/11/05 22.06UT FUJI -KISO





T20241106070936




No.Good Data




FUJI





No.Good Data




3C241 2024/11/05 22.19UT TOYOKAWA-FUJI





T20241106070936




BLK: 6,SNR1: 0.25552 ,SNR2: 1.1228




K20241106070934



BLK: 6,SNR1: 0.90212 ,SNR2: 3.5555





3C241 2024/11/05 22.19UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241106070934




No.Good Data





Frequency (Hz)


3C241 2024/11/05 22.19UT FUJI -KISO





T20241106072105




No.Good Data




FUJI




No.Good Data




1031-11 2024/11/05 22.38UT TOYOKAWA-FUJI



T20241106072105




BLK: 9,SNR1: 0.69825 ,SNR2: 2.7376




Frequency (Hz)

1031-11 2024/11/05 22.38UT TOYOKAWA-KISO


K20241106072103





BLK: 9,SNR1: 13.740 ,SNR2: 31.198




Frequency (Hz)



FUJI





No.Good Data




Frequency (Hz)

K20241106072103




No.Good Data





Frequency (Hz)


1031-11 2024/11/05 22.38UT FUJI -KISO



T20241106072539





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1035-058 2024/11/05 22.46UT TOYOKAWA-FUJI



T20241106072539




BLK: 4,SNR1: 5.1702 ,SNR2: 31.972





1035-058 2024/11/05 22.46UT TOYOKAWA-KISO


K20241106072537




BLK: 4,SNR1: 0.15405 ,SNR2: 1.9089



FUJI





No.Good Data




Frequency (Hz)

K20241106072537




No.Good Data





Frequency (Hz)


1035-058 2024/11/05 22.46UT FUJI -KISO





T20241106073451




No. Good Data




FUJI



No. Good Data





1044-008 2024/11/05 22.61UT TOYOKAWA-FUJI








T20241106073451




BLK: 5,SNR1: 0.90003E-01,SNR2: 0.54687




K20241106073449




BLK: 5,SNR1: 1.7231 ,SNR2: 4.9520



1044-008 2024/11/05 22.61UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106073449




No.Good Data




Frequency (Hz)


1044-008 2024/11/05 22.61UT FUJI -KISO





T20241106074556




No.Good Data




FUJI





No.Good Data




1055+01 2024/11/05 22.79UT TOYOKAWA-FUJI



T20241106074556




BLK: 8, SNR1: 0.36255 , SNR2: 1.3269





1055+01 2024/11/05 22.79UT TOYOKAWA-KISO


K20241106074554



BLK: 8, SNR1: 1.3508 , SNR2: 3.4269



FUJI





No.Good Data




Frequency (Hz)

K20241106074554




No.Good Data





Frequency (Hz)


1055+01 2024/11/05 22.79UT FUJI -KISO





T20241106075713




No.Good Data




FUJI





No.Good Data




1107+109 2024/11/05 22.98UT TOYOKAWA-FUJI





T20241106075713




BLK: 8, SNR1: 0.15460 , SNR2: 1.0525




K20241106075711



BLK: 8, SNR1: 0.71415 , SNR2: 3.5319



1107+109 2024/11/05 22.98UT TOYOKAWA-KISO





FUJI




No.Good Data



K20241106075711



No.Good Data





1107+109 2024/11/05 22.98UT FUJI -KISO








T20241106080651




No.Good Data




FUJI




No.Good Data




3C255 2024/11/05 23.14UT TOYOKAWA-FUJI





T20241106080651




BLK:12,SNR1: 1.1166 ,SNR2: 5.0077




K20241106080649





BLK:12,SNR1: 5.6381 ,SNR2: 15.306




3C255 2024/11/05 23.14UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106080649




No. Good Data




Frequency (Hz)


3C255 2024/11/05 23.14UT FUJI -KISO





T20241106081728




No.Good Data




FUJI




No.Good Data




1127-14 2024/11/05 23.32UT TOYOKAWA-FUJI





T20241106081728




BLK:10,SNR1: 0.21512 ,SNR2: 1.3131




K20241106081726



BLK:10,SNR1: 1.5163 ,SNR2: 5.3443



1127-14 2024/11/05 23.32UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106081726




No. Good Data





Frequency (Hz)


1127-14 2024/11/05 23.32UT FUJI -KISO



T20241106083049





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C263.1 2024/11/05 23.54UT TOYOKAWA-FUJI



T20241106083049





BLK:10,SNR1: 3.7829 ,SNR2: 22.872





3C263.1 2024/11/05 23.54UT TOYOKAWA-KISO

K20241106083046





BLK:10,SNR1: 0.48335 ,SNR2: 1.3464






FUJI





No.Good Data




Frequency (Hz)

K20241106083046




No.Good Data




Frequency (Hz)


3C263.1 2024/11/05 23.54UT FUJI -KISO





T20241106083716




No. Good Data




FUJI





No. Good Data






3C267 2024/11/05 23.65UT TOYOKAWA-FUJI



T20241106083716




K20241106083713



FUJI





No. Good Data




Frequency (Hz)

K20241106083713




No. Good Data




Frequency (Hz)


3C267 2024/11/05 23.65UT FUJI -KISO



T20241106090303





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1213-17 2024/11/06 0.08UT TOYOKAWA-FUJI



T20241106090303




BLK:19,SNR1: 0.31175 ,SNR2: 2.5696





1213-17 2024/11/06 0.08UT TOYOKAWA-KISO

K20241106090301



BLK:19,SNR1: 14.328 ,SNR2: 26.068



FUJI





No. Good Data




Frequency (Hz)

K20241106090301




No. Good Data





Frequency (Hz)


1213-17 2024/11/06 0.08UT FUJI -KISO



T20241106091621





No. Good Data




Frequency (Hz)

FUJI




No. Good Data







Frequency (Hz)


3C273 2024/11/06 0.30UT TOYOKAWA-FUJI










3C273 2024/11/06 0.30UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106091619




No. Good Data





Frequency (Hz)


3C273 2024/11/06 0.30UT FUJI -KISO



T20241106092932





No. Good Data




Frequency (Hz)

FUJI




No. Good Data





Frequency (Hz)


3C275 2024/11/06 0.52UT TOYOKAWA-FUJI



T20241106092932




BLK: 7, SNR1: 0.21410 , SNR2: 1.6127





3C275 2024/11/06 0.52UT TOYOKAWA-KISO


K20241106092930



BLK: 7, SNR1: 0.88417 , SNR2: 2.3067



FUJI





No. Good Data




Frequency (Hz)

K20241106092930




No. Good Data





Frequency (Hz)


3C275 2024/11/06 0.52UT FUJI -KISO



T20241106093537





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1245-19 2024/11/06 0.62UT TOYOKAWA-FUJI








1245-19 2024/11/06 0.62UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106093535




No.Good Data





Frequency (Hz)

1245-19 2024/11/06 0.62UT FUJI -KISO








T20241106094320




No.Good Data




FUJI




No.Good Data




3C279 2024/11/06 0.75UT TOYOKAWA-FUJI




T20241106094320




BLK:24,SNR1: 0.66813 ,SNR2: 5.1103




K20241106094317





BLK:24,SNR1: 0.37975 ,SNR2: 2.7430




3C279 2024/11/06 0.75UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106094317




No. Good Data





Frequency (Hz)


3C279 2024/11/06 0.75UT FUJI -KISO



T20241106095850





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


3C283 2024/11/06 1.01UT TOYOKAWA-FUJI




T20241106095850




BLK:26,SNR1: 2.5026 ,SNR2: 4.5260




K20241106095847





BLK:26,SNR1: 8.8737 ,SNR2: 16.526




3C283 2024/11/06 1.01UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106095847




No. Good Data





Frequency (Hz)


3C283 2024/11/06 1.01UT FUJI -KISO



T20241106101314





No.Good Data




Frequency (Hz)

FUJI








No.Good Data




Frequency (Hz)

1323+32 2024/11/06 1.25UT TOYOKAWA-FUJI







1323+32 2024/11/06 1.25UT TOYOKAWA-KISO






FUJI





No. Good Data




Frequency (Hz)

K20241106101311




No. Good Data





Frequency (Hz)


1323+32 2024/11/06 1.25UT FUJI -KISO





T20241106101804




No.Good Data




FUJI





No.Good Data




3C286 2024/11/06 1.33UT TOYOKAWA-FUJI





T20241106101804




BLK:28,SNR1: 38.576 ,SNR2: 76.333




K20241106101801





BLK:28,SNR1: 47.753 ,SNR2: 81.030




3C286 2024/11/06 1.33UT TOYOKAWA-KISO



FUJI



No. Good Data



Frequency (Hz)

K20241106101801




No. Good Data





Frequency (Hz)


3C286 2024/11/06 1.33UT FUJI -KISO



T20241106103432





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1345+12 2024/11/06 1.60UT TOYOKAWA-FUJI



T20241106103432




BLK:22,SNR1: 5.9702 ,SNR2: 14.146




1345+12 2024/11/06 1.60UT TOYOKAWA-KISO


K20241106103429





BLK:22,SNR1: 25.003 ,SNR2: 41.312




Frequency (Hz)



FUJI



No. Good Data



Frequency (Hz)

K20241106103429




No. Good Data





Frequency (Hz)


1345+12 2024/11/06 1.60UT FUJI -KISO





T20241106104452




No.Good Data




FUJI



No.Good Data




1355+01 2024/11/06 1.78UT TOYOKAWA-FUJI






T20241106104452




BLK:15,SNR1: 2.1932 ,SNR2: 5.6125





1355+01 2024/11/06 1.78UT TOYOKAWA-KISO



K20241106104449




BLK:15,SNR1: 7.0246 ,SNR2: 17.811



FUJI





No.Good Data




Frequency (Hz)

K20241106104449




No.Good Data





Frequency (Hz)


1355+01 2024/11/06 1.78UT FUJI -KISO





T20241106110603




No.Good Data




FUJI





No.Good Data




3C298 2024/11/06 2.13UT TOYOKAWA-FUJI





T20241106110603




BLK:22,SNR1: 7.1433 ,SNR2: 18.005




K20241106110600





BLK:22,SNR1: 80.036 ,SNR2: 101.54



3C298 2024/11/06 2.13UT TOYOKAWA-KISO



FUJI





No. Good Data




Frequency (Hz)

K20241106110600




No. Good Data





Frequency (Hz)


3C298 2024/11/06 2.13UT FUJI -KISO



T20241106111746





No. Good Data




Frequency (Hz)

FUJI




No. Good Data




Frequency (Hz)


1428-03 2024/11/06 2.32UT TOYOKAWA-FUJI



T20241106111746




BLK:11,SNR1: 1.7888 ,SNR2: 5.5559





1428-03 2024/11/06 2.32UT TOYOKAWA-KISO



K20241106111743



BLK:11,SNR1: 7.3237 ,SNR2: 19.294



FUJI





No.Good Data




Frequency (Hz)

K20241106111743




No.Good Data





Frequency (Hz)

1428-03 2024/11/06 2.32UT FUJI -KISO






T20241106112348





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1434+03 2024/11/06 2.42UT TOYOKAWA-FUJI





T20241106112348




BLK:15,SNR1: 5.8908 ,SNR2: 15.244




K20241106112345



BLK:15,SNR1: 0.49430 ,SNR2: 1.5135



1434+03 2024/11/06 2.42UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106112345




No.Good Data





Frequency (Hz)


1434+03 2024/11/06 2.42UT FUJI -KISO



T20241106114251





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1453-10 2024/11/06 2.74UT TOYOKAWA-FUJI



T20241106114251




BLK: 4,SNR1: 9.3767 ,SNR2: 23.662





1453-10 2024/11/06 2.74UT TOYOKAWA-KISO



K20241106114249




BLK: 4,SNR1: 12.964 ,SNR2: 30.772



FUJI





No.Good Data




Frequency (Hz)

K20241106114249



No.Good Data





Frequency (Hz)


1453-10 2024/11/06 2.74UT FUJI -KISO



T20241106115743





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1508-05 2024/11/06 2.99UT TOYOKAWA-FUJI





T20241106115743




BLK:11,SNR1: 0.26472 ,SNR2: 0.78851




K20241106115741



BLK:11,SNR1: 0.42701 ,SNR2: 1.2738



1508-05 2024/11/06 2.99UT TOYOKAWA-KISO





FUJI





No.Good Data




Frequency (Hz)

K20241106115741




No.Good Data





Frequency (Hz)


1508-05 2024/11/06 2.99UT FUJI -KISO



T20241106120643





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


3C318 2024/11/06 3.14UT TOYOKAWA-FUJI



T20241106120643





BLK:20,SNR1: 0.80104 ,SNR2: 2.0619





3C318 2024/11/06 3.14UT TOYOKAWA-KISO



K20241106120640




BLK:20,SNR1: 7.2843 ,SNR2: 18.280



FUJI





No.Good Data




Frequency (Hz)

K20241106120640




No.Good Data





Frequency (Hz)


3C318 2024/11/06 3.14UT FUJI -KISO



T20241106121230





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1523+03 2024/11/06 3.24UT TOYOKAWA-FUJI




T20241106121230




BLK: 8,SNR1: 2.5746 ,SNR2: 7.5217




K20241106121227





BLK: 8,SNR1: 6.0667 ,SNR2: 17.484




1523+03 2024/11/06 3.24UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106121227




No.Good Data






Frequency (Hz)




1523+03 2024/11/06 3.24UT FUJI -KISO




T20241106122409



FUJI





1535+139 2024/11/06 3.43UT TOYOKAWA-FUJI








T20241106122409




BLK: 6,SNR1: 5.9899 ,SNR2: 17.476




K20241106122406





BLK: 6,SNR1: 11.326 ,SNR2: 33.795




1535+139 2024/11/06 3.43UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241106122406




No.Good Data






Frequency (Hz)




1535+139 2024/11/06 3.43UT FUJI -KISO




T20241106123434





FUJI




1545-12 2024/11/06 3.60UT TOYOKAWA-FUJI





T20241106123434




BLK:10,SNR1: 1.7033 ,SNR2: 5.1763




K20241106123431





BLK:10,SNR1: 8.9126 ,SNR2: 23.407




1545-12 2024/11/06 3.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106123431




No.Good Data





Frequency (Hz)




1545-12 2024/11/06 3.60UT FUJI -KISO




T20241106125537





FUJI




1607+26 2024/11/06 3.96UT TOYOKAWA-FUJI





T20241106125537




BLK:12,SNR1: 0.16635 ,SNR2: 0.83306




K20241106125534




BLK:12,SNR1: 2.5486 ,SNR2: 5.8205




1607+26 2024/11/06 3.96UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106125534




No.Good Data






Frequency (Hz)

1607+26 2024/11/06 3.96UT FUJI -KISO









T20241106131307




FUJI




1623-228 2024/11/06 4.25UT TOYOKAWA-FUJI




T20241106131307




BLK: 8,SNR1: 8.0484 ,SNR2: 21.834




K20241106131304





BLK: 8,SNR1: 12.293 ,SNR2: 29.898




1623-228 2024/11/06 4.25UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106131304




No.Good Data





Frequency (Hz)


1623-228 2024/11/06 4.25UT FUJI -KISO



T20241106132137





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1631-222 2024/11/06 4.39UT TOYOKAWA-FUJI




T20241106132137




BLK:10,SNR1: 0.36787 ,SNR2: 1.0454




K20241106132134





BLK:10,SNR1: 1.1681 ,SNR2: 3.5392




1631-222 2024/11/06 4.39UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106132134




No.Good Data






Frequency (Hz)




1631-222 2024/11/06 4.39UT FUJI -KISO




T20241106132714




FUJI




1638-025 2024/11/06 4.48UT TOYOKAWA-FUJI





T20241106132714




BLK: 8,SNR1: 0.21441 ,SNR2: 1.6090




K20241106132711



BLK: 8,SNR1: 0.40128 ,SNR2: 2.1452





1638-025 2024/11/06 4.48UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241106132711




No.Good Data






Frequency (Hz)




1638-025 2024/11/06 4.48UT FUJI -KISO




T20241106133409




FUJI




1644-106 2024/11/06 4.60UT TOYOKAWA-FUJI




T20241106133409




BLK:11,SNR1: 16.731 ,SNR2: 39.073




K20241106133406





BLK:11,SNR1: 10.913 ,SNR2: 26.021




1644-106 2024/11/06 4.60UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106133406




No.Good Data





Frequency (Hz)


1644-106 2024/11/06 4.60UT FUJI -KISO





T20241106133929




No.Good Data




FUJI




No.Good Data




1650+004 2024/11/06 4.69UT TOYOKAWA-FUJI





T20241106133929




BLK:12,SNR1: 1.9560 ,SNR2: 7.6956




K20241106133926





BLK:12,SNR1: 0.31366 ,SNR2: 1.2749




1650+004 2024/11/06 4.69UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106133926




No.Good Data






Frequency (Hz)




1650+004 2024/11/06 4.69UT FUJI -KISO




T20241106134501



FUJI




1656+053 2024/11/06 4.78UT TOYOKAWA-FUJI







T20241106134501




BLK:10,SNR1: 8.9296 ,SNR2: 23.559




K20241106134458






BLK:10,SNR1: 10.028 ,SNR2: 28.580






1656+053 2024/11/06 4.78UT TOYOKAWA-KISO



FUJI






K20241106134458






1656+053 2024/11/06 4.78UT FUJI -KISO




T20241106140131





FUJI




1712-033 2024/11/06 5.05UT TOYOKAWA-FUJI





T20241106140131




BLK: 9,SNR1: 89.853 ,SNR2: 139.26




K20241106140128





BLK: 9,SNR1: 0.27486 ,SNR2: 0.91831




1712-033 2024/11/06 5.05UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106140128




No.Good Data




Frequency (Hz)


1712-033 2024/11/06 5.05UT FUJI -KISO



T20241106141933





No.Good Data




Frequency (Hz)

FUJI




No.Good Data




Frequency (Hz)


1730-13 2024/11/06 5.35UT TOYOKAWA-FUJI




T20241106141933




BLK: 9,SNR1: 13.752 ,SNR2: 32.975




K20241106141930




BLK: 9,SNR1: 8.8778 ,SNR2: 21.579




1730-13 2024/11/06 5.35UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106141930



No.Good Data






Frequency (Hz)

1730-13 2024/11/06 5.35UT FUJI -KISO









T20241106143658





FUJI




1748+031 2024/11/06 5.64UT TOYOKAWA-FUJI





T20241106143658




BLK:14,SNR1: 76.322 ,SNR2: 176.11




K20241106143655





BLK:14,SNR1: 0.47518 ,SNR2: 1.5037




1748+031 2024/11/06 5.64UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106143655




No.Good Data






Frequency (Hz)




1748+031 2024/11/06 5.64UT FUJI -KISO




T20241106144751





FUJI




1759+13 2024/11/06 5.83UT TOYOKAWA-FUJI





T20241106144751




BLK:19,SNR1: 0.81764 ,SNR2: 5.6148




K20241106144748






BLK:19,SNR1: 0.21728 ,SNR2: 0.97700






1759+13 2024/11/06 5.83UT TOYOKAWA-KISO




FUJI





K20241106144748




1759+13 2024/11/06 5.83UT FUJI -KISO



T20241106150851





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1819-096 2024/11/06 6.18UT TOYOKAWA-FUJI





T20241106150851




BLK: 7,SNR1: 0.24559 ,SNR2: 1.2064




K20241106150849



BLK: 7,SNR1: 0.59738E-01,SNR2: 1.4637






1819-096 2024/11/06 6.18UT TOYOKAWA-KISO








FUJI





K20241106150849




1819-096 2024/11/06 6.18UT FUJI -KISO



T20241106152007





No.Good Data




Frequency (Hz)

FUJI





No.Good Data





Frequency (Hz)

1830-210 2024/11/06 6.36UT TOYOKAWA-FUJI







BLK: 9, SNR1: 6.6003 , SNR2: 41.518






BLK: 9, SNR1: 8.3583 , SNR2: 16.770






1830-210 2024/11/06 6.36UT TOYOKAWA-KISO




FUJI






K20241106152005






1830-210 2024/11/06 6.36UT FUJI -KISO




T20241106154631





FUJI




1858+171 2024/11/06 6.80UT TOYOKAWA-FUJI



T20241106154631




BLK: 3,SNR1: 0.25080 ,SNR2: 0.73316




Frequency (Hz)

K20241106154629




BLK: 3,SNR1: 1.7001 ,SNR2: 7.2850






Frequency (Hz)




1858+171 2024/11/06 6.80UT TOYOKAWA-KISO




FUJI






K20241106154629






1858+171 2024/11/06 6.80UT FUJI -KISO




T20241106155716



FUJI





1908-20 2024/11/06 6.98UT TOYOKAWA-FUJI








T20241106155716




BLK: 4,SNR1: 1.2033 ,SNR2: 3.3024




K20241106155713





BLK: 4,SNR1: 0.98573 ,SNR2: 3.6503




1908-20 2024/11/06 6.98UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106155713




No.Good Data






Frequency (Hz)




1908-20 2024/11/06 6.98UT FUJI -KISO




T20241106160406





FUJI




1915-121 2024/11/06 7.10UT TOYOKAWA-FUJI





T20241106160406




BLK: 2,SNR1: 0.14259E-01,SNR2: 0.95668




K20241106160404



BLK: 2,SNR1: 0.64179 ,SNR2: 2.4596




1915-121 2024/11/06 7.10UT TOYOKAWA-KISO



FUJI




No.Good Data




Frequency (Hz)

K20241106160404




No.Good Data




Frequency (Hz)


1915-121 2024/11/06 7.10UT FUJI -KISO



T20241106161748





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1928-142 2024/11/06 7.32UT TOYOKAWA-FUJI





T20241106161748




BLK: 4,SNR1: 0.41014 ,SNR2: 2.7824




K20241106161745





BLK: 4,SNR1: 0.24048E-01,SNR2: 0.28915




1928-142 2024/11/06 7.32UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106161745




No.Good Data





Frequency (Hz)

1928-142 2024/11/06 7.32UT FUJI -KISO






T20241106162727




No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1938-15 2024/11/06 7.49UT TOYOKAWA-FUJI





T20241106162727




BLK: 3,SNR1: 0.43910E-01,SNR2: 1.5844




K20241106162725





BLK: 3,SNR1: 1.2491 ,SNR2: 2.5707




1938-15 2024/11/06 7.49UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106162725




No.Good Data





Frequency (Hz)


1938-15 2024/11/06 7.49UT FUJI -KISO



T20241106164216





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


1953-077 2024/11/06 7.73UT TOYOKAWA-FUJI





T20241106164216




BLK: 2,SNR1: 0.32011 ,SNR2: 1.3201




K20241106164214





BLK: 2,SNR1: 0.84129 ,SNR2: 4.4421




1953-077 2024/11/06 7.73UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241106164214




No.Good Data





Frequency (Hz)


1953-077 2024/11/06 7.73UT FUJI -KISO



T20241106170032





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


2012+010 2024/11/06 8.04UT TOYOKAWA-FUJI





T20241106170032




BLK: 7,SNR1: 0.11054 ,SNR2: 0.60637




K20241106170030



BLK: 7,SNR1: 0.40112 ,SNR2: 3.0901





2012+010 2024/11/06 8.04UT TOYOKAWA-KISO






FUJI





No.Good Data




Frequency (Hz)

K20241106170030



No.Good Data



Frequency (Hz)

2012+010 2024/11/06 8.04UT FUJI -KISO

