




T20241129054023





BLK: 2,SNR1: 0.92626E-01,SNR2: 1.6045




Frequency (Hz)

F20241129054025




BLK: 2,SNR1: 5.1545 ,SNR2: 6.6800





Frequency (Hz)


1020-193 2024/11/28 20.70UT TOYOKAWA-FUJI



T20241129054023





BLK: 5,SNR1: 0.41192E-01,SNR2: 1.4143




Frequency (Hz)

K20241129054022




BLK: 5,SNR1: 0.60407 ,SNR2: 2.4603




Frequency (Hz)

1020-193 2024/11/28 20.70UT TOYOKAWA-KISO






F20241129054025





BLK: 5,SNR1: 0.88329E-01,SNR2: 4.8877




Frequency (Hz)

K20241129054022




BLK: 5,SNR1: 0.46054 ,SNR2: 8.3822





Frequency (Hz)


1020-193 2024/11/28 20.70UT FUJI -KISO



T20241129055039





BLK: 3,SNR1: 0.46809 ,SNR2: 3.3697




Frequency (Hz)

F20241129055041




BLK: 3,SNR1: 0.40471 ,SNR2: 4.6013





Frequency (Hz)


1031-11 2024/11/28 20.87UT TOYOKAWA-FUJI



T20241129055039





BLK: 8,SNR1: 0.26263 ,SNR2: 1.7845




Frequency (Hz)

K20241129055038




BLK: 8,SNR1: 0.92151 ,SNR2: 3.1681





Frequency (Hz)


1031-11 2024/11/28 20.87UT TOYOKAWA-KISO



F20241129055041





BLK: 6,SNR1: 0.30704 ,SNR2: 3.2935




Frequency (Hz)

K20241129055038




BLK: 6,SNR1: 2.0359 ,SNR2: 3.9822




Frequency (Hz)


1031-11 2024/11/28 20.87UT FUJI -KISO



T20241129055513





BLK: 9,SNR1: 9.3026 ,SNR2: 11.704




Frequency (Hz)

F20241129055515




BLK: 9,SNR1: 13.935 ,SNR2: 17.869




Frequency (Hz)


1035-058 2024/11/28 20.95UT TOYOKAWA-FUJI





T20241129055513




BLK: 4,SNR1: 4.6573 ,SNR2: 8.0718




K20241129055512





BLK: 4,SNR1: 5.7762 ,SNR2: 10.908




1035-058 2024/11/28 20.95UT TOYOKAWA-KISO





F20241129055515




BLK: 8,SNR1: 7.1807 ,SNR2: 12.308




K20241129055512





BLK: 8,SNR1: 6.8095 ,SNR2: 15.069




1035-058 2024/11/28 20.95UT FUJI -KISO



T20241129060426





BLK: 4,SNR1: 0.66091E-01,SNR2: 0.46400




Frequency (Hz)

F20241129060428




BLK: 4,SNR1: 2.2241 ,SNR2: 8.9357





Frequency (Hz)

1044-008 2024/11/28 21.10UT TOYOKAWA-FUJI








T20241129060426




BLK: 2,SNR1: 0.11069 ,SNR2: 0.82629




K20241129060425





BLK: 2,SNR1: 0.55511 ,SNR2: 1.9239




1044-008 2024/11/28 21.10UT TOYOKAWA-KISO





F20241129060428




BLK: 1,SNR1:-0.18344E-01,SNR2: 1.9573




K20241129060425





BLK: 1,SNR1: 0.25211E-02,SNR2: 0.54118




1044-008 2024/11/28 21.10UT FUJI -KISO




T20241129061530




BLK: 5,SNR1:-0.15999 ,SNR2: 0.35594




F20241129061532





BLK: 5,SNR1: 0.21480 ,SNR2: 1.3305




1055+01 2024/11/28 21.29UT TOYOKAWA-FUJI





T20241129061530




BLK: 3,SNR1: 0.56947E-01,SNR2: 0.78863




K20241129061529




BLK: 3,SNR1: 0.14177 ,SNR2: 0.86337




1055+01 2024/11/28 21.29UT TOYOKAWA-KISO



F20241129061532




BLK: 2,SNR1: 1.0948 ,SNR2: 4.5177




Frequency (Hz)

K20241129061529




BLK: 2,SNR1: 1.4918 ,SNR2: 7.1056





Frequency (Hz)


1055+01 2024/11/28 21.29UT FUJI -KISO



T20241129062648





BLK: 5,SNR1: 0.24003E-01,SNR2: 1.9387




Frequency (Hz)

F20241129062650




BLK: 5,SNR1: 0.18126 ,SNR2: 2.8723





Frequency (Hz)


1107+109 2024/11/28 21.47UT TOYOKAWA-FUJI





T20241129062648




BLK: 4,SNR1: -0.21962E-01,SNR2: 2.7296




K20241129062647





BLK: 4,SNR1: 8.8942 ,SNR2: 25.314




1107+109 2024/11/28 21.47UT TOYOKAWA-KISO



F20241129062650





BLK: 1,SNR1: 0.20973 ,SNR2: 1.3102




Frequency (Hz)

K20241129062647




BLK: 1,SNR1: 0.76252E-01,SNR2: 0.52890





Frequency (Hz)

1107+109 2024/11/28 21.47UT FUJI -KISO






T20241129063625





BLK: 6,SNR1: 0.36798 ,SNR2: 1.0941




Frequency (Hz)

3C255 2024/11/28 21.64UT TOYOKAWA-FUJI


F20241129063627





BLK: 6,SNR1: 1.8352 ,SNR2: 7.9010




Frequency (Hz)



T20241129063625





BLK: 7, SNR1: 0.21282 , SNR2: 0.83763




Frequency (Hz)

3C255 2024/11/28 21.64UT TOYOKAWA-KISO


K20241129063624




BLK: 7, SNR1: 6.8188 , SNR2: 17.440




Frequency (Hz)



F20241129063627





BLK: 3,SNR1: 0.53492 ,SNR2: 4.6508




Frequency (Hz)

3C255 2024/11/28 21.64UT FUJI -KISO


K20241129063624




BLK: 3,SNR1: 1.8526 ,SNR2: 5.2726




Frequency (Hz)



T20241129064703





BLK: 4,SNR1: 0.13067E-01,SNR2: 1.8948




Frequency (Hz)

F20241129064705




BLK: 4,SNR1: 4.4452 ,SNR2: 20.796





Frequency (Hz)


1127-14 2024/11/28 21.81UT TOYOKAWA-FUJI



T20241129064703





BLK: 5,SNR1: 0.59766E-01,SNR2: 1.4965




Frequency (Hz)

K20241129064702




BLK: 5,SNR1: 2.7980 ,SNR2: 5.5056




Frequency (Hz)


1127-14 2024/11/28 21.81UT TOYOKAWA-KISO



F20241129064705





BLK: 2,SNR1:-0.38024 ,SNR2: 0.0000




Frequency (Hz)

K20241129064702




BLK: 2,SNR1:-0.12901 ,SNR2: 1.6405





Frequency (Hz)


1127-14 2024/11/28 21.81UT FUJI -KISO



T20241129070023





BLK: 4, SNR1: 8.2659 ,SNR2: 37.621




Frequency (Hz)

3C263.1 2024/11/28 22.03UT TOYOKAWA-FUJI


F20241129070025





BLK: 4, SNR1: -0.14055 ,SNR2: 2.2422




Frequency (Hz)



T20241129070023





BLK: 6,SNR1: 15.439 ,SNR2: 112.40




Frequency (Hz)

3C263.1 2024/11/28 22.03UT TOYOKAWA-KISO


K20241129070022



BLK: 6,SNR1: 2.0629 ,SNR2: 3.8098




Frequency (Hz)






F20241129070025





BLK: 2,SNR1: 0.20233 ,SNR2: 1.6854




Frequency (Hz)

K20241129070022




BLK: 2,SNR1: 0.40740 ,SNR2: 1.3617




Frequency (Hz)


3C263.1 2024/11/28 22.03UT FUJI -KISO





T20241129070650




BLK: 5,SNR1:-0.85393E-02,SNR2: 1.2055




F20241129070652





BLK: 5,SNR1: 2.7435 ,SNR2: 5.2322




3C267 2024/11/28 22.14UT TOYOKAWA-FUJI



T20241129070650




BLK: 4,SNR1: 0.24755 ,SNR2: 1.0154




Frequency (Hz)

K20241129070649




BLK: 4,SNR1: 6.7307 ,SNR2: 8.8309





Frequency (Hz)


3C267 2024/11/28 22.14UT TOYOKAWA-KISO




F20241129070652




BLK: 4,SNR1: 2.2177 ,SNR2: 5.6438




K20241129070649





BLK: 4,SNR1:-0.22958 ,SNR2: 2.4469




3C267 2024/11/28 22.14UT FUJI -KISO



T20241129073238




BLK: 3,SNR1: 0.36370 ,SNR2: 3.9173




Frequency (Hz)

F20241129073240




BLK: 3,SNR1: 0.36204 ,SNR2: 1.4356




Frequency (Hz)


1213-17 2024/11/28 22.57UT TOYOKAWA-FUJI




T20241129073238




BLK: 4,SNR1: 0.17162 ,SNR2: 2.2123




K20241129073237




BLK: 4,SNR1: 0.79990E-01,SNR2: 0.59470




1213-17 2024/11/28 22.57UT TOYOKAWA-KISO



F20241129073240





BLK: 7,SNR1:-0.16318 ,SNR2: 0.47473




Frequency (Hz)

K20241129073237




BLK: 7,SNR1: 0.40087 ,SNR2: 2.0304




Frequency (Hz)


1213-17 2024/11/28 22:57UT FWJ -KISO



T20241129074555




BLK:13,SNR1: 0.94981 ,SNR2: 4.5118




Frequency (Hz)

3C273 2024/11/28 22.79UT TOYOKAWA-FUJI


F20241129074557



BLK:13,SNR1:-0.74510E-01,SNR2: 2.1787




Frequency (Hz)







T20241129074555




BLK:21,SNR1: 0.90613 ,SNR2: 3.1931




K20241129074554





BLK:21,SNR1: 0.15807 ,SNR2: 2.0707




3C273 2024/11/28 22.79UT TOYOKAWA-KISO



F20241129074557





BLK: 8,SNR1:-0.23324 ,SNR2: 0.46517




Frequency (Hz)

3C273 2024/11/28 22.79UT FUJI -KISO


K20241129074554




BLK: 8,SNR1: 2.1500 ,SNR2: 6.6420




Frequency (Hz)



T20241129075906




BLK:10,SNR1: 2.3682 ,SNR2: 5.4978




Frequency (Hz)

3C275 2024/11/28 23.01UT TOYOKAWA-FUJI


F20241129075908




BLK:10,SNR1:-0.71467E-01,SNR2: 0.88514




Frequency (Hz)




T20241129075906




BLK:11,SNR1: 2.2081 ,SNR2: 4.6122




K20241129075905





BLK:11,SNR1: 3.8276 ,SNR2: 5.0738




3C275 2024/11/28 23.01UT TOYOKAWA-KISO





F20241129075908




BLK: 3,SNR1:-0.11708 ,SNR2: 1.5709




K20241129075905





BLK: 3,SNR1:-0.45546 ,SNR2: 0.87686




3C275 2024/11/28 23.01UT FUJI -KISO



T20241129080511





BLK:13,SNR1: 0.62496 ,SNR2: 1.9698




Frequency (Hz)

F20241129080513




BLK:13,SNR1: 1.1677 ,SNR2: 4.6182




Frequency (Hz)


1245-19 2024/11/28 23.11UT TOYOKAWA-FUJI



T20241129080511





BLK: 7,SNR1: 0.74991 ,SNR2: 2.4586




Frequency (Hz)

K20241129080510




BLK: 7,SNR1: 2.0436 ,SNR2: 6.2837




Frequency (Hz)


1245-19 2024/11/28 23.11UT TOYOKAWA-KISO



F20241129080513




BLK: 5, SNR1: 2.0073 ,SNR2: 6.8787




Frequency (Hz)

1245-19 2024/11/28 23.11UT FUJI -KISO


K20241129080510



BLK: 5, SNR1: 1.4658 ,SNR2: 4.6729




Frequency (Hz)







T20241129081254




BLK: 6,SNR1: 0.21466 ,SNR2: 2.3760




F20241129081256




BLK: 6,SNR1: 1.3564 ,SNR2: 4.1851




3C279 2024/11/28 23.24UT TOYOKAWA-FUJI




T20241129081254




BLK:12,SNR1: 0.48335 ,SNR2: 2.4982




K20241129081253




BLK:12,SNR1: 5.3163 ,SNR2: 13.226




3C279 2024/11/28 23.24UT TOYOKAWA-KISO



F20241129081256




BLK: 7,SNR1: 1.7991 ,SNR2: 4.5595





3C279 2024/11/28 23.24UT FUJI -KISO



K20241129081253




BLK: 7,SNR1: 5.1059 ,SNR2: 11.324



T20241129082824





BLK: 3, SNR1: 0.74848 , SNR2: 3.0684




Frequency (Hz)

3C283 2024/11/28 23.50UT TOYOKAWA-FUJI


F20241129082826





BLK: 3, SNR1: 0.47588 , SNR2: 4.2529




Frequency (Hz)





T20241129082824




No. Good Data




K20241129082823





No. Good Data




3C283 2024/11/28 23.50UT TOYOKAWA-KISO





F20241129082826




No. Good Data




K20241129082823





No. Good Data




3C283 2024/11/28 23.50UT FUJI -KISO



T20241129084248




BLK: 5,SNR1: 0.86619E-01,SNR2: 2.0996





1323+32 2024/11/28 23.74UT TOYOKAWA-FUJI


F20241129084250




BLK: 5,SNR1:-0.12536 ,SNR2: 0.30709



T20241129084248





BLK: 7,SNR1: 0.10284 ,SNR2: 0.56320





1323+32 2024/11/28 23.74UT TOYOKAWA-KISO

K20241129084247




BLK: 7,SNR1: 0.47375 ,SNR2: 2.0404








F20241129084250




BLK: 3, SNR1: 0.16752 , SNR2: 2.1700




K20241129084247





BLK: 3, SNR1: 0.55676 , SNR2: 6.1550




1323+32 2024/11/28 23.74UT FUJI -KISO



T20241129084739





BLK: 9,SNR1: 4.0907 ,SNR2: 19.468





3C286 2024/11/28 23.82UT TOYOKAWA-FUJI



F20241129084741




BLK: 9,SNR1: 3.6945 ,SNR2: 8.1169



T20241129084739




BLK: 9,SNR1: 6.2775 ,SNR2: 29.541





3C286 2024/11/28 23.82UT TOYOKAWA-KISO



K20241129084738




BLK: 9,SNR1: 3.3032 ,SNR2: 7.1875



F20241129084741




BLK: 6, SNR1: 0.50496 , SNR2: 5.3562





3C286 2024/11/28 23.82UT FUJI -KISO


K20241129084738




BLK: 6, SNR1: 0.69820 , SNR2: 6.0196



T20241129090406





BLK: 9, SNR1: 0.53692 , SNR2: 6.6195





1345+12 2024/11/29 0.10UT TOYOKAWA-FUJI


F20241129090408




BLK: 9, SNR1: 0.18899 , SNR2: 1.4249



T20241129090406





BLK:12,SNR1: 0.45585 ,SNR2: 4.9604





1345+12 2024/11/29 0.10UT TOYOKAWA-KISO


K20241129090405




BLK:12,SNR1: 1.3238 ,SNR2: 3.3115





F20241129090408




BLK: 3,SNR1:-0.13532 ,SNR2: 0.21934E-01




K20241129090405





BLK: 3,SNR1:-0.54049E-01,SNR2: 1.6945




1345+12 2024/11/29 0.10UT FUJI -KISO



T20241129091426





BLK: 2,SNR1: 13.034 ,SNR2: 41.290




Frequency (Hz)

1355+01 2024/11/29 0.27UT TOYOKAWA-FUJI


F20241129091426



BLK: 2,SNR1:-0.27293 ,SNR2: 1.5437





Frequency (Hz)






T20241129091426





BLK: 7,SNR1: 5.1561 ,SNR2: 21.819




Frequency (Hz)

1355+01 2024/11/29 0.27UT TOYOKAWA-KISO


K20241129091425




BLK: 7,SNR1: 0.74659 ,SNR2: 4.4844




Frequency (Hz)




F20241129091428




BLK: 5,SNR1:-0.24099 ,SNR2: 0.73428




K20241129091425




BLK: 5,SNR1: 1.0515 ,SNR2: 2.8247




1355+01 2024/11/29 0.27UT FUJI -KISO



T20241129093537




BLK:13,SNR1: 2.0610 ,SNR2: 4.0223





3C298 2024/11/29 0.62UT TOYOKAWA-FUJI


F20241129093539




BLK:13,SNR1: 0.60197 ,SNR2: 5.8282





T20241129093537




BLK:17,SNR1: 1.4875 ,SNR2: 4.4114




K20241129093536




BLK:17,SNR1: 0.76638 ,SNR2: 3.9347




3C298 2024/11/29 0.62UT TOYOKAWA-KISO



F20241129093539





BLK: 3, SNR1: -0.14664 , SNR2: 2.7803





3C298 2024/11/29 0.62UT FUJI -KISO



K20241129093536




BLK: 3, SNR1: 0.43694 , SNR2: 1.0589



T20241129094720




BLK:10,SNR1: 0.98598 ,SNR2: 5.1636





1428-03 2024/11/29 0.82UT TOYOKAWA-FUJI



F20241129094722




BLK:10,SNR1:-0.15302 ,SNR2: 1.9360



T20241129094720





BLK: 7,SNR1: 0.15342 ,SNR2: 0.49022





1428-03 2024/11/29 0.82UT TOYOKAWA-KISO


K20241129094719




BLK: 7,SNR1: 2.4402 ,SNR2: 5.8201



F20241129094722




BLK: 5, SNR1: 0.63398E-01, SNR2: 1.0881




Frequency (Hz)

K20241129094719




BLK: 5, SNR1: 3.9288, SNR2: 7.4757




Frequency (Hz)

1428-03 2024/11/29 0.82UT FUJI -KISO






T20241129095602




BLK: 6, SNR1: 1.6875 , SNR2: 5.8967





1436-16 2024/11/29 0.96UT TOYOKAWA-FUJI


F20241129095604




BLK: 6, SNR1: 6.9085 , SNR2: 16.408



T20241129095602




BLK: 3, SNR1: 1.7471 , SNR2: 12.305




1436-16 2024/11/29 0.96UT TOYOKAWA-KISO


K20241129095601





BLK: 3, SNR1: 7.0746 , SNR2: 17.337




Frequency (Hz)



F20241129095604





BLK: 1, SNR1: 12.641 , SNR2: 28.029




Frequency (Hz)

K20241129095601




BLK: 1, SNR1: 3.6451 , SNR2: 10.313





Frequency (Hz)


1436-16 2024/11/29 0.96UT FUJI -KISO



T20241129101225





BLK: 8,SNR1: 0.46839 ,SNR2: 1.4862





1453-10 2024/11/29 1.24UT TOYOKAWA-FUJI



F20241129101227




BLK: 8,SNR1:-0.26428 ,SNR2: 0.64603





T20241129101225




BLK: 7,SNR1: 0.56757 ,SNR2: 2.6012




K20241129101224




BLK: 7,SNR1: 0.24528 ,SNR2: 2.0844




1453-10 2024/11/29 1.24UT TOYOKAWA-KISO




F20241129101227




BLK: 6, SNR1: -0.62315E-01, SNR2: 1.0140




K20241129101224







BLK: 6, SNR1: 1.2316, SNR2: 4.2646








1453-10 2024/11/29 1.24UT FUJI -KISO






1508-05 2024/11/29 1.48UT TOYOKAWA-FUJI






1508-05 2024/11/29 1.48UT TOYOKAWA-KISO






F20241129102719




BLK: 4, SNR1: 0.49773E-01, SNR2: 3.0193





1508-05 2024/11/29 1.48UT FUJI -KISO


K20241129102716




BLK: 4, SNR1: 5.8448, SNR2: 10.544




T20241129103617




BLK: 8,SNR1: 0.30335 ,SNR2: 1.8215




F20241129103619




BLK: 8,SNR1: 2.4848 ,SNR2: 8.8421




3C318 2024/11/29 1.63UT TOYOKAWA-FUJI





T20241129103617




BLK:16,SNR1: 0.60347 ,SNR2: 3.0195




K20241129103616




BLK:16,SNR1: 3.2625 ,SNR2: 8.2820




3C318 2024/11/29 1.63UT TOYOKAWA-KISO





F20241129103619




BLK: 5,SNR1: 2.9852 ,SNR2: 11.925




K20241129103616





BLK: 5,SNR1: 6.1304 ,SNR2: 15.980




3C318 2024/11/29 1.63UT FUJI -KISO



T20241129104204





BLK:22,SNR1: 23.033 ,SNR2: 33.528





1523+03 2024/11/29 1.73UT TOYOKAWA-FUJI



F20241129104206




BLK:22,SNR1: 9.9103 ,SNR2: 15.751



T20241129104204





BLK:21,SNR1: 22.507 ,SNR2: 32.759




1523+03 2024/11/29 1.73UT TOYOKAWA-KISO


K20241129104203





BLK:21,SNR1: 8.3082 ,SNR2: 16.757




Frequency (Hz)





F20241129104206




BLK:10,SNR1: 18.050 ,SNR2: 24.117




K20241129104203




BLK:10,SNR1: 11.948 ,SNR2: 16.383




1523+03 2024/11/29 1.73UT FUJI -KISO



T20241129105344




BLK: 4, SNR1: 1.2458 , SNR2: 9.8337





1535+139 2024/11/29 1.92UT TOYOKAWA-FUJI

F20241129105346




BLK: 4, SNR1: 16.920 , SNR2: 30.110







T20241129105344




BLK: 6, SNR1: 35.341 , SNR2: 43.804




K20241129105343





BLK: 6, SNR1: 17.344 , SNR2: 22.600




1535+139 2024/11/29 1.92UT TOYOKAWA-KISO



F20241129105346





BLK: 4, SNR1: 27.056 ,SNR2: 38.940




Frequency (Hz)

K20241129105343




BLK: 4, SNR1: 15.633 ,SNR2: 28.739





Frequency (Hz)


1535+139 2024/11/29 1.92UT FUJI -KISO



T20241129110408




BLK: 3,SNR1: 9.9199 ,SNR2: 17.933




1545-12 2024/11/29 2.10UT TOYOKAWA-FUJI


F20241129110410





BLK: 3,SNR1: 9.5234 ,SNR2: 16.188




Frequency (Hz)



T20241129110408




BLK: 4,SNR1: 9.9746 ,SNR2: 17.952




1545-12 2024/11/29 2.10UT TOYOKAWA-KISO


K20241129110407





BLK: 4,SNR1: 0.40778 ,SNR2: 4.7296




Frequency (Hz)



F20241129110410





BLK: 2,SNR1: 4.4481 ,SNR2: 11.444




Frequency (Hz)

K20241129110407




BLK: 2,SNR1: 9.3363 ,SNR2: 17.381





Frequency (Hz)


1545-12 2024/11/29 2.10UT FUJI -KISO



T20241129112511




BLK: 9,SNR1: 2.2678 ,SNR2: 8.8602





1607+26 2024/11/29 2.45UT TOYOKAWA-FUJI



F20241129112513




BLK: 9,SNR1: 8.8494 ,SNR2: 23.379




T20241129112511




BLK: 8,SNR1: 7.9273 ,SNR2: 20.570




K20241129112510





BLK: 8,SNR1: 9.9551 ,SNR2: 25.527




1607+26 2024/11/29 2.45UT TOYOKAWA-KISO



F20241129112513




BLK: 6,SNR1: 8.9502 ,SNR2: 23.643





1607+26 2024/11/29 2.45UT FUJI -KISO

K20241129112510





BLK: 6,SNR1: 8.0304 ,SNR2: 22.107







T20241129114015




BLK:14,SNR1: 24.651 ,SNR2: 44.402




F20241129114017





BLK:14,SNR1: 78.957 ,SNR2: 83.917




1621-11 2024/11/29 2.70UT TOYOKAWA-FUJI



T20241129114015




BLK:14,SNR1: 9.9119 ,SNR2: 24.628




1621-11 2024/11/29 2.70UT TOYOKAWA-KISO


K20241129114014




BLK:14,SNR1: 39.638 ,SNR2: 43.282




Frequency (Hz)




F20241129114017




BLK:12,SNR1: 79.092 ,SNR2: 84.941




K20241129114014




BLK:12,SNR1: 19.068 ,SNR2: 45.903




1621-11 2024/11/29 2.70UT FUJI -KISO



T20241129115111




BLK: 8,SNR1: 10.199 ,SNR2: 18.262





1631-222 2024/11/29 2.88UT TOYOKAWA-FUJI


F20241129115113




BLK: 8,SNR1: 15.540 ,SNR2: 20.255



T20241129115111





BLK: 9,SNR1: 28.191 ,SNR2: 45.179





1631-222 2024/11/29 2.88UT TOYOKAWA-KISO


K20241129115110




BLK: 9,SNR1: 16.632 ,SNR2: 27.416





F20241129115113




BLK: 8,SNR1: 3.4067 ,SNR2: 10.294




K20241129115110





BLK: 8,SNR1: 23.042 ,SNR2: 23.165




1631-222 2024/11/29 2.88UT FUJI -KISO



T20241129115649





BLK: 7,SNR1: 4.1973 ,SNR2: 8.0168





1638-025 2024/11/29 2.98UT TOYOKAWA-FUJI



F20241129115651




BLK: 7,SNR1: 4.9839 ,SNR2: 8.9205



T20241129115649




BLK: 8,SNR1: -0.52390 ,SNR2: 0.74115





1638-025 2024/11/29 2.98UT TOYOKAWA-KISO

K20241129115648





BLK: 8,SNR1: 6.1676 ,SNR2: 12.230







F20241129115651




BLK: 4,SNR1:-0.22669 ,SNR2: 1.9070




K20241129115648





BLK: 4,SNR1: 15.768 ,SNR2: 27.539




1638-025 2024/11/29 2.98UT FUJI -KISO





T20241129120343




BLK:10,SNR1: 1.3198 ,SNR2: 3.3715




F20241129120345





BLK:10,SNR1: 2.7885 ,SNR2: 6.5590




1644-106 2024/11/29 3.09UT TOYOKAWA-FUJI




T20241129120343




BLK: 4,SNR1: 0.31978 ,SNR2: 3.9403




K20241129120342




BLK: 4,SNR1: 1.0218 ,SNR2: 6.4550




1644-106 2024/11/29 3.09UT TOYOKAWA-KISO





F20241129120345




BLK: 4,SNR1: 10.758 ,SNR2: 23.567




K20241129120342





BLK: 4,SNR1: 8.0680 ,SNR2: 27.678




1644-106 2024/11/29 3.09UT FUJI -KISO




T20241129120904




BLK: 7,SNR1: 12.427 ,SNR2: 29.331




F20241129120906





BLK: 7,SNR1: 8.6752 ,SNR2: 24.824




1650+004 2024/11/29 3.18UT TOYOKAWA-FUJI




T20241129120904




BLK: 9,SNR1: 13.073 ,SNR2: 30.857




K20241129120903




BLK: 9,SNR1: 10.997 ,SNR2: 26.036




1650+004 2024/11/29 3.18UT TOYOKAWA-KISO




F20241129120906




BLK: 6,SNR1: 8.9091 ,SNR2: 22.333




K20241129120903





BLK: 6,SNR1: 8.0534 ,SNR2: 20.684




1650+004 2024/11/29 3.18UT FUJI -KISO




T20241129121435




BLK: 2,SNR1: 0.25444 ,SNR2: 1.2708




F20241129121437



BLK: 2,SNR1: 0.10031 ,SNR2: 2.6229





1656+053 2024/11/29 3.27UT TOYOKAWA-FUJI







T20241129121435




BLK: 2,SNR1: 0.72844 ,SNR2: 2.9199




K20241129121434




BLK: 2,SNR1: 4.1173 ,SNR2: 9.7701




1656+053 2024/11/29 3.27UT TOYOKAWA-KISO




F20241129121437




BLK: 3,SNR1: 1.2176 ,SNR2: 4.3676




K20241129121434





BLK: 3,SNR1: 4.2326 ,SNR2: 10.060




1656+053 2024/11/29 3.27UT FUJI -KISO





T20241129123105




BLK:27,SNR1: 9.8327 ,SNR2: 24.547




F20241129123107





BLK:27,SNR1: 9.2136 ,SNR2: 16.427




1712-033 2024/11/29 3.55UT TOYOKAWA-FUJI





T20241129123105




BLK:28,SNR1: 3.2129 ,SNR2: 14.982




K20241129123104





BLK:28,SNR1: 12.040 ,SNR2: 21.366




1712-033 2024/11/29 3.55UT TOYOKAWA-KISO





F20241129123107




BLK:28,SNR1: 7.7811 ,SNR2: 13.923




K20241129123104




BLK:28,SNR1: 12.433 ,SNR2: 21.996




1712-033 2024/11/29 3.55UT FUJI -KISO




T20241129124908




BLK:10,SNR1: 2.1210 ,SNR2: 7.0991




F20241129124910




BLK:10,SNR1: 0.32937 ,SNR2: 3.6265




1730-13 2024/11/29 3.85UT TOYOKAWA-FUJI





T20241129124908




BLK: 8,SNR1: 5.7013 ,SNR2: 13.170




K20241129124907




BLK: 8,SNR1: 2.6740 ,SNR2: 7.7363




1730-13 2024/11/29 3.85UT TOYOKAWA-KISO





F20241129124910




BLK: 6,SNR1: 3.4699 ,SNR2: 10.309




K20241129124907



BLK: 6,SNR1: 1.9074 ,SNR2: 4.9802




1730-13 2024/11/29 3.85UT FUJI -KISO








T20241129130632




BLK:11,SNR1: 16.568 ,SNR2: 33.518




F20241129130634




BLK:11,SNR1: 8.2991 ,SNR2: 24.156




1748+031 2024/11/29 4.14UT TOYOKAWA-FUJI





T20241129130632




BLK:10,SNR1: 12.122 ,SNR2: 31.321




K20241129130631





BLK:10,SNR1: 11.667 ,SNR2: 34.200




1748+031 2024/11/29 4.14UT TOYOKAWA-KISO





F20241129130634




BLK:11,SNR1: 8.6248 ,SNR2: 25.445




K20241129130631





BLK:11,SNR1: 7.5824 ,SNR2: 21.880




1748+031 2024/11/29 4.14UT FUJI -KISO





T20241129131725




BLK: 7,SNR1: 15.572 ,SNR2: 17.990




F20241129131727





BLK: 7,SNR1: 6.7541 ,SNR2: 14.257




1759+13 2024/11/29 4.32UT TOYOKAWA-FUJI




T20241129131725




BLK: 2,SNR1: 5.8779 ,SNR2: 9.4456




K20241129131724




BLK: 2,SNR1: 9.3606 ,SNR2: 19.805




1759+13 2024/11/29 4.32UT TOYOKAWA-KISO



F20241129131727




BLK: 4,SNR1: 7.9173 ,SNR2: 15.710





1759+13 2024/11/29 4.32UT FUJI -KISO



K20241129131724




BLK: 4,SNR1: 8.7976 ,SNR2: 15.262




T20241129133826




BLK: 3,SNR1: 1.3579 ,SNR2: 3.6677




F20241129133828





BLK: 3,SNR1: 0.26579E-02,SNR2: 1.4618




1819-096 2024/11/29 4.67UT TOYOKAWA-FUJI




T20241129133826




BLK: 6,SNR1: 5.8399 ,SNR2: 9.1501




K20241129133825







BLK: 6,SNR1: 3.2259 ,SNR2: 6.2905




1819-096 2024/11/29 4.67UT TOYOKAWA-KISO










1819-096 2024/11/29 4.67UT FUJI -KISO




T20241129134647




BLK: 6,SNR1: 0.27597 ,SNR2: 1.0928




F20241129134649





BLK: 6,SNR1: 0.76698 ,SNR2: 1.4411




1829+29 2024/11/29 4.81UT TOYOKAWA-FUJI





T20241129134647




BLK: 6,SNR1: 0.13041 ,SNR2: 1.3085




K20241129134646





BLK: 6,SNR1: 4.7546 ,SNR2: 7.3527




1829+29 2024/11/29 4.81UT TOYOKAWA-KISO



F20241129134649





BLK: 7,SNR1:-0.95103E-01,SNR2: 1.7243




Frequency (Hz)

K20241129134646




BLK: 7,SNR1: 0.78804 ,SNR2: 3.7184





Frequency (Hz)


1829+29 2024/11/29 4.81UT FUJI -KISO




T20241129135309




BLK: 5,SNR1: 0.21066 ,SNR2: 0.93451




F20241129135311





BLK: 5,SNR1: 1.3131 ,SNR2: 3.6130




1835+134 2024/11/29 4.91UT TOYOKAWA-FUJI




T20241129135309




BLK: 5, SNR1: 0.83350E-01, SNR2: 0.86874




K20241129135308





BLK: 5, SNR1: 5.1039, SNR2: 9.1891




1835+134 2024/11/29 4.91UT TOYOKAWA-KISO





F20241129135311




BLK: 9,SNR1: 3.1271 ,SNR2: 10.976




K20241129135308





BLK: 9,SNR1: 1.1935 ,SNR2: 2.8582




1835+134 2024/11/29 4.91UT FUJI -KISO




T20241129141605




BLK: 3,SNR1: 0.14393 ,SNR2: 0.66802




F20241129141607



BLK: 3,SNR1: 0.15587 ,SNR2: 5.5908





1858+171 2024/11/29 5.30UT TOYOKAWA-FUJI






T20241129141605





BLK: 8,SNR1: 0.19697 ,SNR2: 0.48447




Frequency (Hz)

K20241129141604




BLK: 8,SNR1: 124.70 ,SNR2: 126.57




Frequency (Hz)


1858+171 2024/11/29 5.30UT TOYOKAWA-KISO





F20241129141607




BLK: 9,SNR1: 0.18962 ,SNR2: 4.0747




K20241129141604





BLK: 9,SNR1: 56.364 ,SNR2: 82.880




1858+171 2024/11/29 5.30UT FUJI -KISO




T20241129142650




BLK: 7,SNR1: 115.53 ,SNR2: 125.41




F20241129142652





BLK: 7,SNR1: 0.52411 ,SNR2: 2.3699




1908-20 2024/11/29 5.48UT TOYOKAWA-FUJI





T20241129142650




BLK: 7,SNR1: 101.24 ,SNR2: 115.45




K20241129142649




BLK: 7,SNR1: 2.2437 ,SNR2: 4.9047




1908-20 2024/11/29 5.48UT TOYOKAWA-KISO




F20241129142652




BLK: 6,SNR1: 0.39208 ,SNR2: 2.0002




K20241129142649





BLK: 6,SNR1: 0.46355 ,SNR2: 1.8082




1908-20 2024/11/29 5.48UT FUJI -KISO




T20241129143341




BLK: 6,SNR1: 1.6262 ,SNR2: 4.8417




F20241129143343





BLK: 6,SNR1: 0.57598 ,SNR2: 1.9784




1915-121 2024/11/29 5.59UT TOYOKAWA-FUJI





T20241129143341




BLK:12,SNR1: 1.2774 ,SNR2: 5.3418




K20241129143340





BLK:12,SNR1: 22.335 ,SNR2: 54.448




1915-121 2024/11/29 5.59UT TOYOKAWA-KISO





F20241129143343




BLK:10,SNR1:-0.57879E-01,SNR2: 2.6892




K20241129143340



BLK:10,SNR1: 101.21 ,SNR2: 120.85





1915-121 2024/11/29 5.59UT FUJI -KISO







T20241129144722




BLK: 9,SNR1: 11.184 ,SNR2: 60.730




F20241129144724





BLK: 9,SNR1: 1.2353 ,SNR2: 7.3931




1928-142 2024/11/29 5.82UT TOYOKAWA-FUJI



T20241129144722





BLK: 6,SNR1: 0.32814 ,SNR2: 2.5231




Frequency (Hz)

K20241129144721




BLK: 6,SNR1: 2.1978 ,SNR2: 7.3375





Frequency (Hz)


1928-142 2024/11/29 5.82UT TOYOKAWA-KISO





F20241129144724




BLK: 5,SNR1:-0.20548 ,SNR2: 0.83951




K20241129144721





BLK: 5,SNR1: 2.1570 ,SNR2: 9.6680




1928-142 2024/11/29 5.82UT FUJI -KISO





T20241129145702




BLK:10,SNR1: 0.85844 ,SNR2: 6.9462




F20241129145704





BLK:10,SNR1:-0.12783 ,SNR2: 1.1427




1938-15 2024/11/29 5.98UT TOYOKAWA-FUJI





T20241129145702




BLK: 6,SNR1: 0.94853 ,SNR2: 3.1555




K20241129145701







BLK: 6,SNR1: 0.33654 ,SNR2: 3.3212




1938-15 2024/11/29 5.98UT TOYOKAWA-KISO








1938-15 2024/11/29 5.98UT FUJI -KISO



T20241129153158





BLK: 2,SNR1: 0.23976 ,SNR2: 0.59020




Frequency (Hz)

F20241129153200




BLK: 2,SNR1:-0.29742E-01,SNR2: 0.74116





Frequency (Hz)


2014+358 2024/11/29 6.56UT TOYOKAWA-FUJI





T20241129153158




BLK: 5,SNR1:-0.33272E-01,SNR2: 0.24442




K20241129153157



BLK: 5,SNR1: 1.7120 ,SNR2: 3.8524




2014+358 2024/11/29 6.56UT TOYOKAWA-KISO








F20241129153200




BLK: 2,SNR1:-0.80606E-01,SNR2: 1.3125




K20241129153157





BLK: 2,SNR1: 1.7527 ,SNR2: 7.6588




2014+358 2024/11/29 6.56UT FUJI -KISO




T20241129160234




BLK: 2,SNR1: 0.50855E-01,SNR2: 0.96047




F20241129160236





BLK: 2,SNR1: 0.59478 ,SNR2: 2.7591




3C422 2024/11/29 7.07UT TOYOKAWA-FUJI





T20241129160234




BLK: 4,SNR1: 0.78787E-01,SNR2: 1.0054




K20241129160233




BLK: 4,SNR1: 0.39742 ,SNR2: 2.7949




3C422 2024/11/29 7.07UT TOYOKAWA-KISO





F20241129160236




BLK: 2,SNR1: 0.12672 ,SNR2: 1.3059




K20241129160233





BLK: 2,SNR1: 0.76569E-01,SNR2: 1.0795




3C422 2024/11/29 7.07UT FUJI -KISO



T20241129162312




BLK: 3,SNR1: 0.41020 ,SNR2: 1.6989




Frequency (Hz)

F20241129162314




BLK: 3,SNR1:-0.33029 ,SNR2: 0.40720E-01





Frequency (Hz)


2105-072 2024/11/29 7.41UT TOYOKAWA-FUJI



T20241129162312





BLK:12,SNR1: 0.18628 ,SNR2: 1.8827




Frequency (Hz)

K20241129162311




BLK:12,SNR1: 0.51767 ,SNR2: 3.2148





Frequency (Hz)


2105-072 2024/11/29 7.41UT TOYOKAWA-KISO



F20241129162314





BLK: 8,SNR1:-0.13227 ,SNR2: 1.5730




Frequency (Hz)

K20241129162311




BLK: 8,SNR1: 0.60863 ,SNR2: 4.2296




Frequency (Hz)


2105-072 2024/11/29 7.41UT FUJI -KISO



T20241129163900




BLK:10,SNR1: 7.1879 ,SNR2: 20.187




Frequency (Hz)

F20241129163902




BLK:10,SNR1: 25.623 ,SNR2: 29.424




Frequency (Hz)

2121-014 2024/11/29 7.68UT TOYOKAWA-FUJI






T20241129163900




BLK: 5,SNR1: 5.1252 ,SNR2: 17.281




Frequency (Hz)

K20241129163859




BLK: 5,SNR1: 26.863 ,SNR2: 34.983




Frequency (Hz)


2121-014 2024/11/29 7.68UT TOYOKAWA-KISO



F20241129163902




BLK: 7,SNR1: 7.6790 ,SNR2: 14.381




Frequency (Hz)

K20241129163859




BLK: 7,SNR1: 8.6703 ,SNR2: 15.359




Frequency (Hz)


2121-014 2024/11/29 7.68UT FUJI -KISO



T20241129165316




BLK: 7, SNR1: 0.82181 , SNR2: 7.3019




Frequency (Hz)

F20241129165318




BLK: 7, SNR1: 2.7413 , SNR2: 5.6577




Frequency (Hz)


2135-209 2024/11/29 7.92UT TOYOKAWA-FUJI



T20241129165316




BLK: 6,SNR1: 0.76857 ,SNR2: 7.6480




Frequency (Hz)

K20241129165315




BLK: 6,SNR1: 13.244 ,SNR2: 23.388




Frequency (Hz)


2135-209 2024/11/29 7.92UT TOYOKAWA-KISO




F20241129165318




BLK: 1,SNR1: 0.32521E-01,SNR2: 1.6825




K20241129165315





BLK: 1,SNR1: 4.2423 ,SNR2: 17.678




2135-209 2024/11/29 7.92UT FUJI -KISO



T20241129171440




BLK: 3,SNR1:-0.90491E-01,SNR2: 1.4702




Frequency (Hz)

F20241129171442




BLK: 3,SNR1:-0.68208E-01,SNR2: 4.1073





Frequency (Hz)


2156-043 2024/11/29 8.27UT TOYOKAWA-FUJI



T20241129171440




BLK: 2, SNR1: 0.52944 , SNR2: 1.9906




Frequency (Hz)

K20241129171439








BLK: 2, SNR1: 6.5208 , SNR2: 16.161




Frequency (Hz)

2156-043 2024/11/29 8.27UT TOYOKAWA-KISO






2156-043 2024/11/29 8.27UT FUJI -KISO






T20241129172128





BLK: 6,SNR1: 0.63073 ,SNR2: 7.2653




Frequency (Hz)

F20241129172130




BLK: 6,SNR1: 9.6751 ,SNR2: 17.259





Frequency (Hz)


2203-18 2024/11/29 8.39UT TOYOKAWA-FUJI



T20241129172128




BLK: 6,SNR1: 0.86865 ,SNR2: 8.7675




Frequency (Hz)

K20241129172127




BLK: 6,SNR1: 1.6555 ,SNR2: 7.1198





Frequency (Hz)


2203-18 2024/11/29 8.39UT TOYOKAWA-KISO



F20241129172130





BLK: 3, SNR1: 1.8674 , SNR2: 4.6719




Frequency (Hz)

K20241129172127




BLK: 3, SNR1: 2.8922 , SNR2: 7.6686





Frequency (Hz)


2203-18 2024/11/29 8.39UT FUJI -KISO



T20241129173150





BLK:18,SNR1: 24.812 ,SNR2: 36.766




Frequency (Hz)

F20241129173152




BLK:18,SNR1: 1.9536 ,SNR2: 12.298




Frequency (Hz)


2213-156 2024/11/29 8.56UT TOYOKAWA-FUJI



T20241129173150





BLK:16,SNR1: 15.371 ,SNR2: 27.641




Frequency (Hz)

K20241129173149




BLK:16,SNR1: 46.689 ,SNR2: 59.985





Frequency (Hz)


2213-156 2024/11/29 8.56UT TOYOKAWA-KISO



F20241129173152





BLK:20,SNR1: 30.814 ,SNR2: 45.643




Frequency (Hz)

K20241129173149



BLK:20,SNR1: 50.780 ,SNR2: 65.231



Frequency (Hz)

2213-156 2024/11/29 8.56UT FUJI -KISO

