




TOYOKAWA 1038-191 2024/12/03(338)05:42:15-05:45:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1048-090 2024/12/03(338)05:52:48-05:56:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055-242 2024/12/03(338)05:59:10-06:02:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1059-010 2024/12/03(338)06:03:21-06:06:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1103-208 2024/12/03(338)06:07:35-06:11:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+045 2024/12/03(338)06:11:27-06:14:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1112-101 2024/12/03(338)06:16:19-06:19:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255


2024/12/03(338)06:20:39-06:24:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1120+057 2024/12/03(338)06:24:23-06:27:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2024/12/03(338)06:31:17-06:34:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1131-171 2024/12/03(338)06:35:34-06:39:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2024/12/03(338)06:40:21-06:43:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C263.1 2024/12/03(338)06:44:37-06:48:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267


2024/12/03(338)06:51:04-06:54:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1152-178 2024/12/03(338)06:56:37-07:00:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1213-17 2024/12/03(338)07:16:52-07:20:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273

2024/12/03(338)07:30:09-07:33:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275

2024/12/03(338)07:43:20-07:46:46JST


21653+/- 100




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1245-19 2024/12/03(338)07:49:25-07:52:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C279


2024/12/03(338)07:57:09-08:00:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283 2024/12/03(338)08:12:38-08:16:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2024/12/03(338)08:16:57-08:20:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1323+32 2024/12/03(338)08:27:03-08:30:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286

2024/12/03(338)08:31:53-08:35:19JST


15018+/- 136




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2024/12/03(338)08:38:30-08:41:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1345+12 2024/12/03(338)08:48:20-08:51:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298

2024/12/03(338)09:19:51-09:23:17JST


18600+/- 750




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2024/12/03(338)09:31:35-09:35:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1436-16 2024/12/03(338)09:40:16-09:43:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1453-10 2024/12/03(338)09:56:39-10:00:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1508-05 2024/12/03(338)10:11:32-10:14:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318

2024/12/03(338)10:20:32-10:23:58JST


16968+/- 72




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1523+03 2024/12/03(338)10:26:19-10:29:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1535+139 2024/12/03(338)10:37:58-10:41:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1548+05 2024/12/03(338)10:51:04-10:54:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1607+26 2024/12/03(338)11:09:25-11:12:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1621-11 2024/12/03(338)11:24:29-11:27:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1638-025 2024/12/03(338)11:41:03-11:44:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1644-106 2024/12/03(338)11:47:58-11:51:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1650+004 2024/12/03(338)11:53:18-11:56:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1656+053 2024/12/03(338)11:58:50-12:02:16JST


20136+/- 276




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1712-033 2024/12/03(338)12:15:20-12:18:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1730-13 2024/12/03(338)12:33:22-12:36:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1748+031 2024/12/03(338)12:50:47-12:54:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1759+13 2024/12/03(338)13:01:40-13:05:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1819-096 2024/12/03(338)13:22:40-13:26:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1829+29 2024/12/03(338)13:31:01-13:34:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1858+171 2024/12/03(338)14:00:20-14:03:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1908-20 2024/12/03(338)14:11:05-14:14:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1915-121 2024/12/03(338)14:17:55-14:21:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1928-142 2024/12/03(338)14:31:37-14:35:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1938-15 2024/12/03(338)14:41:16-14:44:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2014+358 2024/12/03(338)15:16:12-15:19:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C422 2024/12/03(338)15:46:49-15:50:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2105-072 2024/12/03(338)16:07:26-16:10:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2121-014 2024/12/03(338)16:23:15-16:26:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2135-209 2024/12/03(338)16:37:30-16:40:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2147+145 2024/12/03(338)16:49:50-16:53:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156-043 2024/12/03(338)16:58:54-17:02:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2203-18 2024/12/03(338)17:05:43-17:09:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2210+016 2024/12/03(338)17:12:05-17:15:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243-191 2024/12/03(338)17:45:16-17:48:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2247-232 2024/12/03(338)17:49:55-17:53:21JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2254-248 2024/12/03(338)17:57:04-18:00:30JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

