




T20241209054402




BLK: 3,SNR1: 0.11933 ,SNR2: 1.4975




Frequency (Hz)

F20241209054404




BLK: 3,SNR1: 1.0883 ,SNR2: 8.5353





Frequency (Hz)


1103-208 2024/12/08 20.76UT TOYOKAWA-FUJI



T20241209054402





BLK: 3,SNR1: 0.73961E-01,SNR2: 1.6014




Frequency (Hz)

K20241209054400




BLK: 3,SNR1:-0.20981 ,SNR2: 0.13064




Frequency (Hz)

1103-208 2024/12/08 20.76UT TOYOKAWA-KISO






F20241209054404





BLK: 2,SNR1: 0.85969E-01,SNR2: 0.94243




Frequency (Hz)

K20241209054400




BLK: 2,SNR1:-0.10903 ,SNR2: 0.52795E-02





Frequency (Hz)


1103-208 2024/12/08 20.76UT FUJI -KISO



T20241209055030





BLK: 8,SNR1: 0.11661 ,SNR2: 1.9893




Frequency (Hz)

F20241209055032




BLK: 8,SNR1: 0.63933 ,SNR2: 2.3878





Frequency (Hz)


1110-217 2024/12/08 20.87UT TOYOKAWA-FUJI



T20241209055030





BLK:12,SNR1: 0.26024 ,SNR2: 3.0235




Frequency (Hz)

K20241209055028




BLK:12,SNR1: 5.4472 ,SNR2: 12.656




Frequency (Hz)


1110-217 2024/12/08 20.87UT TOYOKAWA-KISO




F20241209055032




BLK: 8,SNR1: 1.2109 ,SNR2: 3.4632




K20241209055028





BLK: 8,SNR1: 1.2928 ,SNR2: 2.4878




1110-217 2024/12/08 20.87UT FUJI -KISO



T20241209055434




BLK: 9,SNR1: 0.60687E-01,SNR2: 1.7332




Frequency (Hz)

F20241209055436




BLK: 9,SNR1: 10.898 ,SNR2: 19.777





Frequency (Hz)


1114-220 2024/12/08 20.94UT TOYOKAWA-FUJI



T20241209055434




BLK: 9,SNR1: 0.40002E-01,SNR2: 1.8388




Frequency (Hz)

K20241209055432




BLK: 9,SNR1: 1.4181 ,SNR2: 4.2329





Frequency (Hz)


1114-220 2024/12/08 20.94UT TOYOKAWA-KISO



F20241209055436





BLK: 2,SNR1: 0.92287 ,SNR2: 3.5701




Frequency (Hz)

K20241209055432




BLK: 2,SNR1: 2.9143 ,SNR2: 6.7184





Frequency (Hz)


1114-220 2024/12/08 20.94UT FUJI -KISO



T20241209060136





BLK: 2,SNR1: 0.38077 ,SNR2: 3.7867




Frequency (Hz)

F20241209060138




BLK: 2,SNR1:-0.12238 ,SNR2: 1.2267





Frequency (Hz)

1121-119 2024/12/08 21.05UT TOYOKAWA-FUJI






T20241209060136




BLK: 2,SNR1: 0.36902 ,SNR2: 1.4153




Frequency (Hz)

K20241209060134




BLK: 2,SNR1: 2.4563 ,SNR2: 6.5869





Frequency (Hz)


1121-119 2024/12/08 21.05UT TOYOKAWA-KISO



F20241209060138




BLK: 1,SNR1:-0.19219 ,SNR2: 1.6523




Frequency (Hz)

K20241209060134




BLK: 1,SNR1: 0.79913 ,SNR2: 2.6227





Frequency (Hz)


1121-119 2024/12/08 21:05UT FUJI -KISO



T20241209060744





BLK: 6,SNR1: 2.1443 ,SNR2: 18.149




Frequency (Hz)

F20241209060746




BLK: 6,SNR1: 0.66585 ,SNR2: 2.6203





Frequency (Hz)


1127-14 2024/12/08 21.16UT TOYOKAWA-FUJI



T20241209060744





BLK: 4,SNR1: 0.21121 ,SNR2: 1.7782




Frequency (Hz)

1127-14 2024/12/08 21.16UT TOYOKAWA-KISO


K20241209060742





BLK: 4,SNR1: 0.54426 ,SNR2: 1.5022




Frequency (Hz)



F20241209060746





BLK: 1,SNR1:-0.62341E-01,SNR2: 0.77154




Frequency (Hz)

K20241209060742




BLK: 1,SNR1: 0.79357 ,SNR2: 3.0094





Frequency (Hz)


1127-14 2024/12/08 21.16UT FUJI -KISO



T20241209061201





BLK: 8,SNR1: 24.624 ,SNR2: 59.918




Frequency (Hz)

F20241209061203




BLK: 8,SNR1: 1.7492 ,SNR2: 4.4841





Frequency (Hz)


1131-171 2024/12/08 21.23UT TOYOKAWA-FUJI



T20241209061201





BLK: 8,SNR1: 18.046 ,SNR2: 142.33




Frequency (Hz)

K20241209061159




BLK: 8,SNR1: 2.8951 ,SNR2: 6.7397





Frequency (Hz)


1131-171 2024/12/08 21.23UT TOYOKAWA-KISO



F20241209061203





BLK: 4,SNR1: 1.0035 ,SNR2: 3.0859




Frequency (Hz)

K20241209061159




BLK: 4,SNR1: 6.7168 ,SNR2: 13.017





Frequency (Hz)

1131-171 2024/12/08 21.23UT FUJI -KISO






T20241209061647




BLK: 6,SNR1: 0.25474 ,SNR2: 1.6326




Frequency (Hz)

F20241209061649




BLK: 6,SNR1: -0.54539E-01,SNR2: 0.78465





Frequency (Hz)


1136-13 2024/12/08 21.31UT TOYOKAWA-FUJI



T20241209061647




BLK: 9,SNR1: 0.28450 ,SNR2: 3.5376




Frequency (Hz)

K20241209061645




BLK: 9,SNR1: 22.916 ,SNR2: 52.975




Frequency (Hz)


1136-13 2024/12/08 21.31UT TOYOKAWA-KISO



F20241209061649





BLK: 4,SNR1: 0.58526E-01,SNR2: 1.5054




Frequency (Hz)

K20241209061645




BLK: 4,SNR1: 9.2059 ,SNR2: 32.380





Frequency (Hz)


1136-13 2024/12/08 21.31UT FUJI -KISO



T20241209062204





BLK: 3,SNR1:-0.10823 ,SNR2: 1.0621




Frequency (Hz)

F20241209062206




BLK: 3,SNR1:-0.87873E-01,SNR2: 0.95173





Frequency (Hz)


1141-174 2024/12/08 21.40UT TOYOKAWA-FUJI



T20241209062204





BLK: 4,SNR1: 8.4919 ,SNR2: 16.338




Frequency (Hz)

K20241209062202




BLK: 4,SNR1: 11.123 ,SNR2: 27.317





Frequency (Hz)


1141-174 2024/12/08 21.40UT TOYOKAWA-KISO



F20241209062206





BLK: 5,SNR1: 1.6596 ,SNR2: 5.1434




Frequency (Hz)

K20241209062202




BLK: 5,SNR1: 7.5400 ,SNR2: 18.623





Frequency (Hz)


1141-174 2024/12/08 21.40UT FUJI -KISO



T20241209063303





BLK: 4,SNR1: 34.976 ,SNR2: 63.082




Frequency (Hz)

F20241209063305




BLK: 4,SNR1: 7.9453 ,SNR2: 19.938




Frequency (Hz)


1152-178 2024/12/08 21.58UT TOYOKAWA-FUJI



T20241209063303




BLK: 1,SNR1: 0.91113E-01,SNR2: 2.4197




Frequency (Hz)

K20241209063301




BLK: 1,SNR1: 2.1533 ,SNR2: 5.5454





Frequency (Hz)

1152-178 2024/12/08 21.58UT TOYOKAWA-KISO






F20241209063305





BLK: 1, SNR1: 8.7986 ,SNR2: 21.718




Frequency (Hz)

K20241209063301




BLK: 1, SNR1: 4.6227 ,SNR2: 11.927





Frequency (Hz)


1152-178 2024/12/08 21:58UT FUJI -KISO



T20241209065319





BLK: 1,SNR1: 2.3135 ,SNR2: 11.198




Frequency (Hz)

F20241209065321




BLK: 1,SNR1: 2.7450 ,SNR2: 12.319





Frequency (Hz)


1213-17 2024/12/08 21.92UT TOYOKAWA-FUJI



T20241209065319





No.Good Data




Frequency (Hz)

K20241209065317




No.Good Data





Frequency (Hz)


1213-17 2024/12/08 21.92UT TOYOKAWA-KISO



F20241209065321





BLK: 1,SNR1: 10.443 ,SNR2: 25.941




Frequency (Hz)

1213-17 2024/12/08 21.92UT FUJI -KISO


K20241209065317





BLK: 1,SNR1: 8.6013 ,SNR2: 21.545




Frequency (Hz)



T20241209070636





BLK: 5,SNR1: 8.0004 ,SNR2: 19.829




Frequency (Hz)

3C273 2024/12/08 22.14UT TOYOKAWA-FUJI


F20241209070638





BLK: 5,SNR1: 19.258 ,SNR2: 34.525




Frequency (Hz)



T20241209070636





BLK: 1,SNR1: 2.3924 ,SNR2: 10.983




Frequency (Hz)

3C273 2024/12/08 22.14UT TOYOKAWA-KISO


K20241209070634





BLK: 1,SNR1: 10.270 ,SNR2: 25.167




Frequency (Hz)



F20241209070638





BLK: 2,SNR1: 5.1567 ,SNR2: 11.277




Frequency (Hz)

3C273 2024/12/08 22.14UT FUJI -KISO


K20241209070634





BLK: 2,SNR1: 8.8460 ,SNR2: 25.916




Frequency (Hz)





T20241209071947




No.Good Data




F20241209071949



No.Good Data





3C275 2024/12/08 22.36UT TOYOKAWA-FUJI






T20241209071947





BLK: 1,SNR1: 19.679 ,SNR2: 36.517




Frequency (Hz)

K20241209071944




BLK: 1,SNR1: 9.0184 ,SNR2: 22.188





Frequency (Hz)


3C275 2024/12/08 22.36UT TOYOKAWA-KISO



F20241209071949





BLK: 2,SNR1: 18.348 ,SNR2: 32.897




Frequency (Hz)

3C275 2024/12/08 22.36UT FUJI -KISO


K20241209071944





BLK: 2,SNR1: 8.7115 ,SNR2: 25.727




Frequency (Hz)



T20241209072552





BLK: 3,SNR1: 1.1828 ,SNR2: 12.273





1245-19 2024/12/08 22.46UT TOYOKAWA-FUJI



F20241209072554




BLK: 3,SNR1: 0.33759 ,SNR2: 3.6837



T20241209072552





BLK: 2,SNR1: 1.1589 ,SNR2: 9.5920





1245-19 2024/12/08 22.46UT TOYOKAWA-KISO



K20241209072549




BLK: 2,SNR1: 0.14898 ,SNR2: 1.3996



F20241209072554





No. Good Data




Frequency (Hz)

K20241209072549




No. Good Data





Frequency (Hz)


1245-19 2024/12/08 22.46UT FUJI -KISO





T20241209073335




BLK: 6,SNR1: 6.5360 ,SNR2: 12.243




F20241209073337





BLK: 6,SNR1: 11.499 ,SNR2: 27.720




3C279 2024/12/08 22.59UT TOYOKAWA-FUJI



T20241209073335




BLK: 6,SNR1: 2.5673 ,SNR2: 7.6625




Frequency (Hz)

3C279 2024/12/08 22.59UT TOYOKAWA-KISO


K20241209073332





BLK: 6,SNR1: 36.078 ,SNR2: 56.526




Frequency (Hz)



F20241209073337





BLK: 4,SNR1: 8.6671 ,SNR2: 21.576




Frequency (Hz)

3C279 2024/12/08 22.59UT FUJI -KISO


K20241209073332



BLK: 4,SNR1: 19.376 ,SNR2: 42.936




Frequency (Hz)






T20241209074905




BLK: 1,SNR1: 18.956 ,SNR2: 34.420




Frequency (Hz)

3C283 2024/12/08 22.85UT TOYOKAWA-FUJI


F20241209074907




BLK: 1,SNR1: 17.481 ,SNR2: 30.683




Frequency (Hz)



T20241209074905




BLK: 1,SNR1: 1.7764 ,SNR2: 5.1945





3C283 2024/12/08 22.85UT TOYOKAWA-KISO



K20241209074902




BLK: 1,SNR1: 4.2264 ,SNR2: 11.849



F20241209074907





BLK: 2, SNR1: 9.9459 , SNR2: 24.402




Frequency (Hz)

3C283 2024/12/08 22.85UT FUJI -KISO


K20241209074902





BLK: 2, SNR1: 4.4188 , SNR2: 9.6155




Frequency (Hz)



T20241209080329




BLK: 3,SNR1: 0.74399 ,SNR2: 3.0582





1323+32 2024/12/08 23.09UT TOYOKAWA-FUJI



F20241209080331




BLK: 3,SNR1: 13.013 ,SNR2: 30.558



T20241209080329




BLK: 2,SNR1: 7.7091 ,SNR2: 19.476





1323+32 2024/12/08 23.09UT TOYOKAWA-KISO


K20241209080326




BLK: 2,SNR1: 7.6051 ,SNR2: 18.905



F20241209080331





BLK: 1, SNR1: 5.7728 , SNR2: 18.683





1323+32 2024/12/08 23.09UT FUJI -KISO



K20241209080326




BLK: 1, SNR1: 11.229 , SNR2: 26.483



T20241209080820





BLK: 8,SNR1: 13.421 ,SNR2: 29.869




Frequency (Hz)

3C286 2024/12/08 23.17UT TOYOKAWA-FUJI


F20241209080822





BLK: 8,SNR1: 10.637 ,SNR2: 26.526




Frequency (Hz)



T20241209080820





BLK:11,SNR1: 13.383 ,SNR2: 29.781




Frequency (Hz)

3C286 2024/12/08 23.17UT TOYOKAWA-KISO


K20241209080817



BLK:11,SNR1: 11.349 ,SNR2: 25.393





Frequency (Hz)






F20241209080822





BLK:10,SNR1: 11.744 ,SNR2: 26.544




Frequency (Hz)

3C286 2024/12/08 23.17UT FUJI -KISO


K20241209080817





BLK:10,SNR1: 11.102 ,SNR2: 24.892




Frequency (Hz)



T20241209082447




BLK:27,SNR1: 14.264 ,SNR2: 19.980





1345+12 2024/12/08 23.44UT TOYOKAWA-FUJI



F20241209082449




BLK:27,SNR1: 10.981 ,SNR2: 20.670



T20241209082447





BLK:21,SNR1: 14.293 ,SNR2: 20.021





1345+12 2024/12/08 23.44UT TOYOKAWA-KISO


K20241209082444




BLK:21,SNR1: 10.794 ,SNR2: 19.336





F20241209082449




BLK:21,SNR1: 12.023 ,SNR2: 22.633




K20241209082444




BLK:21,SNR1: 11.512 ,SNR2: 20.789




1345+12 2024/12/08 23.44UT FUJI -KISO



T20241209083507




BLK: 3, SNR1: 2.0776 , SNR2: 6.4968





1355+01 2024/12/08 23.61UT TOYOKAWA-FUJI


F20241209083509




BLK: 3, SNR1: 17.108 , SNR2: 35.776



T20241209083507




BLK: 7,SNR1: 3.1944 ,SNR2: 5.9603





1355+01 2024/12/08 23.61UT TOYOKAWA-KISO


K20241209083504




BLK: 7,SNR1: 14.546 ,SNR2: 32.524




F20241209083509




BLK: 2, SNR1: 8.1776 ,SNR2: 17.785




K20241209083504





BLK: 2, SNR1: 12.260 ,SNR2: 21.324




1355+01 2024/12/08 23.61UT FUJI -KISO





T20241209085410




BLK: 5, SNR1: 7.3515 ,SNR2: 18.856




F20241209085412



BLK: 5, SNR1: 15.493 ,SNR2: 35.938





1414+074 2024/12/08 23.93UT TOYOKAWA-FUJI






T20241209085410




BLK: 6,SNR1: 8.1874 ,SNR2: 23.126





1414+074 2024/12/08 23.93UT TOYOKAWA-KISO


K20241209085407




BLK: 6,SNR1: 8.0217 ,SNR2: 23.110




F20241209085412




BLK: 4, SNR1: 15.494 ,SNR2: 35.544




K20241209085407




BLK: 4, SNR1: 10.782 ,SNR2: 26.843




1414+074 2024/12/08 23.93UT FUJI -KISO



T20241209090801




BLK: 5,SNR1: 24.343 ,SNR2: 92.042





1428-03 2024/12/09 0.16UT TOYOKAWA-FUJI


F20241209090803




BLK: 5,SNR1: 8.4894 ,SNR2: 17.836



T20241209090801





BLK: 7,SNR1: 0.27654 ,SNR2: 1.6552





1428-03 2024/12/09 0.16UT TOYOKAWA-KISO


K20241209090758




BLK: 7,SNR1: 2.9995 ,SNR2: 3.9759



F20241209090803





BLK: 1,SNR1: 0.40095E-02,SNR2: 0.66506





1428-03 2024/12/09 0.16UT FUJI -KISO



K20241209090758




BLK: 1,SNR1:-0.60930E-01,SNR2: 0.40363



T20241209091643





BLK:13,SNR1: 13.060 ,SNR2: 30.440




Frequency (Hz)

1436-16 2024/12/09 0.31UT TOYOKAWA-FUJI


F20241209091645





BLK:13,SNR1: 14.079 ,SNR2: 33.060




Frequency (Hz)



T20241209091643





BLK:10,SNR1: 12.066 ,SNR2: 28.498




Frequency (Hz)

1436-16 2024/12/09 0.31UT TOYOKAWA-KISO


K20241209091640





BLK:10,SNR1: 14.759 ,SNR2: 34.525




Frequency (Hz)



F20241209091645





BLK:14,SNR1: 13.491 ,SNR2: 31.646




Frequency (Hz)

1436-16 2024/12/09 0.31UT FUJI -KISO


K20241209091640



BLK:14,SNR1: 14.555 ,SNR2: 34.048





Frequency (Hz)








T20241209093306




No. Good Data




F20241209093308





No. Good Data




1453-10 2024/12/09 0.58UT TOYOKAWA-FUJI



T20241209093306




BLK: 7,SNR1: 0.28983 ,SNR2: 2.1815





1453-10 2024/12/09 0.58UT TOYOKAWA-KISO



K20241209093303




BLK: 7,SNR1: 5.4342 ,SNR2: 20.307




F20241209093308




BLK: 6, SNR1: 2.0286 ,SNR2: 4.1541




K20241209093303




BLK: 6, SNR1: 16.632 ,SNR2: 29.420




1453-10 2024/12/09 0.58UT FUJI -KISO



T20241209094758




BLK:15,SNR1: 5.0584 ,SNR2: 13.090




1508-05 2024/12/09 0.83UT TOYOKAWA-FUJI


F20241209094800




BLK:15,SNR1: 0.94272E-01,SNR2: 2.1873




Frequency (Hz)



T20241209094758




BLK:10,SNR1: 7.3468 ,SNR2: 16.519




1508-05 2024/12/09 0.83UT TOYOKAWA-KISO


K20241209094755




BLK:10,SNR1: 4.5436 ,SNR2: 12.005




Frequency (Hz)



F20241209094800




BLK: 9,SNR1: -0.11799 ,SNR2: 1.8972





1508-05 2024/12/09 0.83UT FUJI -KISO



K20241209094755




BLK: 9,SNR1: 3.7727 ,SNR2: 9.9886



T20241209095658





BLK:13,SNR1: 0.29196 ,SNR2: 1.0038





3C318 2024/12/09 0.98UT TOYOKAWA-FUJI



F20241209095700




BLK:13,SNR1: 2.2869 ,SNR2: 9.2264



T20241209095658





BLK: 1,SNR1: 0.11958 ,SNR2: 0.88213




Frequency (Hz)

3C318 2024/12/09 0.98UT TOYOKAWA-KISO


K20241209095655



BLK: 1,SNR1: 1.5208 ,SNR2: 6.4665





Frequency (Hz)







F20241209095700




BLK: 3,SNR1: 0.27349 ,SNR2: 5.0283




K20241209095655





BLK: 3,SNR1: 1.7101 ,SNR2: 4.9461




3C318 2024/12/09 0.98UT FUJI -KISO



T20241209100245




BLK:10,SNR1: 23.825 ,SNR2: 44.680





1523+03 2024/12/09 1.07UT TOYOKAWA-FUJI



F20241209100247




BLK:10,SNR1: 2.6404 ,SNR2: 38.939



T20241209100245




BLK:25,SNR1: 31.716 ,SNR2: 45.767





1523+03 2024/12/09 1.07UT TOYOKAWA-KISO


K20241209100242




BLK:25,SNR1: 3.2471 ,SNR2: 7.3614



F20241209100247





BLK: 9,SNR1: 2.6484 ,SNR2: 41.903





1523+03 2024/12/09 1.07UT FUJI -KISO



K20241209100242




BLK: 9,SNR1: 4.4825 ,SNR2: 9.7431





T20241209101425




BLK:15,SNR1: 13.858 ,SNR2: 27.698




F20241209101427





BLK:15,SNR1: 46.714 ,SNR2: 68.729




1535+139 2024/12/09 1.27UT TOYOKAWA-FUJI





T20241209101425




BLK:13,SNR1: 18.207 ,SNR2: 26.224




K20241209101422





BLK:13,SNR1: 0.25067 ,SNR2: 1.6201




1535+139 2024/12/09 1.27UT TOYOKAWA-KISO





F20241209101427




BLK:12,SNR1: 53.680 ,SNR2: 75.141




K20241209101422




BLK:12,SNR1: 1.0212 ,SNR2: 5.3530




1535+139 2024/12/09 1.27UT FUJI -KISO




T20241209102730




BLK: 7,SNR1: 0.11800 ,SNR2: 1.4191




F20241209102732



BLK: 7,SNR1: 0.43379 ,SNR2: 4.8890




1548+05 2024/12/09 1.49UT TOYOKAWA-FUJI







T20241209102730




BLK: 8,SNR1: 0.34116E-01,SNR2: 0.82063




K20241209102727







BLK: 8,SNR1: 4.8622 ,SNR2: 9.4142




1548+05 2024/12/09 1.49UT TOYOKAWA-KISO








1548+05 2024/12/09 1.49UT FUJI -KISO



T20241209104552





BLK: 2,SNR1: 0.12624 ,SNR2: 0.44099




Frequency (Hz)

F20241209104554




BLK: 2,SNR1: 0.28640 ,SNR2: 2.1709





Frequency (Hz)


1607+26 2024/12/09 1.79UT TOYOKAWA-FUJI



T20241209104552





BLK: 6,SNR1:-0.75188E-02,SNR2: 0.27556





1607+26 2024/12/09 1.79UT TOYOKAWA-KISO


K20241209104550




BLK: 6,SNR1: 0.31084 ,SNR2: 1.6281





F20241209104554




BLK: 3,SNR1: 0.42137 ,SNR2: 1.8195




K20241209104550





BLK: 3,SNR1: 0.41703 ,SNR2: 1.9453




1607+26 2024/12/09 1.79UT FUJI -KISO



T20241209110056





BLK: 1,SNR1: 0.67732 ,SNR2: 1.5446




1621-11 2024/12/09 2.04UT TOYOKAWA-FUJI


F20241209110058





BLK: 1,SNR1: 0.98708 ,SNR2: 11.242




Frequency (Hz)



T20241209110056





BLK:12,SNR1: 0.21580 ,SNR2: 1.0054










1621-11 2024/12/09 2.04UT TOYOKAWA-KISO

K20241209110054





BLK:12,SNR1: 117.39 ,SNR2: 123.47










T20241209111152




BLK:23,SNR1: 4.0157 ,SNR2: 6.6922




F20241209111154





BLK:23,SNR1: 2.6919 ,SNR2: 4.5323




1631-222 2024/12/09 2.23UT TOYOKAWA-FUJI





T20241209111152




BLK:23,SNR1: 2.3877 ,SNR2: 4.6716




K20241209111149




BLK:23,SNR1: 30.045 ,SNR2: 31.436




1631-222 2024/12/09 2.23UT TOYOKAWA-KISO



F20241209111154




BLK:15,SNR1: 10.069 ,SNR2: 21.352





1631-222 2024/12/09 2.23UT FUJI -KISO


K20241209111149




BLK:15,SNR1: 8.7760 ,SNR2: 11.667




T20241209111730




BLK:12,SNR1: 2.1238 ,SNR2: 4.3796




F20241209111732





BLK:12,SNR1: 0.63159 ,SNR2: 3.4920




1638-025 2024/12/09 2.32UT TOYOKAWA-FUJI




T20241209111730




BLK:15,SNR1: 1.9078 ,SNR2: 3.8546




K20241209111728




BLK:15,SNR1: 1.3453 ,SNR2: 2.6215




1638-025 2024/12/09 2.32UT TOYOKAWA-KISO



F20241209111732





BLK:11,SNR1: 0.48220 ,SNR2: 3.0742





1638-025 2024/12/09 2.32UT FUJI -KISO


K20241209111728




BLK:11,SNR1: 1.3523 ,SNR2: 5.0993



T20241209112424





BLK:10,SNR1: 0.83675 ,SNR2: 3.8167





1644-106 2024/12/09 2.43UT TOYOKAWA-FUJI



F20241209112426




BLK:10,SNR1: 0.74424 ,SNR2: 2.3420




T20241209112424




BLK:19,SNR1: 1.0619 ,SNR2: 4.4589




K20241209112422



BLK:19,SNR1: 7.2595 ,SNR2: 18.051




1644-106 2024/12/09 2.43UT TOYOKAWA-KISO







F20241209112426




BLK: 4, SNR1: 1.2951 ,SNR2: 3.6394




K20241209112422




BLK: 4, SNR1: 1.5274 ,SNR2: 5.2977




1644-106 2024/12/09 2.43UT FUJI -KISO




T20241209112945




BLK: 4,SNR1: 0.97338 ,SNR2: 3.6394




F20241209112947




BLK: 4,SNR1: 0.85033E-01,SNR2: 1.3969




1650+004 2024/12/09 2.52UT TOYOKAWA-FUJI





T20241209112945




BLK:12,SNR1: 0.36813 ,SNR2: 3.0667




K20241209112943




BLK:12,SNR1: 0.82007 ,SNR2: 3.6507




1650+004 2024/12/09 2.52UT TOYOKAWA-KISO





F20241209112947




BLK: 4,SNR1:-0.30962 ,SNR2: 0.87564




K20241209112943





BLK: 4,SNR1: 0.46129 ,SNR2: 2.2795




1650+004 2024/12/09 2.52UT FUJI -KISO




T20241209113516




BLK: 7,SNR1: 0.35183 ,SNR2: 1.8090




F20241209113518





BLK: 7,SNR1: 1.7330 ,SNR2: 6.7107




1656+053 2024/12/09 2.62UT TOYOKAWA-FUJI




T20241209113516




BLK: 8,SNR1: 0.34371 ,SNR2: 2.0958




K20241209113514







BLK: 8,SNR1: 3.7982 ,SNR2: 6.8156




1656+053 2024/12/09 2.62UT TOYOKAWA-KISO








1656+053 2024/12/09 2.62UT FUJI -KISO




T20241209115146




BLK:14,SNR1: 0.31806 ,SNR2: 1.5255




F20241209115148



BLK:14,SNR1: 0.52281 ,SNR2: 2.4513





1712-033 2024/12/09 2.89UT TOYOKAWA-FUJI







T20241209115146




BLK:16,SNR1: 0.33965 ,SNR2: 1.5576




K20241209115144




BLK:16,SNR1: 1.2535 ,SNR2: 2.5545




1712-033 2024/12/09 2.89UT TOYOKAWA-KISO




F20241209115148




BLK:20,SNR1: 0.15329 ,SNR2: 2.2970




K20241209115144





BLK:20,SNR1: 1.1757 ,SNR2: 2.4101




1712-033 2024/12/09 2.89UT FUJI -KISO





T20241209120949




BLK:12,SNR1: 1.6193 ,SNR2: 5.4686




F20241209120951




BLK:12,SNR1:-0.49567E-01,SNR2: 2.6264




1730-13 2024/12/09 3.19UT TOYOKAWA-FUJI





T20241209120949




BLK:20,SNR1: 1.5067 ,SNR2: 5.6056




K20241209120947




BLK:20,SNR1: 7.2415 ,SNR2: 18.187




1730-13 2024/12/09 3.19UT TOYOKAWA-KISO




F20241209120951




BLK:11,SNR1:-0.39611E-01,SNR2: 2.7370




K20241209120947





BLK:11,SNR1: 2.2055 ,SNR2: 3.2347




1730-13 2024/12/09 3.19UT FUJI -KISO




T20241209122713




BLK: 2,SNR1:-0.37173E-03,SNR2: 1.5324




F20241209122715







BLK: 2,SNR1:-0.32224 ,SNR2: 0.95529




1748+031 2024/12/09 3.48UT TOYOKAWA-FUJI







1748+031 2024/12/09 3.48UT TOYOKAWA-KISO





F20241209122715




BLK: 2,SNR1:-0.25381 ,SNR2: 1.0355




K20241209122711



BLK: 2,SNR1: 0.20883 ,SNR2: 0.53541





1748+031 2024/12/09 3.48UT FUJI -KISO







T20241209123806




BLK: 3,SNR1: 0.52796 ,SNR2: 2.0768




F20241209123808





BLK: 3,SNR1: 0.22400E-01,SNR2: 2.1545




1759+13 2024/12/09 3.66UT TOYOKAWA-FUJI





T20241209123806




BLK:14,SNR1: 0.17794 ,SNR2: 1.3047




K20241209123804




BLK:14,SNR1: 0.69725 ,SNR2: 5.6275




1759+13 2024/12/09 3.66UT TOYOKAWA-KISO



F20241209123808





BLK: 1,SNR1:-0.24388 ,SNR2: 0.0000





1759+13 2024/12/09 3.66UT FUJI -KISO



K20241209123804




BLK: 1,SNR1:-0.77387E-01,SNR2: 1.5098




T20241209125907




BLK:16,SNR1: 1.7454 ,SNR2: 4.2531




F20241209125909




BLK:16,SNR1: 1.2841 ,SNR2: 3.4683




1819-096 2024/12/09 4.01UT TOYOKAWA-FUJI




T20241209125907




BLK:23,SNR1: 1.2849 ,SNR2: 3.1517




K20241209125905




BLK:23,SNR1: 2.3110 ,SNR2: 4.5141




1819-096 2024/12/09 4.01UT TOYOKAWA-KISO





F20241209125909




BLK:19,SNR1: 0.58407 ,SNR2: 3.1175




K20241209125905




BLK:19,SNR1: 2.6477 ,SNR2: 5.1845




1819-096 2024/12/09 4.01UT FUJI -KISO




T20241209130728




BLK: 4,SNR1: 0.88754E-01,SNR2: 0.36002




F20241209130730





BLK: 4,SNR1: 2.1373 ,SNR2: 5.8330




1829+29 2024/12/09 4.15UT TOYOKAWA-FUJI





T20241209130728




BLK: 3,SNR1: 0.26712 ,SNR2: 2.2273




K20241209130726



BLK: 3,SNR1: 0.24097 ,SNR2: 1.5681





1829+29 2024/12/09 4.15UT TOYOKAWA-KISO






F20241209130730





BLK: 4,SNR1:-0.93845E-02,SNR2: 5.2695





1829+29 2024/12/09 4.15UT FUJI -KISO



K20241209130726




BLK: 4,SNR1: 0.22807 ,SNR2: 2.7893




T20241209131350




BLK: 2,SNR1:-0.11152E-01,SNR2: 0.48182




F20241209131352





BLK: 2,SNR1: 0.66208 ,SNR2: 3.4276




1835+134 2024/12/09 4.26UT TOYOKAWA-FUJI





T20241209131350




BLK: 4,SNR1:-0.67418E-02,SNR2: 0.76637




K20241209131348





BLK: 4,SNR1: 0.15674E-01,SNR2: 2.0724




1835+134 2024/12/09 4.26UT TOYOKAWA-KISO





F20241209131352




BLK: 6,SNR1:-0.20373 ,SNR2: 1.7006




K20241209131348







BLK: 6,SNR1:-0.65103E-01,SNR2: 0.38941








1835+134 2024/12/09 4.26UT FUJI -KISO






1858+171 2024/12/09 4.64UT TOYOKAWA-FUJI







1858+171 2024/12/09 4.64UT TOYOKAWA-KISO





F20241209133648




BLK: 3,SNR1: 1.1762 ,SNR2: 9.9931




K20241209133644





BLK: 3,SNR1: 0.83538 ,SNR2: 2.2122




1858+171 2024/12/09 4.64UT FUJI -KISO




T20241209134731




BLK: 5,SNR1: 0.76323 ,SNR2: 2.4231




F20241209134733



BLK: 5,SNR1: 0.47438 ,SNR2: 3.6873




1908-20 2024/12/09 4.82UT TOYOKAWA-FUJI








T20241209134731




BLK:10,SNR1: 0.42259 ,SNR2: 1.4399




K20241209134729




BLK:10,SNR1: 2.6695 ,SNR2: 6.2816




1908-20 2024/12/09 4.82UT TOYOKAWA-KISO





F20241209134733




BLK: 6,SNR1: 1.8550 ,SNR2: 11.258




K20241209134729





BLK: 6,SNR1: 0.69003E-01,SNR2: 0.99019




1908-20 2024/12/09 4.82UT FUJI -KISO




T20241209135422




BLK: 1,SNR1: 13.423 ,SNR2: 32.089




F20241209135424





BLK: 1,SNR1: 17.116 ,SNR2: 28.211




1915-121 2024/12/09 4.93UT TOYOKAWA-FUJI




T20241209135422




BLK: 2,SNR1: 18.582 ,SNR2: 32.697




K20241209135420




BLK: 2,SNR1: 9.1313 ,SNR2: 22.317




1915-121 2024/12/09 4.93UT TOYOKAWA-KISO




F20241209135424




BLK: 1,SNR1: 10.200 ,SNR2: 24.981




K20241209135420





BLK: 1,SNR1: 4.2581 ,SNR2: 10.590




1915-121 2024/12/09 4.93UT FUJI -KISO




T20241209140803




BLK: 3,SNR1: 5.8417 ,SNR2: 14.499




F20241209140805





BLK: 3,SNR1: 12.483 ,SNR2: 22.058




1928-142 2024/12/09 5.16UT TOYOKAWA-FUJI





T20241209140803




BLK: 3,SNR1: 1.4846 ,SNR2: 6.9257




K20241209140800




BLK: 3,SNR1: 0.41893 ,SNR2: 0.98504





1928-142 2024/12/09 5.16UT TOYOKAWA-KISO







BLK: 2,SNR1: 10.746 ,SNR2: 22.679



BLK: 2,SNR1: 10.377 ,SNR2: 24.021





1928-142 2024/12/09 5.16UT FUJI -KISO







T20241209141743




BLK: 2, SNR1: 19.754 , SNR2: 35.103




F20241209141745




BLK: 2, SNR1: 13.869 , SNR2: 33.389




1938-15 2024/12/09 5.32UT TOYOKAWA-FUJI





T20241209141743




BLK: 8,SNR1: 10.756 ,SNR2: 26.338




K20241209141741




BLK: 8,SNR1: 19.699 ,SNR2: 35.279




1938-15 2024/12/09 5.32UT TOYOKAWA-KISO



F20241209141745





BLK: 4,SNR1: 18.869 ,SNR2: 34.151




Frequency (Hz)

K20241209141741




BLK: 4,SNR1: 20.051 ,SNR2: 34.992




Frequency (Hz)


1938-15 2024/12/09 5.32UT FUJI -KISO



T20241209144455





No.Good Data




Frequency (Hz)

FUJI






No.Good Data




Frequency (Hz)

2007+502 2024/12/09 5.78UT TOYOKAWA-FUJI







2007+502 2024/12/09 5.78UT TOYOKAWA-KISO



FUJI





No.Good Data




Frequency (Hz)

K20241209144453






No.Good Data




Frequency (Hz)





2007+502 2024/12/09 5.78UT FUJI -KISO






2014+358 2024/12/09 5.91UT TOYOKAWA-FUJI










2014+358 2024/12/09 5.91UT TOYOKAWA-KISO









2014+358 2024/12/09 5.91UT FUJI -KISO





T20241209152315




BLK: 2,SNR1: 10.732 ,SNR2: 25.617




F20241209152317




BLK: 2,SNR1: 5.8835 ,SNR2: 9.6409




3C422 2024/12/09 6.42UT TOYOKAWA-FUJI




T20241209152315




BLK: 1,SNR1: 7.0547 ,SNR2: 17.437




K20241209152313





BLK: 1,SNR1: 12.941 ,SNR2: 29.465




3C422 2024/12/09 6.42UT TOYOKAWA-KISO




F20241209152317




BLK: 1,SNR1: 4.7316 ,SNR2: 14.692




K20241209152313





BLK: 1,SNR1: 6.2139 ,SNR2: 15.947




3C422 2024/12/09 6.42UT FUJI -KISO



T20241209154353




BLK: 5,SNR1: 0.67318 ,SNR2: 5.1217




Frequency (Hz)

F20241209154355




BLK: 5,SNR1: 0.20413 ,SNR2: 3.8160





Frequency (Hz)


2105-072 2024/12/09 6.76UT TOYOKAWA-FUJI




T20241209154353




BLK: 1,SNR1: 0.87444 ,SNR2: 6.2223




K20241209154351




BLK: 1,SNR1: 12.648 ,SNR2: 31.045




2105-072 2024/12/09 6.76UT TOYOKAWA-KISO




F20241209154355




BLK: 2,SNR1: 1.4828 ,SNR2: 5.5788




K20241209154351




BLK: 2,SNR1: 2.1010 ,SNR2: 5.9806




2105-072 2024/12/09 6.76UT FUJI -KISO



T20241209161357




BLK: 6,SNR1: 0.11922 ,SNR2: 2.2806




Frequency (Hz)

F20241209161359




BLK: 6,SNR1: 0.96521E-01,SNR2: 8.6512




Frequency (Hz)

2135-209 2024/12/09 7.26UT TOYOKAWA-FUJI






T20241209161357




BLK: 5,SNR1: 0.43162 ,SNR2: 3.8185




Frequency (Hz)

K20241209161354




BLK: 5,SNR1: 0.39146 ,SNR2: 1.3016




Frequency (Hz)


2135-209 2024/12/09 7.26UT TOYOKAWA-KISO





F20241209161359




BLK: 4,SNR1: 0.30351 ,SNR2: 1.1759




K20241209161354





BLK: 4,SNR1: 0.16230 ,SNR2: 3.6491




2135-209 2024/12/09 7.26UT FUJI -KISO



T20241209162616





BLK: 3,SNR1: 0.10364 ,SNR2: 2.5458




Frequency (Hz)

F20241209162618




BLK: 3,SNR1:-0.36954E-01,SNR2: 1.5223





Frequency (Hz)


2147+145 2024/12/09 7.47UT TOYOKAWA-FUJI





T20241209162616




BLK: 6, SNR1: 0.68241E-01, SNR2: 1.8532




K20241209162613




BLK: 6, SNR1: 1.8659, SNR2: 5.1597




2147+145 2024/12/09 7.47UT TOYOKAWA-KISO





F20241209162618




BLK: 5,SNR1: 0.73104E-02,SNR2: 2.0430




K20241209162613





BLK: 5,SNR1: 1.6182 ,SNR2: 4.9087




2147+145 2024/12/09 7.47UT FUJI -KISO



T20241209163521





BLK: 3,SNR1: 0.89642 ,SNR2: 2.9687




Frequency (Hz)

F20241209163523




BLK: 3,SNR1: 6.3449 ,SNR2: 17.506





Frequency (Hz)


2156-043 2024/12/09 7.62UT TOYOKAWA-FUJI



T20241209163521




BLK: 6,SNR1: 1.3842 ,SNR2: 2.3313




Frequency (Hz)

K20241209163518




BLK: 6,SNR1: 12.260 ,SNR2: 30.532





Frequency (Hz)


2156-043 2024/12/09 7.62UT TOYOKAWA-KISO



F20241209163523




BLK: 3,SNR1: 4.0896 ,SNR2: 11.429




Frequency (Hz)

K20241209163518




BLK: 3,SNR1: 11.507 ,SNR2: 33.286





Frequency (Hz)

2156-043 2024/12/09 7.62UT FUJI -KISO






T20241209164209





BLK:13,SNR1: 2.9323 ,SNR2: 5.7916




Frequency (Hz)

F20241209164211




BLK:13,SNR1: 5.1244 ,SNR2: 13.179





Frequency (Hz)


2203-18 2024/12/09 7.73UT TOYOKAWA-FUJI



T20241209164209





BLK: 9,SNR1: 3.5516 ,SNR2: 6.8023




Frequency (Hz)

K20241209164206




BLK: 9,SNR1: 7.0711 ,SNR2: 20.424





Frequency (Hz)


2203-18 2024/12/09 7.73UT TOYOKAWA-KISO





F20241209164211




BLK: 4, SNR1: 5.5784 , SNR2: 16.641




K20241209164206





BLK: 4, SNR1: 8.3050 , SNR2: 23.659




2203-18 2024/12/09 7.73UT FUJI -KISO



T20241209164831





BLK: 5, SNR1: 0.88541, SNR2: 3.5980




Frequency (Hz)

F20241209164833




BLK: 5, SNR1: -0.17039, SNR2: 1.4328





Frequency (Hz)


2210+016 2024/12/09 7.84UT TOYOKAWA-FUJI





T20241209164831




BLK: 7,SNR1: 0.17291 ,SNR2: 1.3421




K20241209164828




BLK: 7,SNR1: 1.2868 ,SNR2: 3.8316




2210+016 2024/12/09 7.84UT TOYOKAWA-KISO



F20241209164833





BLK: 4,SNR1: 0.98350 ,SNR2: 3.2369




Frequency (Hz)

K20241209164828




BLK: 4,SNR1: 1.8474 ,SNR2: 4.6807




Frequency (Hz)


2210+016 2024/12/09 7.84UT FUJI -KISO



T20241209170141




BLK: 7,SNR1: 0.48275E-01,SNR2: 1.0113




Frequency (Hz)

F20241209170143




BLK: 7,SNR1: 0.46766 ,SNR2: 1.8744





Frequency (Hz)


3C446 2024/12/09 8.06UT TOYOKAWA-FUJI





T20241209170141




BLK: 6,SNR1: 0.72344E-01,SNR2: 1.8365




K20241209170138



BLK: 6,SNR1: 0.58703 ,SNR2: 2.2627





3C446 2024/12/09 8.06UT TOYOKAWA-KISO






F20241209170143





BLK: 4, SNR1: -0.13600 , SNR2: 1.0828




Frequency (Hz)

K20241209170138




BLK: 4, SNR1: 0.32079 , SNR2: 0.77740





Frequency (Hz)


3C446 2024/12/09 8.06UT FUJI -KISO



T20241209170825




BLK: 4,SNR1: 0.53936 ,SNR2: 1.3720




Frequency (Hz)

F20241209170827




BLK: 4,SNR1: 9.3380 ,SNR2: 27.482





Frequency (Hz)


2229-093 2024/12/09 8.17UT TOYOKAWA-FUJI



T20241209170825




BLK: 4,SNR1: 0.73848 ,SNR2: 1.9211




Frequency (Hz)

K20241209170822




BLK: 4,SNR1: 10.472 ,SNR2: 30.717





Frequency (Hz)


2229-093 2024/12/09 8.17UT TOYOKAWA-KISO



F20241209170827





BLK: 8, SNR1: 9.1466 , SNR2: 26.922




Frequency (Hz)

K20241209170822




BLK: 8, SNR1: 9.9583 , SNR2: 28.831




Frequency (Hz)


2229-093 2024/12/09 8.17UT FUJI -KISO



T20241209171652




BLK: 9,SNR1: 1.6859 ,SNR2: 5.0152




Frequency (Hz)

F20241209171654





BLK: 9,SNR1: 2.3583 ,SNR2: 6.8293





Frequency (Hz)

2238-113 2024/12/09 8.31UT TOYOKAWA-FUJI







BLK:10,SNR1: 2.6267 ,SNR2: 5.4106




BLK:10,SNR1: 12.796 ,SNR2: 30.828




2238-113 2024/12/09 8.31UT TOYOKAWA-KISO



F20241209171654





BLK: 6,SNR1: 1.1520 ,SNR2: 4.5613




Frequency (Hz)

K20241209171649




BLK: 6,SNR1: 8.9954 ,SNR2: 23.996




Frequency (Hz)


2238-113 2024/12/09 8.31UT FUJI -KISO



T20241209172209





BLK:10,SNR1: 0.25549 ,SNR2: 1.5627




Frequency (Hz)

F20241209172211




BLK:10,SNR1:-0.78106E-01,SNR2: 1.1509





Frequency (Hz)

2243-123 2024/12/09 8.40UT TOYOKAWA-FUJI






T20241209172209





BLK: 7,SNR1: 0.26246 ,SNR2: 1.6542




Frequency (Hz)

K20241209172206




BLK: 7,SNR1: 5.3687 ,SNR2: 15.224




Frequency (Hz)


2243-123 2024/12/09 8.40UT TOYOKAWA-KISO



F20241209172211





BLK: 3,SNR1:-0.74150E-02,SNR2: 1.1670




Frequency (Hz)

K20241209172206




BLK: 3,SNR1:-0.57540E-02,SNR2: 1.9184





Frequency (Hz)


2243-123 2024/12/09 8.40UT FUJI -KISO



T20241209172930




BLK: 5, SNR1: 0.40556 , SNR2: 2.6677




Frequency (Hz)

F20241209172932




BLK: 5, SNR1: 6.8428 , SNR2: 17.695





Frequency (Hz)


2251-089 2024/12/09 8.52UT TOYOKAWA-FUJI



T20241209172930




BLK: 9, SNR1: 4.3357 , SNR2: 10.862




Frequency (Hz)

K20241209172927




BLK: 9, SNR1: 8.4049 , SNR2: 24.732




Frequency (Hz)


2251-089 2024/12/09 8.52UT TOYOKAWA-KISO



F20241209172932




BLK: 8, SNR1: 2.1823 , SNR2: 5.3402




Frequency (Hz)

K20241209172927




BLK: 8, SNR1: 8.3773 , SNR2: 24.616




Frequency (Hz)


2251-089 2024/12/09 8.52UT Fuji -KISO



T20241209175026




BLK: 8,SNR1: 0.25077 ,SNR2: 3.3138




Frequency (Hz)

F20241209175028




BLK: 8,SNR1: 5.4192 ,SNR2: 9.6515




Frequency (Hz)


2311-222 2024/12/09 8.87UT TOYOKAWA-FUJI



T20241209175026





BLK: 8, SNR1: 0.42227 , SNR2: 1.7256




Frequency (Hz)

K20241209175023








BLK: 8, SNR1: 4.0650 , SNR2: 10.172




Frequency (Hz)

2311-222 2024/12/09 8.87UT TOYOKAWA-KISO






2311-222 2024/12/09 8.87UT FWJ -KISO








T20241209175649




BLK: 3,SNR1: 0.50038 ,SNR2: 4.1945




F20241209175651




BLK: 3,SNR1:-0.19146 ,SNR2: 0.22828




2318-244 2024/12/09 8.98UT TOYOKAWA-FUJI





T20241209175649




BLK: 7, SNR1: 0.41045 , SNR2: 2.0399




K20241209175646





BLK: 7, SNR1: 2.7806 , SNR2: 8.0003




2318-244 2024/12/09 8.98UT TOYOKAWA-KISO



F20241209175651





BLK: 1,SNR1:-0.12772 ,SNR2: 0.18481




Frequency (Hz)

K20241209175646



BLK: 1,SNR1: 0.75018 ,SNR2: 4.0981



Frequency (Hz)

2318-244 2024/12/09 8.98UT FUJI -KISO

