




T20241211053610





BLK:10,SNR1: 0.34628 ,SNR2: 2.4387




Frequency (Hz)

F20241211053612




BLK:10,SNR1: 1.6105 ,SNR2: 5.8734





Frequency (Hz)


1103-208 2024/12/10 20.63UT TOYOKAWA-FUJI



T20241211053610





BLK: 5, SNR1: 0.33180 ,SNR2: 1.2689




Frequency (Hz)

K20241211053608




BLK: 5, SNR1: 4.9746 ,SNR2: 12.575




Frequency (Hz)

1103-208 2024/12/10 20.63UT TOYOKAWA-KISO






F20241211053612





BLK: 6,SNR1: 1.5957 ,SNR2: 7.6342




Frequency (Hz)

K20241211053608




BLK: 6,SNR1: 2.5201 ,SNR2: 6.2952





Frequency (Hz)


1103-208 2024/12/10 20.63UT FUJI -KISO



T20241211054238





BLK: 2, SNR1: 0.20646 ,SNR2: 0.92600




Frequency (Hz)

F20241211054240




BLK: 2, SNR1: 3.0493 ,SNR2: 6.7487





Frequency (Hz)


1110-217 2024/12/10 20.74UT TOYOKAWA-FUJI



T20241211054238





BLK: 3,SNR1: 9.6371 ,SNR2: 27.852




Frequency (Hz)

K20241211054236




BLK: 3,SNR1: 11.577 ,SNR2: 26.859





Frequency (Hz)


1110-217 2024/12/10 20.74UT TOYOKAWA-KISO





F20241211054240




No.Good Data




K20241211054236





No.Good Data




1110-217 2024/12/10 20.74UT FUJI -KISO





T20241211054642




BLK: 1,SNR1: 0.34565 ,SNR2: 2.8935




F20241211054644





BLK: 1,SNR1: 7.6416 ,SNR2: 17.527




1114-220 2024/12/10 20.81UT TOYOKAWA-FUJI



T20241211054642





BLK: 1,SNR1: 0.34565 ,SNR2: 2.8935




Frequency (Hz)

K20241211054639




BLK: 1,SNR1: 2.8165 ,SNR2: 8.0626




Frequency (Hz)


1114-220 2024/12/10 20.81UT TOYOKAWA-KISO





F20241211054644




No.Good Data




K20241211054639





No.Good Data




1114-220 2024/12/10 20.81UT FUJI -KISO





T20241211055344




No.Good Data




F20241211055346



No.Good Data





1121-119 2024/12/10 20.92UT TOYOKAWA-FUJI






T20241211055344





BLK: 4,SNR1: 7.4713 ,SNR2: 18.333




Frequency (Hz)

K20241211055341




BLK: 4,SNR1: 4.3229 ,SNR2: 9.0617




Frequency (Hz)


1121-119 2024/12/10 20.92UT TOYOKAWA-KISO



F20241211055346





BLK: 1,SNR1: 0.11988 ,SNR2: 2.1757




Frequency (Hz)

K20241211055341




BLK: 1,SNR1: 10.327 ,SNR2: 37.563





Frequency (Hz)


1121-119 2024/12/10 20.92UT FUJI -KISO



T20241211055952





No.Good Data




Frequency (Hz)

F20241211055954




No.Good Data





Frequency (Hz)


1127-14 2024/12/10 21.03UT TOYOKAWA-FUJI



T20241211055952





No.Good Data




Frequency (Hz)

K20241211055950




No.Good Data





Frequency (Hz)


1127-14 2024/12/10 21.03UT TOYOKAWA-KISO



F20241211055954





BLK: 1,SNR1: 15.618 ,SNR2: 25.568




Frequency (Hz)

K20241211055950




BLK: 1,SNR1: 2.1104 ,SNR2: 10.891




Frequency (Hz)


1127-14 2024/12/10 21.03UT FUJI -KISO



T20241211060409





BLK: 9,SNR1: 1.6704 ,SNR2: 7.9183




Frequency (Hz)

F20241211060411




BLK: 9,SNR1: 7.7871 ,SNR2: 19.300





Frequency (Hz)


1131-171 2024/12/10 21.10UT TOYOKAWA-FUJI



T20241211060409





BLK: 6,SNR1: 16.160 ,SNR2: 28.954




Frequency (Hz)

K20241211060407




BLK: 6,SNR1: 14.210 ,SNR2: 32.271





Frequency (Hz)


1131-171 2024/12/10 21.10UT TOYOKAWA-KISO



F20241211060411





BLK: 8,SNR1: 2.8055 ,SNR2: 7.7307




Frequency (Hz)

K20241211060407




BLK: 8,SNR1: 8.9509 ,SNR2: 22.839





Frequency (Hz)

1131-171 2024/12/10 21.10UT FUJI -KISO






T20241211060856




BLK: 8, SNR1: 11.644 , SNR2: 33.241




Frequency (Hz)

1136-13 2024/12/10 21.18UT TOYOKAWA-FUJI


F20241211060858





BLK: 8, SNR1: 3.2417 , SNR2: 8.5097




Frequency (Hz)



T20241211060856





BLK: 5, SNR1: 12.753 ,SNR2: 32.984




Frequency (Hz)

1136-13 2024/12/10 21.18UT TOYOKAWA-KISO


K20241211060854




BLK: 5, SNR1: 8.6539 ,SNR2: 24.199




Frequency (Hz)





F20241211060858




BLK: 2,SNR1: 3.6823 ,SNR2: 9.7886




K20241211060854





BLK: 2,SNR1: 6.5910 ,SNR2: 17.141




1136-13 2024/12/10 21:18UT FUJI -KISO



T20241211061412





BLK: 2,SNR1: 11.185 ,SNR2: 27.428




Frequency (Hz)

F20241211061414




BLK: 2,SNR1: 10.179 ,SNR2: 25.021





Frequency (Hz)


1141-174 2024/12/10 21.26UT TOYOKAWA-FUJI



T20241211061412





No.Good Data




Frequency (Hz)

K20241211061409




No.Good Data





Frequency (Hz)


1141-174 2024/12/10 21.26UT TOYOKAWA-KISO





F20241211061414




No.Good Data




K20241211061409





No.Good Data




1141-174 2024/12/10 21.26UT FUJI -KISO



T20241211062029




BLK: 1,SNR1: 3.2502 ,SNR2: 10.107




Frequency (Hz)

1148-00 2024/12/10 21.37UT TOYOKAWA-FUJI


F20241211062031





BLK: 1,SNR1: 1.7884 ,SNR2: 5.4814




Frequency (Hz)



T20241211062029





No.Good Data




Frequency (Hz)

K20241211062027




No.Good Data





Frequency (Hz)

1148-00 2024/12/10 21.37UT TOYOKAWA-KISO








F20241211062031




No.Good Data




K20241211062027




No.Good Data




1148-00 2024/12/10 21.37UT FUJI -KISO



T20241211062854





BLK: 9,SNR1: 54.172 ,SNR2: 367.11





1156-221 2024/12/10 21.51UT TOYOKAWA-FUJI


F20241211062856




BLK: 9,SNR1: 0.50718 ,SNR2: 0.86272



T20241211062854




BLK: 9,SNR1: 68.800 ,SNR2: 263.89




Frequency (Hz)

K20241211062852




BLK: 9,SNR1: 0.55409 ,SNR2: 2.1512




Frequency (Hz)


1156-221 2024/12/10 21.51UT TOYOKAWA-KISO



F20241211062856




BLK: 4,SNR1: 0.36792 ,SNR2: 0.78303




Frequency (Hz)

K20241211062852




BLK: 4,SNR1: 0.72357 ,SNR2: 5.4591





Frequency (Hz)


1156-221 2024/12/10 21.51UT FUJI -KISO



T20241211063723





BLK: 1,SNR1: 3.7556 ,SNR2: 14.018




Frequency (Hz)

1205-167 2024/12/10 21.65UT TOYOKAWA-FUJI


F20241211063725





BLK: 1,SNR1: 3.1424 ,SNR2: 8.3487




Frequency (Hz)



T20241211063723





BLK: 7,SNR1: 10.512 ,SNR2: 25.285




Frequency (Hz)

1205-167 2024/12/10 21.65UT TOYOKAWA-KISO


K20241211063721





BLK: 7,SNR1: 12.510 ,SNR2: 29.275




Frequency (Hz)





F20241211063725




BLK: 8,SNR1: 12.487 ,SNR2: 30.485




K20241211063721





BLK: 8,SNR1: 16.104 ,SNR2: 27.969




1205-167 2024/12/10 21.65UT FUJI -KISO





T20241211064527




No.Good Data




F20241211064529



No.Good Data





1213-17 2024/12/10 21.79UT TOYOKAWA-FUJI






T20241211064527





BLK: 4,SNR1: 2.5445 ,SNR2: 11.675




Frequency (Hz)

1213-17 2024/12/10 21.79UT TOYOKAWA-KISO


K20241211064525





BLK: 4,SNR1: 2.0833 ,SNR2: 10.419




Frequency (Hz)



F20241211064529





BLK: 1,SNR1: 16.446 ,SNR2: 27.035




Frequency (Hz)

1213-17 2024/12/10 21.79UT FUJI -KISO


K20241211064525





BLK: 1,SNR1: 2.1921 ,SNR2: 10.622




Frequency (Hz)



T20241211065844





BLK:25,SNR1: 12.134 ,SNR2: 18.701




Frequency (Hz)

3C273 2024/12/10 22.01UT TOYOKAWA-FUJI


F20241211065846





BLK:25,SNR1: 26.846 ,SNR2: 34.949




Frequency (Hz)



T20241211065844





BLK:26,SNR1: 16.128 ,SNR2: 18.515




Frequency (Hz)

3C273 2024/12/10 22.01UT TOYOKAWA-KISO


K20241211065842





BLK:26,SNR1: 16.859 ,SNR2: 21.950




Frequency (Hz)



F20241211065846





BLK:29,SNR1: 26.158 ,SNR2: 33.834




Frequency (Hz)

3C273 2024/12/10 22.01UT FUJI -KISO


K20241211065842




BLK:29,SNR1: 16.229 ,SNR2: 21.677




Frequency (Hz)



T20241211071155




BLK:22,SNR1: 12.083 ,SNR2: 27.908




Frequency (Hz)

3C275 2024/12/10 22.23UT TOYOKAWA-FUJI


F20241211071157




BLK:22,SNR1: 7.3954 ,SNR2: 21.870




Frequency (Hz)



T20241211071155




BLK:24,SNR1: 12.016 ,SNR2: 27.761





3C275 2024/12/10 22.23UT TOYOKAWA-KISO



K20241211071153




BLK:24,SNR1: 9.3080 ,SNR2: 16.675





F20241211071157




BLK:16,SNR1: 7.8221 ,SNR2: 22.666




K20241211071153



BLK:16,SNR1: 13.160 ,SNR2: 30.233





3C275 2024/12/10 22.23UT FUJI -KISO








T20241211071800




BLK: 7,SNR1: 1.6966 ,SNR2: 4.8014




F20241211071802





BLK: 7,SNR1: 3.7700 ,SNR2: 8.1760




1245-19 2024/12/10 22.33UT TOYOKAWA-FUJI



T20241211071800





BLK: 6,SNR1: 0.81003 ,SNR2: 4.3770




Frequency (Hz)

K20241211071758




BLK: 6,SNR1: 2.2061 ,SNR2: 3.6341




Frequency (Hz)


1245-19 2024/12/10 22.33UT TOYOKAWA-KISO





F20241211071802




BLK: 7,SNR1: 5.0493 ,SNR2: 11.148




K20241211071758




BLK: 7,SNR1: 4.9669 ,SNR2: 8.1880




1245-19 2024/12/10 22.33UT FUJI -KISO



T20241211072544




BLK: 7,SNR1: 8.0604 ,SNR2: 20.227





3C279 2024/12/10 22.46UT TOYOKAWA-FUJI



F20241211072546




BLK: 7,SNR1: 15.255 ,SNR2: 36.045



T20241211072544





BLK: 7,SNR1: 10.702 ,SNR2: 31.478




Frequency (Hz)

3C279 2024/12/10 22.46UT TOYOKAWA-KISO


K20241211072542




BLK: 7,SNR1: 14.028 ,SNR2: 33.313




Frequency (Hz)



F20241211072546




BLK: 6, SNR1: 14.419 , SNR2: 34.398





3C279 2024/12/10 22.46UT FUJI -KISO



K20241211072542




BLK: 6, SNR1: 10.058 , SNR2: 24.521



T20241211073416





BLK: 8, SNR1: 2.1785 ,SNR2: 10.545





1302-035 2024/12/10 22.60UT TOYOKAWA-FUJI



F20241211073418




BLK: 8, SNR1: 36.926 ,SNR2: 39.676



T20241211073416




BLK: 5, SNR1: 5.0294 , SNR2: 13.008





1302-035 2024/12/10 22.60UT TOYOKAWA-KISO

K20241211073413





BLK: 5, SNR1: 7.0091 , SNR2: 17.473







F20241211073418




BLK: 2, SNR1: 21.971 ,SNR2: 40.383




K20241211073413




BLK: 2, SNR1: 18.042 ,SNR2: 37.494




1302-035 2024/12/10 22.60UT FUJI -KISO



T20241211074113




BLK: 7,SNR1: 1.0856 ,SNR2: 4.9771





3C283 2024/12/10 22.72UT TOYOKAWA-FUJI


F20241211074115




BLK: 7,SNR1: 2.4372 ,SNR2: 5.0630





T20241211074113




No. Good Data




KISO





No. Good Data




3C283 2024/12/10 22.72UT TOYOKAWA-KISO





F20241211074115




No.Good Data




KISO





No.Good Data




3C283 2024/12/10 22.72UT FUJI -KISO





T20241211074947




BLK: 4, SNR1: 12.639 , SNR2: 29.439




F20241211074949





BLK: 4, SNR1: 18.400 , SNR2: 35.114




1317+179 2024/12/10 22.86UT TOYOKAWA-FUJI





T20241211074947




No. Good Data




KISO





No. Good Data




1317+179 2024/12/10 22.86UT TOYOKAWA-KISO





F20241211074949




No.Good Data




KISO





No.Good Data




1317+179 2024/12/10 22.86UT FUJI -KISO





T20241211075538




BLK: 3, SNR1: 0.52591 , SNR2: 1.9661




F20241211075540



BLK: 3, SNR1: 11.100 , SNR2: 19.771





1323+32 2024/12/10 22.96UT TOYOKAWA-FUJI






T20241211075538





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1323+32 2024/12/10 22.96UT TOYOKAWA-KISO





F20241211075540




No. Good Data




KISO





No. Good Data




1323+32 2024/12/10 22.96UT FUJI -KISO



T20241211080028




BLK: 4,SNR1: 11.108 ,SNR2: 26.767





3C286 2024/12/10 23.04UT TOYOKAWA-FUJI



F20241211080030




BLK: 4,SNR1: 12.084 ,SNR2: 26.244





T20241211080028




No. Good Data




KISO





No. Good Data




3C286 2024/12/10 23.04UT TOYOKAWA-KISO





F20241211080030




No. Good Data




KISO





No. Good Data




3C286 2024/12/10 23.04UT FUJI -KISO



T20241211081655




BLK: 5, SNR1: 0.65936 , SNR2: 1.8192





1345+12 2024/12/10 23.31UT TOYOKAWA-FUJI



F20241211081657




BLK: 5, SNR1: 12.726 , SNR2: 22.669



T20241211081655





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)


1345+12 2024/12/10 23.31UT TOYOKAWA-KISO



F20241211081657





No. Good Data




Frequency (Hz)

KISO




No. Good Data





Frequency (Hz)

1345+12 2024/12/10 23.31UT FUJI -KISO






T20241211082715




BLK: 6,SNR1: 0.24143 ,SNR2: 2.1455





1355+01 2024/12/10 23.48UT TOYOKAWA-FUJI



F20241211082717




BLK: 6,SNR1: 0.81123 ,SNR2: 4.7039



T20241211082715




BLK: 4, SNR1: 0.44078 , SNR2: 2.7931





1355+01 2024/12/10 23.48UT TOYOKAWA-KISO


K20241211082712




BLK: 4, SNR1: 14.384 , SNR2: 26.089



F20241211082717




BLK: 1, SNR1: 3.6309 ,SNR2: 9.1367





1355+01 2024/12/10 23.48UT FUJI -KISO



K20241211082712




BLK: 1, SNR1: 0.82654 ,SNR2: 4.5606



T20241211084826





BLK:12,SNR1: 0.54815 ,SNR2: 2.3959





3C298 2024/12/10 23.84UT TOYOKAWA-FUJI



F20241211084828




BLK:12,SNR1: 0.54906 ,SNR2: 4.5223





T20241211084826




BLK:10,SNR1: 0.42414 ,SNR2: 6.6796




K20241211084824




BLK:10,SNR1: 1.7331 ,SNR2: 4.3574




3C298 2024/12/10 23.84UT TOYOKAWA-KISO



F20241211084828




BLK: 2, SNR1: 1.7728 ,SNR2: 5.9537





3C298 2024/12/10 23.84UT FUJI -KISO



K20241211084824




BLK: 2, SNR1: 0.19785 ,SNR2: 1.5963



T20241211085408




BLK: 9,SNR1: 8.9422 ,SNR2: 22.114





1422+202 2024/12/10 23.93UT TOYOKAWA-FUJI


F20241211085410




BLK: 9,SNR1: 0.19164 ,SNR2: 1.9502




T20241211085408




BLK:22,SNR1: 8.1896 ,SNR2: 20.251




K20241211085406



BLK:22,SNR1: 8.5543 ,SNR2: 15.137




1422+202 2024/12/10 23.93UT TOYOKAWA-KISO







F20241211085410




BLK:13,SNR1: 0.29824 ,SNR2: 3.6510




K20241211085406




BLK:13,SNR1: 6.4409 ,SNR2: 15.707




1422+202 2024/12/10 23.93UT FUJI -KISO




T20241211090010




BLK: 4,SNR1: 0.30148 ,SNR2: 1.3237




F20241211090012





BLK: 4,SNR1: 0.94437 ,SNR2: 1.9666




1428-03 2024/12/11 0.03UT TOYOKAWA-FUJI





T20241211090010




BLK: 4, SNR1: 0.51457E-02, SNR2: 0.70419




K20241211090008




BLK: 4, SNR1: 1.2283, SNR2: 3.8291




1428-03 2024/12/11 0.03UT TOYOKAWA-KISO





F20241211090012




BLK: 5, SNR1: 1.2858 ,SNR2: 2.8437




K20241211090008




BLK: 5, SNR1: 2.2287 ,SNR2: 5.0834




1428-03 2024/12/11 0.03UT FUJI -KISO



T20241211090851




BLK: 7,SNR1: 1.3319 ,SNR2: 6.9412





1436-16 2024/12/11 0.18UT TOYOKAWA-FUJI


F20241211090853




BLK: 7,SNR1: 0.40718 ,SNR2: 1.4275



T20241211090851




BLK: 6, SNR1: 3.5573 ,SNR2: 6.3866





1436-16 2024/12/11 0.18UT TOYOKAWA-KISO


K20241211090849




BLK: 6, SNR1: 5.8759 ,SNR2: 15.905




F20241211090853




BLK: 2,SNR1: 0.21960E-01,SNR2: 0.46615




K20241211090849




BLK: 2,SNR1: 3.7122 ,SNR2: 8.9897




1436-16 2024/12/11 0.18UT FUJI -KISO



T20241211092514




BLK: 8,SNR1: 1.0608 ,SNR2: 4.0654





1453-10 2024/12/11 0.45UT TOYOKAWA-FUJI





F20241211092516




BLK: 8,SNR1: 0.44058 ,SNR2: 3.3956









1453-10 2024/12/11 0.45UT TOYOKAWA-KISO




F20241211092516




BLK: 3,SNR1: 4.7155 ,SNR2: 12.138




K20241211092511





BLK: 3,SNR1: 14.779 ,SNR2: 28.417




1453-10 2024/12/11 0.45UT FUJI -KISO



T20241211094007




BLK: 5, SNR1: 0.15663 , SNR2: 1.0926





1508-05 2024/12/11 0.70UT TOYOKAWA-FUJI



F20241211094009




BLK: 5, SNR1: 0.49340 , SNR2: 2.3545



T20241211094007




BLK: 7,SNR1: 0.38861 ,SNR2: 1.1761










1508-05 2024/12/11 0.70UT TOYOKAWA-KISO

K20241211094005





BLK: 7,SNR1: 5.5976 ,SNR2: 13.275








T20241211094906




BLK: 2,SNR1: 0.15823 ,SNR2: 3.3894




F20241211094908





BLK: 2,SNR1: 0.67726 ,SNR2: 3.6858




3C318 2024/12/11 0.85UT TOYOKAWA-FUJI





T20241211094906




BLK: 4,SNR1: 0.22995 ,SNR2: 0.75953




K20241211094904





BLK: 4,SNR1:-0.88540E-01,SNR2: 1.1628




3C318 2024/12/11 0.85UT TOYOKAWA-KISO



F20241211094908





BLK: 3,SNR1:-0.26371 ,SNR2: 0.38759E-01





3C318 2024/12/11 0.85UT FUJI -KISO

K20241211094904





BLK: 3,SNR1: 0.67132 ,SNR2: 2.0723







T20241211095453




BLK: 4,SNR1: 0.74561E-01,SNR2: 2.2505




F20241211095455




BLK: 4,SNR1:-0.18065 ,SNR2: 2.0120




1523+03 2024/12/11 0.94UT TOYOKAWA-FUJI



T20241211095453




BLK: 6,SNR1: 0.46718 ,SNR2: 1.7148





1523+03 2024/12/11 0.94UT TOYOKAWA-KISO


K20241211095451




BLK: 6,SNR1: 1.1835 ,SNR2: 7.9663





F20241211095455




BLK: 4,SNR1:-0.19102 ,SNR2: 0.86970




K20241211095451





BLK: 4,SNR1: 0.40800 ,SNR2: 1.7586




1523+03 2024/12/11 0.94UT FUJI -KISO




T20241211100633




BLK: 6,SNR1: 0.19478 ,SNR2: 0.41792




F20241211100635





BLK: 6,SNR1: 0.55966 ,SNR2: 2.2679




1535+139 2024/12/11 1.14UT TOYOKAWA-FUJI




T20241211100633




BLK: 3,SNR1: 0.32041E-01,SNR2: 1.1844




K20241211100630




BLK: 3,SNR1: 0.48295 ,SNR2: 4.4041




1535+139 2024/12/11 1.14UT TOYOKAWA-KISO




F20241211100635




BLK: 1,SNR1: 1.6984 ,SNR2: 6.5626




K20241211100630





BLK: 1,SNR1: 1.1160 ,SNR2: 10.434




1535+139 2024/12/11 1.14UT FUJI -KISO



T20241211101939




BLK: 3,SNR1: 0.52666E-01,SNR2: 0.74147





1548+05 2024/12/11 1.36UT TOYOKAWA-FUJI


F20241211101941




BLK: 3,SNR1: 1.0766 ,SNR2: 2.9594





T20241211101939




BLK: 5,SNR1: 0.15852 ,SNR2: 1.4071




K20241211101937



BLK: 5,SNR1: 0.99918 ,SNR2: 4.5836




1548+05 2024/12/11 1.36UT TOYOKAWA-KISO








F20241211101941




BLK:14,SNR1: 0.13909 ,SNR2: 2.2611




K20241211101937





BLK:14,SNR1: 0.57893 ,SNR2: 2.3152




1548+05 2024/12/11 1.36UT FUJI -KISO




T20241211103800




BLK: 3,SNR1: 0.28223 ,SNR2: 1.2600




F20241211103802





BLK: 3,SNR1: 1.5012 ,SNR2: 3.7406




1607+26 2024/12/11 1.66UT TOYOKAWA-FUJI




T20241211103800




BLK: 4,SNR1: 0.19661 ,SNR2: 0.68281




K20241211103758




BLK: 4,SNR1: 0.41217 ,SNR2: 1.2033




1607+26 2024/12/11 1.66UT TOYOKAWA-KISO





F20241211103802




BLK: 5,SNR1: 0.34452 ,SNR2: 2.6871




K20241211103758





BLK: 5,SNR1: 0.41249 ,SNR2: 0.85463




1607+26 2024/12/11 1.66UT FUJI -KISO




T20241211105531




BLK: 7,SNR1: 0.28711 ,SNR2: 2.8353




F20241211105533




BLK: 7,SNR1: 3.0907 ,SNR2: 9.1155




1623-228 2024/12/11 1.95UT TOYOKAWA-FUJI



T20241211105531




BLK:12,SNR1: 0.26169 ,SNR2: 2.7265






1623-228 2024/12/11 1.95UT TOYOKAWA-KISO

K20241211105529





BLK:12,SNR1: 14.036 ,SNR2: 25.138







BLK:16,SNR1: 2.7791 ,SNR2: 6.5107





BLK:16,SNR1: 27.471 ,SNR2: 30.643




1623-228 2024/12/11 1.95UT FUJI -KISO




T20241211110401




BLK:16,SNR1: 3.9847 ,SNR2: 6.9677




F20241211110403



BLK:16,SNR1: 2.5648 ,SNR2: 7.5619





1631-222 2024/12/11 2.10UT TOYOKAWA-FUJI








T20241211110401




BLK:14,SNR1: 3.1127 ,SNR2: 5.5478




K20241211110358





BLK:14,SNR1: 30.185 ,SNR2: 64.321




1631-222 2024/12/11 2.10UT TOYOKAWA-KISO





F20241211110403




BLK:10,SNR1: 9.6808 ,SNR2: 22.033




K20241211110358





BLK:10,SNR1: 7.6696 ,SNR2: 28.305




1631-222 2024/12/11 2.10UT FUJI -KISO



T20241211110938





BLK: 5,SNR1: 0.44744 ,SNR2: 2.0065




Frequency (Hz)

F20241211110940








BLK: 5,SNR1:-0.19018 ,SNR2: 0.85944




Frequency (Hz)

1638-025 2024/12/11 2.19UT TOYOKAWA-FUJI








1638-025 2024/12/11 2.19UT TOYOKAWA-KISO




F20241211110940




BLK: 5,SNR1:-0.49528E-01,SNR2: 3.1437




K20241211110936





BLK: 5,SNR1: 100.06 ,SNR2: 132.74




1638-025 2024/12/11 2.19UT FUJI -KISO





T20241211111632




BLK:14,SNR1: 3.9052 ,SNR2: 14.253




F20241211111634





BLK:14,SNR1: 0.19244 ,SNR2: 3.0643




1644-106 2024/12/11 2.30UT TOYOKAWA-FUJI





T20241211111632




BLK:14,SNR1: 3.8201 ,SNR2: 13.995




K20241211111630




BLK:14,SNR1: 3.1704 ,SNR2: 5.4845




1644-106 2024/12/11 2.30UT TOYOKAWA-KISO





F20241211111634




BLK: 5,SNR1: 0.72216 ,SNR2: 2.4671




K20241211111630



BLK: 5,SNR1: 0.94668 ,SNR2: 2.2039





1644-106 2024/12/11 2.30UT FUJI -KISO








T20241211112153




BLK: 8,SNR1: 0.28680 ,SNR2: 1.2827




F20241211112155





BLK: 8,SNR1:-0.17665 ,SNR2: 1.3523




1650+004 2024/12/11 2.39UT TOYOKAWA-FUJI





T20241211112153




BLK: 7,SNR1: 0.38855 ,SNR2: 2.8293




K20241211112151




BLK: 7,SNR1: 3.1126 ,SNR2: 6.9233




1650+004 2024/12/11 2.39UT TOYOKAWA-KISO




F20241211112155




BLK: 2,SNR1: 0.30978 ,SNR2: 4.6244




K20241211112151





BLK: 2,SNR1: 5.2747 ,SNR2: 9.4593




1650+004 2024/12/11 2.39UT FUJI -KISO




T20241211112725




BLK: 6,SNR1: 0.43584 ,SNR2: 1.9728




F20241211112727





BLK: 6,SNR1: 0.51192 ,SNR2: 4.0853




1656+053 2024/12/11 2.49UT TOYOKAWA-FUJI





T20241211112725




BLK: 4,SNR1: 0.28850 ,SNR2: 0.92016




K20241211112723




BLK: 4,SNR1: 4.5767 ,SNR2: 10.612




1656+053 2024/12/11 2.49UT TOYOKAWA-KISO




F20241211112727




BLK: 8,SNR1: 1.8643 ,SNR2: 7.4189




K20241211112723




BLK: 8,SNR1: 4.4462 ,SNR2: 10.855




1656+053 2024/12/11 2.49UT FUJI -KISO





T20241211114355




BLK:10,SNR1: 0.24010 ,SNR2: 1.5938




F20241211114357




BLK:10,SNR1: 4.2626 ,SNR2: 16.918




1712-033 2024/12/11 2.76UT TOYOKAWA-FUJI





T20241211114355




BLK:17,SNR1: 0.32019 ,SNR2: 3.3723




K20241211114353



BLK:17,SNR1: 40.393 ,SNR2: 51.583





1712-033 2024/12/11 2.76UT TOYOKAWA-KISO








F20241211114357




BLK: 4,SNR1: 28.969 ,SNR2: 55.533




K20241211114353




BLK: 4,SNR1: 55.268 ,SNR2: 66.801




1712-033 2024/12/11 2.76UT FUJI -KISO




T20241211120157




BLK:11,SNR1: 4.3037 ,SNR2: 9.1493




F20241211120159




BLK:11,SNR1:-0.29746 ,SNR2: 0.93632




1730-13 2024/12/11 3.06UT TOYOKAWA-FUJI





T20241211120157




BLK:17,SNR1: 3.6387 ,SNR2: 7.9180




K20241211120155




BLK:17,SNR1: 18.152 ,SNR2: 33.106




1730-13 2024/12/11 3.06UT TOYOKAWA-KISO





F20241211120159




BLK:14,SNR1:-0.21092 ,SNR2: 1.0851




K20241211120155





BLK:14,SNR1: 4.7781 ,SNR2: 7.0209




1730-13 2024/12/11 3.06UT FUJI -KISO





T20241211121921




BLK: 9,SNR1: 0.95568 ,SNR2: 4.3155




F20241211121923





BLK: 9,SNR1: 1.5612 ,SNR2: 13.872




1748+031 2024/12/11 3.35UT TOYOKAWA-FUJI





T20241211121921




BLK: 7,SNR1: 1.1370 ,SNR2: 3.4032




K20241211121918





BLK: 7,SNR1: 3.9911 ,SNR2: 12.616




1748+031 2024/12/11 3.35UT TOYOKAWA-KISO





F20241211121923




BLK: 6,SNR1: 3.3438 ,SNR2: 16.681




K20241211121918




BLK: 6,SNR1: 4.4924 ,SNR2: 17.111




1748+031 2024/12/11 3.35UT FUJI -KISO




T20241211123015




BLK: 8,SNR1: 0.48450 ,SNR2: 3.1663




F20241211123017



BLK: 8,SNR1: 0.64920 ,SNR2: 3.0486





1759+13 2024/12/11 3.53UT TOYOKAWA-FUJI







T20241211123015




BLK: 5, SNR1: 0.41833 , SNR2: 2.9651




K20241211123013




BLK: 5, SNR1: 2.5129 , SNR2: 6.3919




1759+13 2024/12/11 3.53UT TOYOKAWA-KISO




F20241211123017




BLK: 4,SNR1: 0.72390 ,SNR2: 3.3867




K20241211123013




BLK: 4,SNR1: 0.19244 ,SNR2: 2.9045




1759+13 2024/12/11 3.53UT FUJI -KISO





T20241211125115




BLK:14,SNR1: 0.74330 ,SNR2: 4.2658




F20241211125117





BLK:14,SNR1: 1.7101 ,SNR2: 8.2686




1819-096 2024/12/11 3.88UT TOYOKAWA-FUJI





T20241211125115




BLK:16,SNR1: 0.93537 ,SNR2: 4.3769




K20241211125113





BLK:16,SNR1: 4.1099 ,SNR2: 9.1587




1819-096 2024/12/11 3.88UT TOYOKAWA-KISO





F20241211125117




BLK:14,SNR1: 1.6766 ,SNR2: 7.9965




K20241211125113




BLK:14,SNR1: 7.6057 ,SNR2: 7.0631




1819-096 2024/12/11 3.88UT FUJI -KISO





T20241211125936




BLK: 7,SNR1: 13.710 ,SNR2: 23.783




F20241211125938




BLK: 7,SNR1: 9.4363 ,SNR2: 20.564




1829+29 2024/12/11 4.02UT TOYOKAWA-FUJI





T20241211125936




BLK: 3,SNR1: 5.6912 ,SNR2: 14.057




K20241211125933




BLK: 3,SNR1: 2.8528 ,SNR2: 12.648




1829+29 2024/12/11 4.02UT TOYOKAWA-KISO



F20241211125938





BLK: 7,SNR1: 13.569 ,SNR2: 28.344





1829+29 2024/12/11 4.02UT FUJI -KISO

K20241211125933





BLK: 7,SNR1: 18.611 ,SNR2: 32.990






T20241211130559





BLK: 2,SNR1: 0.13301 ,SNR2: 1.3090




Frequency (Hz)

F20241211130601




BLK: 2,SNR1: 0.66379 ,SNR2: 4.5542





Frequency (Hz)


1835+134 2024/12/11 4.13UT TOYOKAWA-FUJI





T20241211130559




No.Good Data




K20241211130556





No.Good Data




1835+134 2024/12/11 4.13UT TOYOKAWA-KISO



F20241211130601





BLK: 4,SNR1: 2.3657 ,SNR2: 6.8776




Frequency (Hz)

K20241211130556




BLK: 4,SNR1: 0.23343 ,SNR2: 1.0293





Frequency (Hz)


1835+134 2024/12/11 4.13UT FUJI -KISO



T20241211132855





BLK: 2,SNR1: 0.35839 ,SNR2: 2.5849




Frequency (Hz)

F20241211132857




BLK: 2,SNR1: 0.35393 ,SNR2: 3.4657





Frequency (Hz)


1858+171 2024/12/11 4.51UT TOYOKAWA-FUJI



T20241211132855





BLK: 3,SNR1: 0.26590 ,SNR2: 0.51203




Frequency (Hz)

K20241211132852




BLK: 3,SNR1: 2.0815 ,SNR2: 6.6135





Frequency (Hz)


1858+171 2024/12/11 4.51UT TOYOKAWA-KISO





F20241211132857




No.Good Data




K20241211132852





No.Good Data




1858+171 2024/12/11 4.51UT FUJI -KISO




T20241211133939




BLK: 7,SNR1: 1.4713 ,SNR2: 4.5629




F20241211133941





BLK: 7,SNR1: 0.17656E-01,SNR2: 0.44854




1908-20 2024/12/11 4.69UT TOYOKAWA-FUJI





T20241211133939




BLK: 8,SNR1: 2.8954 ,SNR2: 12.349




K20241211133937



BLK: 8,SNR1: 0.88388 ,SNR2: 4.0371




1908-20 2024/12/11 4.69UT TOYOKAWA-KISO








F20241211133941




BLK: 3,SNR1: 0.16824 ,SNR2: 0.78842




K20241211133937





BLK: 3,SNR1: 2.3446 ,SNR2: 5.4158




1908-20 2024/12/11 4.69UT FUJI -KISO



T20241211134630




BLK:28,SNR1: 17.189 ,SNR2: 22.391




Frequency (Hz)

F20241211134632




BLK:28,SNR1: 10.675 ,SNR2: 24.176





Frequency (Hz)


1915-121 2024/12/11 4.80UT TOYOKAWA-FUJI




T20241211134630




BLK:27,SNR1: 16.360 ,SNR2: 21.574




K20241211134628




BLK:27,SNR1: 7.9720 ,SNR2: 18.751




1915-121 2024/12/11 4.80UT TOYOKAWA-KISO




F20241211134632




BLK:30,SNR1: 10.518 ,SNR2: 20.394




K20241211134628




BLK:30,SNR1: 8.1161 ,SNR2: 18.826




1915-121 2024/12/11 4.80UT FUJI -KISO





T20241211140012




BLK: 6,SNR1: 97.354 ,SNR2: 100.83




F20241211140014




BLK: 6,SNR1: 0.32362 ,SNR2: 4.3229




1928-142 2024/12/11 5.03UT TOYOKAWA-FUJI



T20241211140012





BLK: 4,SNR1: 78.487 ,SNR2: 87.538




Frequency (Hz)

K20241211140010




BLK: 4,SNR1: 1.6203 ,SNR2: 4.4658





Frequency (Hz)


1928-142 2024/12/11 5.03UT TOYOKAWA-KISO





F20241211140014




BLK: 2,SNR1: 0.55181 ,SNR2: 2.3656




K20241211140010





BLK: 2,SNR1: 1.4868 ,SNR2: 3.8404




1928-142 2024/12/11 5.03UT FUJI -KISO



T20241211140951




BLK: 1,SNR1: 16.812 ,SNR2: 27.431




Frequency (Hz)

F20241211140953




BLK: 1,SNR1: 4.6704 ,SNR2: 12.789





Frequency (Hz)

1938-15 2024/12/11 5.19UT TOYOKAWA-FUJI






T20241211140951




BLK: 1,SNR1: 6.4066 ,SNR2: 20.937




Frequency (Hz)

K20241211140949




BLK: 1,SNR1: 17.348 ,SNR2: 36.512




Frequency (Hz)


1938-15 2024/12/11 5.19UT TOYOKAWA-KISO



F20241211140953




BLK: 1,SNR1: 4.6704 ,SNR2: 12.789




Frequency (Hz)

K20241211140949




BLK: 1,SNR1: 7.4507 ,SNR2: 19.291





Frequency (Hz)


1938-15 2024/12/11 5.19UT FUJI -KISO



T20241211143703





No.Good Data




Frequency (Hz)

FUJI




No.Good Data





Frequency (Hz)


2007+502 2024/12/11 5.65UT TOYOKAWA-FUJI




T20241211143703




BLK: 5,SNR1: 11.379 ,SNR2: 47.340




K20241211143701






BLK: 5,SNR1: 2.7562 ,SNR2: 14.469






2007+502 2024/12/11 5.65UT TOYOKAWA-KISO




FUJI





K20241211143701




2007+502 2024/12/11 5.65UT FUJI -KISO



T20241211144447





BLK: 4,SNR1: 95.111 ,SNR2: 133.23




Frequency (Hz)

F20241211144449




BLK: 4,SNR1: 3.0645 ,SNR2: 7.7794





Frequency (Hz)


2014+358 2024/12/11 5.77UT TOYOKAWA-FUJI



T20241211144447




BLK: 4,SNR1: 91.713 ,SNR2: 128.47




Frequency (Hz)

K20241211144444




BLK: 4,SNR1: 27.022 ,SNR2: 57.197





Frequency (Hz)


2014+358 2024/12/11 5.77UT TOYOKAWA-KISO




F20241211144449




BLK: 3, SNR1: 11.985 , SNR2: 26.277




K20241211144444



BLK: 3, SNR1: 14.422 , SNR2: 33.763





2014+358 2024/12/11 5.77UT FUJI -KISO








T20241211151523




BLK:13,SNR1: 9.2349 ,SNR2: 27.171




F20241211151525





BLK:13,SNR1: 7.0718 ,SNR2: 22.774




3C422 2024/12/11 6.28UT TOYOKAWA-FUJI



T20241211151523





BLK:12,SNR1: 11.955 ,SNR2: 28.794




Frequency (Hz)

K20241211151520




BLK:12,SNR1: 7.8910 ,SNR2: 23.293





Frequency (Hz)


3C422 2024/12/11 6.28UT TOYOKAWA-KISO



F20241211151525





BLK:14,SNR1: 54.930 ,SNR2: 71.029




Frequency (Hz)

K20241211151520




BLK:14,SNR1: 7.7629 ,SNR2: 22.878




Frequency (Hz)


3C422 2024/12/11 6.28UT FUJI -KISO



T20241211153601




BLK: 4,SNR1: 3.2998 ,SNR2: 7.7305




Frequency (Hz)

F20241211153603








BLK: 4,SNR1: 10.903 ,SNR2: 29.009




Frequency (Hz)

2105-072 2024/12/11 6.63UT TOYOKAWA-FUJI







2105-072 2024/12/11 6.63UT TOYOKAWA-KISO



F20241211153603




BLK: 8,SNR1: 9.3832 ,SNR2: 25.008




Frequency (Hz)

K20241211153558




BLK: 8,SNR1: 10.123 ,SNR2: 29.814





Frequency (Hz)


2105-072 2024/12/11 6.63UT FUJI -KISO



T20241211160605




BLK: 9,SNR1: 0.76044 ,SNR2: 6.2814




Frequency (Hz)

F20241211160607




BLK: 9,SNR1: 1.4727 ,SNR2: 4.1029





Frequency (Hz)


2135-209 2024/12/11 7.13UT TOYOKAWA-FUJI




T20241211160605




BLK: 8, SNR1: 0.47648 , SNR2: 4.0145




K20241211160603



BLK: 8, SNR1: 0.62434 , SNR2: 1.9410




2135-209 2024/12/11 7.13UT TOYOKAWA-KISO







F20241211160607




BLK: 3,SNR1: 0.56642 ,SNR2: 3.0786




K20241211160603





BLK: 3,SNR1: 0.65228 ,SNR2: 2.7098




2135-209 2024/12/11 7.13UT FUJI -KISO



T20241211161825





BLK: 2,SNR1: 0.15251 ,SNR2: 0.58707




Frequency (Hz)

F20241211161827




BLK: 2,SNR1:-0.11522 ,SNR2: 1.3618





Frequency (Hz)


2147+145 2024/12/11 7.34UT TOYOKAWA-FUJI



T20241211161825





BLK: 4,SNR1: 0.78661E-01,SNR2: 0.51309




Frequency (Hz)

K20241211161823








BLK: 4,SNR1: 0.52818 ,SNR2: 1.7494




Frequency (Hz)

2147+145 2024/12/11 7.34UT TOYOKAWA-KISO







2147+145 2024/12/11 7.34UT FUJI -KISO



T20241211162729




BLK: 6,SNR1: 0.12846 ,SNR2: 2.5234




Frequency (Hz)

F20241211162731




BLK: 6,SNR1: 0.29847E-01,SNR2: 2.0743





Frequency (Hz)


2156-043 2024/12/11 7.49UT TOYOKAWA-FUJI



T20241211162729





BLK: 3,SNR1: 0.30382 ,SNR2: 2.2737




Frequency (Hz)

K20241211162727




BLK: 3,SNR1: 1.9726 ,SNR2: 6.5528





Frequency (Hz)


2156-043 2024/12/11 7.49UT TOYOKAWA-KISO



F20241211162731





BLK: 6,SNR1: 4.3077 ,SNR2: 12.166




Frequency (Hz)

K20241211162727




BLK: 6,SNR1: 0.74109 ,SNR2: 2.1085




Frequency (Hz)


2156-043 2024/12/11 7.49UT FUJI -KISO



T20241211163417




BLK: 8,SNR1: 2.4685 ,SNR2: 6.2673




Frequency (Hz)

F20241211163419




BLK: 8,SNR1: 1.3548 ,SNR2: 4.5261




Frequency (Hz)

2203-18 2024/12/11 7.60UT TOYOKAWA-FUJI






T20241211163417




BLK:13,SNR1: 1.2969 ,SNR2: 2.6721




Frequency (Hz)

K20241211163415




BLK:13,SNR1: 7.8240 ,SNR2: 21.176




Frequency (Hz)


2203-18 2024/12/11 7.60UT TOYOKAWA-KISO



F20241211163419




BLK: 8,SNR1: 2.5508 ,SNR2: 6.7413




Frequency (Hz)

K20241211163415




BLK: 8,SNR1: 6.1333 ,SNR2: 17.818





Frequency (Hz)


2203-18 2024/12/11 7.60UT FUJI -KISO



T20241211164040




BLK: 3, SNR1: 0.20062 , SNR2: 0.39480




Frequency (Hz)

F20241211164042




BLK: 3, SNR1: 0.47685 , SNR2: 1.9552





Frequency (Hz)


2210+016 2024/12/11 7.71UT TOYOKAWA-FUJI





T20241211164040




BLK: 4,SNR1: 0.19319 ,SNR2: 1.0572




K20241211164038




BLK: 4,SNR1: 0.57820E-01,SNR2: 1.0658




2210+016 2024/12/11 7.71UT TOYOKAWA-KISO



F20241211164042





BLK: 3, SNR1: -0.30980 , SNR2: 0.42595




Frequency (Hz)

K20241211164038




BLK: 3, SNR1: 0.58880 , SNR2: 4.7511




Frequency (Hz)


2210+016 2024/12/11 7.71UT FWJ -KISO



T20241211164803




BLK: 6, SNR1: 1.0738 , SNR2: 3.7364




Frequency (Hz)

F20241211164805




BLK: 6, SNR1: 1.2968 , SNR2: 4.0441




Frequency (Hz)


2217+128 2024/12/11 7.83UT TOYOKAWA-FUJI



T20241211164803




BLK: 8, SNR1: 0.72076 , SNR2: 2.0920




Frequency (Hz)

K20241211164801





BLK: 8, SNR1: 8.1050 , SNR2: 20.151





Frequency (Hz)

2217+128 2024/12/11 7.83UT TOYOKAWA-KISO







BLK: 7, SNR1: 3.2366 , SNR2: 7.8827



BLK: 7, SNR1: 4.1482 , SNR2: 11.347




2217+128 2024/12/11 7.83UT FWJ -KISO






T20241211165349




BLK:10,SNR1: 26.701 ,SNR2: 42.777




Frequency (Hz)

F20241211165351




BLK:10,SNR1:-0.70443E-01,SNR2: 2.8367





Frequency (Hz)


3C446 2024/12/11 7.93UT TOYOKAWA-FUJI



T20241211165349





BLK: 5, SNR1: 54.166 , SNR2: 82.201




Frequency (Hz)

K20241211165347




BLK: 5, SNR1: 0.18303 , SNR2: 1.4340




Frequency (Hz)


3C446 2024/12/11 7.93UT TOYOKAWA-KISO



F20241211165351





BLK:10,SNR1:-0.16297 ,SNR2: 1.5393




Frequency (Hz)

K20241211165347




BLK:10,SNR1: 0.20506 ,SNR2: 1.2243





Frequency (Hz)


3C446 2024/12/11 7.93UT FUJI -KISO



T20241211170033





BLK: 8,SNR1: 0.16177 ,SNR2: 2.2706




Frequency (Hz)

F20241211170035




BLK: 8,SNR1: 0.18442 ,SNR2: 3.1859





Frequency (Hz)


2229-093 2024/12/11 8.04UT TOYOKAWA-FUJI



T20241211170033




BLK: 3,SNR1: 0.89307 ,SNR2: 2.7411




Frequency (Hz)

K20241211170031




BLK: 3,SNR1: 5.2063 ,SNR2: 13.993





Frequency (Hz)


2229-093 2024/12/11 8.04UT TOYOKAWA-KISO



F20241211170035





BLK: 6,SNR1: 0.39783 ,SNR2: 1.6923




Frequency (Hz)

K20241211170031




BLK: 6,SNR1: 7.1584 ,SNR2: 20.753




Frequency (Hz)


2229-093 2024/12/11 8.04UT FUJI -KISO



T20241211170900




BLK: 7,SNR1: 0.93388 ,SNR2: 3.1630




Frequency (Hz)

F20241211170902




BLK: 7,SNR1: 0.13301 ,SNR2: 2.6159




Frequency (Hz)


2238-113 2024/12/11 8.18UT TOYOKAWA-FUJI



T20241211170900





BLK: 8, SNR1: 0.76888 , SNR2: 2.6523




Frequency (Hz)

K20241211170858




BLK: 8, SNR1: 6.6294 , SNR2: 18.893




Frequency (Hz)

2238-113 2024/12/11 8.18UT TOYOKAWA-KISO






F20241211170902





BLK: 5,SNR1: 0.86487E-01,SNR2: 1.5907




Frequency (Hz)

K20241211170858




BLK: 5,SNR1: 4.9727 ,SNR2: 12.504





Frequency (Hz)


2238-113 2024/12/11 8.18UT FUJI -KISO



T20241211172138





BLK: 3,SNR1: 0.36685 ,SNR2: 1.9148




Frequency (Hz)

F20241211172140






BLK: 3,SNR1: 0.54388 ,SNR2: 1.9121




Frequency (Hz)

2251-089 2024/12/11 8.39UT TOYOKAWA-FUJI








2251-089 2024/12/11 8.39UT TOYOKAWA-KISO




F20241211172140




BLK:10,SNR1: 0.84950 ,SNR2: 3.2910




K20241211172136





BLK:10,SNR1: 4.9577 ,SNR2: 14.105




2251-089 2024/12/11 8.39UT FUJI -KISO



T20241211172821





BLK:15,SNR1: 4.4047 ,SNR2: 11.493




Frequency (Hz)

F20241211172823




BLK:15,SNR1: 3.9312 ,SNR2: 10.218




Frequency (Hz)


2257-104 2024/12/11 8.50UT TOYOKAWA-FUJI



T20241211172821





BLK:17,SNR1: 4.2803 ,SNR2: 11.466




Frequency (Hz)

K20241211172819




BLK:17,SNR1: 2.4585 ,SNR2: 11.966





Frequency (Hz)


2257-104 2024/12/11 8.50UT TOYOKAWA-KISO



F20241211172823





BLK:13,SNR1: 3.9597 ,SNR2: 10.869




Frequency (Hz)

K20241211172819




BLK:13,SNR1: 3.4247 ,SNR2: 13.150





Frequency (Hz)


2257-104 2024/12/11 8.50UT FUJI -KISO



T20241211174428




BLK: 6,SNR1: 0.89970 ,SNR2: 4.7934




Frequency (Hz)

F20241211174430




BLK: 6,SNR1:-0.30782 ,SNR2: 0.64589





Frequency (Hz)

2313-167 2024/12/11 8.77UT TOYOKAWA-FUJI






T20241211174428





BLK:11,SNR1: 0.48204 ,SNR2: 2.9923




Frequency (Hz)

K20241211174426




BLK:11,SNR1: 3.6941 ,SNR2: 9.6822





Frequency (Hz)


2313-167 2024/12/11 8.77UT TOYOKAWA-KISO



F20241211174430





BLK: 4,SNR1: 0.20703E-01,SNR2: 0.83869




Frequency (Hz)

K20241211174426





BLK: 4,SNR1: 1.5631 ,SNR2: 2.9602






Frequency (Hz)

2313-167 2024/12/11 8.77UT FUJI -KISO







BLK:10,SNR1: 70.984 ,SNR2: 320.04





BLK:10,SNR1: 1.3211 ,SNR2: 2.7501




2318-244 2024/12/11 8.84UT TOYOKAWA-FUJI







2318-244 2024/12/11 8.84UT TOYOKAWA-KISO




F20241211174900




BLK: 4,SNR1: 1.6775 ,SNR2: 6.1520



K20241211174856



BLK: 4,SNR1:-0.21413E-01,SNR2: 0.68244



2318-244 2024/12/11 8.84UT FUJI -KISO

