




TOYOKAWA 1555-246 2025/02/15(046)06:08:13-06:11:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1602-174 2025/02/15(046)06:14:43-06:18:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1609-141 2025/02/15(046)06:21:46-06:25:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1614-172 2025/02/15(046)06:26:39-06:30:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1623-228 2025/02/15(046)06:35:59-06:39:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1631-222 2025/02/15(046)06:44:29-06:47:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1638-025 2025/02/15(046)06:50:06-06:53:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1644-106 2025/02/15(046)06:57:01-07:00:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1650+004 2025/02/15(046)07:02:21-07:05:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1656+053 2025/02/15(046)07:07:53-07:11:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1712-033 2025/02/15(046)07:24:23-07:27:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1730-13 2025/02/15(046)07:42:26-07:45:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 1748+031 2025/02/15(046)07:59:50-08:03:16JST


20094+/- 382




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1759+13 2025/02/15(046)08:10:43-08:14:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1819-096 2025/02/15(046)08:31:43-08:35:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1830-210 2025/02/15(046)08:42:59-08:46:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1842+066 2025/02/15(046)08:53:33-08:56:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1858+171 2025/02/15(046)09:09:23-09:12:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1908-20 2025/02/15(046)09:20:08-09:23:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1915-121 2025/02/15(046)09:26:59-09:30:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1928-142 2025/02/15(046)09:40:40-09:44:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1938-15 2025/02/15(046)09:50:19-09:53:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2007+502 2025/02/15(046)10:17:31-10:20:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2014+358 2025/02/15(046)10:25:15-10:28:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C422 2025/02/15(046)10:55:52-10:59:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2025/02/15(046)11:16:30-11:19:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2025/02/15(046)11:42:15-11:45:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2135-209 2025/02/15(046)11:46:34-11:50:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2147+145 2025/02/15(046)11:58:53-12:02:19JST


18220+/- 192




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2156-043 2025/02/15(046)12:07:58-12:11:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2203-18 2025/02/15(046)12:14:46-12:18:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2210+016 2025/02/15(046)12:21:08-12:24:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 2218+395 2025/02/15(046)12:28:49-12:32:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C446

2025/02/15(046)12:34:18-12:37:44JST


13896+/- 574




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2229-093 2025/02/15(046)12:41:01-12:44:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2235+511 2025/02/15(046)12:45:34-12:49:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2239+333 2025/02/15(046)12:49:46-12:53:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2243+394 2025/02/15(046)12:54:04-12:57:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C454.3 2025/02/15(046)13:02:18-13:05:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2259+481 2025/02/15(046)13:10:00-13:13:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C456

2025/02/15(046)13:20:48-13:24:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C459


2025/02/15(046)13:24:54-13:28:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2318-16 2025/02/15(046)13:29:22-13:32:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2325+269 2025/02/15(046)13:36:14-13:39:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2344+09 2025/02/15(046)13:54:52-13:58:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2347-02 2025/02/15(046)13:58:39-14:02:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2354+14 2025/02/15(046)14:05:32-14:08:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C2

2025/02/15(046)14:14:35-14:18:01JST

12841+/- 4977




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0011+344 2025/02/15(046)14:21:57-14:25:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0019-00 2025/02/15(046)14:30:33-14:33:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C12

2025/02/15(046)14:40:48-14:44:14JST


13523+/- 75




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0038+328 2025/02/15(046)14:49:06-14:52:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )



TOYOKAWA 0044-056 2025/02/15(046)14:54:49-14:58:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C26

2025/02/15(046)15:02:11-15:05:37JST


12571+/- 385




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0056-00 2025/02/15(046)15:07:09-15:10:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0106+01 2025/02/15(046)15:16:52-15:20:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0115-01 2025/02/15(046)15:26:14-15:29:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0120+405 2025/02/15(046)15:31:36-15:35:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0128+03 2025/02/15(046)15:39:14-15:42:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C48


2025/02/15(046)15:45:48-15:49:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0148+274 2025/02/15(046)15:59:31-16:02:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0155-109 2025/02/15(046)16:05:32-16:08:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0202+15 2025/02/15(046)16:12:40-16:16:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0213+178 2025/02/15(046)16:24:30-16:27:56JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C67

2025/02/15(046)16:32:12-16:35:38JST

12417+/- 134




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C71


2025/02/15(046)16:50:27-16:53:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0320+05 2025/02/15(046)17:31:03-17:34:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0332-187 2025/02/15(046)17:42:34-17:46:00JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0338-196 2025/02/15(046)17:48:35-17:52:01JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

