




TOYOKAWA 1915+556 2025/04/16(106)05:29:03-05:32:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1931+364 2025/04/16(106)05:46:17-05:49:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1936+266 2025/04/16(106)05:51:45–05:55:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 1941+336 2025/04/16(106)05:56:27-05:59:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 1945+267 2025/04/16(106)06:00:12-06:03:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1949+115 2025/04/16(106)06:04:27-06:07:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1954+513 2025/04/16(106)06:08:05-06:11:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 1958+252 2025/04/16(106)06:12:51-06:16:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2001+003 2025/04/16(106)06:16:33-06:19:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 2007+502 2025/04/16(106)06:21:37-06:25:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2009-162 2025/04/16(106)06:25:43-06:29:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2014+358 2025/04/16(106)06:29:21-06:32:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2018+231 2025/04/16(106)06:33:46-06:37:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2022+119 2025/04/16(106)06:37:29-06:40:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2025-155 2025/04/16(106)06:41:09-06:44:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2029-018 2025/04/16(106)06:45:20-06:48:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2034-066 2025/04/16(106)06:49:36-06:53:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2038-013 2025/04/16(106)06:54:05-06:57:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 3C422 2025/04/16(106)06:59:58-07:03:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2049+166 2025/04/16(106)07:04:09–07:07:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2054+570 2025/04/16(106)07:08:13–07:11:39JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2056+028 2025/04/16(106)07:11:54-07:15:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2101+139 2025/04/16(106)07:16:18-07:19:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2105-072 2025/04/16(106)07:20:36-07:24:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2109+328 2025/04/16(106)07:24:22-07:27:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2114+608 2025/04/16(106)07:28:11-07:31:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2116-250 2025/04/16(106)07:31:58-07:35:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2120-102 2025/04/16(106)07:35:41-07:39:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2124+349 2025/04/16(106)07:39:31-07:42:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2131+379 2025/04/16(106)07:46:21-07:49:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2135-209 2025/04/16(106)07:50:39-07:54:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2139+028 2025/04/16(106)07:54:53-07:58:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2147+145 2025/04/16(106)08:02:59–08:06:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2152+450 2025/04/16(106)08:06:41-08:10:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2156-043 2025/04/16(106)08:12:03-08:15:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2203-18 2025/04/16(106)08:18:52-08:22:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 2210+016 2025/04/16(106)08:25:14–08:28:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2217+128 2025/04/16(106)08:32:37-08:36:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C446


2025/04/16(106)08:38:24-08:41:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2229-093 2025/04/16(106)08:45:07-08:48:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2235+511 2025/04/16(106)08:49:40-08:53:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2238-113 2025/04/16(106)08:53:35-08:57:01JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C454.3 2025/04/16(106)09:06:23-09:09:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2259+481 2025/04/16(106)09:14:06–09:17:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 3C456

2025/04/16(106)09:24:54-09:28:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C459


2025/04/16(106)09:29:00–09:32:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2318-16 2025/04/16(106)09:33:27-09:36:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2325+269 2025/04/16(106)09:40:20-09:43:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2344+09 2025/04/16(106)09:58:58–10:02:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 2347-02 2025/04/16(106)10:02:45-10:06:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 2354+14 2025/04/16(106)10:09:38–10:13:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C2

2025/04/16(106)10:18:41-10:22:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0011+344 2025/04/16(106)10:26:03–10:29:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0019-00 2025/04/16(106)10:34:39-10:38:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C12


2025/04/16(106)10:44:54–10:48:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0038+328 2025/04/16(106)10:53:12–10:56:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0044-056 2025/04/16(106)10:58:55-11:02:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C26


2025/04/16(106)11:06:17-11:09:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0056-00 2025/04/16(106)11:11:15-11:14:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0106+01 2025/04/16(106)11:20:57-11:24:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0115-01 2025/04/16(106)11:30:20-11:33:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




11143+/- 238




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0128+03 2025/04/16(106)11:43:20-11:46:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C48


2025/04/16(106)11:49:54–11:53:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0148+274 2025/04/16(106)12:03:37-12:07:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0155-109 2025/04/16(106)12:09:38-12:13:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0202+15 2025/04/16(106)12:16:46–12:20:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0213+178 2025/04/16(106)12:28:36–12:32:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






TOYOKAWA 0223+341 2025/04/16(106)12:38:10–12:41:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 3C71


2025/04/16(106)12:54:33-12:57:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0258+350 2025/04/16(106)13:13:48–13:17:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0308+305 2025/04/16(106)13:23:38–13:27:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0320+05 2025/04/16(106)13:35:09–13:38:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0324+119 2025/04/16(106)13:39:14–13:42:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0333+32 2025/04/16(106)13:48:31–13:51:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0347+05 2025/04/16(106)14:01:32-14:04:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0355+50 2025/04/16(106)14:11:46–14:15:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0403-132 2025/04/16(106)14:17:06-14:20:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0411+05 2025/04/16(106)14:26:17-14:29:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0418+236 2025/04/16(106)14:33:11–14:36:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0422+178 2025/04/16(106)14:37:10–14:40:36JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0531+194 2025/04/16(106)15:46:19–15:49:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 3C147     2025/04/16(106)15:54:40–15:58:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )




TOYOKAWA 0548+16 2025/04/16(106)16:02:50-16:06:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0552+12 2025/04/16(106)16:07:01-16:10:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0556+191 2025/04/16(106)16:11:28–16:14:54JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2 )







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0652-130 2025/04/16(106)17:05:54-17:09:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)







TOYOKAWA 0703+138 2025/04/16(106)17:17:31-17:20:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)




TOYOKAWA 0732+33 2025/04/16(106)17:47:20-17:50:46JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)



TOYOKAWA 0744+464 2025/04/16(106)17:59:17-18:02:43JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE ( 2)

