




TOYOKAWA 2054+570 2025/06/03(154)03:59:29-04:02:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2104+570 2025/06/03(154)04:08:55-04:12:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2110+567 2025/06/03(154)04:15:43-04:19:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2114+608 2025/06/03(154)04:19:27-04:22:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2124+641 2025/06/03(154)04:28:44-04:32:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2146+608 2025/06/03(154)04:51:40-04:55:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2152+450 2025/06/03(154)04:57:57-05:01:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2156+435 2025/06/03(154)05:02:34-05:06:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2200+420 2025/06/03(154)05:06:23-05:09:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2207+374 2025/06/03(154)05:13:04-05:16:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2213+353 2025/06/03(154)05:19:08–05:22:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2218+395 2025/06/03(154)05:24:12–05:27:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2222+345 2025/06/03(154)05:27:58-05:31:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2227+444 2025/06/03(154)05:33:00-05:36:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2231+357 2025/06/03(154)05:37:19-05:40:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2235+511 2025/06/03(154)05:40:57-05:44:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2239+333 2025/06/03(154)05:45:09-05:48:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2243+394 2025/06/03(154)05:49:26–05:52:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2246+205 2025/06/03(154)05:53:03-05:56:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C454.3 2025/06/03(154)05:57:40-06:01:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2255+092 2025/06/03(154)06:01:26-06:04:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2259+481 2025/06/03(154)06:05:23-06:08:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2304+006 2025/06/03(154)06:10:27-06:13:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C456

2025/06/03(154)06:16:11-06:19:37JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



2025/06/03(154)06:20:16-06:23:42JST


Figure 1 is a plot of Intensity [7841-12745] versus Time (min). The y-axis ranges from 0 to 10540 +/- 212. The x-axis ranges from 0 to 3 minutes. The plot shows a noisy signal with several peaks and troughs, indicating the presence of the 7841-12745 transition.

Normalized Power


Frequency (Hz)

Tot.P:	2150.4
NosLv:	5.2224
StDev:	1.0600
NosPo:	103.79
PS-P:	2046.6
S/N R:	19.720
Sci.P:	2047.9
N.ScP:	46.422
MaxLv:	11516.


TOYOKAWA 2318-001 2025/06/03(154)06:25:07-06:28:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2325+269 2025/06/03(154)06:31:37-06:35:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2329+172 2025/06/03(154)06:35:38–06:39:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2334+085 2025/06/03(154)06:40:19–06:43:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2344+09 2025/06/03(154)06:50:15-06:53:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2347-02 2025/06/03(154)06:54:01-06:57:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 2354+14 2025/06/03(154)07:00:55-07:04:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C2


2025/06/03(154)07:09:58-07:13:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0011+344 2025/06/03(154)07:17:19–07:20:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0019-00 2025/06/03(154)07:25:56-07:29:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C12


2025/06/03(154)07:36:10-07:39:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0038+328 2025/06/03(154)07:44:28–07:47:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0044-056 2025/06/03(154)07:50:12-07:53:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C26


2025/06/03(154)07:57:33-08:00:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0056-00 2025/06/03(154)08:02:32-08:05:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0106+01 2025/06/03(154)08:12:14–08:15:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0115-01 2025/06/03(154)08:21:37-08:25:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0120+405 2025/06/03(154)08:26:59–08:30:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0128+03 2025/06/03(154)08:34:37-08:38:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C48


2025/06/03(154)08:41:11-08:44:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0148-092 2025/06/03(154)08:54:06-08:57:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0155-109 2025/06/03(154)09:00:55-09:04:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0202+15 2025/06/03(154)09:08:02-09:11:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0213+178 2025/06/03(154)09:19:53–09:23:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0223+341 2025/06/03(154)09:29:26–09:32:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C71


2025/06/03(154)09:45:50-09:49:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2025/06/03(154)10:05:05–10:08:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0308+305 2025/06/03(154)10:14:54–10:18:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C84


2025/06/03(154)10:23:15–10:26:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2025/06/03(154)10:30:31–10:33:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2025/06/03(154)10:39:47-10:43:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2025/06/03(154)10:52:49–10:56:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2025/06/03(154)11:03:03–11:06:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2025/06/03(154)11:08:23-11:11:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2025/06/03(154)11:17:34-11:21:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2025/06/03(154)11:24:28–11:27:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0422+178 2025/06/03(154)11:28:27-11:31:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C119 2025/06/03(154)11:35:56–11:39:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138


2025/06/03(154)12:24:03-12:27:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0531+194 2025/06/03(154)12:37:36–12:41:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147


2025/06/03(154)12:45:57-12:49:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2025/06/03(154)12:54:07-12:57:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2025/06/03(154)12:58:18–13:01:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2025/06/03(154)13:02:45–13:06:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0605-08 2025/06/03(154)13:10:30-13:13:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158

2025/06/03(154)13:24:23-13:27:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161


2025/06/03(154)13:29:38–13:33:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2025/06/03(154)13:57:11-14:00:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2025/06/03(154)14:08:48–14:12:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2025/06/03(154)14:18:10-14:21:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2025/06/03(154)14:21:50–14:25:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2025/06/03(154)14:28:22-14:31:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2025/06/03(154)14:38:37-14:42:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2025/06/03(154)14:46:38-14:50:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2025/06/03(154)14:56:23-14:59:49JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2025/06/03(154)15:11:03-15:14:29JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2025/06/03(154)15:23:07–15:26:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2025/06/03(154)15:27:33-15:30:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2025/06/03(154)15:39:12-15:42:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2025/06/03(154)15:44:17-15:47:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2025/06/03(154)16:01:38-16:05:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2025/06/03(154)16:12:00-16:15:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2025/06/03(154)16:16:44-16:20:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2025/06/03(154)16:24:11-16:27:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2025/06/03(154)16:30:50-16:34:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2025/06/03(154)16:45:35-16:49:01JST





DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)






DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2025/06/03(154)17:16:14–17:19:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)







DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




9343+/- 24




TOYOKAWA 1043+158 2025/06/03(154)17:48:00–17:51:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1049+207 2025/06/03(154)17:54:19–17:57:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1101+596 2025/06/03(154)18:06:41-18:10:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1113+596 2025/06/03(154)18:18:07–18:21:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1124+498 2025/06/03(154)18:28:58-18:32:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1129+636 2025/06/03(154)18:34:26–18:37:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1138+594 2025/06/03(154)18:42:36–18:46:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1145+485 2025/06/03(154)18:49:34–18:53:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2025/06/03(154)18:58:59–19:02:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1159+583 2025/06/03(154)19:03:42-19:07:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1204+544 2025/06/03(154)19:08:50-19:12:16JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1215+643 2025/06/03(154)19:19:10–19:22:36JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

