




TOYOKAWA 2327+568 2025/07/08(189)04:15:53-04:19:19JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 2341+535 2025/07/08(189)04:29:48–04:33:14JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0017+565 2025/07/08(189)05:05:54–05:09:20JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0025+373 2025/07/08(189)05:14:12–05:17:38JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0031+391 2025/07/08(189)05:20:13–05:23:39JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0038+328 2025/07/08(189)05:26:52-05:30:18JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0044+301 2025/07/08(189)05:33:02–05:36:28JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0049+379 2025/07/08(189)05:38:14–05:41:40JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0100+256 2025/07/08(189)05:48:44-05:52:10JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0103+422 2025/07/08(189)05:52:40–05:56:06JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0108+258 2025/07/08(189)05:57:14–06:00:40JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0116+31 2025/07/08(189)06:05:27-06:08:53JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0120+405 2025/07/08(189)06:09:22-06:12:48JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0128+03 2025/07/08(189)06:17:00-06:20:26JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C48


2025/07/08(189)06:23:34–06:27:00JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0148+274 2025/07/08(189)06:37:17-06:40:43JST 206Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0155-109 2025/07/08(189)06:43:18-06:46:44JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0202+15 2025/07/08(189)06:50:26-06:53:52JST 207Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0213+178 2025/07/08(189)07:02:16–07:05:42JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C67

2025/07/08(189)07:09:59–07:13:25JST 195Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C71


2025/07/08(189)07:28:13–07:31:39JST 202Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2025/07/08(189)07:47:29–07:50:55JST 178Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2025/07/08(189)07:57:18–08:00:44JST 174Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2025/07/08(189)08:08:49-08:12:15JST 182Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2025/07/08(189)08:12:54–08:16:20JST 175Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2025/07/08(189)08:22:11-08:25:37JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2025/07/08(189)08:35:12-08:38:38JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2025/07/08(189)08:45:26-08:48:52JST 157Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2025/07/08(189)08:50:46-08:54:12JST 183Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2025/07/08(189)09:06:52-09:10:18JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0422+178 2025/07/08(189)09:10:50–09:14:16JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C119 2025/07/08(189)09:18:19–09:21:45JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138 2025/07/08(189)10:06:26–10:09:52JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0531+194 2025/07/08(189)10:20:00–10:23:26JST 82Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147 2025/07/08(189)10:28:20-10:31:46JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2025/07/08(189)10:36:31-10:39:57JST 71Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2025/07/08(189)10:40:41-10:44:07JST 74Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2025/07/08(189)10:45:08–10:48:34JST 61Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0605-08 2025/07/08(189)10:52:54-10:56:20JST 123Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158 2025/07/08(189)11:06:47-11:10:13JST 51Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161 2025/07/08(189)11:12:01–11:15:27JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2025/07/08(189)11:39:34-11:43:00JST 127Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2025/07/08(189)11:51:11–11:54:37JST 33Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2025/07/08(189)12:00:34-12:04:00JST 92Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2025/07/08(189)12:04:14–12:07:40JST 76Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2025/07/08(189)12:10:46–12:14:12JST 47Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2025/07/08(189)12:21:01–12:24:27JST 46Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2025/07/08(189)12:29:02-12:32:28JST 110Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2025/07/08(189)12:38:46-12:42:12JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2025/07/08(189)12:46:21–12:49:47JST 56Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2025/07/08(189)12:53:26-12:56:52JST 128Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196 2025/07/08(189)12:58:47-13:02:13JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2025/07/08(189)13:05:30–13:08:56JST 65Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2025/07/08(189)13:09:56–13:13:22JST 86Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2025/07/08(189)13:21:35-13:25:01JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2025/07/08(189)13:26:41-13:30:07JST 133Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208 2025/07/08(189)13:37:42-13:41:08JST 96Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2025/07/08(189)13:44:02-13:47:28JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2025/07/08(189)13:54:24–13:57:50JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2025/07/08(189)13:59:07-14:02:33JST 160Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2025/07/08(189)14:06:35-14:10:01JST 165Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2025/07/08(189)14:13:14–14:16:40JST 125Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2025/07/08(189)14:20:58-14:24:24JST 140Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2025/07/08(189)14:27:58-14:31:24JST 164Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230 2025/07/08(189)14:36:20–14:39:46JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C237 2025/07/08(189)14:52:21-14:55:47JST 155Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1011+110 2025/07/08(189)14:58:37–15:02:03JST 156Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241


2025/07/08(189)15:06:18–15:09:44JST 152Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2025/07/08(189)15:17:47-15:21:13JST 190Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2025/07/08(189)15:22:21-15:25:47JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2025/07/08(189)15:31:34-15:35:00JST 185Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2025/07/08(189)15:42:38–15:46:04JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2025/07/08(189)15:53:56–15:57:22JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2025/07/08(189)16:03:33-16:06:59JST 199Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2025/07/08(189)16:14:11-16:17:37JST 209Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2025/07/08(189)16:23:14-16:26:40JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2025/07/08(189)16:27:31-16:30:57JST 194Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2025/07/08(189)16:33:58–16:37:24JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2025/07/08(189)16:41:23–16:44:49JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2025/07/08(189)16:53:12–16:56:38JST 196Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2025/07/08(189)16:59:46-17:03:12JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2025/07/08(189)17:13:03-17:16:29JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1237-030 2025/07/08(189)17:23:35-17:27:01JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1256+215 2025/07/08(189)17:42:23–17:45:49JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1303+192 2025/07/08(189)17:49:35–17:53:01JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1308+277 2025/07/08(189)17:54:50–17:58:16JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2025/07/08(189)17:59:50–18:03:16JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2025/07/08(189)18:09:56–18:13:22JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2025/07/08(189)18:14:46-18:18:12JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1335+479 2025/07/08(189)18:21:09–18:24:35JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1339+472 2025/07/08(189)18:25:14–18:28:40JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1351+586 2025/07/08(189)18:36:13–18:39:39JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1358+538 2025/07/08(189)18:43:38–18:47:04JST 214Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1448+634 2025/07/08(189)19:32:10–19:35:36JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

