




TOYOKAWA 0147+400 2025/07/27(208)05:21:32-05:24:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0152+435 2025/07/27(208)05:26:44-05:30:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0157+442 2025/07/27(208)05:31:54–05:35:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0204+327 2025/07/27(208)05:38:04–05:41:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0211+348 2025/07/27(208)05:46:07-05:49:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C67


2025/07/27(208)05:55:17-05:58:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2025/07/27(208)06:32:47-06:36:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2025/07/27(208)06:42:36–06:46:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2025/07/27(208)06:54:07-06:57:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2025/07/27(208)06:58:12-07:01:38JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2025/07/27(208)07:07:29–07:10:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2025/07/27(208)07:20:30-07:23:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2025/07/27(208)07:30:44-07:34:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2025/07/27(208)07:36:04-07:39:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2025/07/27(208)07:45:15–07:48:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2025/07/27(208)07:52:10–07:55:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0422+178 2025/07/27(208)07:56:08–07:59:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C119

2025/07/27(208)08:03:37-08:07:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138


2025/07/27(208)08:51:44–08:55:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0531+194 2025/07/27(208)09:05:18–09:08:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147


2025/07/27(208)09:13:38–09:17:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2025/07/27(208)09:21:49–09:25:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2025/07/27(208)09:25:59–09:29:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2025/07/27(208)09:30:26–09:33:52JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C152 2025/07/27(208)09:34:59-09:38:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158

2025/07/27(208)09:52:05–09:55:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161


2025/07/27(208)09:57:19–10:00:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2025/07/27(208)10:24:52-10:28:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2025/07/27(208)10:36:29–10:39:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2025/07/27(208)10:45:52-10:49:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2025/07/27(208)10:49:32–10:52:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2025/07/27(208)10:56:04–10:59:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2025/07/27(208)11:06:19–11:09:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2025/07/27(208)11:14:20-11:17:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2025/07/27(208)11:24:04-11:27:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2025/07/27(208)11:31:39–11:35:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0806-103 2025/07/27(208)11:38:44-11:42:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196


2025/07/27(208)11:44:05–11:47:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2025/07/27(208)11:55:14–11:58:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2025/07/27(208)12:06:53-12:10:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0839-071 2025/07/27(208)12:11:59-12:15:25JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208


2025/07/27(208)12:23:00–12:26:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2025/07/27(208)12:29:20-12:32:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2025/07/27(208)12:39:42-12:43:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2025/07/27(208)12:44:25-12:47:51JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2025/07/27(208)12:51:52-12:55:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2025/07/27(208)12:58:32–13:01:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2025/07/27(208)13:06:16–13:09:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2025/07/27(208)13:13:16-13:16:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230 2025/07/27(208)13:21:38–13:25:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C236 2025/07/27(208)13:35:46–13:39:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1011+110 2025/07/27(208)13:43:55–13:47:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241


2025/07/27(208)13:51:36–13:55:02JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2025/07/27(208)14:03:05-14:06:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2025/07/27(208)14:07:39-14:11:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2025/07/27(208)14:16:51-14:20:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2025/07/27(208)14:27:56–14:31:22JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2025/07/27(208)14:39:14–14:42:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2025/07/27(208)14:48:51-14:52:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2025/07/27(208)14:59:28-15:02:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2025/07/27(208)15:08:32-15:11:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2025/07/27(208)15:12:49–15:16:15JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2025/07/27(208)15:19:16–15:22:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2025/07/27(208)15:26:41-15:30:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2025/07/27(208)15:38:30–15:41:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1213-17 2025/07/27(208)15:45:04-15:48:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273


2025/07/27(208)15:58:21-16:01:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2025/07/27(208)16:11:32-16:14:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1245-19 2025/07/27(208)16:17:37-16:21:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C279 2025/07/27(208)16:25:20-16:28:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283


2025/07/27(208)16:40:50–16:44:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2025/07/27(208)16:45:08–16:48:34JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2025/07/27(208)16:55:14–16:58:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2025/07/27(208)17:00:04–17:03:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2025/07/27(208)17:16:32-17:19:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2025/07/27(208)17:26:52-17:30:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1408+141 2025/07/27(208)17:39:52-17:43:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C296


2025/07/27(208)17:45:46–17:49:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1427+220 2025/07/27(208)17:58:11–18:01:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1438+357 2025/07/27(208)18:09:40-18:13:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1452+502 2025/07/27(208)18:22:31-18:25:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1501+456 2025/07/27(208)18:31:47-18:35:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



8172+/- 28



TOYOKAWA 1536+574 2025/07/27(208)19:05:26–19:08:52JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

