




TOYOKAWA 0158+531 2025/08/05(217)04:57:49–05:01:15JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0219+545 2025/08/05(217)05:19:03–05:22:29JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0225+494 2025/08/05(217)05:24:41-05:28:07JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0232+411 2025/08/05(217)05:31:42-05:35:08JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0239+322 2025/08/05(217)05:37:49–05:41:15JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0244+377 2025/08/05(217)05:43:17–05:46:43JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0250+358 2025/08/05(217)05:49:08–05:52:34JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0258+350 2025/08/05(217)05:57:24-06:00:50JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0302+341 2025/08/05(217)06:01:19–06:04:45JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0308+305 2025/08/05(217)06:07:13–06:10:39JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0320+05 2025/08/05(217)06:18:44-06:22:10JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0324+119 2025/08/05(217)06:22:49–06:26:15JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2025/08/05(217)06:32:06–06:35:32JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2025/08/05(217)06:45:07-06:48:33JST 211Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2025/08/05(217)06:55:21-06:58:47JST 201Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2025/08/05(217)07:00:41-07:04:07JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2025/08/05(217)07:09:52-07:13:18JST 205Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2025/08/05(217)07:16:46–07:20:12JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0422+178 2025/08/05(217)07:20:45–07:24:11JST 197Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C119 2025/08/05(217)07:28:14–07:31:40JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138


2025/08/05(217)08:16:21–08:19:47JST 172Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0531+194 2025/08/05(217)08:29:54–08:33:20JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147 2025/08/05(217)08:38:15–08:41:41JST 170Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2025/08/05(217)08:46:25-08:49:51JST 154Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2025/08/05(217)08:50:36–08:54:02JST 153Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158 2025/08/05(217)09:16:41-09:20:07JST 134Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C161 2025/08/05(217)09:21:56–09:25:22JST 151Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2025/08/05(217)09:49:29-09:52:55JST 149Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2025/08/05(217)10:01:06–10:04:32JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2025/08/05(217)10:10:28-10:13:54JST 116Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2025/08/05(217)10:14:09–10:17:35JST 105Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2025/08/05(217)10:20:40-10:24:06JST 87Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2025/08/05(217)10:30:56–10:34:22JST 91Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2025/08/05(217)10:38:57-10:42:23JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2025/08/05(217)10:48:41-10:52:07JST 141Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2025/08/05(217)10:56:16–10:59:42JST 54Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2025/08/05(217)11:03:21-11:06:47JST 109Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196 2025/08/05(217)11:08:42-11:12:08JST 117Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2025/08/05(217)11:15:25–11:18:51JST 35Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2025/08/05(217)11:19:51–11:23:17JST 87Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2025/08/05(217)11:31:30-11:34:56JST 132Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0839-071 2025/08/05(217)11:36:36-11:40:02JST 91Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208 2025/08/05(217)11:47:37-11:51:03JST 13Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0857-191 2025/08/05(217)11:53:56-11:57:22JST 129Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216


2025/08/05(217)12:04:19–12:07:45JST 95Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2025/08/05(217)12:09:02-12:12:28JST 111Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2025/08/05(217)12:16:29-12:19:55JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2025/08/05(217)12:23:09–12:26:35JST 33Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2025/08/05(217)12:30:53–12:34:19JST 57Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2025/08/05(217)12:37:53-12:41:19JST 100Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C230 2025/08/05(217)12:46:15–12:49:41JST 78Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C236 2025/08/05(217)13:00:23-13:03:49JST 85Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1011+110 2025/08/05(217)13:08:32–13:11:58JST 70Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241 2025/08/05(217)13:16:13–13:19:39JST 73Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2025/08/05(217)13:27:42-13:31:08JST 131Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2025/08/05(217)13:32:16-13:35:42JST 119Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2025/08/05(217)13:41:28-13:44:54JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2025/08/05(217)13:52:33–13:55:59JST 118Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1107+109 2025/08/05(217)14:03:50–14:07:16JST 115Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255


2025/08/05(217)14:13:28–14:16:54JST 139Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2025/08/05(217)14:24:05-14:27:31JST 163Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2025/08/05(217)14:33:09-14:36:35JST 166Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2025/08/05(217)14:37:26–14:40:52JST 135Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2025/08/05(217)14:43:53-14:47:19JST 143Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2025/08/05(217)14:51:18–14:54:44JST 168Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2025/08/05(217)15:03:07-15:06:33JST 161Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2025/08/05(217)15:09:41-15:13:07JST 187Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2025/08/05(217)15:22:58–15:26:24JST 174Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2025/08/05(217)15:36:09–15:39:35JST 186Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1245-19 2025/08/05(217)15:42:14-15:45:40JST 200Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C279


2025/08/05(217)15:49:57-15:53:23JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283 2025/08/05(217)16:05:27-16:08:53JST 208Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2025/08/05(217)16:09:45–16:13:11JST 188Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2025/08/05(217)16:19:51-16:23:17JST 191Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2025/08/05(217)16:24:41-16:28:07JST 193Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2025/08/05(217)16:31:19-16:34:45JST 212Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2025/08/05(217)16:41:08–16:44:34JST 203Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2025/08/05(217)16:51:29–16:54:55JST 210Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2025/08/05(217)17:12:40-17:16:06JST 213Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2025/08/05(217)17:24:23-17:27:49JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1434+03 2025/08/05(217)17:30:25–17:33:51JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)





TOYOKAWA 1452+16 2025/08/05(217)17:47:41-17:51:07JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




6500+/- 31




TOYOKAWA 1504+323 2025/08/05(217)17:59:18–18:02:44JST 215Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1512+370 2025/08/05(217)18:07:48–18:11:14JST 216Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1522+546 2025/08/05(217)18:16:52-18:20:18JST 214Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1526+378 2025/08/05(217)18:21:29–18:24:55JST 217Rs




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1536+574 2025/08/05(217)18:30:03–18:33:29JST 215Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1545+497 2025/08/05(217)18:40:06–18:43:32JST 216Rs



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

