




TOYOKAWA 0255+460 2025/08/11(223)05:30:45-05:34:11JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0301+350 2025/08/11(223)05:36:58-05:40:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0308+305 2025/08/11(223)05:43:37-05:47:03JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C84


2025/08/11(223)05:51:58–05:55:24JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0322+245 2025/08/11(223)05:57:02-06:00:28JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0326+455 2025/08/11(223)06:02:33-06:05:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0333+32 2025/08/11(223)06:08:30-06:11:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0337+319 2025/08/11(223)06:12:09–06:15:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0347+05 2025/08/11(223)06:21:32-06:24:58JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0349+382 2025/08/11(223)06:25:14-06:28:40JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0355+50 2025/08/11(223)06:31:46–06:35:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0403-132 2025/08/11(223)06:37:06-06:40:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0406+386 2025/08/11(223)06:41:24-06:44:50JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0411+05 2025/08/11(223)06:46:17-06:49:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0418+236 2025/08/11(223)06:53:11–06:56:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0422+178 2025/08/11(223)06:57:10–07:00:36JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C119

2025/08/11(223)07:04:39–07:08:05JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C138


2025/08/11(223)07:52:46–07:56:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0531+194 2025/08/11(223)08:06:19–08:09:45JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C147 2025/08/11(223)08:14:40–08:18:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0548+16 2025/08/11(223)08:22:50–08:26:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0552+12 2025/08/11(223)08:27:01-08:30:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0556+191 2025/08/11(223)08:31:28–08:34:54JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C152 2025/08/11(223)08:36:00-08:39:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C158


2025/08/11(223)08:53:06–08:56:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0652-130 2025/08/11(223)09:25:54-09:29:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0703+138 2025/08/11(223)09:37:31–09:40:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0713-024 2025/08/11(223)09:46:53-09:50:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0716+022 2025/08/11(223)09:50:33–09:53:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0723+10 2025/08/11(223)09:57:05–10:00:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0732+33 2025/08/11(223)10:07:20–10:10:46JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0741-06 2025/08/11(223)10:15:21-10:18:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0752-200 2025/08/11(223)10:25:05-10:28:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C190 2025/08/11(223)10:32:41-10:36:07JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0806-103 2025/08/11(223)10:39:46-10:43:12JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C196 2025/08/11(223)10:45:06–10:48:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0817+183 2025/08/11(223)10:51:50–10:55:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0821+394 2025/08/11(223)10:56:16–10:59:42JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0834-19 2025/08/11(223)11:07:55-11:11:21JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 0839-071 2025/08/11(223)11:13:00-11:16:26JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C208


2025/08/11(223)11:24:01-11:27:27JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0857-191 2025/08/11(223)11:30:21-11:33:47JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C216 2025/08/11(223)11:40:43-11:44:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0912-132 2025/08/11(223)11:45:27-11:48:53JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0919-142 2025/08/11(223)11:52:54-11:56:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0926+117 2025/08/11(223)11:59:33–12:02:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C222 2025/08/11(223)12:07:18–12:10:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 0941-08 2025/08/11(223)12:14:18-12:17:44JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 3C230 2025/08/11(223)12:22:40-12:26:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C236


2025/08/11(223)12:36:47-12:40:13JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1011+110 2025/08/11(223)12:44:57–12:48:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C241


2025/08/11(223)12:52:38–12:56:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1031-11 2025/08/11(223)13:04:07-13:07:33JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1035-058 2025/08/11(223)13:08:40-13:12:06JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1044-008 2025/08/11(223)13:17:53-13:21:19JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1055+01 2025/08/11(223)13:28:57-13:32:23JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1059-010 2025/08/11(223)13:32:34-13:36:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1107+109 2025/08/11(223)13:40:15–13:43:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C255 2025/08/11(223)13:49:52-13:53:18JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1127-14 2025/08/11(223)14:00:30-14:03:56JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1136-13 2025/08/11(223)14:09:34-14:13:00JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C263.1 2025/08/11(223)14:13:50-14:17:16JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C267 2025/08/11(223)14:20:17-14:23:43JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1154+552 2025/08/11(223)14:27:42-14:31:08JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1206+439 2025/08/11(223)14:39:31–14:42:57JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1213-17 2025/08/11(223)14:46:05-14:49:31JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C273 2025/08/11(223)14:59:22–15:02:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C275 2025/08/11(223)15:12:33–15:15:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1245-19 2025/08/11(223)15:18:38-15:22:04JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C279

2025/08/11(223)15:26:22–15:29:48JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C283


2025/08/11(223)15:41:51–15:45:17JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1313+453 2025/08/11(223)15:46:09–15:49:35JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1323+32 2025/08/11(223)15:56:15–15:59:41JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C286 2025/08/11(223)16:01:06–16:04:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1334-17 2025/08/11(223)16:07:43-16:11:09JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1345+12 2025/08/11(223)16:17:33–16:20:59JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1355+01 2025/08/11(223)16:27:54–16:31:20JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C298 2025/08/11(223)16:49:04-16:52:30JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1428-03 2025/08/11(223)17:00:48-17:04:14JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1436-16 2025/08/11(223)17:09:29-17:12:55JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1452+16 2025/08/11(223)17:24:06–17:27:32JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1456+092 2025/08/11(223)17:29:11–17:32:37JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 3C318


2025/08/11(223)17:49:44-17:53:10JST




DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)




TOYOKAWA 1536+574 2025/08/11(223)18:06:27-18:09:53JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)



TOYOKAWA 1545+497 2025/08/11(223)18:16:31–18:19:57JST



DC REMOVAL:DRIFT WINDOW:HAMMING SMOOTHING:PRE (2)

